### **TSD File Inventory Index**

Date: August 14, 2001
Initial: Conference

Facility Name: Premix, Sc. (On Felder Sete)  Facility Identification Number: DHD 004 200 094								
Facility Identification Number: DHD 504	200	094						
A.1 General Correspondence	1/	B.2 Permit Docket (B.1.2)						
A.2 Part A / Interim Status	V	.1 Correspondence						
.1 Correspondence	1/	.2 All Other Permitting Documents (Not Part of the ARA)						
.2 Notification and Acknowledgment	Ty	C.1 Compliance - (Inspection Reports)	V					
.3 Part A Application and Amendments	Тy	C.2 Compliance/Enforcement						
.4 Financial Insurance (Sudden, Non Sudden)		.1 Land Disposal Restriction Notifications						
.5 Change Under Interim Status Requests		2 Import/Export Notifications						
.6 Annual and Biennial Reports		C.3 FOIA Exemptions - Non-Releasable Documents						
A.3 Groundwater Monitoring		D.1 Corrective Action/Facility Assessment						
.1 Correspondence		1 RFA Correspondence						
2 Reports		.2 Background Reports, Supporting Docs and Studies						
A.4 Closure/Post Closure	Ιv	.3 State Prelim. Investigation Memos						
.1 Correspondence	Ιγ	. 4 RFA Reports	χ					
.2 Closure/Post Closure Plans, Certificates, etc	X	D. 2 Corrective Action/Facility Investigation	1					
A.5 Ambient Air Monitoring		.1 RFI Correspondence						
.1 Correspondence		.2 RFI Workplan						
.2 Reports		.3 RFI Program Reports and Oversight						
B.1 Administrative Record		.4 RFI Draft /Final Report	1					

.5 RFI QAPP	.7 Leb data, Soli Sampling/Groundwater
.6 RFI QAPP Correspondence	.8 Progress Reports
.7 Lab Data, Soil-Sampling/Groundwater	D.5 Corrective Action/Enforcement
.8 RFI Progress Reports	.1 Administrative Record 3008(h) Order
.9 Interim Measures Correspondence	.2 Other Non-AR Documents
.10 Interim Measures Workplan and Reports	D.6 Environmental Indicator Determinations
3 Corrective Action/Remediation Study	.1 Forms/Checklists
.1 CMS Correspondence	E. Bollere and Industrial Furnaces (Bir)
.2 Interim Measures	.1 Correspondence
.3 CMS Workplan	.2 Reports
.4 CMS Draft/Final Report	F Imagery/Special Studies (Videos, photos, disks, maps, blueprints, drawings, and other special materials.)
' .5 Stabilization	G.1 Rick Assessment
.6 CMS Progress Reports	.1 Human/Ecological Assessment
.7 Lab Data, Soil-Sampling/Groundwater	.2 Compliance and Enforcement
).4 Corrective Action Remediation Implementation	.3 Enforcement Confidential
.1 CMM Correspondence	.4 Ecological - Administrative Record
.2 CMI Workplan	.5 Permitting
.3 CMI Program Reports and Oversight	.6 Corrective Action Remediation Study
4 CMI Druft/Final Reports	.7 Corrective Action/Remediation Implementation
.5 CMM QAPP	.8 Endengered Species Act

Note: Transmitted I after to Re inchesed	with Seconds	
Comments: Description ( co	Zet trestidas	individual felder per siladale!
	1 11	

A.1 Public Participation



State of Ohio Environmental Protection Agency

P.O. Box 1049, 1800 WaterMark Dr. Columbus, Ohio 43266-0149



Richard F. Celeste

Governor

January 8, 1988

Re: Premix, Inc.

Closure Plan

US EPA ID No.: OHDOO4200044 Ohio Permit No.: 02-04-0567

Premix, Inc.

Attn: Debra Hall, CHMM

Environmental/Industrial Hygiene Coordinator

Harmon Road & Route 20

N. Kingsville, Ohio 44068

Dear Madam:

A public notice acknowledging the Ohio EPA's receipt of a closure plan for Premix, Inc. located in N. Kingsville, Ohio, will appear the week of January 11, 1988, in <a href="https://doi.org/10.1088/">The Star Beacon</a>, Ashtabula, Ohio. The Director of the Ohio EPA will act upon the closure plan request following the close of the public comment period, February 17, 1988.

Copies of the closure plan will be available for public review at the Kingsville Public Library, Academy Street, Kingsville, Ohio 44048 and the Ohio EPA, Northeast District Office, 2110 East Aurora Road, Twinsburg, Ohio 44087.

Please contact me at (614) 481-7217, if you have any questions concerning this matter.

Sincerely,

Thomas E. Crepeau

Program Planning and Management Section

homas E. Crepeau

Division of Solid & Hazardous Waste Management

TEC/dhs

cc: Rebecca Strom, U.S. EPA, Region V Randy Meyer, Ohio EPA, DSHWM, TA&ES Theresa Sabol, Ohio EPA, DSHWM, NEDO

2044R(27)

RECELVED

JAN 1 3 1988

U.S. EPA. REGION V

### RECEIPT OF HAZARDOUS WASTE CLOSURE PLAN

For: Premix, Inc., U.S. EPA ID No.: OHD004200044, Ohio Permit No.: 02-04-0567, Harmon Road & Route 20, N. Kingsville, Ohio 44068. Pursuant to OAC Rule 3745-66-10 thru 17 and 40 CFR, Subpart G, 265.110 thru 117, the Ohio Environmental Protection Agency (Ohio EPA) is hereby giving notice of the receipt of a Hazardous Waste Facility Closure Plan for the above referenced facility. Ohio EPA is also giving notice that this facility is subject to a determination concerning corrective action, a requirement under the Hazardous and Solid Waste Amendments of 1984, which concerns any possible uncorrected releases of hazardous waste or hazardous constituents to the environment from any current or previous solid waste management units at the above facility. A corrective action determination is required from hazardous waste facilities intending to close.

Copies of the facility's Closure Plan will be available for public review at the Kingsville Public Library, Academy Street, Kingsville, Ohio 44048 and the Ohio EPA, Northeast District Office, 2110 East Aurora Road, Twinsburg, Ohio 44087.

Comments concerning the Closure Plan or factual information concerning any releases of hazardous waste or hazardous waste constituents by the above facility requiring corrective action should be submitted within 30 days of this notice to: Ohio Environmental Protection Agency, Div. of Solid & Hazardous Waste Mgmt., Program Planning and Management Section, Attn: Thomas E. Crepeau, Box 1049, Columbus, Ohio 43266-0149.



State of Ohio Environmental Protection Agency

P.O. Box 1049, 1800 WaterMark Dr. Columbus, Ohio 43266-0149



Richard F. Celeste Governor

August 27, 1987

Re: Premix, Inc.

US EPA ID No.: OHD004200044 Ohio Permit No.: 02-04-0567

Partial Closure Plan

Premix, Inc. Attn: Debra Hall Route 20 & Harmon Road N. Kingsville, Ohio 44068

Dear Madam:

A public notice acknowledging the Ohio EPA's receipt of a partial closure plan for Premix, Inc. in N. Kingsville, Ohio will appear the week of August 24, 1987, in <a href="The Star Beacon">The Star Beacon</a>, Ashtabula, Ohio. The Director of the Ohio EPA will act upon the partial closure plan request following the close of the public comment period, September 30, 1987.

Copies of the partial closure plan will be available for public review at the Ashtabula County District Library, 335 W. 44th Street, Ashtabula, Ohio 44004 and the Ohio EPA, Northeast District Office, 2110 East Aurora Road, Twinsburg, Ohio 44087.

Please contact me at (614) 481-7217, if you have any questions concerning this matter.

Sincerely,

Thomas E. Crepeau

Program Planning and Management Section

Marias E. Crepeau

Division of Solid & Hazardous Waste Management

TEC/dhs

cc: Rebecca Strom, U.S. EPA, Region V
Dan Fisher, OEPA, DSHWM, TA&ES
Debbie Berg, OEPA, DSHWM, NEDO

REGELVE

AUG 3 1 1987

U.S. EPA. REGION V

1013R

### RECEIPT OF HAZARDOUS WASTE PARTIAL CLOSURE PLAN

For: Premix, Inc., US EPA ID No.: OHD004200044, Ohio Permit No.: 02-04-0567, Route 20 & Harmon Road, N. Kingsville, Ohio 44068. The Ohio Environmental Protection Agency (Ohio EPA) is hereby giving notice of the receipt of a Hazardous Waste Facility Partial Closure Plan involving a container storage area for the above referenced facility.

Copies of the facility's Partial Closure Plan will be available for public review at the Ashtabula County District Library, 335 W. 44th Street, Ashtabula, Ohio 44004 and the Ohio EPA, Northeast District Office, 2110 East Aurora Road, Twinsburg, Ohio 44087.

Comments concerning the partial Closure Plan should be submitted before September 30, 1987 to: Thomas E. Crepeau, Div. of Solid & Hazardous Waste Mgmt., Program Planning and Management Section, P.O. Box 1049, 1800 WaterMark Drive, Columbus, Ohio 43266-0149.



WMD RCRA RECORD CENTER

George V. Voinovich Governor Donald R. Schregardus Director

P.O. Box 1049, 1800 WaterMark Dr. Columbus, Ohio 43266-0149 (614) 644-3020 FAX (614) 644-2329

May 11, 1993

Premix Inc.

Attn: Raymond A. Kovacs

P.O. Box 281

North Kingsville, OH 44068

RE: EPA ID#: OHD004200044

LOCATION of INSTALLATION: Harmon Rd and Rte 20

North Kingsville, OH 44068

In response to your request of March 1993 the following information has been updated:

Contact: Raymond A. Kovacs

Status: large quantity generator

If you have any questions, please contact Beth Barrett at (614)644-2977.

Sincerely,

Thomas E. Crepeau, Manager

Data Management Section

Division of Hazardous Waste Management

Thomas E. Crepeau

TEC/bab

cc: U.S. EPA, Region V

Ohio EPA District Office



## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION V

111 West Jackson Blvd. CHICAGO, ILLINOIS 60604

REPLY TO ACT ENTINE OF

MAY 19 1982

Debbi Hall, Env. Spec.

Premix Inc.

P.O. Box 281

N. Kingsville, Ohio 44068

RE: Interim Status Acknowledgement

USEPA ID No. OHDOO4200044

FACILITY NAME: Premix Inc.

Dear Ms. Hall:

This is to acknowledge that the U.S. Environmental Protection Agency (USEPA) has completed processing your Part A Hazardous Waste Permit Application. It is the opinion of this office that the information submitted is complete and that you, as an owner or operator of a hazardous waste management facility, have met the requirements of Section 3005(e) of the Resource Conservation and Recovery Act (RCRA) for Interim Status. However, should USEPA obtain information which indicates that your application was incomplete or inaccurate, you may be requested to provide further documentation of your claim for Interim Status. Our opinion will be reevaluated on the basis of this information.

As an owner or operator of a hazardous waste management facility, you are required to comply with the interim status standards as prescribed in 40 CFR Parts 122 and 265, or with State rules and regulations in those States which have been authorized under Section 3006 of RCRA. In addition, you are reminded that operating under interim status does not relieve you from the need to comply with all applicable State and local requirements.

The printout enclosed with this letter identifies the limit(s) of the process design capacities your facility may use during the interim status period. This information was obtained from your Part A Permit application. If you wish to handle new wastes, to change processes, to increase the design capacity of existing processes, or to change ownership or operational control of the facility, you may do so only as provided in 40 CFR Sections 122.22 and 122.23.

As stated in the first paragraph of this letter, you have met the requirements of 40 CFR Part 122.23; your facility may operate under interim status until such time as a permit is issued or denied. This will be preceded by a request from this office or the State (if authorized) for Part B of your application. Please contact Arthur Kawatachi of my staff at (312) 886-7449, if you have any questions concerning this letter or the enclosure.

Sincerely yours,

Karl J. Klepitsch, Jr., Chief

Waste Management Branch

-Enclosure

cc: Ford Davey, Sr. V/P

EPA ID NUMBER

FACILITY NAME

PREMIX INC

OHD004200044

FACILITY OPERATOR

PREMIX, INC

FACILITY OWNER

PREMIX INC

FACILITY LOCATION

HARMON RD AND RT 20 N KINGSVILLE

KEY

OH 44068

PROCESS CODE

DESIGN CAPACITY

UNIT OF MEASURE

S01

17270

G

PROCESS	PRO- APPROPRIATE CESS UNITS OF CODE MEASURE	* * UNIT OF * MEASURE CODE *
STORAGE:  CONTAINER TANK WASTE PILE SURFACE IMPOUNDMENT DISPOSAL:  INJECTION WELL LAND APPLICATION OCEAN DISPOSAL SURFACE IMPOUNDMENT TREATMENT:  TANK	\$01 G or L \$02 G or L \$03 Y or C \$04 G or L D79 G,L,U, or V D80 A or F D81 B or Q D82 U or V D83 G or L	* GALLONS G * LITERS L * CUBIC YARDS Y * CUBIC METERS C * GALLONS PER DAY U * LITERS PER DAY V * TONS PER HOUR D * METRIC TONS/HOUR W * GALLONS/HOUR E * LITERS/HOUR H * ACRE-FEET A * HECTARE-METER F * ACRES B * HECTARES Q * POUNDS/HOUR R
SURFACE IMPOUNDMENT INCTHERATOR OTHER	TO2 U or V TO3 D,W,E, or F TO4 U,V,J,R,N,	* TONS PER DAY N  * METRIC TONS/DAY S  *

or S

Form Approved OMB No. 158-S79016

GSA No. 0246-EPA-OT

om transport of the second of the second strong of the second of the second of the second second All Strong on the second of	n i de Maria de La Maria de Maria (m. 1864). 1840 - Maria Harris, de Maria de Maria (m. 1864). 1854 - Maria Daniel Maria de Maria (m. 1864).	in the property of the second		<b>\$</b> 0HD004	4200044 <del>7746</del>
X. DESCRIPTION OF H	AZARDOUS WAST	ES (continued from ;	front)		
A. HAZARDOUS WASTES F waste from non-specific s				40 CFR Part 261.31 fo	r each listed hazardo
	2			5	6
F002	FOOS	F017			
23 - 28 7	23 - 26 8	9	10	23 - 26	12
	23 - 261 	23 - 26	23 - 26	23 - 26	23 - 26
B. HAZARDOUS WASTES F specific industrial sources y	HOM SPECIFIC SOUR your installation handle	ICES. Enter the four—ous. Use additional sheets	ligit number from 40 CFI if necessary.	R Part 261,32 for each	isted hazardous waste from
13	14	15	16	17	18
23 - 26 19	23 - 26	23 - 26 21	23 + 26	23 - 26	23 - 26 2.6
23 - 26	23 - 26	23 ~ 26	23 - 26	23 - 26	23 - 26
25	26	27	28	29	30
23 + 26	23 + 26	23 - 26	23 - 26	23 + 26	23 - 26
C. COMMERCIAL CHEMICA stance your installation ha		DOUS WASTES. Enter	the four-digit number f	rom 40 CFR Part 261.	33 for each chemical sub-
31	32	33	34	35	36
23 - 26 37	38	39	23 - 26 40	23 - 26 41	23 - 26 42
<del>23 - 26</del>	23 - 26	23 = 26	23 - 26	23 - 26	23 - 26
43 		45	46	47	48
23 - 26	23 - 26	23 - 26	23 - 26	23 7 26	23 - 26
D. LISTED INFECTIOUS Wa hospitals, medical and rese		r-digit number from 40			e from hospitals, veterinary
49	50	51	52	53	54
E. CHARACTERISTICS OF	NON-LISTED HAZA	RDOUS WASTES. Mar	k "X" in the boxes corre	23 - 26 sponding to the charact	eristics of non-listed
hazardous wastes your inst				<i>90</i> 0,311 <b>3</b> 12 - 12 - 17	
区1, IGNITABI (19001)		2. CORROSIVE 002)	☐3. REAC (D003)	TIVE	(A. TOXIC
X. CERTIFICATION	•		()		
I certify under penalty	of law that I have	-12-			, , , , , , , , , , , , , , , , , , , ,

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

SIGNATURE, 2001

NAME & OFFICIAL TITLE (type or print)

PRESIDENT

8/13/BC

EPA Form 8700-12 (6-80) REVERSE

\*C0 - XC2 X



# ACKNOWLEDGEMENT OF NOTIFICATION OF HAZARDOUS WASTE ACTIVITY (VERIFICATION)

This is to acknowledge that you have filed a Notification of Hazardous Waste Activity for the installation located at the address shown in the box below to comply with Section 3010 of the Resource Conservation and Recovery Act (RCRA). Your EPA Identification Number for that installation appears in the box below. The EPA Identification Number must be included on all shipping manifests for transporting hazardous wastes; on all Annual Reports that generators of hazardous waste, and owners and operators of hazardous waste treatment, storage and disposal facilities must file with EPA; on all applications for a Federal Hazardous Waste Permit; and other hazardous waste management reports and documents required under Subtitle C of RCRA.

EPA I.D. NUMBER	•	OHD004200044	REACKN	OWLEC	GEMENT
e de la companya de		PREMIX INC PO BOX 281 N KINGSVILLE		ОН	44068
INSTALLATION ADDRESS		HARMON RD AND R' N KINGSVILLE	T. 50.	OH	44068
EPA Form 8700-12B (4-80)		09/29/81			and this beauty and the state of the state o

P.O. Box 1049, 1800 WaterMark Dr. Columbus, Ohio 43266-0149 (614) 644-3020 FAX (614) 644-2329 George V. Voinovich
Governor

Donald R. Schregardus
Director

May 6, 1992

Premix, Inc. Attn: Debbie Hall P.O. Box 281 North Kingsville, OH 44068

RE: EPA ID#: 0HD004200044

In response to your request of April 1992 the following information has been updated:

Status: large quantity generator and transporter

If you have any questions, please contact Beth Harris at (614)644-2977.

Sincerely,

Thomas E. Crepeau, Manager

No longer listed as a TSD facility.

Data Management Section

Division of Hazardous Waste Management

homas E. Crepeau

TEC/bah

cc: U.S. EPA, Region V



P. O. BOX 281

### NORTH KINGSVILLE, OHIO 44068

PHONE (216) 224-2181

January 7, 1986



JAN 1 0 1986

U.S. EPA, REGION V

Mr. Ken Chiu USEPA/Region V RCRA Activities P.O. Box A 3587 5 SH13 Chicago, IL 60690

Dear Mr. Chiu:

Premix, Inc., is a facility located in North Kingsville, Ohio that manufactures reinforced thermoset plastic (Sic 30-79). We are currently permitted under Storage Permit #02-04-0567. The EPA identification number is OHD004200044. G, TR, TSD, PA

I am in the process of reviewing ways to reduce the hazards and toxicity of the waste streams that are being generated at North Kingsville.

The waste streams are as follows:

 Waste Resin Solution Flammable Liquid UN1866, D001

which contains styrene monomer,

- Waste Paint related materials Flammable Liquid NA 1263 D001
- Non-hazardous waste paste which has been approved for sanitary landfill by the Ohio EPA.

The best available technology that I have found for our use is that of solidification.

A facility by the name of Solidify Corporation, located in Eastlake, Ohio, has initiated trial samples consisting of one quart of each type of waste. The solidification occurs by blending the three above-mentioned waste streams together in a portable auger mixer and adding calciumated lime and water. This is then thoroughly mixed. Within 30 minutes following the mixing process, the water will evaporate leaving a solid non-hazardous mass.

The solid mass was analyzed for ignitability and E.P. Toxicity (due to the styrene monomer) results are attached.

Mr. Ken Chiu Page Two January 7, 1986

I would like approval for a one-time trial at the North Kingsville facility using a large enough quantity (yet to be determined) to judge the feasibility of the solidification process.

If approval is granted for a one-time exemption under Ohio Code #3734.02g, I would need approximately a 30 to 60 day allowance period to edify the trial process due to the severe weather conditions in this area.

I have previously spoken to Mr. Bob Carry, Ohio EPA, and Ms. Debby Burg regarding this exemption.

If there are any questions pertaining to this request, please do not hesitate to phone.

Sincerely yours,

PREMIX, INC.

Debra Hall

Environmental Engineer

CC: Ms. D. Burg
Ohio EPA
2110 E. Aurora Rd.
Twinsburg, OH 44087

Mr. B. Carey Ohio EPA P.O. Box 1049 Columbus, OH 43215

Mr. F. Davey Premix, Inc.

DREMIX, INC.

P. O. BOX 281

NORTH KINGSVILLE, OHIO

DEBRA HALL

PHONE: 216 224-2181 TWX: 810 427-2929

ENVIRONMENTAL ENGINEER

REMIA, INC.

P. O. BOX 281

NORTH KINGSVILLE, OHIO 44068

PHONE (216) 224-2181

September 21, 1982

G,T,TSD, PA PPO 004 200 044

USEPA RCRA Activities Region V Box A 3587 Chicago, IL 60690 WASTE MANAGEMENT BRANCH EPA, REGION

To whom it may concern:

On Form 3 for our storage permit we had initially listed that we generate three (3) types of hazardous waste, F002, F003, F005 being stillbottoms from our solvent recovery unit; D001 paint from our paint spraying process; and D001 resin paste from our material process.

The waste D001 or resin paste we had analyzed by two outside laboratories for ignitability. We felt that this waste was improperly classified as a flammable solid. The OEPA was notified and on their inspection tour of our facility, they witnessed bench demonstrations of trying to ignite this waste. They were also shown copies of the data received from the private labs.

Due to the above information the OEPA agreed that this resin waste was not a flammable solid hazardous waste and should be reclassified.

Attached is a copy of the letter received on the change of classification.

Please attach this information to the Part A form for our storage permit.

Sincerely,

PREMIX, INC.

P. O. BOX 281

NORTH KINGSVILLE, OHIO

DEBBI HALL

Attachment

mkl

P. O. BOX 281

NORTH KINGSVILLE, OHIO 44068

PHONE (216) 224-2181

April 7, 1982

OHD 004 200044

Mr. Joel Schaffer RCR Activities (?) USEPA Region 5 P. O. Box A3587 Chicago, IL 60690

Dear Mr. Schaffer:

Attached you will find a copy of the map that accompanied our Part "A" form that was filed with Ohio EPA.

If the map is not specific enough, please contact our Plant Engineer, Mr. Mark Fickenscher, and he will try to find something in our files that will help you. Thank you for your patience.

Sincerely,

PREMIX, INC.

Mrs. Debbi Hall

Environmental Specialist

mkl


Attachment



RECEIVED

APR 16 1930

WASTE MANAGEMENT BRANCH EPA, DECICIO V



P. O. BOX 281

NORTH KINGSVILLE, OHIO

DEBBI HALL

Please print or type in the unshaded areas only (fill—in areas are spaced for elite type, i.e., 12 characters/line	ch).		* 0		Form A	pproved OMB No. 1	58-R0	175	251
FUNIVI				CTION AGENCY	I. EPA I	D. NUMBER			
				IATION	FOH	0004200044	1 1	7 7	3 D
			Permits Pi tructions"	before starting.)	1 2	11 h 1 h 1 h 1 h			13 14 15
LABEL ITEMS		1	1		15 0 01	GENERAL INSTR			ad affic
OHDO042000	7.7.				it in th	e designated space.	Review	w the	inform-
11111	144					arefully; if any of in it and enter the			
III. FACILITY NAME	XIMS	TM	C		approp	riate fill-in area be	low. A	Iso, i	f any of
	BOY					printed data is abse the label space li			
V			ILLE,	OH	that sh	ould appear), pleas	e prov	ride i	t in the
111111	17.2.11	30 4		44968		fill—in area(s) belote and correct, you			
1111111					Items	I, III, V, and VI	(excep	t VI-I	B which
FACILITY						<i>e completed regan</i> f no label has been			
VI. LOCATION HARMON RI	). δ.	Rt	. 20			structions for detained for the legal a			
	5 (7) 5.					this data is collected.		Latioi	is dilder
II DOLLUTANT CHADACTEDICTICS					AND DESCRIPTION OF THE PARTY OF		100		
II. POLLUTANT CHARACTERISTICS			need to	submit one permit applies	etion forms t	the EPA If you an	major 11.	100"	to any
INSTRUCTIONS: Complete A through J to determine questions, you must submit this form and the supplemental through J to determine the supplemental through J to determi	ental fo	er you	u neeu to	submit any perime applica narenthesis following the	guestion. Ma	rk "X" in the box in	the th	ird co	olumn
if the cumplemental form is attached if you answer "n	n" to ea	ach o	uestion, v	ou need not submit any of	these forms.	You may answer "n	o" it y	our ac	ctivity
is excluded from permit requirements; see Section C of t	he instr	uction	ns. See als	o, Section D of the instruc	tions for defi	nitions of bold-face	d term		
SPECIFIC QUESTIONS		MAR	K 'X'		IC QUESTIO	<b>医罗斯斯斯</b> 加斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯		MAR	FORM ATTACHE
SPECIFIC GOESTIONS	YES	ИО	ATTACHED	Market Medical Control			YES	NO	ATTACHE
A. Is this facility a publicly owned treatment work which results in a discharge to waters of the U.S		10		<ul> <li>B. Does or will this faci include a concentrate</li> </ul>				v	With a
(FORM 2A)	i une	X	OT - 10	aquatic animal produ				X	
C. Is this a facility which currently results in discharge	16	17	18	D. Is this a proposed fa			19	20 X	21
to waters of the U.S. other than those described	in	X		in A or B above) w	hich will resu				
A or B above? (FORM 2C)	22	23	24	F. Do you or will you		facility industrial or	25	26	2.7
E. Does or will this facility treat, store, or dispose				municipal effluent b	elow the low	ermost stratum con-		X	
hazardous wastes? (FORM 3)	X			taining, within one underground sources	of drinking v	e of the well bore,	31	32	33
G. Do you or will you inject at this facility any product	28 ed	29	30	H. Do you or will you i				32	33
water or other fluids which are brought to the surfa	ce	X		cial processes such a	as mining of	sulfur by the Frasch		X	-
duction, inject fluids used for enhanced recovery	of	A		process, solution mi tion of fossil fuel, o	ining of mine	rals, in situ combus- geothermal energy?		A	
oil or natural gas, or inject fluids for storage of liqu hydrocarbons? (FORM 4)	34	35	36	(FORM 4)			37	38	39
I. Is this facility a proposed stationary source which	is			J. Is this facility a pro					
one of the 28 industrial categories listed in the i	ns	X		NOT one of the 28 instructions and whi	ich will poter	tially emit 250 tons		X	
per year of any air pollutant regulated under the Clean Air Act and may affect or be located in	he	1.75		per year of any air p Air Act and may aff	ollutant regul	ated under the Clear		12	- Maria
attainment area? (FORM 5)	40	41	42	area? (FORM 5)	rect of be loc	iceo ili bir accaminent	9	44	45
III. NAME OF FACILITY							Value (		TALL.
SKIP PREMIX INC.	1 1	1	1 1 1		1 1 1 1	, , , , , ,	.		
15 16 - 29 30			ATT ME TO				69		
IV. FACILITY CONTACT							The William		
A. NAME & TITLE (last,						(area code & no.)			
2 PARSHALL, DEBBI ENVIRONME	NTAL	S S	PECIA	LIST	216	224 2181			
15 16			NEW STATE	45 4	6 - 48 49	- 51 52 - 5	5		
V. FACILITY MAILING ADDRESS									
A. STREET OR P.	0. BOX	1	111	<del></del>					
3 / P.O. BOX 281									
B. CITY OR TOWN				C.STATE D. ZIP	CODE				
	П	1	1 1 1	OH 4406	8				
4 N. KINGSVILLE				40 41 42 47	- '51				
VI. FACILITY LOCATION									
A. STREET, ROUTE NO. OR OTHE	R SPEC	IFIC	IDENTIF	IER			West.	Section 1	MARKET SALE
5 HARMON RD. AND RT. 20	0	1	T T T						
5 HARMON RD. AND RI. 29				45					
B. COUNTY NAME	A Part								
ASHTABULA	1 1	1	1 1						
46				70		COLINEY			
C. CITY OR TOWN			1 1 1	<del>, ,                                  </del>	CODE	(if known)			
6 N N. KINGSVILLE				oh 4496	58	997			
35 16				40 41 42 47	. 11	52 - 54			201
EPA Form 3510-1 (6-80)				MUV 18 19	80	CON	TINUE	ON	REVERS

I. SIC CODES (4-digit, in order of priority)					Sala Reserv
A. FIRST				ECOND	
3 079 (specify)	DARMAGA	7	(specify)		7.79
MISC. PLASTIC P	RODUCTS	15 16 - 19	24055		
C. THIRD		<u>c                                      </u>	(specify)	OURTH	
(specify)		7	(specify)		
I. OPERATOR INFORMATION		15 16 - 19	State William Colonia	A TANKS A TOTAL	
LOPERATOR INFORMATION	A. NAME		SHURLE HOUSE		B. Is the name listed
		111111		11111	item VIII-A also owner?
PREMIX, INC.					YES LIN
16	-(Fe			51	
C. STATUS OF OPERATOR (Enter the a			specify.)	D. PHONE (d	rea code & no.)
F = FEDERAL M = PUBLIC (other th S = STATE O = OTHER (specify) P = PRIVATE	an federal or state)	(specify) STOCKHOLD		216. 2	24 21 22 28 28
E, STREET	OR P.O. BOX				
P.O. BOX. 281	rodenie Jenerali				
	-	G.STATE	H. ZIP CODE IX.	INDIAN LAND	Mark Line Harris
F. CITY OR TO	T T T T T T T T T T T T T T T T T T T	111111		he facility located	on/Indian lands?
N. KINGSVILLE		ОН	44068	YES	₩ NO
16		40 41 42	47 - 81	52	
EXISTING ENVIRONMENTAL PERMITS				HWATT VE	
A. NPDES (Discharges to Surface Water)		sions from Proposed Sc	ources)		
7 1	9 P				
N 16 17 18 -	30 15 16 17 18		30		
B. UIC (Underground Injection of Fluids)		THER (specify)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
U	9		(specify)		
16 17 18 -	30 15 16 17 18		30		
C. RCRA (Hazardous Wastes)	E. O	THER (specify)	(specify)		
R 7	. 9		[apecigy)		
. MAP	30 15 16 17 18		30		
Attach to this application a topographic the outline of the facility, the location of reatment, storage, or disposal facilities, vater bodies in the map area. See instruct	of each of its existing a and each well where it tions for precise require	nd proposed intake injects fluids under	and discharge stru ground. Include a	ctures, each of i	ts hazardous waste
The second secon	escription)				
II. NATURE OF BUSINESS (provide a brief d					
II. NATURE OF BUSINESS (provide a brief d					
I. NATURE OF BUSINESS (provide a brief d					
	OLDING OF FIBE	RGLASS REIN	FORCED POL	YESTER'S	
COMPOUNDING AND MO	OLDING OF FIBE	RGLASS REIN	FORCED POL	YESTER'S	
	OLDING OF FIBE	RGLASS REIN		CALLA	
	OLDING OF FIBE	ERGLASS REIN		CALLA	
	OLDING OF FIBE	RGLASS REIN		YESTER'S A/51	
	OLDING OF FIBE	ERGLASS REIN		CALLA	
	OLDING OF FIBE	RGLASS REIN		CALLA	
	OLDING OF FIBE	RGLASS REIN		CALLA	
COMPOUNDING AND MO	OLDING OF FIBE	ERGLASS REIN		CALLA	ALMAN A
COMPOUNDING AND MO		TI FATOR S	F9	A/51	ALIMAN A
COMPOUNDING AND MO  III. CERTIFICATION (see instructions)  I certify under penalty of law that I have attachments and that, based on my incapplication, I believe that the informati	ve personally examined quiry of those persons on is true, accurate and	and am familiar with immediately respor d complete. I am av	F9  the information spible for obtainin	A/51  submitted in this g the information	on contained in the
COMPOUNDING AND MO  III. CERTIFICATION (see instructions)  I certify under penalty of law that I have attachments and that, based on my inequality information application, I believe that the information of the possibility information, including the possibility.	ve personally examined quiry of those persons on is true, accurate and ty of fine and imprison	and am familiar with immediately respor i complete. I am aw nent.	F9  the information spible for obtainin	A/51  submitted in this g the information significant pena	on contained in the lities for submitting
IIII. CERTIFICATION (see instructions)  I certify under penalty of law that I have attachments and that, based on my interpolation, I believe that the information false information, including the possibility.  NAME & OFFICIAL TITLE (type or print)	ve personally examined quiry of those persons on is true, accurate and ty of fine and imprison	and am familiar with immediately respor d complete. I am av	F9  the information spible for obtainin	A/5/ submitted in this g the information significant pena	on contained in the
COMPOUNDING AND MO  III. CERTIFICATION (see instructions)  I certify under penalty of law that I has attachments and that, based on my interpolication, I believe that the information false information, including the possibility.  NAME & OFFICIAL TITLE (type or print)  FORD DAVEY	ve personally examined quiry of those persons on is true, accurate and ty of fine and imprison	and am familiar with immediately respor i complete. I am aw nent.	F9  the information spible for obtainin	A/5/ submitted in this g the information significant pena	on contained in the
COMPOUNDING AND MO  III. CERTIFICATION (see instructions)  I certify under penalty of law that I have attachments and that, based on my incapplication, I believe that the informatifalse information, including the possibility.  NAME & OFFICIAL TITLE (type or print)  FORD DAVEY Senior Vice PRESIDENT	ve personally examined quiry of those persons on is true, accurate and ty of fine and imprison	and am familiar with immediately respor i complete. I am aw nent.	F9  the information spible for obtainin	A/5/ submitted in this g the information significant pena	on contained in the
COMPOUNDING AND MO  III. CERTIFICATION (see instructions)  I certify under penalty of law that I have a that the information of the compound o	ve personally examined quiry of those persons on is true, accurate and ty of fine and imprison	and am familiar with immediately respor i complete. I am aw nent.	F9  the information spible for obtainin	A/5/ submitted in this g the information significant pena	on contained in the
COMPOUNDING AND MO  III. CERTIFICATION (see instructions)  I certify under penalty of law that I have a trachments and that, based on my interpolication, I believe that the informatifialse information, including the possibility.  NAME & OFFICIAL TITLE (type or print)  FORD DAVEY  Senior Vice PRESIDENT  OMMENTS FOR OFFICIAL USE ONLY	ve personally examined quiry of those persons on is true, accurate and ty of fine and imprison	and am familiar with immediately respor i complete. I am aw nent.	F9  the information spible for obtainin	A/5/ submitted in this g the information significant pena	on contained in the

089181 VOV



PLANT #1 11/23/80 MFG



PLANT #1 11/23/80 MFG



MOLDED FIBER GLASS CO. 4401 BENEFIT AVE. ASHTABULA, OH. 44009

	7/A C 3 1 13 14 15									
OR OFFICIAL USE ONLY  SPLICATION DATE RECEIVED (Yr, mo., & day)  I. FIRST OR REVISED APPLICATION  Clace an "X" in the appropriate box in A or B below (mark one box only) to indicate whether this is the first application you are submitting for your face evised application. If this is your first application and you already know your facility's EPA I.D. Number, or if this is a revised application, enter your face.	3 1									
OR OFFICIAL USE ONLY  APPROVED (yr, mo., & day)  I. FIRST OR REVISED APPLICATION  Comments  Clace an "X" in the appropriate box in A or B below (mark one box only) to indicate whether this is the first application you are submitting for your face evised application. If this is your first application and you already know your facility's EPA I.D. Number, or if this is a revised application, enter your face.										
I. FIRST OR REVISED APPLICATION  Take an "X" in the appropriate box in A or B below (mark one box only) to indicate whether this is the first application you are submitting for your face evised application. If this is your first application and you already know your facility's EPA I.D. Number, or if this is a revised application, enter your face.										
Place an "X" in the appropriate box in A or B below (mark one box only) to indicate whether this is the first application you are submitting for your face evised application. If this is your first application and you already know your facility's EPA I.D. Number, or if this is a revised application, enter your facility's EPA I.D. Number, or if this is a revised application, enter your facility's EPA I.D. Number, or if this is a revised application, enter your facility's EPA I.D. Number, or if this is a revised application.	COMP									
Place an "X" in the appropriate box in A or B below (mark one box only) to indicate whether this is the first application you are submitting for your face evised application. If this is your first application and you already know your facility's EPA I.D. Number, or if this is a revised application, enter your facility's EPA I.D. Number, or if this is a revised application, enter your facility's EPA I.D. Number, or if this is a revised application, enter your facility's EPA I.D. Number, or if this is a revised application.										
evised application. If this is your first application and you already know your facility's EPA I.D. Number, or if this is a revised application, enter your facility's										
	ace an "X" in the appropriate box in A or B below <i>(mark one box only)</i> to indicate whether this is the first application you are submitting for your facility or a vised application. If this is your first application and you already know your facility's EPA I.D. Number, or if this is a revised application, enter your facility's PA I.D. Number in Item I above.									
A. FIRST APPLICATION (place an "X" below and provide the appropriate date)  A. FIRST APPLICATION (place an "X" below and provide the appropriate date)  I SUISTING FACILITY (See instructions for definition of "existing" facility.  Complete item below.)  71  FOR NEW FACILITY (Complete item below.)	ILITIES.									
YR. MO. DAY OPERATION BEGAN OR THE DATE CONSTRUCTION COMMENCED (use the boxes to the left)  YR. MO. DAY OPERATION BEGAN OR THE DATE CONSTRUCTION COMMENCED (use the boxes to the left)	OPERA-									
B. REVISED APPLICATION (place an "X" below and complete Item I above)  1. FACILITY HAS INTERIM STATUS  2. FACILITY HAS A RCRA PERMIT	and the									
III. PROCESSES — CODES AND DESIGN CAPACITIES	are been									
A. PROCESS CODE — Enter the code from the list of process codes below that best describes each process to be used at the facility. Ten lines are provi										
entering codes. If more lines are needed, enter the code(s) in the space provided. If a process will be used that is not included in the list of codes belonger the process (including its design capacity) in the space provided on the form (Item III-C).	w, then									
B. PROCESS DESIGN CAPACITY — For each code entered in column A enter the capacity of the process.										
<ol> <li>AMOUNT — Enter the amount.</li> <li>UNIT OF MEASURE — For each amount entered in column B(1), enter the code from the list of unit measure codes below that describes the unit</li> </ol>	of									
measure used. Only the units of measure that are listed below should be used.  PRO- APPROPRIATE UNITS OF  PRO- APPROPRIATE UNITS OF	SOF									
CESS MEASURE FOR PROCESS CODE DESIGN CAPACITY PROCESS CODE DESIGN CAPACITY	CESS									
Storage: Treatment:										
CONTAINER (barrel, drum, etc.) S01 GALLONS OR LITERS TANK T01 GALLONS PER DAY OF TANK S02 GALLONS OR LITERS LITERS PER DAY OF TANK S03 CUBIC YARDS OR SURFACE IMPOUNDMENT T02 GALLONS PER DAY OF TANK SURFACE IMPOUNDMENT T02 GALLONS PER DAY OF TANK SURFACE IMPOUNDMENT T03 GALLONS PER DAY OF TANK SURFACE IMPOUNDMENT T04 GALLONS PER DAY OF TANK SURFACE IMPOUNDMENT T05 GALLONS PER DAY OF TANK SURFACE IMPOUNDMENT TO TOTAL SURFACE IMPOUNDMENT										
SURFACE IMPOUNDMENT S04 GALLONS OR LITERS INCINERATOR T03 TONS PER HOUR OR										
Disposal:  INJECTION WELL  OF GALLONS OR LITERS  METRIC TONS PER HOUR GALLONS PER HOUR LITERS PER HOUR										
LANDFILL D80 ACRE-FEET (the volume that OTHER (Use for physical, chemical, T04 GALLONS PER DAY C would cover one acre to a thermal or biological treatment LITERS PER DAY	R									
depth of one foot) OR processes not occurring in tanks, HECTARE-METER surface impoundments or inciner- LAND APPLICATION D81 ACRES OR HECTARES ators. Describe the processes in										
OCEAN DISPOSAL D82 GALLONS PER DAY OR the space provided; Item III-C.) LITERS PER DAY SURFACE IMPOUNDMENT D83 GALLONS OR LITERS										
	NIT OF									
	EASURE CODE									
GALLONSG LITERS PER DAYV ACRE-FEETLITERSL TONS PER HOURD HECTARE-METER										
CUBIC YARDSY METRIC TONS PER HOURW ACRESCUBIC METERS GALLONS PER HOURE HECTARES	в									
EXAMPLE FOR COMPLETING ITEM III (shown in line numbers X-1 and X-2 below): A facility has two storage tanks, one tank can hold 200 gallons	and the									
other can hold 400 gallons. The facility also has an incinerator that can burn up to 20 gallons per hour.										
C DUP 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	11									
P PROCESS DESIGN CARACITY										
DI CONTI OFFICIAL DI CONTI C	FOR FFICIAL USE									
CODE 1. AMOUNT SURE (from list above)  OF MEA SURE (from list above)  OF MEA SURE (from list above)	ONLY									
16 - 18 19 - 27 28 25 - 32 16 - 18 19 - 27 28 25	- 32									
X-1 S 0 2 600 S 5										
X-2 T 0 3 20 D 6										
1 TØ 1 3ØØØØ Ø 7										
2 8										
3 9 10 10										

	mm a	amaa	777 678	1 1 11	
	12 12 (1)	100	100	(continued)	
ALL .				I CUILLIILIACUI	

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESSES (code "T04"). INCLUDE DESIGN CAPACITY. FOR EACH PROCESS ENTERED HERE

#### IV. DESCRIPTION OF HAZARDOUS WASTES

- A. EPA HAZARDOUS WASTE NUMBER Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If you handle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.
- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE CODE	METRIC UNIT OF MEASURE CODE
POUNDSP	KILOGRAMSK
TONS	METRIC TONS

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

### D. PROCESSES

1. PROCESS CODES:

For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item III

to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code/s/ from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER — Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

- 1. Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B,C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste
- In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
- 3. Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.

EXAMPLE FOR COMPLETING ITEM IV (shown in line numbers X-1, X-2, X-3, and X-4 below) - A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

	A. EPA		C. UNIT									D. PROCESSES
LINE NO.	HAZARD. WASTENO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	OF MEA SURE (enter code)	9	THE RESIDENCE OF THE PARTY OF T		1. PROCESS CODES (enter)				2. PROCESS DESCRIPTION (if a code is not entered in D(1))	
X-1	K 0 5 4	900	P		T	0 3	3	D	8	0		
X-2	D 0 0 2	400	P		T	0 3	3	D	8	0		
X-3	D 0 0 1	100	P		$T^{1}$	0 3	3	D	8	0		
X-4	D 0 0 2											included with above

PAGES OF S  POR OFFICIAL USE WILLY  OR HIGH A SPAN DESTINATED ANNUAL CONTINUED  N. DESCRIPTION OF HAZARDOUS WASTES Continued)  N. DESCRIPTION OF HAZARDOUS WASTES CONTINUED  N. DESCRIPTION OF HAZARDOUS WASTES  N. DESCRIPTIO	Contin VOTE:	ued Pho	from pa	ge 2.	page before completing	u hav	e mo	ore ti	han 20	6 wa	stes to list			Form Approved OMB No. 158-\$80004
N. DESCRIPTION OF HAZARDOUS WASTES (continued)	S W/	П		Τ.	T/A C		1	1	s W				AL USE	T/AC
1	A STATE OF THE PARTY OF		Witness of the Park of the Par	STREET, SQUARE, SQUARE,			(cor		THE OWNER OF TAXABLE PARTY.	>	Sun			13 14 13 23 - 26
F   g   g   g   g   g   g   g   g   g	ш				B. ESTIMATED ANNUA	LO	, UN FME	A-						D. PROCESSES
F   8   8   2   36, 444   500   F   S   1   F005 included with F002	NO.			0			code	r			(en	ter)		2. PROCESS DESCRIPTION (if a code is not entered in $D(1)$ )
2 D Ø Ø D 115,2000000 P SØ 1 3 C Ø 12 28,3000000 P SØ 1 6 7 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	81	F F	øø	2	36, øøøbbø	35			sø	1	1 1	27 - 29	27 - 29	F005 included with F002
5 5 6 7 8 8 9 9 10 11 12 13 14 14 15 15 16 16 17 17 18 18 19 20 20 21 12 22 23 24 24 25 26 25 26 26 26 26 26 26 26 26 26 26 26 26 26	2	D	g g	3	115,200000		P			1				
5	3	F	d 1	7	28,888000		P		sø	1		arinde/museum	8 %	
6	ST	E	00	5			100			-	1 1	1 1		
7 8 9 9 10 11 12 13 14 14 15 16 16 17 18 18 19 20 21 12 22 23 24 24 25 26 26 27 27 28 28 28 29 29 20 20 20 20 20 20 20 20 20 20 20 20 20	5.				: :X		V			1	- 1 1	1 1	1 1	
7	6				*				+	I	1 1	1 1	1 1	
8 9 9 10 10 11 12 13 14 15 16 16 17 18 18 19 20 20 21 22 23 24 24 25 26 26 26 26 26 26 26 26 26 26 26 26 26				+							-1-1	1 1	_1 1	
9 10 11 12 13 13 14 15 15 16 16 17 18 18 19 20 21 22 23 24 25 26 2 24 25 26 2 24 25 26 20 20 20 20 20 20 20 20 20 20 20 20 20									-	1	1 1	. 1 1	1 1	
9   10   11   12   13   14   15   16   16   17   18   19   20   21   22   23   24   25   26   21   22   23   24   25   26   27   28   27   29   27	8										31 =			* - ""
11	9													
11	10	1										- 1		
12	11		<sub>3</sub> 1			- 11			1	T	1 1	1 1	1 - 1	
13	12				1 3 - 1 2 2 30 N	LE N			T	Ţ	1-1-	11		
14	13				1 ,				1	1	1-1	1 1		
15	7.50								1	1		1 1	1.1	
16				+	и				1	1	1 1	11	1 1	
16	15			4			1		_			1 1		-
17	16				11 12 E									-
18	17													
20	18								1	1	1_1_			
20	19				Jehr Joseph					1			1. 1	La ra re-
21	20								1	1	1.1	11	1 1	
22 23 24 25 26 27 29 27				1	9				1	T	11	11	1 1	10 3
23 24 25 26 27 29 29 27 29 29 27 29 29 27 29 29 27 29 27 29 27 29 27 29 27 29 27 29					a = -	10 11			Ţ	1	1 1	1		
24   25   26   27   29   2									J	1	1 1	-		e <sub>2</sub>
24   25   26   27   29   2	23													
25   26   27 - 29   27 - 2	24				Pr. No. of the Control of the Contro							w =	11	
26 23 - 26 27 - 35 36 27 - 29	25													9 N N N N N N N N N N N N N N N N N N N
EPA Form 3510-3 (6-80) CONTINUE ON REVE	26										111			
	EPA	Forr				35	36						27 - 29	CONTINUE ON REVERS

Continued from the front.			
IV. DESCRIPTION OF HAZARDOUS WASTES	ntinued)		
E. USE THIS SPACE TO LIST ADDITIONAL FACE	CESS CODES FROM I	TEM D(1) ON PAGE 3.	
= 1			
			(
	<u> </u>		
		% 555	
			* * * * * * * * * * * * * * * * * * * *
EPA I.D. NO. (enter from page 1)			
F 000000000000000000000000000000000000			
F OHD \$ 42 \$ \$ \$ 44 15	WORLD WORLD WITH THE PARTY OF T		A CONTRACTOR OF THE STATE OF TH
V. FACILITY DRAWING  All existing facilities must include in the space provided or			r more detail). F6 N/55
VI. PHOTOGRAPHS	1 page 5 a scale drawing of	the facility (see mistructions for	inore decails.   \$\phi \rangle 10/33
All existing facilities must include photographs (ae.	rial or ground Javall th	at clearly delineate all evict	ing structures; existing storage
treatment and disposal areas; and sites of future sto	orage, treatment or disp	osal areas (see instructions	for more detail). FL N.56
VII. FACILITY GEOGRAPHIC LOCATION		AR SHIP AT HE TAKE SHIP	
LATITUDE (degrees, minutes, & second	ls)	LONGITUDE (	degrees, minutes, & seconds)
	ENALTH ELECTRICAL		Part and the second sec
7 / 3 8 69 - 71		72 -	74 75 76 77 - 79
VIII, FACILITY OWNER			
A. If the facility owner is also the facility operator as	s listed in Section VIII on F	orm 1, "General Information"	, place an "X" in the box to the left and
skip to Section IX below.			
B. If the facility owner is not the facility operator as	listed in Section VIII on F	orm 1 complete the following	items:
B. If the lability owner is not the lability operator as	nated in occiton with only	om r, complete the renorms	
	ILITY'S LEGAL OWNER		2. PHONE NO. (area code & no.)
E STOCKHOLDERS			216 224 2181
15 16 BTOOKHODDIKO			55 56 2 58 31 62 -
3. STREET OR P.O. BOX	C	I. CITY OR TOWN	5. ST. 6. ZIP CODE
F P.O. BOX 281	<u>C</u>	IGSVILLE	04 44 068
15 16 L.O. BOX 201	45 15 16 16 14 1	Walles and the second	40 41 42 47 51
IX. OWNER CERTIFICATION			unberitted in this and all attached
I certify under penalty of law that I have personally documents, and that based on my inquiry of those			
submitted information is true, accurate, and compl			
including the possibility of fine and imprisonment.			
A. NAME (print or type)	B. SIGNATURE		C. DATE SIGNED
Ford Davey	9 1		1
Ford Davey Senior Vice Senior Vice	Soul (	Lave	NOU- 18 1980
X, OPERATOR CERTIFICATION		/	AND STATE OF THE PARTY OF THE P
I certify under penalty of law that I have personally	y examined and am fam	iliar with the information s	submitted in this and all attached
documents, and that based on my inquiry of those	individuals immediately	responsible for obtaining	the information, I believe that the
submitted information is true, accurate, and compl	lete. I am aware that the	ere are significant penalties	for submitting false information,
including the possibility of fine and imprisonment.			
A. NAME (print or type)	B. SIGNATURE		C. DATE SIGNED
		e 1	χ,
		2	
EDA Form 2510.2 (6.90)			CONTINUE ON PAGE

	re spaced for elite typ			Name and the same of the same		41.		Form Appi	oved OMB No.	. 158-S	80004	ţ ·	
FORM	EPA	HAZAF	VIRONMEN OUS WAST	TE PER ted Permit	MIT Al s Program	PPLICA	TION	I. EPA I. FOH	D. NUMBER	>3 3 7 5	2	) 1 5	Λ
" R OFFIC	IAL USE ONLY		ation is requi	rea under	Section :	1005 of R	CRA.)	1112			1-1	13	4 1;
LICATIO:						С	OMMENTS						
23	24 29			7 1			· · · ·			No.			
	R REVISED APPL		15.					4 - 1 - 14				. * . *\f	
EPA I.D. Num	n the appropriate box ition. If this is your fi ber in Item I above.	4	a you ancua	KHOW YO	ui racinty	whether i	this is the fir D. Number,	st application yo or if this is a rev	u are submitti ised applicatio	ng for y n, enter	our f your	acility facility	ora /'s
A. FIRST A.	PPLICATION (place ISTING FACILITY (	See instructions fo Complete item be	or definition : low.)	of "existin	g" facilit			2.NEW F	ACILITY (Co	mplete FOR NI			
8 5 6	6 (use	EXISTING FAC RATION BEGAN the boxes to the l	eft)	TE CONS	TRUCTI	(yr., mo. ON COM	& day) MENCED		O. DAY	PROVIE yr. mo TION B EXPEC	DE TH ., & da Egai	IE DA' IV) OPI	E ERA-
B. REVISED	APPLICATION ()	olace an "X" belo IM STATUS	w and compl	ete Item I	above)			46 L 1200	76 [ ] 77 78 ]	- Y- j-g.	22.2		er (Aγ.
7 2	SES – CODES AN		PACITIES	> : ,				72 72	ITY HAS A F	RCRAF	ERM	IT ( STA	
A. PROCESS	CODE — Enter the co	de from the list o	f process code	es below t	hat best o	describes	each process	to be used at th	e facility. Ten	lines a	re pro	vided f	or
	e process (including it  DESIGN CAPACITY  NT — Fotor the amount		iii tiio space	provided (	on the lo	ini lifeni	III-C).		iuded in the in	st of co	des be	low,ith	en .
2. UNIT	NT — Enter the amou OF MEASURE — For a sused. Only the unit	nt. each amount ente	red in colum	n B/11 ans	ter the co	da from t			below that de	scribes	the ur	nit of	
		PRO APPRO	PRIATE UN JRE FOR PR	ITS OF				PR		PRIATI	E UNI	TS OF	
torage:	ROCESS		IGN CAPAC		."		ROCESS	CO		RE FO	R PRO	OCESS TY	
,	R (barrel, drum, etc.)	S01 GALLON S02 GALLON	NS OR LITER	₹ <b>S</b>	Tre TA	atment: NK	<del>-</del> property	ing and a section of the section of	) GALLON	SPER	DAY	OR	
SURFACE I	E MPOUNDMENT	S03 CUBIC Y	'ARDS OR ' 'ETERS	: '			MPOUNDM	150	LITERS I 2 GALLON LITERS I	PER DA	DAY	200	
Disposal:		SUA GALLOR	NS OR LITE	₹ <b>S</b> ,	INC	INERAT	OR		TONS PE METRIC GALLON	R HOU TONS	ROR	(OUR:	
LANDFILL	WELL GOVERNMENT OF THE	D80 ACRE-F	NS OR LITES EET (the volu ver one acre	ime that	ΩT	HER (Use	for physica	l, chemical, T	LITERS I	PERHO	วบล	192	
LAND APPL	ICATION	gepth of	one (oot) OF RE-METER		pro suri	cesses not face impo	ological trea t occurring in undments or	tanks,	LITERS	PER DA		(1) (1)	
OCEAN DIS	POSAL MPOUNDMENT	D82 GALLON	OR HECTAR NS PER DAY PER DAY	OR	010	rs. Descri	be the proce vided; Item	esses in					
College College		D83 GALLON	NS OR LITER	<b>ts</b>			UNITOR				h, Shq		
UNIT OF MI	1 1 m 531 1 h 1 h 1	MEASURE CODE	UNITO	F MEASU			UNIT OF TEASURE OF TOOLS		NEADURE !			UNIT ( MEASU	RE
ALITERS	e e e e e e e e e e e e e e e e e e e	<b>s</b>	LITERS	PER DAY	·		v	ACRE-F	MEASURE		7 (3.4	COD	TANKE.
CUBIC VAN	ese	Y	METRIC	TONSP	ER HOU	₹	w 1988	HECTAR ACRES.	E-METER.		ing Villa Matar	F	
	PER DAY OR COMPLETING IT! 400 gallons. The fac	rivi III (chown in i	line numbers	PER HOL	JR.	<b></b> .	н	storage tanks, o	re tank can ho	(d. 200 a	rallon	e and +	
<b>S</b>	1, 4, 5, 7	T/A C \	icinerator tha	t can burn	up to 20	gallons p	er hour,	<del>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</del>		<del>,,</del>	Baitoti	a miu ti	19.
<u>C</u>	DUP	13 14 15		1						/:/			1:
CESS		DESIGN CAPA		FOR	7 H	1	, - ,	ROCESS DES	IGN CAPAC	ITY	<u> </u>		4.5
U∑ CODE Z∑ (from list	. 1. AM	OUNT	2. UNIT OF MEA SURE	OFFICE	ALI 🗖	0000	35. (4.5)	1. AMOUN		2, UI OF M	EA-	FOI OFFIC USI	IAL
JZ above)			(enter code)	ONL	Z Z Z			· [1] 在 [2] [2] [2] [3] [4] [4] [4] [4] [4] [4] [4] [4] [4] [4	클라시아 ()* 	SUF (ent	er:	ONL	Ϋ́
X-1 S 0 2	600	)	27   21   G	25	5	16 - 18	19	-	27	28	1. 2		32
		1.50		3	6			Ψt	·	+	1:1.	-   -   -   -   -   -   -   -   -   -	ğ.,
X-2 T 0 3	20				1 1 0				•				21
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	300		E		7				ĝ,				発 :
					++-				i),				
1 S 0 1	300		+G		7				3,				
1 S 0 1	300 200 50		G G		7 8				3				
1 S 0 1 S 0 1 3 S 0 1 4	300 200 50		G G	29 PA(	7 8 9	16 - 11	C 19		277	, , , , , , , , , , , , , , , , , , ,			322

٠.

\_

18 19

27

					N OF HAZARDOUS WASTE														
ha	ndi	e ha	zar	dou	OUS WASTE NUMBER — Enter is wastes which are not listed in 4 oxic contaminants of those hazard	0 C	FR, S	ubp	nu art l	mbi D, e	er i	froi er t	m 4 he f	O Ou	CFR, ır—dię	Sü gít i	bpar numb	D f er(s)	or each listed hazardous waste you will handle. If you from 40 CFR, Subpart C that describes the characteris-
ba	sis.	Fo	r ea	ch e	NNUAL QUANTITY — For each haracteristic or toxic contaminant at characteristic or contaminant.	list t en	ed wa tered	ster e in co	nte lum	red in A	in \ es	co	lum nate	n a Eth	A esti ne tot	ima al a	te th	e qua I qua	entity of that waste that will be handled on an annual ntity of all the non—listed waste(s) that will be handled
	VIT des			EAS	SURE - For each quantity entere	ed ir	r colu	mn I	3 er	iter	th	eι	ınit	of	mea	sur	cod	e. Ur	nits of measure which must be used and the appropriat
				PO	GLISH UNIT OF MEASURE UNDS					· ·					KII	.0	GRA	VIS.	OF MEASURE CODE
ac	COU	nt	the	app	s use any other unit of measure opriate density or specific gravity	for of t	quant the wa	itγ, ste.	the	uni	ts c	of !	mea	su	re mu	ıst l	oe co	nvert	ed into one of the required units of measure taking into
D. PI					DDES:			•					-		-	٠			
	Fo	or I	ste	ha	zardous waste: For each listed h	azar	dous	wast	e er	nter	red	in	col	un	nn A	sele	ct th	e coc	le(s) from the list of process codes contained in Item III
	F	) T	on-	-list	ow the waste will be stored, treate ed hazardous wastes: For each o	hara	acteris	tic c	r to	xic	: cc	'nt	amii	กลเ	nt en	tere	ed in	colu	mn A, select the code(s) from the list of process codes
	CC	nta	ine	nì b	Item III to indicate all the processic or toxic contaminant.	esse	s. that	will	be	use	ed 1	to:	stor	e,	treat,	, an	d/or	dispo	ose of all the non-listed hazardous wastes that possess
ļ. ·	N	ote	F	OUL	spaces are provided for entering	рг	ocess	code	s. I	fm	ore	a	e n	eer	ded:	(1)	Ente	r the	first three as described above; (2) Enter "000" in the
				_	box of Item IV-D(1); and (3) En				-				-	_					
2.	PF	OF	CES	S D	ESCRIPTION: If a code is not list	ted 1	for a c	roce	ss ti	nat	wii	ΙЬ	e us	ed	i, desc	rib	e the	proc	ess in the space provided on the form.
																JS 1	NAS	FE.N	UMBER - Hazardous wastes that can be described by
	Se	lec	t or	e o	Hazardous Waste Number shall be the EPA Hazardous Waste Numb	ers :	and er	nter i	t in	col	lum	מו	4. C	)n	the sa	ame	line	com	plete columns B,C, and D by estimating the total annual
. 2	qu In	ian	ity	of t	he waste and describing all the pro	Cess EP/	ses to A: Haz	be u ardo	sed us V	to t Vasi	trea te l	rt, : Nu	store mbe	e, a	and/o	rd an	ispos be u	of t	he waste. o describe the waste. In column D(2) on that line enter
	"	nci	ude	iw b	th above" and make no other entr 2 for each other EPA Hazardous W	ies o	on tha	t line	<b>.</b>										
		•		•						. '									
EXA per v	MP) ear	LE of	FOI chr	₹ C	OMPLETING ITEM IV (shown in shavings from leather tanning an	<i>line</i> d fi	<i>e num</i> nishin	<i>bers</i> : g op:	X-1 erat	, X ion	-2, . In	X∙. ac	3 <i>, ai</i> Iditi	<i>nd</i> or	X-4 I	belo fac	ility :	- A fa wiii t	icility will treat and dispose of an estimated 900 pounds reat and dispose of three non—listed wastes. Two wastes
are c	orre	siv	o e	ılv a	and there will be an estimated 20 r of that waste. Treatment will be	0 pc	ounds	per	vea	r of	f ea	3ch	wa	ste	. The	e at	her v	vaste	is corrosive and ignitable and there will be an estimated
1001	T		EP.		1 Of that waste, freatment will be	T	UNIT	1		21.74	-	,,,,,	<b>341</b>				10.10		D. PROCESSES
ᄪ	ÌН	A 7	ΔF	D.	B. ESTIMATED ANNUAL QUANTITY OF WASTE	OF S	MEA	┰		1	1. 2	PC	CF		COL	res		· · · · · · · · · · · · · · · · · · ·	2. PROCESS DESCRIPTION
NO.	(e	n te	co	de)	GOARTILI OF WASIE	(e	enter ode)	1					(en	te	r)				(if a code is not entered in $D(1)$ )
X-1	K	0	5	4	900		P	T	0	3			0					1	
X-2	D	0	0	2	400		P	<u> </u>			D		0		1 1		ı	1	
X-3	D	0	0	1	100		P	T	0	3	D	8	0		,		1	,	
X-4	L	0	0	2								1	i		7		}	1	included with above
EPA	ОП	n 3	510	-3 (	6-80)		W.S.	• _		P	ΑC	ΞE	2	Ō	F 5				CONTINUE ON PAGE 3
							•												

Continued from the front.
III. PROCESSES (continued)

C. SPACE FOR ADDITIONAL PROCESS CODES OR INCLUDE DESIGN CAPACITY.

FOR EACH PROCESS ENTERED HERE


Contin NOTE	ued : <i>Ph</i> e	froi otoc	n p:	age / th	2. is page before completing if	you hav	e m	ore	than 26	wast	tes to lis	٤		2000 (51 ptp2201 520000121 132 pt	Form Approved OMB No. 158-S80004
3.	H				00044 T/A	<u>=</u>		\ \	s W			D U I		AL USE	T/AC DUP
1 2	·····			-	N OF HAZARDOUS W		(co	7	1 2	>					13 14 15 23 - 25
LSN.	IH/	A. E AZ/ AST ater	RI En	0	B. ESTIMATED ANNO QUANTITY OF WAS	JAL O	F M SUF (ent	ea- ei		١.	PROCE (en	ss coi	DES		2 PROCESSES (if a code is not entered to \$(1))
1	23	0		25		33	36		27 -	29 2	7 - 29	27 -	29	27 - 29 J	F003
2	V				133, 200		P		74	1	1.1.	1 1		- 1 T	Eggs included and all many
3	D 		0	-			P		S 0	1	1 1	,		1 1	Dood proved incorrect - Waste is ignitable, but NOT HEACTIVE Our PAINT RESIDUES ARE ICONITATION
Je	D	0	0	1	<u>40,000</u>		P	-	S 0	1	<del>-i</del>				This Dool is ACUTALLY FOIT was
4				_					1 1		1 1	1		1	
5				_								1			
6											, ,			. ,	
7					:						1-1-				
8						1					<u> </u>	-			
9					**************************************						7 1		-	<del></del>	
10									1 7 7		- T	1		<del></del>	
11					-				1-1-		<del>-1</del>	<del>                                     </del>	'		
12	T	-			The state of the s				7		1 1	<del>                                     </del>	'	T	
13		-						16 to	1		1 1	1 .	•	<del>-     -         -   -   -  </del>	
14					And the state of t				1		*****		1	1 1	\
15									1		11		1	77	
16						70 70 70 70 70 70 70 70 70 70 70 70 70 7			1		11	-	1	1 1	
17								100	1			1	1		
18					**************************************						1 1		_	1-1-	
⊺19											1	. 1	ı	1 1	
20								134			1 1 1 2			7	
21		<u> </u>			**************************************	د د			1		1 . 1	1		Į I	
22											1				
23					MACHINA CONTRACTOR CON						1 1	!			
24	_					5		ili y			1	1	1		
25									1				1		7
26	23			26		35	36			29	27 - 29	-	29	27 - 29	
EPA	Fon	n 3	510					- Zinkozum	utereingsviere	an ann an Aireann an A	-		00000 0000		CONTINUE ON REVERSE


Continued from the front.				
IV. DESCRIPTION OF HAZARDOUS WASTES (contin		/1) ON BAC		
E. USE THIS SPACE TO LIST ADDITIONAL COLE	S CODES FROM ITEM D	(I) ON PAG		
			•	
				: .
	•	**		
·		1		
•				
. •		- 	•	1
		•	•	•
•				
and the formation and fi				
EPA I.D. NO. (enter from page 1)		•		
F 0HD004200044 6				
V. FACILITY DRAWING				
All existing facilities must include in the space provided on pag	e 5 a scale drawing of the facil	ity (see instructions for mo	re detail).	
VI. PHOTOGRAPHS		de delineste ell'existing	atruaturas oxistina s	torage
All existing facilities must include photographs (aerial of treatment and disposal areas; and sites of future storage	or ground—level) that clear	ty defineate all existing	structures, existing s	torage,
r treatment and disposal areas; and sites of future storage	e, treatment or disposal are	eas (see instructions for I	more aetaii).	
VII. FACILITY GEOGRAPHIC LOCATION	e, treatment or disposal are	eas (see instructions for i	nore detail).	
The second secon	e, treatment or disposal are		es, minutes, & seconds	).
VII. FACILITY GEOGRAPHIC LOCATION	e, treatment or disposal are			
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  7 4 38 5 66 57 68 68 71	e, treatment or disposal are	LONGITUDE (degre		)
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74  65  65  65  74  VIII. FACILITY OWNER		LONGITUDE (degre	es, minutes, & seconds,	
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  7 4 38 5 66 57 68 68 71		LONGITUDE (degre	es, minutes, & seconds,	
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  7 4 38 57 55 69 71  VIII. FACILITY OWNER  A: If the facility owner is also the facility operator as listed skip to Section IX below.	d in Section VIII on Form 1,	LONGITUDE (degre	es, minutes, & seconds,  0 2 75 75 75 75 75 75 75 75 75 75 75 75 75	
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  7 4 38  65 66 67 65 69 21  VIII. FACILITY OWNER  A: If the facility owner is also the facility operator as listed skip to Section IX below.  B. If the facility owner is not the facility operator as listed.	ed in Section VIII on Form 1, d in Section VIII on Form 1, (	LONGITUDE (degre	es, minutes, & seconds,  0 2 75 76 77 - 75   ce an "X" in the box to	the left and
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  7 4 38 57 55 59 71  VIII. FACILITY OWNER  A: If the facility owner is also the facility operator as listed skip to Section IX below.  B. If the facility owner is not the facility operator as listed 1. NAME OF FACILITY	ed in Section VIII on Form 1, d in Section VIII on Form 1, (	LONGITUDE (degre	es, minutes, & seconds,  0 2 75 76 77 - 75   ce an "X" in the box to	
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  7 4 38 57 55 59 71  VIII. FACILITY OWNER  A: If the facility owner is also the facility operator as listed skip to Section IX below.  B. If the facility owner is not the facility operator as listed 1. NAME OF FACILITY	ed in Section VIII on Form 1, d in Section VIII on Form 1, (	LONGITUDE (degre	ce an "X" in the box to 2. PHONE NO.	the left and (area code & no.)
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38  74 38  VIII. FACILITY OWNER  A. If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister 1. NAME OF FACILITY  C. E. STOCKHOLDERS	d in Section VIII on Form 1, d in Section VIII on Form 1, 0	LONGITUDE (degre	ce an "X" in the box to  2. PHONE NO.	o the left and
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38  74 38  VIII. FACILITY OWNER  A. If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister 1. NAME OF FACILITY  C. E. STOCKHOLDERS  15 16  3. STREET OR P.O. BOX	d in Section VIII on Form 1, d in Section VIII on Form 1, d y's LEGAL OWNER	LONGITUDE (degre	ce an "X" in the box to  2. PHONE NO.  2. PHONE NO.  55 56 - 58 59 -  5. ST. 6. Z	area code & no.
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38  74 38  VIII. FACILITY OWNER  A. If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister 1. NAME OF FACILITE  STOCKHOLDERS  18 16 3. STREET OR P.O. BOX	d in Section VIII on Form 1, d in Section VIII on Form 1, o Y'S LEGAL OWNER	"General Information", placemplete the following item	ce an "X" in the box to  2. PHONE NO.	(area code & no.)
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38 65 67 65 69 71  VIII. FACILITY OWNER  A: If the facility owner is also the facility operator as listed skip to Section IX below.  B: If the facility owner is not the facility operator as listed skip to Section IX below.  1. NAME OF FACILITE  STOCKHOLDERS  3. STREET OR P.O. BOX  F P.O. BOX 281  IX. OWNER CERTIFICATION	d in Section VIII on Form 1, of the Section VIII on Form 1, of	"General Information", placemplete the following item	es, minutes, & seconds, 0 2 75 75 77 77 79  ce an "X" in the box to ns:  2. PHONE NO. 216 - 53 59 - 5, ST. 6. Z 0 11 52 4406	the left and  (area code & no.)  1
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38  74 38  75 55 67 55 69 71  VIII. FACILITY OWNER  A: If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister skip to Section IX below.  1. NAME OF FACILITY  S TOCKHOLDERS  15 16  3: STREET OR P.O. BOX  F P.O. BOX 281  1X. OWNER CERTIFICATION  I certify under penalty of law that I have personally ex	d in Section VIII on Form 1, of the Section VIII on Form 1, of	"General Information", placemplete the following item  OR TOWN  Le 49	es, minutes, & seconds,  0 2	the left and  (area code & no.)  IF CODE  attached
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38 65 67 65 67 65 68 71  VIII. FACILITY OWNER  A: If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister skip to Section IX below.  1. NAME OF FACILITY  S TOCKHOLDERS  15 16 2. STREET OR P.O. BOX  F P.O. BOX 281 13 14 15 1X. OWNER CERTIFICATION  I certify under penalty of law that I have personally explored the documents, and that based on my inquiry of those indicates.	d in Section VIII on Form 1, of the section VIII on Form 1, of	"General Information", placemplete the following item  OR TOWN  The information submarsible for obtaining the information of th	ce an "X" in the box to  2. PHONE NO.  2. PHONE NO.  5. ST.  6. Z  A 4 0 6  Aritted in this and all information, I believ	the left and  (area code & no.)  IF CODE  attached  e that the
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38  74 38  75 55 67 55 69 71  VIII. FACILITY OWNER  A: If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister skip to Section IX below.  1. NAME OF FACILITY  S TOCKHOLDERS  15 16  3: STREET OR P.O. BOX  F P.O. BOX 281  1X. OWNER CERTIFICATION  I certify under penalty of law that I have personally ex	d in Section VIII on Form 1, of the section VIII on Form 1, of	"General Information", placemplete the following item  OR TOWN  The information submarsible for obtaining the information of th	ce an "X" in the box to  2. PHONE NO.  2. PHONE NO.  5. ST.  6. Z  A 4 0 6  Aritted in this and all information, I believ	the left and  (area code & no.)  IF CODE  attached  e that the
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38  74 38  VIII. FACILITY OWNER  A: If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister 1. NAME OF FACILITE  STOCKHOLDERS  3: STREET OR P.O. BOX  F P.O. BOX 281  IX. OWNER CERTIFICATION  I certify under penalty of law that I have personally expected documents, and that based on my inquiry of those indicated information is true, accurate, and complete, including the possibility of fine and imprisonment.	d in Section VIII on Form 1, of the section VIII on Form 1, of	"General Information", placemplete the following item  OR TOWN  The information submarsible for obtaining the information of th	ce an "X" in the box to  2. PHONE NO.  2. PHONE NO.  5. ST.  6. Z  A 4 0 6  Aritted in this and all information, I believ	the left and  (area code & no.)  IF CODE  attached  e that the
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38  74 38  VIII. FACILITY OWNER  A: If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister 1. NAME OF FACILITE  STOCKHOLDERS  3: STREET OR P.O. BOX  F P.O. BOX 281  IX. OWNER CERTIFICATION  I certify under penalty of law that I have personally expected and that based on my inquiry of those indicated information is true, accurate, and complete, including the possibility of fine and imprisonment.  A. NAME (print or type)  FORM DAYLEY	d in Section VIII on Form 1, of the Section VIII on Form 1, of	"General Information", placemplete the following item  OR TOWN  The information submarsible for obtaining the information of th	ce an "X" in the box to  2. PHONE NO.  2. PHONE NO.  3. St. 6. Z  5. ST. 6. Z  mitted in this and all information, I believe submitting false info	attached e that the rmation,
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38 65 67 65 69 71  VIII. FACILITY OWNER  A. If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister in NAME OF FACILITY.  E. STOCKHOLDERS  3. STREET OR P.O. BOX  F. P.O. BOX 281  IX. OWNER CERTIFICATION  I certify under penalty of law that I have personally ex documents, and that based on my inquiry of those indiscubmitted information is true, accurate, and complete, including the possibility of fine and imprisonment.  A. NAME (print or type)  Ford Dayey  Senfor Vice	d in Section VIII on Form 1, of the Section VIII on Form 1, of	"General Information", placemplete the following item  OR TOWN  The information submarsible for obtaining the information of th	ce an "X" in the box to see an "X" in the box	the left and  (area code & no.)  IF CODE  attached  e that the
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38  VIII. FACILITY OWNER  A. If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister 1. NAME OF FACILITY  C. E. STOCKHOLDERS  15 16  3. STREET OR P.O. BOX  C. F. P.O. BOX 281  13 16  IX. OWNER CERTIFICATION  I certify under penalty of law that I have personally extended and that based on my inquiry of those indicated information is true, accurate, and complete, including the possibility of fine and imprisonment.  A. NAME (print or type)  Ford Davey  Senfor Vice President  X. OPERATOR CERTIFICATION	d in Section VIII on Form 1, of in Section VIII on Form 1, of the section VIII on Form 1, of	CONGITUDE (degree 3 3 3 72 - 74 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	ce an "X" in the box to  2. PHONE NO.  2. PHONE NO.  3. Se - 53 Se - 53 Se - 59 Se - 5	attached e that the rmation,
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38  VIII. FACILITY OWNER  A. If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister skip to Section IX below.  1. NAME OF FACILITY  S. TOCKHOLDERS  3. STREET OR P.O. BOX  F P.O. BOX 281  IX. OWNER CERTIFICATION  I certify under penalty of law that I have personally extended and information is true, accurate, and complete, including the possibility of fine and imprisonment.  A. NAME (print or type)  Ford Davey  Senfor Vice  X. OPERATOR CERTIFICATION  I certify under penalty of law that I have personally extended and imprisonment.  I certify under penalty of law that I have personally extended and imprisonment.	d in Section VIII on Form 1, of in Section VIII on Form 1, of the Section VIII on Form 1, of	"General Information", place complete the following item on Town  11e 49  1th the information submissible for obtaining the insignificant penalties for significant penalties for submissible for obtaining the information submissible for obta	ce an "X" in the box to  2. PHONE NO.  2. PHONE NO.  2. PHONE NO.  3. So 59 59 59  5. ST.  6. Z  4.406  Al 32  Altitud in this and all information, I believe submitting false info	the left and  (area code & no.)  10 CODE  attached e that the rmation,
VII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38  VIII. FACILITY OWNER  A. If the facility owner is also the facility operator as lister skip to Section IX below.  B. If the facility owner is not the facility operator as lister 1. NAME OF FACILITY  C. E. STOCKHOLDERS  15 16  3. STREET OR P.O. BOX  C. F. P.O. BOX 281  13 16  IX. OWNER CERTIFICATION  I certify under penalty of law that I have personally extended and that based on my inquiry of those indicated information is true, accurate, and complete, including the possibility of fine and imprisonment.  A. NAME (print or type)  Ford Davey  Senfor Vice President  X. OPERATOR CERTIFICATION	d in Section VIII on Form 1, of in Section VIII on Form 1, of the section VIII on Form 1, of	CONGITUDE (degree 3 3 3 72 - 74 3 4 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 -	ce an "X" in the box to  2. PHONE NO.  2. PHONE NO.  3. Se - 53 Se - 53 Se - 59 Se - 5	attached that the the that the the that the that the that the that the that the the the that
VII. FACILITY GEOGRAPHIC LOCATION    The complete of the facility of facility of the facility of facility of facility of the facility of the facility of the facility of the facility of facility of facility of facility of facility of the facility of facility of the facility of the facility of the facility of the facility of facility of facility of the facility of the facility of the facility of facility of facility of facility of facility of facility of the facility of f	d in Section VIII on Form 1, of in Section VIII on Form 1, of the section VIII on Form 1, of	CONGITUDE (degree 3 3 3 72 - 74 3 4 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 -	ce an "X" in the box to  2. PHONE NO.  2. PHONE NO.  3. Se - 53 Se - 53 Se - 59 Se - 5	the left and  (area code & no.)  1P CODE  attached that the rmation,  attached the that the
VIII. FACILITY GEOGRAPHIC LOCATION    The content of the facility operator as listed in the	d in Section VIII on Form 1, of in Section VIII on Form 1, of the section VIII on Form 1, of	CONGITUDE (degree 3 3 3 72 - 74 3 4 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 -	ce an "X" in the box to  2. PHONE NO.  2. PHONE NO.  3. Se - 53 Se - 53 Se - 59 Se - 5	attached that the the that the the that the that the that the that the that the the the that
VIII. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes, & seconds)  74 38 55 65 67 68 77 68 88 71 71  VIII. FACILITY OWNER  At if the facility owner is also the facility operator as listed skip to Section IX below.  B. If the facility owner is not the facility operator as listed skip to Section IX below.  B. If the facility owner is not the facility operator as listed skip to Section IX below.  B. If the facility owner is not the facility operator as listed skip to Section IX below.  B. If the facility owner is not the facility operator as listed skip to Section IX below.  B. If the facility owner is not the facility operator as listed skip to Section IX below.  B. If the facility owner is not the facility operator as listed skip to Section IX below.  B. If the facility owner is not the facility operator as listed skip to Section IX below.  B. If the facility owner is not the facility operator as listed skip to Section IX below.  B. If the facility owner is also the facility operator as listed skip to Section IX below.  B. If the facility owner is also the facility operator as listed skip to Section IX below.  B. If the facility owner is also the facility operator as listed skip to Section IX below.  B. If the facility owner is also the facility operator as listed skip to Section IX below.  B. If the facility owner is also the facility operator as listed skip to Section IX below.  B. If the facility owner is also the facility operator as listed skip to Section IX below.  B. If the facility owner is also the facility operator as listed skip to Section IX below.  B. If the facility operator as listed skip to Section IX below.  B. If the facility operator as listed skip to Section IX below.  B. If the facility operator as listed skip to Section IX below.  B. If the facility operator as listed skip to Section IX below.  B. If the facility operator as listed skip to Section IX below.  B. If the facility operator as listed skip to Section IX below.  B. If the facility operator as listed skip to Section IX bel	d in Section VIII on Form 1, of the Section VIII on Form 1, of	CONGITUDE (degree 3 3 3 72 - 74 3 4 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 - 74 3 72 -	ce an "X" in the box to  2. PHONE NO.  2. PHONE NO.  2. PHONE NO.  3. S.	attached that the the that the the that the that the that the that the that the the the that

Continued from page 4.

V. FACILITY DRAWING (see page 4)

SEE ATTACHED





P.O. BOX 281

Conf

NORTH KINGSVILLE, OHIO 44068

PHONE (216) 224-2181



MAY 20 1992

OFFICE OF RCRA Waste Management Division U.S. EPA, REGION W

May 13, 1992

USEPA Division of Hazardous Waste Management 230 South Dearborn Street Chicago, IL 60604

To Whom It May Concern:

Recently I located a file here at my office pertaining to the closure of a hazardous waste storage area (Permit #02-04-0567) here at Premix, Inc. (EPA ID #OHD004200044). A post-closure inspection was conducted on Friday, August 11, 1989 by Marion Toumazos, Ohio EPA. Ohio EPA has since recognized that the area has been closed in accordance with the Ohio Administrative Code (see enclosure).

However, I could not locate any documentation from USEPA regarding their acceptance of this closure. Therefore, through this letter, I respectfully request documentation from USEPA verifying that this area is indeed closed.

If this request is unclear or if you have any questions, feel free to contact me at the above address/telephone number (extension 295). Thank you for your attention to this matter, your assistance is greatly appreciated.

Sincerely,

Raymond A. Kovacs, CHMM Environmental Manager

XC: F. Davey, Premix, Inc.

M. Fickenscher, Premix, Inc.

T. Warren, Esq., Warren & Young, Attorneys at Law

State of Ohio Environmental Protection Agency

P.O. Box 1049, 1800 WaterMark Dr. Columbus, Ohio 43266-0149 (614) 644-3020 FAX (614) 644-2329 George V. Voinovich
Governor

Donald R. Schregardus Director

April 20, 1992

Re: Premix, Inc.

EPA ID No.: OHD004200044 Ohio ID No.: 02-04-0567 Completion of Closure

Premix, Inc. Attn: Debbie Hall PO Box 281 North Kingsville, Ohio 44068

Dear Ms. Hall:

According to our records, on April 18, 1988, the Director of Ohio EPA approved a closure plan submitted by Premix, Inc. for the hazardous waste concrete container storage pad located at Harmon Road & Route 20, North Kingsville, Ohio 44068. On August 3, 1989, Premix, Inc. submitted to the Director certification documents that the hazardous waste concrete container storage pad had been closed according to the specifications in the approved closure plan. Ohio EPA District Office personnel completed a certification of closure inspection and a review of documents pertaining to the hazardous waste concrete container storage pad on September 26, 1989. Based on this inspection and review, the Ohio EPA has determined that the hazardous waste concrete container storage pad has been closed in accordance with the approved closure plan and Rules 3745-66-12 through 3745-66-15 of the Ohio Administrative Code (OAC) and Premix, Inc. will maintain the status of a generator of hazardous waste.

You should continue to use the identification number assigned to you for purposes of compliance with the Ohio EPA manifest, recordkeeping and reporting requirements as appropriate.

If you have any questions concerning your current status, please contact the Ohio EPA, Northeast District Office, Attn: Nancy Zikmanis, 2110 East Aurora Road, Twinsburg, Ohio 44087, tel.: (216) 425-9171.

In accordance with Rules 3745-66-43(H) and 3745-66-47(E) of the OAC, Premix, Inc. will not be required to maintain financial assurance for closure costs and liability coverage for accidental occurences at this facility.

April 20, 1992 Premix, Inc. Completion of Closure Pg. 2

Please note that this letter does not relieve you of any corrective action responsibilities that may be required.

Should you have further questions concerning this procedure, please call Randy Sheldon, Data Management Section at (614) 644-2977.

Very truly yours,

Thomas E. Crepeau, Manager

Data Management Section

Division of Hazardous Waste Management

TC/rs

cc: Randy Meyer, RCRA TAS, DHWM
Laurie Stevenson, HW ES, DHWM
Beth Harris, DMS, DHWM
Rhonda Rothschild, DMS, DHWM
Nancy Zikmanis, DHWM, NEDO
File

P. O. BOX 281

NORTH KINGSVILLE, OHIO 44068

PHONE (216) 224-2181

July 27, 1989



U.S. EPA, REGION V WASTE MANAGEMENT DIVISION OFFICE OF THE DIRECTOR

والمراقب المنافية والمراجدات

U.S. EPA Region 5 Waste Management Division 230 South Dearborn Street Chicago, IL 60604

#### Gentlemen:

This is to notify you that the closure, OAC 3745-66, for the permited storage facility at Premix, Inc., North Kingsville has been completed in an environmentally safe manner and that we are functioning under generator regulations 40 CFR 262.

Enclosed are the original request for closure; the Ohio EPA letter from Richard L. Shank dated April 18, 1988; and the Free-Col Laboratories, Inc. analytical report form dated June 12, 1989 needed to complete the full closure for Premix, Inc., North Kingsville facility, EPA ID# 004200044,/Permit #02-04-0567.

If there are any questions, I can be reached at (216) 224-2181, Extension 295.


Respectfully,

PREMIX, INC.

Brenda L. Ritchie

dgl

Enclosures



#### CHARLES H. GROSSMAN, P.E.

CONSULTING ENGINEER

7805 LAUREN J. DRIVE

(216) 255-0063

MENTOR, DHIO 44060

June 3, 1988

To Whom It May Concern % Premix, Incorporated P. O. Box 281 North Kingsville, Ohio 44125

> Re: Completion of Partial Closure Premix, Incorporated Facility North Kingsville, Ohio OH004200044

I certify under penalty of law that this document and all attachments were prepared under the direction and supervision of Debra Parshall Hall, CHMM in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

CHARLES
H.
GROSSMAN
24/13

Very truly yours,

Charles H. Grossman, P. E.

In cooperation with:

Premix, Incorporated

Debra Parshall- Hall, CHMM

Encl: Request for Partial Closure dated February 26, 1987
U.S.E.P.A. Letter from Basil G. Constantelos Dated December 2, 1987
Professional Service Industries' Report on Soil Boring Operations
and Laboratory Testing Operations-Waste Storage Area dated
February 8, 1988

NORTH KINGSVILLE, OHIO

OHD 004 200 044

Ms. Marion Toumazos Ohio EPA, DHSWM 2110 E. Aurora Road Twinsburg, Ohio 44087 May 2, 1989

MAY 00 1989

Waste Management Division
U.S. EPA, REGION V

Dear Ms. Toumazos:

On April 21, 1989, you notified the Premix, Inc., North Kingsville facility that the closure plan submitted December 21, 1987 was in violation of closure proceedings under Rule 3745-66-12 of the Ohio Administrative Code.

This letter is to inform you that the storage facility closure has been initiated in accordance with OAC 3745-66-12(A&B). The closure will consist of a new accumulation area being built, start date for construction is set for May 1, 1989.

The storage facility will be closed in a manner that minimizes the need for further maintenance, controls and maintains to the maximum extent necessary protection of human health and the environment, OAC 3745-66-22(A)(B), OAC 3745-66-12(1).

The drum storage shall be swept and the sweepings shall be managed as hazardous wastes. The foundation for the storage area will be pressure rinsed with water. The rinseate will be collected and analyzed using US EPA publication SW-846, "Test Methods for Evaluating Solid Wastes". Volatiles analyzed for shall be methylene chloride, acetone, toluene and pyridine using SW-846 Methods 8240 and 8250. Methyl isobutyl ketone and methyl ethyl ketone will be analyzed by SW-846 Method 8015. Lead and chromium will be analyzed by SW-846 methods.

The storage foundation shall be examined for fissures. Should any fissure be found, soil analysis will be performed in six inch increments to a depth of one foot. If soil sampling is necessary, analysis using SW-846 Methods 8016, 8240 and 8250 will be performed. Samples will be analyzed for the presence of methylene chloride, acetone, toluene, pyridine, methyl ethyl ketone, methyl isobutyl ketone, lead and chromium.

If further action is required for soil analysis, it will be addressed at that time.

A detailed drawing of the storage area is enclosed that explains the area in concern and how diking will be done.

At the conclusion of the decontamination, an independent registered engineer

Ms. Marion Toumazos Page Two May 2, 1989

will verify the closure was completed according to the plan OAC 3745-50-42 and a written certification OAC 3745-50-42(D) by said engineer will be included.

If there are any further questions, I can be contacted at (216) 224-2181, Ext. 295.

Sincerely,

PREMIX, INC.

Debra Parshall-Hall, CHMM

dgl

#### Enclosure

CC: Mr. G. Hamper, 5HS-13
Ohio Permit Unit
US EPA Region V
230 S. Dearborn Street
Chicago, IL 60404

Mr. Tom Crepeau, DSHWN Data Management Unit OEPA P.O. Box 1049 Columbus, OH 43266-1049

Mr. Ford Davey Mr. Jeff Davis Mr. David Randall Premix, Inc.



NORTH KINGSVILLE, OHIO

Ms. Teresa Sabol, DHSWM OEPA Northeast District Office 2110 E. Aurora Road Twinsburg, Ohio 44087 JUL 0 8 1988

U. S. EPA, REGION V
SWB — PMS

SUBJECT:

Partial Closure Plan

Dear Ms. Sabol:

This packet contains the information needed to complete the partial closure for Premix, Inc., North Kingsvile facility, EPA ID #OHD 004200044, Permit #02-04-0567.

Enclosed is the original "Request for Closure" dated February 26, 1987; the soil boring and laboratory testing operations, dated February 8, 1988; the letter from USEPA approving closure dated May 31, 1988; and a letter from Charles H. Grossman, P.E., certifying the closure.

This information should finalize the partial closure and show our good faith in insuring protection of human health and the environment.

If there are any question, I can be contacted at ((216) 224-2181, Ext. 295.

Sincerely,

PREMIX, INC.

Debra Parshall-Hall CHMM

dgl

**Enclosures** 

cc:

Mr. George Hamper 
Ohio Permit Unit
USEPA

Mr. Thomas Crepeau, DHSWM Program Planning & Management Section

Mr. Ford Davey Mr. Mark Fickenscher Premix, Inc.

# CERTIFIED MAIL

Debra Parshall-Hall Premix, Incorporated Post Office Box 281 North Kingsville, Ohio 44068

> RE: Partial Closure Plan Premix, Incorporated OHD 004 200 044

Dear Ms. Parshall-Hall:

The United States Environmental Protection Agency (U.S. EPA) received a copy of the above-referenced facility's partial closure plan on December 29, 1987. This plan was previously submitted to the Ohio Environmental Protection Agency (OEPA) on December 22, 1987. The plan concerned the closure of a hazardous waste container storage area located at the facility.

The OEPA approved the plan conditionally, in a letter dated April 18, 1988. The U.S. EPA approves the closure plan submitted by Premix, Incorporated, with the conditions stipulated by the OEPA in the April 18, 1988, letter.

If you have any further questions, please contact Ms. Rebecca Strom of my staff, at (312) 886-6194.
Sincerely,


Basil G. Constantelos, Director Waste Management Division

cc: Randy Meyer, OEPA
Tony Sasson, OEPA
Teresa Sabol, OEPA-NEDO

5HS-13:Strom:vmc

05/24/88

Disk #4



NORTH KINGSVILLE, OHIO

February 19, 1988

Ms. Teresa Sabol, DSHWM OEPA Northeast District Office 2110 E. Aurora Road Twinsburg, Ohio 44087 MAR 0 4 1988

J. S. EPA, REGION V
SWB - PMS

RE:

Closure Plan Premix, Inc.

OH0004200044, O2-04-0567

U.S. EPA, REGION V

Dear Ms. Sabol:

On this date, soil analysis results were received from the December 18, 1987 test borings.

In accordance with the letter dated October 15, 1987, from Richard L. Shank, PH. D, Director OEPA Columbus, the following modifications have been completed.

- Soil samples collected in the area designated in the plan, collected using appropriate method found in 40 CFR 261 Appendix I.
- Soil samples collected to a minimum depth of one foot.
- 3. Soil samples handled and analyzed for organic contaminants using Method 8240 and Method 8250 found in USEPA publication SW-846, for the presence of methylene chloride, acetone, toluene, pyridine, methanol, chloroform and styrene.

The attached pages contain the procedure that was used for collection of samples, decontamination of sampling/boring equipment, and disposal of rinseates.

The laboratory results, listed on Page Four of the attachment, are reported in microgram per kilogram (PPB) with the exception of Methanol that is reported in milligrams per kilogram (dry weight).

Upon discussion with the laboratory (Aquatest) who performed the analysis, the results are non-detectable, and the variation seen from sample to sample is the result of the matrix analyzed.

The last pages consist of the description of each boring, and the sampling depth.

NORTH KINGSVILLE, OHIO

December 21, 1987

Mr. Tom Crepeau, DSHWM Data Management Unit Ohio EPA P.O. Box 1049 Columbus, Ohio 43266-1049 DEC 2 3 1987

SULIS EPA REGION V

Dear Mr. Crepeau:

Attached is a request for closure of a waste storage unit, OAC 3745-66-12 (C), for Premix, Inc., North Kingsville facility, EPA ID OHD 0042 00044, Permit No. 02-04-0567.

If there are any questions, I can be contacted at (216) 224-2181, Ext. 295.

Sincerely,

PREMIX, INC.

Debra Parshall-Hall, CHMM

Environmental/Industrial Hygiene Coordinator

dgl

#### Attachment

CC: Mr. G. Hamper, 5HS-13
Ohio Permit Unit
U.S. EPA Region V
230 South Dearborn Street
Chicago, IL 60404

Ms. Teresa Sabol OEPA Twinsburg, Ohio

Mr. F.M. Davey Mr. M. Fickenscher Mr. D. Batchelor Premix, Inc.







Debra Parshall-Hall Premix, Incorporated Post Office Box 281 North Kingsville, Ohio 44068

> Partial Closure Plan Premix, Incorporated OHD 004200044

Dear Ms. Parshall-Hall:

The United States Environmental Protectin Agency (U.S. EPA) received a copy of the above-referenced facility's partial closure plan on August 31, 1987. This plan was previously submitted to the Ohio Environmenal Protection Agency (OEPA) on March 6, 1987. The plan concerned the closure of a hazardous waste container area located at the facility.

The OEPA approved the plan conditionally in a letter dated October 15, 1987. The U.S. EPA concurs with the OEPA's review and approval. U.S. EPA approves the closure plan submitted by Premix, Incorporated, with the conditions stipulated by the OEPA in the October 15, 1987, letter.

If you have any further questions, please contact Ms. Rebecca Strom of my staff, at (312) 886-6194.

Sincerely.

Basil G. Constantelos, Director Waste Management Division

cc: Randy Meyer, OEPA Tom Crepeau, OEPA Debbie Berg, OEPA-NEDO Tony Sasson, OEPA

bcc: File

5HS/Strom: VW 11/20/87 Disk #3 11/23/87

revised

THE AREA ME.								om/kg/x		M
11/23	TYP.	AUTH.	IL. CHIEF	IN. CHIEF	MI, CHIÉF	MN/WI CHIEF	ОН. ЛОНІЕБ	TPS	SWB	DIR
INIT. DATE	Vm	2/2					1/2/17	KS/3 11/25/8	7 1998	Popur
				gen contemposarios por T.	Land State of Ball 14	11 "25 mapped 57	1. Academy of the	TO THE ACT OF THE OWNER, AND THE	50	19-1-10:

#### CERTIFIED MAIL RETURN RECEIPT REQUESTED

Mr. L. E. Perkey Premix, Inc. P.O. Box 281 North Kingsville, Ohio 44068

Re: Premix, Inc.
North Kingsville, Ohio
U.S. EPA ID #: OHD 004-200-044

Dear Mr. Perkey:

The enclosed financial instruments—naming the United States Environmental Protection Agency as the beneficiary—were submitted for the referenced hazardous waste management facility. This is required by the Resource Conservation and Recovery Act to ensure that funds are available to cover costs of closure and post-closure activities, should the facilities cease operation. Closure and post-closure activities are done to clean up sites to leave them environmentally safe.

As part of the process to transfer hazardous waste management programs to the States, the Ohio Environmental Protection Agency has been authorized to administer the financial responsibility program. This means that new financial instruments—naming the Ohio Environmental Protection Agency as the beneficiary—must be submitted to the State; consequently, we consent to the termination of the present financial instrument.

The new financial instruments--naming the Ohio Environmental Protection Agency as the beneficiary--can be established so that it will satisfy future Federal permit requirements for the facility. This should result in savings for the facilities because it avoids having both a Federal and a State financial instrument for the same facility.

For details, please refer to the following regulations: Ohio EPA requirements--Ohio Administrative Code Rule 3745 for closure, post-closure, liability, and instrument wording; Federal Permit requirements--Resource Conservation and Recovery Act (RCRA) as amended, Section 3004 (42 USC §6924), Title 40 of the Code of Federal Regulations (40 CFR §264.149); State authorization requirements--RCRA Section 3006 (42 USC §6926).



#### State of Ohio Environmental Protection Agency

P.O. Box 1049, 1800 WaterMark Dr. Columbus, Ohio 43266-0149



Richard F. Celeste Governor

#### CERTIFIED MAIL

October 15, 1987

Re: CLOSURE PLAN

PREMIX, INC.

OHD004200044, 02-04-0567

Ms. Debra Parshall-Hall Premix, Inc. P.O. Box 281 North Kingsville, Ohio 44068

Dear Ms. Parshall-Hall:

On March 6, 1987, Premix, Inc. submitted to Ohio EPA a closure plan for a hazardous waste drum storage area located at Route 20 and Harmon Road, Harmon, Ohio. The closure plan was submitted pursuant to Rule 3745-66-12 of the Ohio Administrative Code (OAC) in order to demonstrate that Premix's proposal for closure complies with the requirements of OAC Rules 3745-66-11 and 3745-66-12.

The public was given the opportunity to submit written comments regarding the closure plan of Premix, Inc. in accordance with OAC Rule 3745-66-12. No comments were received by Ohio EPA in this matter.

Based upon review of the company's submittal and subsequent revisions, I conclude that the closure plan for the hazardous waste facility at Premix, Inc. meets the performance standard contained in OAC Rule 3745-66-11 and complies with the pertinent parts of OAC Rule 3745-66-12.

The closure plan submitted to Ohio EPA by Premix, Inc. is hereby approved with the following modifications:

- Soil samples collected in the area designated in the plan to be closed shall be collected using the appropriate representative sampling method found in 40 CFR 261 Appendix I.
- 2. Soil samples shall be initially collected to a minimum depth of 1 foot below the crushed limestone/soil interface; samples shall be analyzed in individual 6 inch increments.
- Soil samples shall be handled and analyzed (for organic contaminants)
  using Method 8240 and Method 8250 found in USEPA Publication SW-846, "Test
  Methods for Evaluating Solid Wastes." At a minimum, Premix shall analyze

I certify this to be a true and accurate copy of the control document as filed in the records of the Ohio Electronmental Protection Agency.

34: Mary Capin Date 10-15-87

Clas Environmental Protection Agency ENTERED DIRECTOR'S JOURNAL

OCT 15 1987

Ms. Debra Parshall-Hall Page Two October 15, 1987

samples for the presence of methylene chloride, acetone, toluene, pyridine, methanol, chloroform and styrene. Analyses for the other compounds detected by those methods shall also be conducted and reported.

- 4. Soils in the area undergoing closure shall be considered contaminated if soil samples contain greater than the analytical detection limit of any RCRA waste solvent. Analytical detection limits shall be taken from the appropriate methods in USEPA Publication SW-846, "Test Methods for Evaluating Solid Wastes."
- 5. If styrene is detected in the soil samples, Premix shall demonstrate to Ohio EPA that the presence of this compound does not present a risk to human health or the environment.
- 6. Premix shall continue to remove contaminated soils from the closure area until subsequent soil testing, both laterally and vertically, demonstrates that no contamination by organic compounds remains. Premix shall manage contaminated limestone gravel and soil as hazardous waste.
- 7. Equipment used to collect samples and to remove contaminated gravel and soil shall be adequately decontaminated following use, by washing with an appropriate cleaner and then triple-rinsing. No more than 1 mg/liter of any RCRA regulated waste solvent shall remain in the final (3rd) rinseate in order for the equipment to be considered decontaminated. Rinseates shall be analyzed using methods found in USEPA Publication SW-846, "Test Methods for Evaluating Solid Wastes." Washwaters and rinsewaters containing greater than 1 mg/liter of any RCRA regulated waste solvent shall be managed as hazardous waste. Samples shall be analyzed for the same parameters using the same analytical methods as specified in Modification #3.
- 8. Premix shall submit all closure analytical results to Ohio EPA Northeast District Office (NEDO) and Central Office (CO) within ten (10) working days of receipt by Premix. Premix shall also submit, at that time, evidence of a laboratory QA/QC program.
- 9. Prior to initiating these closure activities, Premix shall notify and receive approval from Ohio EPA NEDO of the facility's chosen soil sampling method, procedures for removing contaminated soil, and method for containment of generated washwaters/rinsewaters. Premix shall notify the Ohio EPA NEDO at least ten (10) working days in advance of the initiation of closure activities.

Please be advised that approval of this closure plan does not release Premix, Inc. from any responsibilities as required under the Hazardous and Solid Waste Amendments of 1984 regarding corrective action for all releases of hazardous waste or constituents from any solid waste management unit, regardless of the time at which waste was placed in the unit.

I certify this to be a true and accurate copy of the official document as filed in the records of the Ohio Environmental Protection Agency.

3y: Mary Caun Date 10-15-87

THE Endocumental Protection Agency Entened director's Journal Ms. Debra Parshall-Hall Page Three October 15, 1987

Premix shall notify the Ohio EPA Northeast District Office (NEDO) at least ten (10) working days in advance of the initiation of closure activities.

Due to the fact that the Ohio EPA is not currently authorized to conduct the federal hazardous waste program in Ohio, your closure plan also must be reviewed and approved by USEPA. Federal RCRA closure regulations (40 CFR 265.112) require that you submit a closure plan to George Hamper, Chief, Waste Management Division, Technical Programs Section, Ohio Unit, USEPA, Region V, 5HS-13, 230 South Dearborn Street, Chicago, Illinois 60604. Approval by both agencies is necessary prior to commencement of activities required by the approved closure plan.

You are notified that this action of the Director is final and may be appealed to the Environmental Board of Review pursuant to Section 3745.04 of the Ohio Revised Code. The appeal must be in writing and set forth the action complained of and the grounds upon which the appeal is based. It must be filed with the Environmental Board of Review within thirty (30) days after notice of the Director's action. A copy of the appeal must be served on the Director of the Ohio Environmental Protection Agency and the Environmental Enforcement Section of the Office of the Attorney General within three (3) days of filing with the Board. An appeal may be filed with the Environmental Board of Review at the following address: Environmental Board of Review, 236 East Town Street, Room 300, Columbus, Ohio 43266-0557.

When closure is completed, the Ohio Administrative Code Rule 3745-66-15 requires the owner or operator of a facility to submit to the Director of the Ohio EPA certification by the owner or operator and a registered professional engineer that the facility has been closed in accordance with the approved closure plan. The certification by the owner or operator shall include the statement found in OAC 3745-50-42(D). These certifications should be submitted to: Ohio Environmental Protection Agency, Division of Solid and Hazardous Waste Management, Attn: Thomas Crepeau, Program Planning and Management Section, P.O. Box 1049, Columbus, Ohio 43266-0149.

Sincerely,

Richard L. Shank, Ph.D.

Director

RLS/DF/ara

cc: Thomas Crepeau/DSHWM Central File, Ohio EPA Rebecca Strom, USEPA, Region V Deborah Berg, NEDO, Ohio EPA

Forman for

13700

I certify this to be a true and accurate copy of the Signature Agancy official document as filed in the records of the Ohio Engraphmental Protection Agency.

Mary Cavin Oate 10-15-87 OCT 15 1987



#### State of Ohio Environmental Protection Agency

P.O. Box 1049, 1800 WaterMark Dr. Columbus, Ohio 43266-0149



Richard F. Celeste Governor

#### CERTIFIED MAIL

April 18, 1988

Re: CLOSURE PLAN

PREMIX INC.

OHD004200044, 02-04-0567

Ms. Debra Parshall-Hall Premix Inc. Route 20 and Harmon Road North Kingsville, Ohio 44068

Dear Ms. Parshall-Hall:

On December 22, 1987, Premix Inc. submitted to Ohio EPA a closure plan for a concrete container storage pad located at Route 20 and Harmon Road, North Kingsville, Ohio. The closure plan was submitted pursuant to Rule 3745-66-12 of the Ohio Administrative Code (OAC) in order to demonstrate that Premix Inc.'s proposal for closure complies with the requirements of OAC Rules 3745-66-11 and 3745-66-12.

The public was given the opportunity to submit written comments regarding the closure plan of Premix Inc. in accordance with OAC Rule 3745-66-12. No comments were received by Ohio EPA in this matter.

Based upon review of the company's submittal, I conclude that the closure plan for the hazardous waste facility at Premix Inc. meets the performance standard contained in OAC Rule 3745-66-11 and complies with the pertinent parts of OAC Rule 3745-66-12.

The closure plan submitted to Ohio EPA by Premix Inc. is hereby approved with the following modifications:

- 1. The drum storage area shall be swept and the sweepings shall be managed as hazardous waste.
- 2. Subsequently, the drum storage area shall be power rinsed with water and the rinseate collected and tested for volatile organics, solvents, and paint wastes. The rinseate shall be analyzed using methods found in USEPA publication SW-846, "Test Methods for Evaluating Solid Wastes." At a minimum, Premix Inc. shall analyze for methylene chloride, acetone, toluene, and pyridine (SW-846 Methods 8240 & 8250); methyl isobutyl ketone and methyl ethyl ketone (SW-846 Method 8015); lead and chromium (SW-846 Methods). Analyses for other compounds detected in the organics testing shall be conducted and reported to further quantify wastes.

I certify this to be a true and accurate copy of the official document as filed in the records of the Ohio Environmental Protection Agency.

By: Natura Davis Date 4-18-88

Ohio Environmental Protection Agency ENTERED DIRECTOR'S JOURNAL

APR 1 8 1988

Ms. Debra Parshall-Hall Page Two April 18, 1988

- 3. Both rinseates and the storage pad shall be considered contaminated if the rinseates contain greater than 1 mg/l of any RCRA regulated solvents or organics, or greater than the maximum concentrations of lead and chromium under the characteristic of EP Toxicity in OAC 3745-51-24. Contaminated rinseates (as defined above) shall be considered hazardous waste and disposed of accordingly. The pad shall be power rinsed with water until contamination is removed as defined above.
- 4. All equipment used in the decontamination of the storage pad must be power rinsed with water and the rinseate must be tested for volatile organic compounds, waste solvents, and paint wastes. Samples shall be analyzed and managed for the parameters using the same analytical methods as specified #2 and #3 above.
- 5. Prior to initiating these closure activities, Premix shall notify Teresa Sabol, Ohio EPA, Northeast District Office (NEDO), and receive approval from Ohio EPA, NEDO, of the facility's chosen sampling methods, and methods for containment of generated soils and washwaters/rinseates. Premix shall notify Teresa Sabol, Ohio EPA, NEDO, at least ten (10) business days in advance of the initiation of closure activities.
- 6. Premix shall submit all closure analytical results to Teresa Sabol, Ohio EPA, NEDO, within ten (10) business days of receipt by Premix. Premix shall also submit, at that time, evidence of laboratory QA/QC program ensuring that the equipment and methods used for analysis provided precise and accurate results for the SW-846 analyses performed.
- 7. The storage pad shall be checked for cracks. Should cracks be found, Premix must sample soils under the crack along its entire length. Sampling can be done by boring holes through the concrete (along the crack line) and taking soil samples using a split spoon sampler. Samples shall be taken in six (6) inch depth increments to a minimum depth of one (1) foot beneath the soil surface.
- 8. Soil samples shall be handled and analyzed for organic contaminants using Method 8015, Method 8240, and Method 8250 found in USEPA Publication SW-846, "Test Methods for Evaluating Solid Wastes." At a minimum, Premix shall analyze samples for the presence of methylene chloride, acetone, toluene, pyridine, methyl ethyl ketone and methyl isobutyl ketone. Analyses for lead and chromium must also be performed. The facility shall analyze soils for background levels of total metals in areas on site with similar geology (as those that are contaminated) that are not impacted by solid or hazardous waste operations. These background levels of lead and chromium shall then be compared to the levels of total lead and total chromium found in the soils underneath the storage pad. A minimum of four (4) background soil sample sites shall be selected with the approval of Teresa Sabol, Ohio EPA, NEDO.

I certify this to be a true and accurate copy of the official document as filed in the records of the Ohio Environmental Protection Agency.

APR 1 8 1988

ENTERED DIRECTOR'S JOHRNÁL

Environmental Protection Agency.

By: Natice Davis Date 4-18-88

- 9. The soil shall be considered contaminated (and managed as hazardous waste) if soil samples contain greater than the analytical detection limit of any RCRA waste solvent (see SW-846) or with EP Toxic metals above the maximum concentrations specified in OAC 3745-51-24. Soils contaminated with metals at levels greater than background but less than EP toxic levels shall be managed as solid waste.
- 10. Premix shall continue to remove contaminated soils from underneath and around the storage pad until subsequent soil testing (both laterally and vertically) demonstrates that no contamination by organic compounds or metals remain in the soils.
- 11. On page 5, item #6, soil removal and backfilling are mentioned but they are not addressed in the closure plan. These proposed processes shall be expounded upon and submitted to Teresa Sabol, Ohio EPA, NEDO, at least ten (10) working days in advance of initiation of closure activities.
- 12. Premix Inc. shall provide a detailed drawing of the storage area to be closed to Teresa Sabol, Ohio EPA, NEDO, at least ten (10) business days in advance of initiation of closure activities. The extent of the diking shall be emphasized.
- 13. The owner/operator's and independent registered engineer's certification's of closure must follow the signature requirements found in OAC 3745-50-42 and the owner certification statements must include the exact wording found in OAC 3745-50-42(0).
- 14. Premix Inc. shall notify Teresa Sabol, Ohio EPA, NEDO, at least five (5) business days in advance of critical closure activities (i.e., soil sampling, pad cleaning and rinsing, soil removal, etc.) so that she can be present to observe these activities. Premix shall also ensure that the registered independent professional engineer will be present during crucial closure activities.

Please be advised that approval of this closure plan does not release Premix Inc. from any responsibilities as required under the Hazardous and Solid Waste Amendments of 1984 regarding corrective action for all releases of hazardous waste or constituents from any solid waste management unit, regardless of the time at which waste was placed in the unit.

Due to the fact that the Ohio EPA is not currently authorized to conduct the federal hazardous waste program in Ohio, your closure plan also must be reviewed and approved by USEPA. Federal RCRA closure regulations (40 CFR 265.112) require that you submit a closure plan to George Hamper, Chief, Waste Management Division, Technical Programs Section, Ohio Unit, USEPA, Region V, 5HS-13, 230 South Dearborn Street, Chicago, Illinois 60604. Approval by both agencies is necessary prior to commencement of activities required by the approved closure plan. If closure activities will, of necessity, take longer than 180 days to complete in order to allow for a period of time for review

I certify this to be a true and accurate copy of the official document as filed in the records of the Ohio Environmental Protection Agency.

Obio Environmental Protection Agency ENTERED DIRECTOR'S JOURNAL

By: Nature Davis Date 4-18-88

APR 181988

Ms. Debra Parshall-Hall Page Four April 18, 1988

and approval by USEPA, a longer closure period is hereby approved pursuant to OAC rule 3745-66-13(B) provided Premix Inc. shall commence closure upon receipt of this approval by Ohio EPA or upon receipt of approval by USEPA, whichever occurs later. The closure period shall not exceed 180 days beyond the latter approval.

You are notified that this action of the Director is final and may be appealed to the Environmental Board of Review pursuant to Section 3745.04 of the Ohio Revised Code. The appeal must be in writing and set forth the action complained of and the grounds upon which the appeal is based. It must be filed with the Environmental Board of Review within thirty (30) days after notice of the Director's action. A copy of the appeal must be served on the Director of the Ohio Environmental Protection Agency and the Environmental Enforcement Section of the Office of the Attorney General within three (3) days of filing with the Board. An appeal may be filed with the Environmental Board of Review at the following address: Environmental Board of Review, 236 East Town Street, Room 300, Columbus, Ohio 43266-0557.

When closure is completed, the Ohio Administrative Code Rule 3745-66-15 requires the owner or operator of a facility to submit to the Director of the Ohio EPA certification by the owner or operator and a registered professional engineer that the facility has been closed in accordance with the approved closure plan. The certification by the owner or operator shall include the statement found in OAC 3745-50-42(D). These certifications should be submitted to: Richard L. Shank, Director, Ohio Environmental Protection Agency, Attn: Thomas Crepeau, Program Planning and Management Section, Division of Solid and Hazardous Waste Management, P.O. Box 1049, Columbus, Ohio 43266-0149.

Sincerely.

Richard L. Shank, Ph.D.

Director

RLS/PV/ara

cc: Thomas Crepeau/DSHWM Central File, Ohio EPA
Rebecca Strom, USEPA, Region V
Teresa Sabol, NEDO, Ohio EPA
Dave Wertz, NEDO, Ohio EPA
Paul Vandermeer, DSHWM, Ohio EPA

13700

I certify this to be a true and accurate copy of the official document as filed in the records of the Ohio Environmental Protection Agency.

By: Natice Daris Date 4-18-88

Ohio Environmental Protection Agency Entered Director's Journal

APR 18 1988

P. O. BOX 281

#### NORTH KINGSVILLE, OHIO 44068

PHONE (216) 224-2181

February 26, 1987

Mr. Tom Crepeau
Data Management Unit
OHIO EPA
Division of Solid and Hazardous Waste Management
P. O. Box 1049
Columbus, OH 43266-1049

Dear Mr. Crepeau:

Attached is a request for partial closure of a waste management unit, OAC 3745-66-12(C) for the Premix, Inc., North Kingsville facility, EPA I.D. #OHD 004200044, Permit No. 02-04-0567.

Please review and comment.

Sincerely,

PREMIX, INC.

Debra Parshall-Hall, CHMM

Environment Engineer

bw

Attachment

v cc: Mr. George Hamper, 5HS-13 Ohio Permit Unit

U.S. EPA Region V

230 South Dearborn Street

Chicago, IL 60404

Ms. Deborah J. Berg

Ohio EPA

Northeast District Office Twinsburg, OH 44087-1969

Mr. F. M. Davey Mr. M. Fickenscher Premix, Inc.

### REQUEST FOR PARTIAL CLOSURE

Premix, Inc.

N. Kingsville, Ohio 44068

February 26, 1987

### Index

Page	
1	Description of Facility (OAC 3745-66-12)
2	Description of Waste Management Unit to be Closed
3	Map of Facility
4	Detailed Drawing of Unit to be Closed
5	List of Hazardous Waste (OAC 3745-66-12)
6	Schedule of Closure (OAC 3745-66-13) (A)
7	Air Emissions (OAC 3745-66-11)
8	Personnel Safety and Fire Prevention (OAC 3745-66-11)
9	Decontamination Efforts (OAC 3745-66-14)
10	"Clean" Levels for Soil (OAC 3745-66-11)

### DESCRIPTION OF FACILITY (40 CFR 265.112 and OAC 3745-66-12)


Request for: Partial Closure for Purposes of Drum Storage Upgrade Plan

- Premix, Inc.
  Route 20 and Harmon Road
  North Kingsville, Ohio 44068
- SIC 30-79: Manufacturer of reinforced thermoset molding compounds
- Products manufactured: molding compounds and custom molded fiberglass parts.
- Employees: 500 persons

#### DESCRIPTION OF WASTE MANAGEMENT UNIT TO BE CLOSED

#### Partial Closure of S01 Storage Consisting of:

- 1. Waste Resin Solution, D001 (Not Listed on Part A Permit)
- 2. Waste Combustible Liquid, F002, F003, F005 (Line 1, Part A)
- 3. Waste Paint Related Materials, D001 (Line 3, Part A)
- Period of Use: November 8, 1980 to July, 1982
- Dimension of Area: 15' wide x 30' long
- Soil: Analysis Performed 3-21-79 Found 0.0.7' crushed limestone; 0.7' to 14' brown coarse to fine sand, some gravel. Trace silt, loose, moist. Sample performed by Herron Testing Lab, using a Model B-61 rotary mobile drill rig. Hollow tube flight augers 7.0" O.D. x 2.75 I.D., ASTM D-1586-67.



## LIST OF HAZARDOUS WASTE (40 CFR 265.112 and OAC 3745-66-22)


#### SO1 Storage:

- 1. Waste Resin Solution
  Flammable Liquid UN1866, D001
  20 40 drums
- Waste Combustible Liquid Nos.
   Combustible Liquid, NA 1993
   F002, F003, F005
   80 100 drums
- 3. Waste Paint Related Materials Flammable Liquid UN1263, D001 10 - 20 drums

#### SCHEDULE OF CLOSURE (40 CFR 265.113 [1] and OAC 3745-66-13 [A])

Waste has not been stored at Partial Closure Site since July 1982. Waste is currently stored at location noted on map.

Sample analysis will be performed in the following manner:



1 sample for every 75 square ft.

Two samples will also be performed at a predetermined clean site to determine how clean is clean regarding partial storage closure sample.

(40 CFR 265.113 [2] and OAC 3745-66-13[B])

#### Closure Timetable:

- 1. Waste Removal: Completed July 1982
- 2. Sampling: Will be done within 30 days of Directors approval of Partial Closure Plan.
- 3. Soil Removal: Will be done within 30 days of receiving sample results.
- 4. Independent Engineer Present: Within 30 days of soil removal.
- 5. Backfilling, if needed: Within 30 days of Independent's Engineer's Certification.

# AIR EMISSIONS (40 CFG 265.111 and OAC 3745-66-11)

Not applicable.

#### PERSONNEL SAFETY AND FIRE PREVENTION

(40 CRF 265.111 and OAC 3745-66-11)

The procedure of sampling, soil removal, or backfilling will not present any fire hazard for residents, employees or contractors. Once sampling results have been achieved, a decision will be made on any protective clothing or respiratory protection that will be needed. No employee or contractor will work at the site unless trained on the hazardous constituents that are involved.

No resident will be allowed on the premises.

If Personnel decontamination needs to be done according to sample results or due to personnel being contaminated during working at the site, total decontamination will be done:

- 1. Remove all clothing.
- 2. Use emergency shower.
- 3. Do not reuse clothing until it has been washed.

#### **DECONTAMINATION EFFORTS**

(40 CFR 265.114 and OAC 3745-66-14)

There is not any contamination that could be present that affects anything else but the soil. No tanks, paved areas, concrete, pipes, pumps, or sumps or any other appurtenances at the waste management unit. See Page 10.

# "CLEAN" LEVELS FOR SOIL (40 CFR 265.111 and OAC 3745-66-11)

Alternative A will be used for soil analysis to determine "clean" levels. See page 6.

### Request For Closure

Of Hazardous Waste Storage Unit

40 CFR 265.112 (C) + OAC 3745-66-12 (C)

Premix, Inc.

North Kingsville, Ohio 44068

### Index

*	Description of Facility OAC 3745-66-12	Page 1
*	Description of Waste Unit to be Closed OAC 3745-66-12 (1) (2)	Page 2
*	Detailed Drawings of Unit to be Closed OAC 3745-66-12 (1)	Page 4
*	Description of Final Closure OAC 3745-66-12 (A) (B) OAC 3745-66-12 (1)	Page 5
*	Schedule of Closure OAC-66-13 (A)	Page 6
*	Decontamination/Disposal OAC-3745-66-14	Page 7
*	Certification of Closure OAC-3745-66-15	Page 8
*	Map of Facility (attachment)	

# Description of Facility (40 CFR 265.112 and OAC 3745-66-12)

Request For:

Total Closure Of Hazardous Waste Storage Unit

Premix, Inc.

Route 20 & Harmon Road

North Kingsville, Ohio 44068 EPA ID Number: OHD004200044

Sic 30-79:

Manufacturer of reinforced Thermoset Molding Compounds

and custom molded parts

Employees:

500 persons

Area:

Latitude

Residential/Farm 42° 00<sup>l</sup> Longitude 80° 00l

### Description of Waste Unit to be Closed 40 CFR 265.112 (3) and OAC-3745-66-12 (1) (2)

The waste storage area is a concrete pad, consisting of approximately 910 square feet and partially diked. S01 storage is limited to two hundred and ten barrels, under Permit Number 02-04-0567.

In reference to Permit Application Part A, Form 3 RCRA, the following wastes were originally listed.

Line 1. F002, F003, F005 Solvent Blend, SP-21 (methylene chloride, toluene, acetone)

Line 3. D001, paint residues

Waste not listed on Part A Permit:

- A. Waste Resin Solution, D001
- B. Waste Pyridine, U196
- C. Waste Acetone, U002
- D. Waste Alcohol, D001
- E. Waste 731 (D001)
- F. Waste Solvent (replaces SP-21) Effective March 1987 F002, F003, F005, 1-1-1 Trichloroethane, Acetone, Toluol, Trichlorotrifluoroethane.
- \* This storage area originated in August of 1982 and has been continually in use to date.

Estimated maximum inventory of hazardous waste ever on site over the active life of storage unit was one hundred and sixty, S01 containers.

Methods to be used prior to and including closure:

Disposal dates will be arranged prior to closure with licensed TSDF's for removal of hazardous waste. Removal of waste from storage unit to shipping prior to transportation will be done by a persons trained in hazardous waste operations.

Transportation of hazardous wastes will be done by the specific disposal facility approved for incineration/reclamation/land disposal of hazardous waste.

The following waste streams will be disposed of by Ross Incineration, 394 Giles Rd., Grafton, OH.

- 1. Waste Pyridine (U196)
- 2. Waste Solvent Solids (F002, F003, F005)
- 3. Waste Paint (D001)


Chemical Solvents, Inc., 3751 Jennings Rd., Cleveland, OH will remove and dispose of:

- 1. Waste Solvent Liquid (F002, F003, F005)
- 2. Waste Acetone (U002)
- 3. Waste Solvent (D001)
- 4. Waste Solvent SP-731 Solids, (D001)

Northeast Chemical, 3301 Monroe Ave., Cleveland, OH will remove and dispose of the remaining waste stream.

1. Waste Resin (D001)

PREMIX, INC. North Kingsville OH.



EE ← Concrete Areas

#### Description of Final Closure 40 CFR 265.112 (2), 40 CFR 265.111 (a) (b) (c) OAC 3745-66-11 (A) (B), OAC 3745-66-12 (1)

- 1. The facility will be closed in a manner that minimizes the need for further maintenance, controls, and eliminates to the maximum extent necessary to protect human health and the environment.
- 2. The closure will be conducted by trained professionals. Scrapping and sampling of storage area will be performed.
- Clean levels for soil are not applicable as storage area is concreted and diked.
- 4. Contamination of water and soil will be prevented by staying in the concreted area that is to be closed.
- 5. Air emissions will be monitored, by trained individuals, during the course of the closure if any hazardous chemicals or hazardous substances are used for waste removal off the concreted area.
- 6. The procedure of sampling, soil removal, backfilling will not present any fire hazard for residents, employees or contractors. Once sampling results have been achieved, a decision will be made on any protective clothing or respiratory protection that will be needed. No employee or contractor will work at the site unless trained on the hazardous constituents that are involved.

No resident will be allowed on the premises.

If Personnel decontamination needs to be done according to sample results or due to personnel being contaminated during working at the site, total decontamination will be done:

- 1. Remove all clothing.
- 2. Use emergency shower.
- 3. Do not reuse clothing until it has been washed.
- 7. Facility will remain "active" during the closure operation. Waste being accumulated during this time will be transported prior to storage.

After closure is completed, and certified according to all applicable regulations, the storage unit will be utilized as a less than ninety day accumulation area.

#### Schedule of Closure OAC 3745-66-13 (A and B) and 40 CFR 265.113 (a thru b)

Within ninety day after receiving approval of the approved closure plan, all waste will be removed from the closure unit and disposed of off-site at licensed TSDF's, in accordance with the approved closure plan.

Within one hundred and eighty days of waste removal disposal, final closure activities will be completed in accordance with the approved closure plan.

## Disposal/Decontamination (40 CFR 265.114 and OAC 3745-66-14)

- 1. During final closure period, all contaminated equipment or structures will be properly decontaminated or disposed of.
- 2. Any equipment used to collect samples and to remove contaminants shall be adequately decontaminated following use, by washing with an appropriate cleaner and thru triple rinsing.
- 3. Any waste generated by decontamination will be analyzed and then incinerated at a licensed TSDF.

#### Certification of Closure (OAC 3745-66-15)

Within sixty days of completion of closure, a certification of closure will be submitted, by registered mail to the Regional Administrator.

The certification will be signed by the owner/operator and by the Independent registered professional engineer, who documented the closure.

dgl 12/14/87

SOIL BORING OPERATIONS

AND LABORATORY TESTING OPERATIONS

WASTE STORAGE AREA

PREMIX, INC.

NORTH KINGSVILLE, OHIO



Professional Service Industries, Inc. Pittsburgh Testing Lab./Herron Consultants Div.



# Professional Service Industries, Inc. Pittsburgh Testing/Herron Consultants Division

February 8, 1988

Premix, Inc.

P. O. Box 281

North Kingsville, Ohio 44068

Attention: Ms. Debra Parshall-Hall

Re: Soil Boring Operations and Laboratory Testing Operations Waste Storage Area North Kingsville, Ohio PSI File Number: 142-75175

Dear Ms. Hall:

This report summarizes the performance and results of soil boring operations and laboratory testing operations conducted at Premix, Inc.'s existing facilities located at Route 20 and Harmon Road in North Kingsville, Ohio. The investigation was verbally authorized by Ms. Debra Parshall-Hall and confirmed per Premix, Inc.'s P. O. #80367.

Per the request of Ms. Debra Parshall-Hall, a series of six (6) test borings was conducted within a former waste storage area at the Premix facilities on December 18, 1987. The test boring locations were selected and field located by Premix, Inc. A boring location plan is currently unavailable.

All test borings were carried to depths ranging between about three
(3) and 4.5 feet below the existing site grades by means of rotary drive

drilling procedures employing hollow stem continuous flight augers.

To avoid cross contamination, all auger and sampling equipment was steam cleaned prior to the initiation of the drilling operations and washed with detergent solution (Alconox) and clean water rinse between the individual test locations.

During the drilling operations, variations of the site's subsurface materials and groundwater conditions were recorded and continuous samples of the existing materials taken at regular intervals by means of a two (2)-inch o.d. split-spoon sampling device, driven by a 140 pound hammer, free falling through a distance of thirty (30) inches. During the course of sampling operations, the number of hammer blows required to achieve eighteen (18) inches of sample spoon penetration, was noted and recorded for each six-inch increment. These blow counts are shown on the accompanying Test Boring Logs.

No groundwater seepage was evidenced during or at the completion of the drilling operations. It should be recognized that the permeability of soils, seasonal variations, temperature and recent rainfall conditions may influence water levels at other times.

Sample materials obtained as a result of field sampling operations were visually classified and placed in properly-identified sealed glass sample jars. Subsequently, all samples were transported to PSI's Cleveland soil mechanics laboratory for analysis.

In the laboratory, all samples of materials derived from the drilling operations were classified in substantial accordance with the requirements of the American Society for Testing and Materials' standard method designation D-2488, "Description of Soils (Visual-Manual Procedure)" and identified employing the terminology and group symbols of the Unified

Soil Classification System (ASTM D-2487). The results of visual-manual classification operations, together with data developed during the field drilling operations, are included on the accompanying Test Boring Logs. The stratification lines noted on the boring logs represent approximate boundaries between the soil types, and the transitions may be gradual or abrupt.

In addition to classifying the materials, a composite soil sample from each test boring location was sent to Aqua Tech Environment Consultants, and analyzed for the presence of Methylene Chloride, Acetone, Toluene, Pyridine, Methanol, Chloroform and Styrene using method 8240 of EPA publication SW-846. These test results are included in the accompanying table.

This report is submitted as confidential property of our client. Any information pertaining to the report would only be released with the client's written approval.

We wish to thank you for the opportunity of working with you on this project and look forward to continued association in the future.

Should you have any questions, please feel free to contact us.

Very truly yours,

PROFESSIONAL SERVICE INDUSTRIES, INC.

Lynton L. Price, P.E. Project Engineer

Vijay K. Khosla, Ph.D., P.E.

Division Manager

LLP/md

2cc: Premix, Inc.

Professional Service I. stries APPENDIX

#### LABORATORY TEST RESULTS

	B-1 Composite 0.0-4.5	B-2 Composite 0.0-3.0	B-3 Composite 0.0-3.0	B-4 Composite 0.0-3.0	B-5 Composite 0.0-3.0	B-6 Composite 0.0-3.0
Chloroform	<18.0	<18.0	<16.5	<15.6	<12.0	<16.8
Methylene Chloride	<30.0	<30.0	<27.5	<26.0	<20.0	<28.0
Toluene	<18.0	<18.0	<16.5	<15.6	<12.0	<16.8
Acetone	<30.0	<30.0	<27.5	<26.0	<20.0	<28.0
Pyridine	<60.0	<60.0	<55.0	<52.0	< 40.0	<56.0
Styrene	<18.0	<18.0	<16.5	<15.6	<12.0	<16.8
Methanol	<10.0	<10.0	<10.0	<10.0	<10.0	<10.0

All results with the exception of Methanol are expressed as ug/kg (PPB) dry weight Methanol is expressed as mg/kg (PPM) dry weight

## RECORD OF SUBSURFACE EXPLORATION

Boring B-1

roject Name: Premix, Inc.							r 18,1987
te:Waste Storage Area, North Kingsvi	11e,	Ohio	P	roject N	o.:	142-751	75
DESCRIPTION	DEPTH	SAMPLE	Blow Count		α <sub>p</sub>	Mc	REMARKS
Brown Silty Sand, Trace Gravel, Moist, Dense. (SM) Brown Silty Sand, Trace Gravel, Clay Moist, Med. Dense. (SM)  End of Boring - 4.5'		1SS 2SS 3SS	Count 15- 14-10 4-5-6 1-4-4		5 P		

### RECORD OF SUBSURFACE EXPLORATION

Boring B-2

Project Name: Premix, Inc.			Da	ate of B	oring: _	Decembe	r 18, 1987
Site: Waste Storage Area, North Kingsv	ille,	Ohio_	P	roject N	o.:	142-751	.75
			Blow Count			Mc	REMARKS
DESCRIPTION	DEPTH	SAMPLE	Count	Qu	Ωp	Ι"ε	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Brn. Silty Sand, Some Gravel, Moist,	l	100	4-5-		- · ·		<del>-</del>
Med. Dense. (SM)	_	1SS	10			1 . [	_
*	] -	<u> 255</u>	4-5-7			1	-
End of Boring - 3.0'	] -	-	] ]				-
1	5 ■						Till Control of the C
*Brn. Silty Sand, Some Gravel, Clay,	-	1		· ·	ļ	1 1	
Moist, Med. Dense. (SM)	-	1					_
}-	1 :	]					-
	<b>\</b> ,						
	] .	]				1	
		4	ζ.			,	-
		┪					- -
<u>'</u>		1				1 1	
 		<b>F</b>					- -
<b>-</b>	]	]		1			
<u> </u>							
		4	1				-
							i
	1	4	1.		1		•
	1	7	i i				
		_					
•			**				
		]					
<b>-</b>		_ `		İ			i.
		4		1		'	
_		-	1		1		
23		·					
<b>-</b>		4		1			
<b>+</b>		]			-	Ì	
<b>†</b>		4					
		4			1	1	
		1			1.		
<b>-</b>		]					
<b>+</b>							
<b>E</b>		]				. [	
<b>†</b>		4				Ì	
				[			
		4		1			
	ĺ				1		
	ı	-	1		- [	i	<u> </u>

#### RECORD OF SUBSURFACE EXPLORATION

Boring	B-3

		D	ate of B	oring: _	Decemb	er 18, 1987
ille,	Ohio_	P	roject N	o.:	142-75	175
DEPTH	SAMPLE	Blow Count	۵ <sub>u</sub>	Ω <sub>p</sub>	М <sub>с</sub>	REMARKS
, -	1SS 2SS			3		
-						
_		. 1				
		·		,	•	
-						
-			·			
-					,	·
-		:				
-						
				·		
<u> </u>			•			
-				:		
- -	<u> </u> 					
		:				
-	]		٠			
-						
-						
	DEPTH	DEPTH SAMPLE  - 1SS - 2SS -	DEPTH   SAMPLE   Blow   Count	Ille, Ohio Project N  DEPTH SAMPLE Blow Count Qu  - 1SS 4-8-8  - 2SS 6-4-3	DEPTH SAMPLE Blow Count Qu Qp  - 1SS 4-8-8 - 2SS 6-4-3	- 1SS 4-8-8 - 2SS 6-4-3

#### RECORD OF SUBSURFACE EXPLORATION

Boring	B-4

Project Name: Premix, Inc.			D	ate of B	oring: _	Decem	her 18, 1987
Site: Waste Storage Area, North Kings	ville,	Ohio	P	roject N	o.:	142-7	5175
DESCRIPTION	DEPTH	SAMPLE	Blow Count	, Qu	Οp	Мc	REMARKS
	T						

## RECORD OF SUBSURFACE EXPLORATION

Boring B-5

\_\_ Date of Boring: December 18, 1987

SURFACE Town Silty Sand, Some Clay, Trace Travel, Moist, Dense. (SM)  End of Boring - 3.0'  5	Waste Storage Area, North Kingsv	DEPTH	SAMPLE	Blow Count	O <sub>u</sub>	O <sub>p</sub>	₩c	REMARKS
End of Boring - 3.0'  5	OWN Silty Sand, Some Clay, Trace avel, Moist, Dense. (SM)	-	1SS 2SS	1 1				
		5 1	Z 5 5					

Project Name: Premix, Inc.

## RECORD OF SUBSURFACE EXPLORATION

Boring B-6

#### **GENERAL NOTES**

#### SAMPLE IDENTIFICATION

The Unified Soil Classification System is used to identify the soil unless otherwise noted.

#### SOIL PROPERTY SYMBOLS

N: Standard "N" penetration: Blows per foot of a 140 pound hammer falling

30 inches on a 2 inch O.D. split-spoon.

Qu: Unconfined compressive strength, TSF

Op: Penetrometer value, unconfined compressive strength, TSF

Mc: Water content, %

LL: Liquid limit, %

PI: Plasticity Index, %

δ d: Natural dry density, PCF

: Apparent groundwater level at time noted after completion.

#### DRILLING AND SAMPLING SYMBOLS

SS: Split-Spoon - 1 3/8" I.D., 2" O.D., except where noted.

ST: Shelby Tube - 3" O.D., except where noted.

AU: Auger Sample.
DB: Diamond Bit.
CB: Carbide Bit.

WS: Washed Sample.

#### RELATIVE DENSITY AND CONSISTENCY CLASSIFICATION

TERM (NON-COHESIVE SOILS)	STANDARD PENETRATION RESISTANCE					
Very Loose	0 - 2					
Loose	2 - 4					
Slightly Compact	4 - 8					
Medium Dense	8 • 16					
Dense	16 - 26					
Very Dense	Over 26					
TERM (COHESIVE SOILS)	Qu · (TSF)					
Very Soft	0-0.25					

Very Soft	0 - 0.25
Soft	0.25 - 0.50
Firm (Medium)	0.50 - 1.00
Stiff	1.00 - 2.00
Very Stiff	2.00 - 4.00
Hard	4.00+


#### **PARTICLE SIZE**

Boulders	8 in. +	Coarse Sand	5mm-0.6mm	Silt	0.074mm-0.005mm
Cobbles	8 in3 in.	Medium Sand	0.6mm-0.2mm	Clay	-0.005mm
Gravel	3 in5mm	Fine Sand	0.2mm-0.074mm	•	

#### FREE-COL LABORATORIES

RICHARD WOHLER Ph. D. LABORATORY DIRECTOR

DIVISION OF FREEPORT BRICK COMPANY P.O. BOX 557, COTTON ROAD MEADVILLE, PENNSYLVANIA 16335 PHONE: (814) 724-6242



DATE SAMPLE(S) RECEIVED 7/18/85/054

P.O.#: 68310

TO: Premix Incorporated

Box 281

North Kingsville, OH

44068

Debbi Hall ATTN:

#### ANALYTICAL REPORT FORM

Parameter

Sample.

Flammability

See Note Below

The sample would not ignite in 5 seconds or less; therefore Note:

it is not considered flammable.

Parameter

Leachate

Styrene Monomer mg/L

0.628

"The Leachate was prepared in accordance with the E.P. Toxicity Test Methods described in the May 19, 1980 Federal Register."

8/6/85

/mh

A I.H.A Accreditation No. 98 W/CLIA Lic. No. 37-1129

WV E.P.A. Certification No. 21-R OH E.P.A. Approval No. 01060 & 970 ADMINISTRATIVE ASSISTANT

PA. Department of Health Clinical Laboratory Permit No. 561

E.P.A. Facility No. 38-073

KEY:

= LESS THAN


= GREATER THAN

w.f. = WILL FOLLOW

#### FREE-COL LABORATORIES, INC.

HARD WOHLER, Ph.D.

P.O. BOX 557, COTTON ROAD MEADVILLE, PENNSYLVANIA 16335 PHONE: (814) 724-6242 FAX: (814) 333-1466



07/31/89

TO:

PREMIX INCORPORATED

ATTN: HR-MARK-MITCHAN Brade Rivel

P.O. #M89320

P.O. BOX 281

NORTH KINGSVILLE

OH 44068-0281

ACCOUNT NO. 00354

#### ANALYTICAL REPORT FORM

	. 40. 540 550 650 777 7	SAMPLE ID :	1	2	3	4
PARAMETER	}	LAB ID DATE RECEIVED:	90728052 07/28/89	90728053 07/28/89	9072805 <b>4</b> 07/28/89	90728055
STYRENE	MG/L		<0.002	<0.002	<0.002	<0.002
OLATILE	SET-UP		X	x	x	X

.A. Accreditation No. 98 WCLIA Lic. No. 37-1129 U.S. Public Health Services Approved Facility PA D.E.R. Laboratory I.D. No. 20-073 PA Dept. of Health Cert. No. 000021 PA Dept. of Agriculture Approved Dairy Laboratory

NY Dept. of Health Laboratory I.D. No. 10552 NY Dept. of Env. Conservation Approved Facility MD Dept. of Health Cert. No. 130 VA Dept. of Health Laboratory I.D. No. 00145 WV Dept, of Health Certification No. 21-R NJ Dept. of Env. Protection Lab I.D. No. 77613

NC Dept. of Natural Resources Cert. No. 236 SC Dept. of Health Laboratory I.D. No. 89004 GA Dept. of Natural Resources Cert. No. 821 MI Dept. of Public Health Approved Facility U.S. Office of Surface Mining Approved Facility

#### FREE-COL LABORATORIES, INC.

P.O. BOX 557, COTTON ROAD **MEADVILLE, PENNSYLVANIA 16335** PHONE: (814) 724-6242 FAX: (814) 333-1466



07/31/89

TO:

HARD WOHLER, Ph.D.

PREMIX INCORPORATED

P.O. # 89327

ATTN: MR-MARK-MITCHAM Brende River

P.O. BOX 281

NORTH KINGSVILLE

OH 44068-0281

ACCOUNT NO.M 00354

ANALYTICAL REPORT FORM

SAMPLE ID

BLANK

LAB ID

90728056

PARAMETER

DATE RECEIVED:

07/28/89

STYRENE MG/L 0.031

OLATILE SET-UP

X

'.A. Accreditation No. 98 #CLIA Lic. No. 37-1129 U.S. Public Health Services Approved Facility PA D.E.R. Laboratory I.D. No. 20-073 PA Dept. of Health Cert. No. 000021 PA Dept. of Agriculture Approved Dairy Laboratory

NY Dept. of Health Laboratory I.D. No. 10552 NY Dept. of Env. Conservation Approved Facility MD Dept. of Health Cert. No. 130 VA Dept. of Health Laboratory I.D. No. 00145 WV Dept. of Health Certification No. 21-R NJ Dept. of Env. Protection Lab I.D. No. 77613

NC Dept. of Natural Resources Cert. No. 236 SC Dept. of Health Laboratory I.D. No. 89004 GA Dept. of Natural Resources Cert. No. 821 MI Dept. of Public Health Approved Facility U.S. Office of Surface Mining Approved Facility

JULY 1, 1983

/meriTrust

#### IMPORT DOCUMENTARY SERVICES

YO	IIR	REF. DATED	OUR REF DATED
			SB 21401 JULY 1, 1983
NAM	Œ:		BENEFICIARY:
			ENVIRONMENTAL PROTECTION AGENCY
			REGION V, 230 DEARBORN STREET
A3//C	ATTRIO	r.	CHICAGO, ILLINOIS 60604 ATTN: CHARLES B. SLARSTASA APPLICANT:
AMO	JUIN.	ı:	PREMIX. INC. Off Oryzonyy
		\$12,000.00	PREMIX, INC.
			FOLLOWING CLAUSES MARKED BELOW**
( X	19	terms, you should contact the request that amended instructi	nal Letter of Credit. Please examine the vent that you are unable to comply with its Applicant (stated above) directly and lons be issued.
(	)	Enclosed please find Amendment of the above referenced Letter	NO. which forms an integral part of Credit.
(	)	directly to the Beneficiary (s	f the Letter of Credit referenced above to be original Letter of Credit has been forwarded stated above).
(	)	this copy for your fifes.	f Amendment NO Kindly retain
(	)	Amendment NO. has lenclosed is a copy to be retained.	been forwarded directly to the Beneficiary. ined for your files.
(	)	Copy of telex opening enclosed	d. Kindly retain for your files.
(	)	its entirety. Kindly advise	nat the above referenced Credit be cancelled in us the Beneficiary's consent to cancellation.
(	)	The Applicant has requested the entirety. Kindly confirm you original Letter of Credit direarliest.	he above referenced Credit be cancelled in its r consent to cancellation and return the ect to our International Department at the
(	)	Please note of the Beneficiary. Kindly r charge.	emit charges are for the account representing our
(	)	Other:	
		· ·	
			The state of the s
		9	Elle Mily and

SIGNATURE

# HAZARDOUS WASTE FACILITY CERTIFICATE OF POLLUTION LIABILITY INSURANCE

<ol> <li>Liberty Mutual Insurar hereby certifies that it has</li> </ol>	ice Company (the "Insurer" issued pollution liability in	"), of 175 Berkeley S nsurance covering bo	treet, Boston, Mass dily injury and pro -	achusetts 02117, perty damage to:
(Name of Insured) P	remix Inc.			_(the ''insured''),
(Address) P.O. Box	281, North Kingsvil	1e, OH 44068		
in connection with the ins 265.147. The coverage ap		nstrate financial resp	onsibility under 40	CFR 264.147 or
(Name and Address of	Each Facility)		(EPA Ident	ification Number)
Premix Inc. Harman Rd. Rt. 20 North Kingsville, OH	44068		ОНО00420	00044
		·		
for ⊠ sudden acciden □ sudden and nor	tal occurrences, sudden accidental occurre	ences.		
The limits of liability are:	\$ 2,000,000	annual aggregate		
	\$ <u>1,000,000</u>	_each occurrence		
	exclusive of legal defense	costs.		
The coverage is provide  The effective date of said p	issued on (date) ate of said policy is (date)	LG1-181-026682- 10-1-82 10-1-82 6-20-83	052	,
2. The Insurer further co	ertifies the following with re	espect to the insurar	nce described in Pa	ragraph 1:

GPO 2991 R1 Page 1 of 2

(a) Bankruptcy or insolvency of the insured shall not relieve the Insurer of its obligations under the policy.

- (b) The Insurer is liable for the payment of amounts within any deductible applicable to the policy, with a right of reimbursement by the insured for any such payment made by the Insurer. This provision does not apply with respect to that amount of any deductible for which coverage is demonstrated as specified in 40 CFR 264.147(f) or 265.147(f).
- (c) Whenever requested by a Regional Administrator of the U.S. Environmental Protection Agency (EPA), the Insurer agrees to furnish to the Regional Administrator a signed duplicate original of the policy and all endorsements.
- (d) Cancellation of the insurance, whether by the Insurer or the insured, will be effective only upon written notice and only after the expiration of sixty (60) days after a copy of such written notice is received by the Regional Administrator(s) of the EPA Region(s) in which the facility(ies) is (are) located.
- (e) Any other termination of the insurance will be effective only upon written notice and only after the expiration of thirty (30) days after a copy of such written notice is received by the Regional Administrator(s) of the EPA Region(s) in which the Facility(ies) is (are) located.

I hereby certify that the wording of this instrument is identical to the wording specified in 40 CFR 264.151(j) as such regulation was constituted on the date first above written, and that the Insurer is licensed to transact the business of insurance, or eligible to provide insurance as an excess or surplus lines insurer, in one or more States

F. R. Wilson			
(Signature of authorized representative of Insurer)			
F.R. Wilson, Business Policy Production Manager			
(Type Name and Title) Authorized Representative of (Liberty Mutua	al Insurance Co	0.)	
2501 Wilmington Rd., New Castle PA 16105			
(Address of Representative)	,		

GPO 2991 R1 Page 2 of 2

AmeriTrust Company P.O. Box 5937 Cleveland, Ohio 44101 (216) 687-5687

International Division Cable Address 'AmeriTrust''

JULY 1, 1983

THIS CREDIT IS FORWAR	DED TO THE ADD	COTRO DANK RV	ATRMATT.		
THIS CREDIT IS FORWARD THIS CREDIT IS CONFIDENTED					
ADVISING BANK:	14		APPLICANT:	PREMIX, INC.	
				P.O. BOX 281 MORTH KINGSVIL	LE, OHIO 44068
				ATTN: L.E. PER	KEY
BENEFICIARY: ENVIRON				2,000.00 (TWELVE	
	, 230 DEARBORN ILLINOIS 6060		DO	LLARS AND NO/100	1
ATTN: C	HARLES B. SLARS	TASA			
IEGHNICHL FEM	ilib a continuan	CAS STATE A CONTRACTOR	EXPIRY DA	TE: SEE BELOW**	
AR SIRS:					

WE HEREBY ISSUE THIS IRREVOCABLE DOCUMENTARY LETTER OF CREDIT NO. SB 21401 AVAILABLE BY BENEFICIARY'S DRAFT(S) AT SIGHT DRAWN ON THE AMERITRUST COMPANY

ACCOMPANIED BY THE FOLLOWING DOCUMENTS:

SIGNED STATEMENT READING AS FOLLOWS: "I CERTIFY THAT THE AMOUNT OF THE DRAFT IS PAYABLE PURSUANT TO REGULATIONS ISSUED UNDER AUTHORITY OF THE RESOURCE CONSERVATION AND RECOVERY ACT OF 1976 AS AMENDED."

DRAFTS MUST DRAWN AND PRESENTED AT THIS OFFICE ON OR BEFORE JUNE 30, 1984.\*\*

SPECIAL CONDITIONS: THIS LETTER OF CREDIT IS EFFECTIVE AS OF JUNE 27, 1983 AND SHALL EXPIRE JUNE 30, 1984, BUT SUCH EXPIRATION DATE SHALL BE AUTOMATICALLY EXTENDED FOR A PERIOD OF (AT LEAST 1 YEAR) ON (DATE) AND ON EACH SUCCESSIVE EXPIRATION DATE, UNLESS, AT LEAST 120 DAYS BEFORE THE CURRENT EXPIRATION DATE, WE NOTIFY BOTH YOU AND PREMIX, INC. BY CERTIFIED MAIL THAT WE HAVE DECIDED NOT TO EXTEND THIS LETTER OF CREDIT BEYOND THE CURRENT EXPIRATION DATE. IN THE EVENT YOU ARE SO NOTIFIED, ANY UNUSED PORTION OF THE CREDIT SHALL BE AVAILABLE UPON PRESENTATION OF YOUR SIGHT DRAFT FOR 120 DAYS AFTER THE DATE OF RECEIPT BY BOTH YOU AND PREMIK, INC., AS SHOWN ON THE SIGNED RETURN RECEIPTS.

WHENEVER THIS LETTER OF CREDIT IS DRAWN ON UNDER AND IN COMPLIANCE WITH THE TERMS OF THIS CREDIT, WE SHALL DULY HONOR SUCH DRAFT UPON PRESENTATION TO US, AND WE SHALL DEPOSIT THE AMOUNT OF THE DRAFT DIRECTLY INTO THE STANDBY TRUST FUND OF PREMIX, INC. IN ACCORDANCE WITH YOUR INSTRUCTIONS.

WE CERTIFY THAT THE WORDING OF THIS LETTER OF CREDIT IS IDENTICALL TO THE WORDING SPECIFIED IN 9 CFR 264.151 (d) AS SUCH REGULATIONS WERE CONSTITUTED ON AUGUST 27, 1982.

AUTHORIZED SIGNATURE

AmeriTrust Company P.O. Box 5937 Cleveland, Ohio 44101 (216) 687-5687 International Division
Cable Address
"AmeriTrust"

PAGE TWO

/mer/Trust

THIS IS AN ATTACHMENT TO LETTER OF CREDIT NO. SB 21401 AND FORMS AND INTEGRAL PART THERETO.

L/C#: SB 21401

F/O : ENVIRONMENTAL PROTECTION AGENCY

A/C : PREMIX, INC. AMT : \$12,000.00 EXP : JUNE 30, 1984

EACH DRAFT ACCOMPANYING DOCUMENTS MUST STATE DRAWN UNDER CREDIT NO. SB 21401 OF THE AMERITRUST COMPANY DATED JULY 1, 1983.

SPECIAL CONDITIONS: FORWARD ALL DOCUMENTS TO US IN ONE AIRMAILING.

ORIGINAL LETTER OF CREDIT MUST ACCOMPANY REQUIRED DOCUMENTS. NEGOTIATIONS ARE RESTRICTED TO THE POUNTERS OF THE AMERITRUST COMPANY CLEVELAND, OHIO.

WE HEREBY AGREE WITH THE DRAWERS, ENDORSERS AND BONA FIDE HOLDERS OF DRAFTS DRAWN AND NEGOTIATED UNDER AND IN COMPLIANCE WITH THE TERMS OF THIS CREDIT THAT THE SAME SHALL BE DULY HONORED ON DUE PRESENTATION TO THE DRAWEE.

EXCEPT AS OTHERWISE EXPRESSLY STATED, THIS CREDIT IS SUBJECT TO THE "UNIFORM CUSTOMS AND PRACTICE FOR DOCUMENTARY CREDITS" (1974 REVISION) INTERNATIONAL CHAMBER OF COMMERCE, PUBLICATION NO. 290.

KINDLY ACKNOWLEDGE RECEIPT

AUTHORIZED SIGNATURE

53105-S1/83

F310



P. O. BOX 281

## OHD 004200044

NORTH KINGSVILLE, OHIO 44068

PHONE (216) 224-2181

June 16, 1983

Environmental Protection Agency Technical, Permits, & Compliance Section 230 South Dearborn Street Chicago, Illinois 60604

Attn: Charles B. Slaustas

Subject: Your letter of 6 June 83 (copy enclosed)

Dear Mr. Slaustas:

In your letter you requested that I forward to you "either demonstrations of financial responsibility, or an estimated date when these demonstrations will be forwarded".

I have requested that our insurance carrier prepare and forward directly to you an appropriate Financial Guarantee Bond and a Certificate of Liability Insurance. I anticipate that these documents will be delivered to you on or before June 30, 1983.

Very truly yours,

PREMIX, INC.

L. E. Perkey

Controller

/slm

JUN 2 3 1983

WASTE MANAGEMENT BRANCH

# ONITED STATES

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

#### REGION V 230 SOUTH DEARBORN ST CHICAGO, ILLINOIS 60604

REPLY TO ATTENTION OF:

16 JUN 1983

5HW-13

Mr. Lowell Perkey Premix Inc. P.O. Box 281 North Kingsville, Ohio 44068

RE: Financial Responsibility

Requirements

EPA ID No.: OHD 004 200 044

Dear Mr. Perkey:

In response to our telephone conversation on June 2, 1983, enclosed is a copy of a summary of Federal <u>financial requirements</u> for owners and operators of hazardous waste treatment, storage and disposal facilities. In addition, I am enclosing extracts of the applicable parts of Federal regulations pertaining to <u>liability coverage requirements</u>.

After reviewing these documents, please forward either demonstrations of financial responsibility, or an estimated date when these demonstrations will be forwarded, to this office.

Respectfully,

Charles B. Slaustas

Charles B. Slaws Fas

Technical, Permits, and Compliance Section

5 日 13

Mr. Lowell Perkey Premix Inc. P.O. Box 281 North Kingsville, Ohio 44068

> RE: Financial Responsibility Requirements EPA ID No.: OHD 004 200 044

Dear Mr. Perkey:

In response to our telephone conversation on June 2, 1983, enclosed is a copy of a summary of Federal Financial Requirements for owners and operators of hazardous waste treatment, storage and disposal facilities. In addition, I am enclosing extracts of the applicable parts of Federal regulations pertaining to liability coverage requirements

After reviewing these documents, please forward either demonstrations of financial responsibility, or an estimated date when these demonstrations will be forwarded, to this office.

Respectfully,

Charles B. Slaustas Technical, Permits, and Compliance Section

THEF STU #2 STU #3 TPS WINES WIND DATE 6/3/3 6/6/3

MAY 3 1 1983

CERCIFIED MAIL PETUDA BECRIPT REQUESTED

5HW-13

Ms. Debbi Hall Premix Inc. Harmon Road and Route 20 North Kingsville, Ohio 44058

> Ro: Promix Inc. EPA I.D. No. CED 004200044 Harmon Road and Route 20 North Kingsville, Ohio 44068

Dear Ms. Hall:

The above referenced facility is a hazardous waste treatment, storage, or disposal facility subject to the Resource Conservation and Recovery Act (MCRA) as amended. Pederal regulations (40 CFR Part 265 Subpart II) require that such a facility shall provide to the United States Environmental Protection Agency (U.S. EPA) proof of financial assurance for closure by July 6, 1982, and liability coverage by July 15, 1982, (40 CPR 265.143 and 265.147 respectively).

To date U.S. EPA has not received these proofs; consequently, the facility is in violation of requirements of 40 CFR Part 265 Subpart H. The Agency considers these financial responsibility proofs as significant requirements of the hazardous waste regulations. Pailure to provide these required proofs within 30 days of receipt of this notice may subject the facility to enforcement action. MCRA provides for civil penalties up to \$25,000 per violation. Please forward the financial responsibility proofs to:

> RCRA Activities Attn: Financial Roquirements P.O. BOX A3587 Chicago, Illinois 60690

If you have any questions or desire additional information, please contact Mr. Charles B. Slaustas of my staff, at (312) 353-2474.

Sincerely,

William Hiner, Chief Technical, Permits, and Compliance Section

cc: Deborah L. Tegtmeyer, OEPA



July 12, 1982

Regional Administrator U.S. Environmental Protection Agency Attn: RCRA Financial Requirements Box A 3587 Chicago, Illinois 60690 3587

Re: Premix, Inc.

North Kingsville, Ohio 44068

The above corporation has contacted our bank in reference to the financial requirements for EPA Hazardous Waste. The total funding required to enact the approved closing plan amounts to \$17,360.00

Our bank currently provides Premix, Inc. with a \$3,850,000 Line of Credit which is seldom totally utilized. With a net worth of approximently \$8,000,000 and the \$3,850,000 Line of Credit it would appear that Premix, Inc. could more than adequately cover the financial requirements of \$17,360.00 should the Hazardous Waste closing plan be instituted. Therefore, it would appear unnecessary for our customer to incur additional expense associated with a formal Letter of Credit.

If your office would like to discuss this any further, please feel free to contact me at your convenience.

Sincerely,

William F. Hodgkiss Jr.

Vice President

#### Schedule of Closure OAC 3745-66-13 (A and B) and 40 CFR 265.113 (a thru b)

Within ninety day after receiving approval of the approved closure plan, all waste will be removed from the closure unit and disposed of off-site at licensed TSDF's, in accordance with the approved closure plan.

Within one hundred and eighty days of waste removal disposal, final closure activities will be completed in accordance with the approved closure plan.

## Disposal/Decontamination (40 CFR 265.114 and OAC 3745-66-14)

- 1. During final closure period, all contaminated equipment or structures will be properly decontaminated or disposed of.
- 2. Any equipment used to collect samples and to remove contaminants shall be adequately decontaminated following use, by washing with an appropriate cleaner and thru triple rinsing.
- 3. Any waste generated by decontamination will be analyzed and then incinerated at a licensed TSDF.

## Certification of Closure (OAC 3745-66-15)

Within sixty days of completion of closure, a certification of closure will be submitted, by registered mail to the Regional Administrator.

The certification will be signed by the owner/operator and by the Independent registered professional engineer, who documented the closure.

dgl 12/14/87

5AHMH

CERTIFIED MAIL RETURN RECEIPT REQUESTED

Ms. Debra Hall Premix, Inc. P.O. Box 28 North Kingsville, Ohio 44004

Certificate of insurance

Facility EPA ID No. OHD004200044

Dear Ms. Hall:

The U.S. Environmental Protection Agency (USEPA) has postponed the effective date for submission of proof of financial responsibility from the scheduled July 13, 1981, until October 13, 1981. Enclosed is a copy of the notice announcing postponement which was published in the Federal Register on May 18, 1981 (46 FR 27119). To enable you to minimize costs in the period before October 13, 1981, we are returning your certificate of insurance. USEPA is also anticipating some changes this fall in the regulatory wording required in the various financial instruments. Therefore, you may wish to contact us for any relevant changes in the regulations later this year.

If you have any questions, please do not hesitate to contact Tom Golz of my staff at (312) 886-4023.

Sincerely,

Karl J. Klepitsch, Jr., Chief, Waste Management Branch

Enclosures: Liability insurance policies
May 18, 1981 Federal Register

5A&HWMB: A. KAWATACHI: B. THOMPSON: 8/6/81

C.2 Compliance
And Enforcement

#### **Northeast District Office**

E. Aurora Road sburg, Ohio 44087-1969 TELE (330) 425-9171 FAX (330) 487-0769

Bob Taft, Governor Christopher Jones, Director

July 8, 2004

RE: PREMIX, INC.

LARGE QUANTITY GENERATOR

OHD 004 200 044 ASHTABULA COUNTY

Bill Kennedy, CEO Premix, Inc. P.O. Box 281 North Kingsville, OH 44068

Dear Mr. Kennedy:

On June 10, 2004 Brenda Oswald of the US EPA and I conducted an inspection of Premix, Inc. located at Rt. 20 and Harmon Road in North Kingsville, Ohio. Ms. Oswald inspected to determine Premix's current state of compliance with the organic air emission standards contained in the Code of Federal Regulations, Title 40, Parts 264/265. She will provide a separate letter covering this.

The purpose of my inspection was to determine Premix's state of compliance with Ohio's hazardous waste, used oil, and universal waste laws as found in Chapter 3734 of the Ohio Revised Code and Chapter 3745 of the Ohio Administrative Code and to discuss pollution prevention options. We did not conduct a complete inspection covering all rules and reviewing all paperwork. This was because I had conducted such an inspection in September 2003 and the processes and waste management did not appear to have changed greatly. We did, however, review the waste generated and conduct a tour of the plant and some of the outside areas. Please see the enclosed process description/waste activities summary sheets.

No violations of Ohio's hazardous waste, used oil, or universal waste laws were found.

Ms. Coltman did mention that, at times, partially full drums of spent SP331 FV (generated in the laboratory) are shipped out in order to comply with the 90 day accumulation limit. We discussed that this waste may be able to be stored in the same drum as the spent SP173C in order to avoid this problem.

Also enclosed is a list of references regarding energy conservation.

Premix may be able to reduce its operating costs with waste minimization and energy conservation practices. The Ohio EPA offers Pollution Prevention Assessments to help you decide which practices would benefit your operations. Ms. Coltman and I are in the process of setting up such as assessment for your office operations. This will focus on such things as paper use reduction. If you would like to have an expanded or additional Pollution Prevention Assessment or would like more information regarding waste minimization, please contact me. The Office of Pollution Prevention web site at <a href="http://www.epa.state.oh.us/opp/oppmain.html">http://www.epa.state.oh.us/opp/oppmain.html</a> also has information regarding waste minimization.



July , 2004

RE: PREMIX, INC.

LARGE QUANTITY GENERATOR OHD 004 200 044 ASHTABULA COUNTY

Bill Kennedy, CEO Premix, Inc. P.O. Box 281 North Kingsville, OH 44068

Dear Mr. Kennedy:

On June 10, 2004 Brenda Oswald of the US EPA and I conducted an inspection of Premix, Inc. located at Rt. 20 and Harmon Road in North Kingsville, Ohio. Ms. Oswald inspected to determine Premix's current state of compliance with the organic air emission standards contained in the Code of Federal Regulations, Title 40, Parts 264/265. She will provide a separate letter covering this.

The purpose of my inspection was to determine Premix's state of compliance with Ohio's hazardous waste, used oil, and universal waste laws as found in Chapter 3734 of the Ohio Revised Code and Chapter 3745 of the Ohio Administrative Code and to discuss pollution prevention options. We did not conduct a complete inspection covering all rules and reviewing all paperwork. This was because I had conducted such an inspection in September 2003 and the processes and waste management did not appear to have changed greatly. We did, however, review the waste generated and conduct a tour of the plant and some of the outside areas. Please see the enclosed process description/waste activities summary sheets.

No violations of Ohio's hazardous waste, used oil, or universal waste laws were found.

Ms. Coltman did mention that, at times, partially full drums of spent SP331 FV (generated in the laboratory) are shipped out in order to comply with the 90 day accumulation limit. We discussed that this waste may be able to be stored in the same drum as the spent SP173C in order to avoid this problem.

Also enclosed is a list of references regarding energy conservation.

Premix may be able to reduce its operating costs with waste minimization and energy conservation practices. The Ohio EPA offers Pollution Prevention Assessments to help you decide which practices would benefit your operations. Ms. Coltman and I are in the process of setting up such as assessment for your office operations. This will focus on such things as paper use reduction. If you would like to have an expanded or additional Pollution Prevention Assessment or would like more information regarding waste minimization, please contact me. The Office of Pollution Prevention web site at <a href="http://www.epa.state.oh.us/opp/oppmain.html">http://www.epa.state.oh.us/opp/oppmain.html</a> also has information regarding waste minimization.

You can find copies of the laws and other information on the Ohio EPA web page at <a href="https://www.epa.state.oh.us">www.epa.state.oh.us</a>. If you have any questions, please contact me by phone at (330) 963-1217, or by email at robert.almquist@epa.state.oh.us.

Sincerely,

Premix, Rt. 20 and Harmon Road, North Kingsville, OH (OHD 004 200 044) 6-10-04
Brenda Oswald, US EPA
Robert Almquist, Ohio EPA (notes of)

We met with Kenna Coltman, Ken Lazo, and John Tackett. They are a Title 5 air pollution facility. They use heater bands to polymerize some waste in an outside unit. Ethyle acetate is the main solvent they use for cleanup. They have talked to some companies about getting a solvent recycler. They have determined that there is a big cost savings to running the polymerization unit. Kenna has posted some of their waste material on Ohio Materials Exchange (OMEX) but has not gotten any takers. They are looking to become certified ISO 14001 next year. ISO 14001 is an environmental management system. In early 2004 they updated their contingency plan. They have it in Adobe electronic form. They did hazardous waste refresher training in Jan. 2004.

We then took a tour of the facility. It had new looking lights. It had a strong solvent smell. They tried covered drum lids, but the screens go clogged. They save the pipe cleanout from loading to be used for the next pump flush. The large tank washer we saw uses SP-298 to clean the tanks. They have 3 air compressors. As part of their scrap (waste paste) reduction they got rid of the AB system because it was prone to leaks. Waste in the labs is collected in gallon, glass jugs. These are put into lab packs which go out every 90 days. At the pump and pipe cleaning area there are five washers - 3 are ethyl acetate and 2 are SP-298.

They make bulk molded compound (used for injection molding) and sheet molded compound. All the molding they do there is closed molding. They have injection molding machines. Premix is now getting products in drums that are UN certified so that they can be used to ship waste out.



### Waste, Pesticides and Toxics Division

) <u>*</u>	No Violation Letter Letter of Acknowled Information Request						
	Pre-Filing and Oppo State Notification of						
Facility Name :	PREMIX						
Facility Location:	P.O. BOX	281	107				
City: North	KINGSVILLE	State: ©H					
U.S. EPA ID#	D 004200044	,					
Assigned Staff Bu	cele Could	Phone: 3	-4796				
	4 <u>-</u>	1 9					
Name	Signature		Date				
Author	Author Bull Opelel 7-6-04						
Regional Counsel	,						
Section Chief	RA	-60	7904				
Branch Chief			0 2				

### **Directions/Request for Clerical Support:**

After the Section Chief/Branch Chief signs this sheet and original letter:

- 1. Date stamp the cover letter;
- 2. Make four copies of the contents of this folder:

One copy for the assigned staff;

One copy for the section file;

One copy for the branch file; and

One copy for the official file.

- 3. Make any additional copies for cc's or bcc's.
- 4. Mail the original certified mail and distribute office copies and cc's and bcc's. Once the certified mail receipt is returned:
- 5. File the certified mail receipt (green card), with this sign-off sheet and the official file copy, and take to 7<sup>th</sup> floor RCRA file room;
- 6. E-mail staff the date that the letter was received by facility.

7001 0320 0006 0007 2664



#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

#### REGION5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

DE-9J

JUL 1 2 2004

<u>CERTIFIED MAIL</u> RETURN RECEIPT REQUESTED

Mr. Bill Kennedy Chief Executive Officer Premix, Inc. P.O. Box 281 North Kingsville, OH 44068

Re:

Compliance Evaluation Inspection

EPA I.D. No.: OHD 004 200 044

Dear Mr. Kennedy:

On June 10, 2004, representatives of the United States Environmental Protection Agency (U.S. EPA) and the Ohio Environmental Protection Agency (OEPA) inspected Premix located in North Kingsville, Ohio. The U.S. EPA's purpose for the inspection was to evaluate your facility's compliance with certain requirements of the Resource Conservation and Recovery Act (RCRA), specifically the Air Emission Standards Applicable to Generators of Hazardous Waste set forth in 40 CFR 265, Subparts AA, BB, and CC. Enclosed, please find copies of the applicable checklists and the federal inspection report dated June 18, 2004.

As of this writing, based upon information available to the U.S. EPA, our review of the inspection has not resulted in the detection of violations of any of the specific RCRA requirements under evaluation. This determination does not limit the applicability of the requirements evaluated, other RCRA regulations, or regulations under other environmental statutes. The OEPA will issue a separate letter regarding their findings based on the general Standards Applicable to Generators of Hazardous Waste. The U.S. EPA and OEPA will continue to evaluate your facility in the future.

### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, ILLINOIS 60604

#### **MEMORANDUM**

DATE:

June 18, 2004

TO:

File

FROM:

Brenda Oswald - Environmental Engineer

Waste, Pesticides and Toxics Division

Enforcement and Compliance Assurance Branch

Compliance Section 2

SUBJECT:

Inspection Notes for June 10, 2004

Compliance Evaluation Inspection - Premix

OHD 004 200 044

Large Quantity Generator

A joint Compliance Evaluation Inspection (CEI) of Premix, located at Rt. 20 and Harmon Road, North Kingsville, OH 44068, was conducted on June 10, 2004. The federal portion of the inspection focused on 40 CFR 265, Subparts AA, BB, and CC. The following people were present for this inspection:

77 77 1.		CITTO ES E		** .
Kenna ( Oltman	PH	f 'H-1 N/1 N/1 -	Environmental Manager	Premix
ixuma Comman		CITIATIAI -	· Liiviioiiiiciitai waasaet	1 IUIIIA

Ken Lazo - Director Human Resources Premix

John Tackett - Operations Manager Premix

Robert Almquist - Division of Hazardous Waste Management OEPA

Brenda Oswald - Environmental Engineer U.S. EPA

#### Facility Background

Premix develops, formulates and manufactures thermoset compounds. The corporation was founded in 1958 and operations at the North Kingsville plant began prior to 1980. Premix products are used in various sectors such as the aerospace, automotive, appliance, electric and

recovery. Premix has developed a color-coding method to prevent unintentional mixing of ethyl acetate with any other solvents so as to reduce the amount of hazardous waste produced.

When the machinery is cleaned out for a color change, plastic is used to line the floor to catch resin that drips out of the open pipes. Drum liners, gloves and other debris become contaminated with ignitable paste and all are treated as hazardous waste.

Fluorescent bulbs (taken by Air Cycle, IN) and batteries are treated as universal waste. Air Cycle also takes computer equipment and other light bulbs.

The facility no longer houses any paint lines or bake ovens. The old paint room is now used as a storage area for molds.

#### **Facility Tour**

The tour began in the Molding Division at the southwest end of the plant. Specially formulated fiberglass materials, which are processed in the Compound Division, are molded into high strength, light-weight items such as firefighter helmets. One drum was held in a metal storage room in this division. It contained hydrocarbon-based solvents from the machine room. The drum was closed and labeled. Further north along the west wall, was an area set aside for fire protection equipment including a small vehicle able to transport fire suppressant foam to the main indoor 90 day storage area and outside to the waste polymerization unit and second main 90 day storage area.

The Compound Division is the northern sector of the facility. Near the south wall of this section was a drum of waste ethyl acetate that was labeled, dated from 03/26/04, and treated as a 90 day area with weekly inspections and a spill kit. Because this drum fills up slowly, the inspectors suggested making it a satellite drum as it is near the point of waste generation and under the control of the operator.

Upstairs on a mixing platform for the different paste formulations, another small 90 day area with 3 drums was positioned next to a tank washer. All drums were closed, labeled with a description of the material and the words "Hazardous Waste," and dated as 5/20/04, 6/08/04, and 4/16/04. A spill kit is next to the drums as well. Approximately 20 feet from these three drums was a satellite container holding waste polyester resins labeled as hazardous waste and closed. The tank washer is approximately 6 feet square. Premix holds a Permit to Install for daily emissions tracking even though it is classified as an insignificant emissions source. The solvent used in the tank washer is non-hazardous SP-298.

Downstairs, on the main floor, is another small 90 day area with 2 drums. A container of waste ethyl acetate was closed, labeled, and dated as 5/21/04. The second drum containing waste polyester pastes was closed, labeled, and dated 6/09/04. A spill kit is located nearby.

### 40 CFR § 265 Subparts AA, BB, and CC

This facility is exempt from RCRA air emissions regulations of 40 CFR § 265, Subparts AA, and BB. Subpart AA does not apply because the facility does not have any process vents associated with distillation, fractionation, thin film evaporation, solvent extraction, or air stripping units. Subpart BB is not applicable because the facility does not have equipment (pumps, compressors, pressure release devices, sampling connections, open-ended valves and lines, valves, flanges or connectors) associated with units as delineated in 40 CFR § 265.1050(b)(1)-(3). Subpart CC does apply to this generator. All containers in 90 day storage areas, however, were properly closed and inspected.

INTERIM STATUS FACILITIES ORGANIC AIR EMISSION STANDARDS FOR PROCESS VENTS		A	·Α
Facility's Name PREMIX			
Date 6-10-04 ID# OHD 004 200 044			
Now. Use of the words "process vents" means process vents associated with distillation, fractionation, thin-film evaporation, stripping operations managing hazardous waste with organic concentrations of at least 10 ppmw (time weight annual av Note: Total Organic Emissions shall be abbreviated to TOE	solvent erage ba	extraction or isis).	air or steam
ASSOCIATED WITH THE ABOVE.		YES NO	NI N/A
APPLICABILITY (40 CFR 265.1030)			
1. Manage hazardous waste w/ organic concentrations of at least 10 ppmw in units w/ process vents? (265.1030(b))	QAE	No	
IF YES	٠١		
a) Are the units subject to the permitting requirements under part 270? (265.1030(b)(1))	DAE	*	
OR	7		
b) Are there hazardous waste recycling units with process vents that are located at the facility that is otherwise subjet the permitting requirements? (265.1030(b)(2))	ct to DAE		
* If the answers to the above questions is no the following regulations do not apply, except you must verify the facility w 40 CFR 265.1034(d) and 40 CFR 265.1034(e) and this information must be recorded in a log: 40 CFR 265.1035(f).	aste has	less than 10	ppmw: see
STANDARDS: PROCESS VENTS (40 CFR 265.1032)  Note: A determination of vent emissions may be based on engineering calculations or tests (265.1032(c)) with any performance requirements of 265.1034(c).	mance to	ests meeting (	he
2. Has the owner/operator of a facility with process vents:			
a) Reduced TOE from all affected process vents < 1.4 kg/h (3 lb/h) & 2.8 mg/yr (3.1 tons/yr)? (265.1032(a)(1))	DAE	[]1	NI N/A
OR		e de la composition della comp	
b) Reduced, by use of a control device (that meets the requirements of 265,1033) the TOE from all affected process by 95 weight percent? (265,1032(a)(2))	s vents DAE		NI N/A
Note: If the process vents emit below the limits with out an add-on control device the facility the only additional requirem	nent is 2	65.1035(f)	
STANDARDS: CLOSED-VENT SYSTEMS AND CONTROL DEVICES (40 CF	R 265.	1033)	
3. Was a closed-vent system and control device installed by 12/21/90 or as per an implementation schedule with a compate date as soon as possible but no later than June 21, 1992? (265.1033(a)(2))	pletion DAE		NI N/A
4. If the owner/operator has installed a closed-vent system and control device by their effective date, was: (265.1033(a	1)(1))		
a) Control device involving vapor recovery designed/operated to recover organic vapors vented to it w/ an efficience 95 weight percent or greater? (265.1033(b)) (N/A if TOE for all affected process vents can be attained at an efficience less than 95 weight percent?)	cy of iciency DAE		NI N/A
b) Enclosed combustion device designed and operated to reduce organic emissions vented to it by 95 weight percent	t or grea	iter to: (265.	1033(c))
I) Achieve a total organic compound concentration of 20 ppmv?	DAE	[]_1	NI N/A
OR		T.	<u></u>
ii) Provide minimum resident time of 0.50 seconds at minimum temp. of 760 degrees C? (265.1033(c))	DAE		NI N/A
c) A flare:			

Designed/operated w/ no visible emissions except periods not to exceed total of 5 minutes during any 2 consecutive hours? (255,1033(d)(1))

ii) Operated with a flame present at all times? (265,1033(d)(2))

NI N/A

DAE

		YES N	IO NI N/A
b) Monitor device w/ continuous recorder to measure parameter that indicates the carbon bed is regenerated on regular predetermined time cycle?	DAE	[]	NI N/A
AND			11
c) Replaces existing carbon w/ fresh at pre-servinterval no longer than carbon service life? (265.1033(g))	DAE	[]_	NÎ N/A
viii) If using a carbon adsorption system that does not regenerate carbon bed on-site in the control device, the exis fresh carbon on a regular basis by either: (265.1033(h)(1-2))	ting carl	bon will	be replaced w/
a) Monitoring the concentration level of the organic compounds regularly and replace the carbon with fresh in	nmediate	ely after	break-through?
I) Monitoring daily?	DAE	U_	NI N/A
ii) Monitoring at interval no greater than 20% of time required to consume total carbon working capacity?	DAG	LU_	NI N/A
b) Replace the existing carbon with fresh at regular, predetermined intervals?	CHARLE .	U_	NI N/A
c) Inspecting readings from (except 265.1033(h)) monitoring device(s) at least once each operating day? (265.1033(f)(3))	DAR		NI N/A
AND			
d) If needed, implement necessary corrective measures to ensure control devices work? (265.1033(f)(3))	DAS		NI N/A
Note: An alternative operational or process parameter may be monitored see 40 CFR 265.1033(I).			
6. The closed-vent system(s):			
a) Was it designed for and operated with no visible emissions? (265.1033(j)(1))	DAE	<b>1</b> ,	NI N/A
b) Have initial leak detection monitoring conducted: (265.1033(j)(2))		<u> </u>	
By date facility becomes subject to these regulations?	DAR	Tri	NI N/A
ii) Annually thereafter?	DAE	[]	NI N/A
c) Control detectable emissions (>500 ppm) as soon as possible but: (265.1033(j)(3-4))	100		_
I) No later than 15 calendar days after detected?	DAE		NI N/A
ii) First attempt at repair made no later than 5 calendar days after detection?	DAE	lu.	NI N/A
7. Were closed-vent systems and control devices operated at all times when emissions may be vented to them?  (265.1033(k))	DAS	3	ep said NI N/A
TEST METHODS AND PROCEDURE (40 CFR 265.1034)			
8. Were correct test methods and procedures used? (265.1034(a))	-a		
a) For a closed-vent system tested for no detectable emissions? (265.1034(b)(1-7))	DAE		NI N/A
b) To determine compliance with the 10 ppmw and with the total organic compound limit (95%)? (265.1034(c))	DAE		NI N/A
<ol> <li>Did the facility determine that the process vents are not subject to the requirements of this subpart? If so, did the orderermination that the time-weighted annual average total organic concentration managed by the unit is less than 10</li> </ol>	wner/op ppmw b	erator m by: (265	ake an initial .1034(d))
a) Direct measurement? (265.1034(d)(1))	DAE		NI N/A
b) Using knowledge? (265.1034(d)(2))	DAE		NI N/A
10. Was the determination that distillation, fractionation, thin-film evaporation, solvent extraction or air or stream strip wastes time-weighted annual average total organic concentration is less than 10 ppmw made as follows: (265.1034)		erations 1	manage hazardous
) By date the facility is first subject to the regulations or the date the waste is first managed, whichever is first?	DAE		NI N/A
For continuously generated waste annually?	DAE		NI N/A

	YES N	O NI N/A
e) Condenser, consider vent stream composition/constituent composition/flow rate/relative humidity & temp.  Include design outlet organic compound concentration level, design average temp. of the exhaust vent stream, and the design average temp. of the coolant fluid at the condenser outlet and inlet? (265.1035(b)(4)(iii)(E)) DAE		NI N/A
f) Carbon adsorption system that regenerates bed on-site in the control device, consider the vent stream composition/constituent concentrations/flow rate/relative humidity/temperature. Include design exhaust vent stream organic compound concentration level/number & capacity of carbon beds/type & capacity of activated carbon/total stream flow/bed steaming/cooling/drying cycles/temp. regeneration/time of regeneration/service life? (265.1035(b)(4)(iii)(F))	<u>U</u>	NI N/A
g) Carbon adsorption system that does not regenerate on-site in a control device, consider the vent stream composition/constituent concentrations/flow rate/relative humidity/temperature. Include the design outlet organic concentration level/capacity of the bed/type & capacity of the carbon in the bed/replacement interval? (265.1035(b)(4)(iii)(G))		NI N/A
e) A statement signed/dated by the owner/operator certifying that the operating parameters used in the design analysis reasonably represent the conditions that exist when the hazardous waste management unit is or would be operating at the highest load or capacity level reasonably expected to occur? (265.1035(b)(iv))  DAE	U_	NI N/A
f) A statement signed/dated by the owner/operator certifying that the control device is designed to operate at an efficiency of ≥ 95% (are alternatives)? A statement from the device manufacture or vendor certifying that the control equipment meets the design specifications will suffice? (265.1035(b)(v)) DAE		NI N/A
g) If test performance tests are used to demonstrate compliance, all test results? (265.1035(b)(vi))  DAE	<u> </u>	NI N/A
h) Design documentation & monitoring/operating & inspection information for each closed-vent system/control device rec including: (265.1035(c))	orded, kep	ot up-to-date and
I) Description and date of each modification? (265.1035(c)(1))		NI N/A
ii) Id operating parameters/describe monitoring devices/diagram monitoring sensor locations? (265.1035(c)(2)) DAE	<u>U</u>	NI N/A
iii) Monitoring/operating & inspection information required in 265.1033(f-j)? (265.1035(c)(3))  DAE		NI N/A
iv) Date, time and duration when monitoring values exceed the value established? (254.1035(c)(4)) DAE		NI N/A
v) Explanation for each period the control device operating parameter exceeded the design value & the measures implemented to correct the control device? 265.1035(c)(5))  DAE	<u>lo</u>	NI N/A
vi) Carbon adsorption systems where the carbon is regenerated in the control device or a system that changes the carbon at a regular, predetermined interval give the date when existing carbon is replaced? (265.1035(c)(6))  DATE		NI N/A
vii) For a carbon adsorption system that changes the carbon at breakthrough have a log that records: (265.1035(c)(7)(I-	ii))	
a) Date and time of breakthrough and the monitoring device reading?  DAE		NI N/A
b) Date when existing carbon is replaced with fresh carbon?  DATE		NI N/A
viii) Date of control device start up and shut down? (265.1035(c)(8))		NI N/A
<ul> <li>Control device other than thermal or catalytic vapor incinerator/flare/boiler/process heater/condenser/carbon adsorption bed, the monitoring/inspection information indicating proper operation &amp; maintenance? (265.1035(e)) DAR</li> </ul>		NI N/A
<ul> <li>j) Up-to-date information/data used to determine if a process vent falls under (265.1032) &amp; supporting documentation (265.1034(d)(2)) when knowledge of the nature of hazardous waste stream or process is used? (265.1035(f)) DATE</li> </ul>		NI N/A
12. Are records of monitoring, operating and inspection information kept at least 3 years? (265.1035(d))  DAI		NI N/A

# INTERIM STATUS FACILITIES AND FULLY REGULATED GENERATOR BB ORGANIC AIR EMISSION STANDARDS FOR EQUIPMENT LEAKS REMIX OHD 004 200 044 ID# Use of the words "process vents" means process vents associated with distillation, fractionation, thin-film evaporation, solvent extraction or air or steam stripping operations managing hazardous waste with organic concentrations of at least 10 ppmw (time weight annual average basis). Note: Total Organic Emissions shall be abbreviated to TOE Note: Equipment with closed-vent systems and control devices shall comply with the provisions of section 265.1033. (rev. 4/25/97 [z/bb.nzw] - EAB-MDEQ) NI - not inspected N/A - not applicable YES NO NI N/A APPLICABILITY (40 CFR 265.1050) If the equipment contains or contacts hazardous waste w/ organic concentrations of at least 10 percent by weight: 0 a) Are the units subject to the permitting requirements of part 270? (265.1050(b)(1)) OR b) Are there hazardous waste recycling units located at the facility that are otherwise subject to the permitting **√**0 . requirements? (265.1050(b)(2)) \* If the answers to the above questions are no the following regulations do not apply. STANDARDS: PUMPS IN LIGHT LIQUID (40 CFR 265.1052) Note: Delays in repair are allowed see 265.1059 (#37) Note: Did the owner/operator subject to the provisions of this subpart comply with the required test methods and procedures: (265.1063(b-l)) (#41) Pump equipped w/ duel mechanical seal system that includes a barrier fluid system? If yes, its exempt from monthly NI N/A monitoring (#5) and visual inspections (#6) if: (265.1052(d)) Each duel mechanical seal system is: NI N/A Operated with a barrier fluid with pressure greater than the pump stuffing box pressure. (265.1052(d)(1)(I)) OR NI N/A ii) Has a barrier fluid degassing reservoir connected by closed-loop to a control device. (265.1052(d)(1)(ii))

Facility's Name

Date

OR		_
iii) System that purges the barrier fluid into a hazardous waste stream w/no detectable emissions? (265.1052(d)(1)(iii)	u	NI N/A
b) Barrier fluid is not a hazardous waste w/ organic concentrations 10% or greater by weight. (265.1052(d)(2))		NI N/A
c) Each barrier fluid system equipped w/ a sensor to detect failure of the seal/barrier fluid system. (265.1052(d)(3)) DAN		NI N/A
d) Each calendar week pump has visual inspection for signs of liquids dripping from pump seals. (265.1052(d)(4))		NI N/A
e) Each sensor is checked: (265.1052(d)(5)(l))		
I) Daily.		NI N/A
OR		

NI N/A ii) Equipped with audible alarm that is checked monthly to see if working. DAR NI N/A f) Owner/operator has determined a criteria indicating failure of the seal/barrier fluid system. (265.1052(d)(5)(ii)) DAR g) Indications of liquids dripping from pump seal/sensor means failure of seal/barrier fluid system & a leak has been detected: (265.1052(d)(6)(l)) NI N/A Was it repaired as soon as practicable but no later than 15 calendar days after detected? (265.1052(d)(6)(ii)) DAE A first attempt at repair was made no later than 5 calendar days after leak is detected? (265.1052(d)(6)(iii)) NI N/A DAE The pump designed as in 264.1064(g)(2) for no detectable emissions as indicated by an instrument reading of < 500 ppm above background? Yes, pump exempt from monthly monitoring (#5), visual monitoring (#6), repairs (#7a & #7b) and barrier fluid system (#2) if: (265.1052(e)) NI N/A a) It does not have an externally actuated shaft penetrating the pump housing. (265.1052(e)(1)) NI N/A DAE

Air Emission Standards for Equipment Leaks		
	YES NO	NI N/A
a) Was it repaired as soon as practicable but no later than 15 calendar days after detected? (265.1052(g)(1)) DAE		NI N/A
b) Was a first attempt at repair was made no later than 5 calendar days after leak is detected? (265.1052(g)(2)) DAE	LU	NI N/A
STANDARDS: PRESSURE RELIEF DEVICES IN GAS/VAPOR SERVICE (40 CFR 26 NOTE: Delays in repair are allowed see 265.1059 (#37)	5.1054)	
17. Is the pressure relief device equipped with a closed-vent system capable of capturing and transporting leakage to a control devices specified in 265.1060? If yes, the device is exempt from relief device monitored for no detectable emissions (#18), specifications to reset device and time frame (#19 & #20). (265.1054(c))		NI N/A
18. Pressure relief devices in gas/vapor service operated w/ no detectable emissions indicated by an instrument reading of <500 ppm above background, except during pressure releases? (265.1054(a))		NI N/A
19. After a pressure release, was the device returned to a condition of no detectable emissions indicated by an instrument reading of < 500 ppm above background, as soon as practical but no later than 5 calendar days? (265.1054(b)(1))		NI N/A
20. No later than 5 calendar days after a pressure release, is the pressure relief device monitored to confirm no detectable emissions indicated by an instrument reading of < 500 ppm above background,? (265.1054(b)(2))		NI N/A
STANDARDS: SAMPLING CONNECTING SYSTEMS (40 CFR 265.1055)		<del></del> 1
21. Is the sampling system in situ? If yes, the system isn't required to have closed-vent or closed-purge system (#22 & #23).  (265.1055(c))		NI N/A
22. Is each sampling connection system equipped with a closed-purge system or closed-vent system? (265.1055(a))	<u> </u>	NI N/A
23. Does each closed-purge or closed-vent system: (265.1055(b))		
Return purged hazardous waste stream directly to hazardous waste management process line w/ no detectable emissions? (265.1055(b)(1))		NI N/A
OR		
b) Collect and recycle the purged hazardous waste stream with no detectable emissions? (265.1055(b)(2))		NI N/A
OR		
c) Designed/operated to capture/transport all purged hazardous waste stream to a control device? (265.1055(b)(3))		NI N/A
STANDARDS: OPEN-ENDED VALVES OR LINES (40 CFR 265.1056)  Note: Delays in repair are allowed see 265.1059 (#37)  Note: Did the owner/operator subject to the provisions of this subpart comply with the required test methods and procedures:	(265.1063 <u>(</u> )	-I)) (#41)
24. Is each open-ended valve or line equipped with a cap, blind flange, plug or second valve? (265.1056(a)(1))		NI N/A
25. Cap/blind flange/plug/second valve always seal open end except when waste must flow through? (265.1056(a)(2))		NI N/A
26. If using a second valve, is the first valve closed before the second? (265.1056(b))		NI N/A
27. If a double block and bleed system is used and the bleed line/valve stays open during venting, is the line between the block valves have cap/blind flange/plug/second value and sealed at all other times? (265.1056(c))	k B   U	NI N/A
STANDARDS: VALVES IN GAS/VAPOR SERVICE OR IN LIGHT LIQUID SERVICE (40 Note: There are alternate standards for valves in gas/vapor or light liquid service where owners/operators may elect to have a waste management unit comply with alternative standards which: (1) allows no greater than 2% of the valves to leak. allows for skip period leak detection and repair. (265.1062(a-b))  Note: Delays in repair are allowed see 265.1059 (#37)	l valves with	in a hazardous

NI N/A

Valve designated as an unsafe-to-monitor valve as described in 265.1064(h)(1). If yes, the valve is exempt from monthly

monitoring (#31) if: (265.1057(g))

		YES	NO NI	N/A
c) Was the first repair attempt include, but not limited to: (265.1058(d))				
I) Tightening of bonnet bolts?	DAE		NI	N/A_
ii) Replacement of bonnet bolts?	DAE		NI	N/A
iii) Tightening of packing gland nuts?	pas	LL	NI	N/A
iv) Injection of lubricant into lubricating packing?	DAB		NI	N/A
•				

STANDARDS: DELAY OF REPAIR (40 CFR 265.1059)

STANDARDS: DELAT OF REPAIR (40 CFR 203.1039)						
37. Was there a delay in repair of equipment for which leaks have been detected? If yes, the delay is allowed if:	DAR		NI N/A			
a) Was the repair technically infeasible without a shutdown of the hazardous waste management unit and did the repa occur before the end of the next shutdown? (265.1059(a))	ir DAB		NI N/A			
b) Was the equipment isolated from the hazardous waste management unit and the unit does not contain or contact hazardous waste with organic concentrations at least 10% by weight. (265.1059(b))	DAE	<u>U</u>	NI N/A			
38. Was there a delay in repair of a valve? If yes, the delay is allowed if:	DAE		NI N/A			
<ul> <li>a) Determine emissions from purged material from immediate repair are greater than emissions resulting from a delathe repair. (265.1059(c)(1))</li> </ul>	y of	<u>U</u>	NI N/A			
b) When repaired, the purged material is collected and destroyed or recovered in a control device. (265.1059(c)(2))		LI.	NI N/A			
39. Was there a delay in repair of a pump? If yes, the delay will be allowed if:	DIFFEE		NI N/A			
a) Repair requires the use of a duel mechanical seal system that includes a barrier fluid system. (265.1059(d)(1))	DAB	ப	NI N/A			
b) Repair is completed as soon as practicable but within 6 months. (265.1059(d)(2))	DAE	u	NI N/A			
40. Was there a delay in repair of a valve beyond a hazardous waste management unit shutdown? If yes, the delay will b allowed until the next shutdown or longer if the shutdown is within 6 months if: (265.1059(e))	e Dae		NI N/A			
a) The valve assembly replacement is necessary during shutdown.	DAR	U	NI N/A			
b) Valve assembly supplies have been depleted & supplies were sufficiently stocked before supplies were depleted.	DAR	l u	NI N/A			

TEST METHODS AND PROCEDURES (40 CFR 265,1063)

41.	11. Did the owner/operator subject to the provisions of this subpart comply with the required test methods and procedures: (265.1063(b-1))						
	a)	For leak detection monitoring? (265.1063(b))	U	NI	N/A		
	b)	For 'no detectible' emissions determination? (265.1063(c))	U <u>·</u>	NI	N/A		
	c)	To determine if each piece of equipment contains or contacts a hazardous waste w/ organic concentrations > 10% by weight? (265.1063(d))	U _	NI	N/A		
	d)	To determine if pumps or valves are in light liquid service? (265.1063(h))	U_	וא	N/A		
	e)	To determine if the control device achieved 95 weight percent organic emissions? (265.1063(I))	lu_	NI	N/A		
42.		ere samples used in determine the percent organic content representative of the highest TOC hazardous waste that is extend to be contained in or contact the equipment? (265.1063(g))	l u _	. NI	Ņ/A		

### RECORDKEEPING REQUIREMENTS (40 CFR 265.1064)

Note: Owners/operators with more than one hazardous waste management unit, subject to these regulations, may use one recordkeeping system if each unit is identified.

Did the owners/operators record the following information in the operating record for each piece of equipment subject to Subpart BB? (265.1064(b))

		Equipment	

	VCC	NO NI	N/A
	IES	NO 141	N/A
1) Dates of each test? (265.1064(g)(4)(I))	U	NI	N/A
2) Background level measured during each test? (265.1064(g)(4)(ii))		М	N/A
3) The maximum instrument reading measured at the equipment during each test? (265.1064(g)(4)(iii)) DAE		<u>NI</u>	N/A_
e) List of all identification numbers for equipment in vacuum service? (265.1064(g)(5))  DAE		NI	N/A.
vi) A log with a list of identification numbers for the valves that are designated unsafe or difficult to monitor, an explanation stating why they are unsafe or difficult and the plan for monitoring? (265.1064(h)(1-2))		NI	N/A_
vii) For valves in gas/vapor or light liquid service with alternative standards the operating record will record: (265.106	\$(I))		
a) A schedule of monitoring? (265.1064(I)(1))	Lu	NI	N/A
b) The percent of valves found leaking during each monitoring period? (265.1064(I)(2))		N	N/A
viii) Is the following information shall be recorded in a log and kept in the operating record: (265.1064(j))		~···	
a) Criteria for failure of seal system indicated by sensor used w/ light liquid service pumps? (265.1064(j)(1)) DAR		N	N/A
b) Criteria for failure of seal system indicated by sensor used w/ compressors? (265.1064(j)(!))	ļu	N	N/A
c) Any changes to these criteria and the reason for change? (265.1064(j)(2))		N	I N/A
ix) The following information kept in a log and used to determine exemptions for the hazardous waste management unit:	(265.1	064(k))	
a) An analysis determining the design capacity of the management unit? (265.1064(k))	l .		I N/A
b) A statement listing the hazardous waste influent to and effluent from each unit and analysis determining whether the waste is a heavy liquid? (265.1064(k)(2))	L	N	I N/A
c) Up-to-date analysis/supporting data used to determine if equipment is subject to standards? (265.1064(k)(3)) DAI	<u>l</u>	N	I N/A
d) Documentation when knowledge of the hazardous waste stream or process is used? (265.1064(k)(3))		N	IL N/A
e) Any new determinations if the owner/operator takes any action that could result in an increase of the organic content of the waste? (265.1064(k)(3))		. 1	II N/A
43. Are records of equipment leak information in 265.1064(d) and closed-vent and control device information in 265.1064(e) kept 3 years? (265.1064(1))		7	II N/A

Comments:	<u> </u>	



Northeast District Office

E. Aurora Road sburg, Ohio 44087-1969

TELE (330) 425-9171 FAX (330) 487-0769

Bob Taft, Governor Christopher Jones, Director

July 8, 2004

RE: PREMIX. INC.

LARGE QUANTITY GENERATOR

OHD 004 200 044 ASHTABULA COUNTY

Bill Kennedy, CEO Premix, Inc. P.O. Box 281 North Kingsville, OH 44068

Dear Mr. Kennedy:

On June 10, 2004 Brenda Oswald of the US EPA and I conducted an inspection of Premix, Inc. located at Rt. 20 and Harmon Road in North Kingsville, Ohio. Ms. Oswald inspected to determine Premix's current state of compliance with the organic air emission standards contained in the Code of Federal Regulations, Title 40, Parts 264/265. She will provide a separate letter covering this.


The purpose of my inspection was to determine Premix's state of compliance with Ohio's hazardous waste, used oil, and universal waste laws as found in Chapter 3734 of the Ohio Revised Code and Chapter 3745 of the Ohio Administrative Code and to discuss pollution prevention options. We did not conduct a complete inspection covering all rules and reviewing all paperwork. This was because I had conducted such an inspection in September 2003 and the processes and waste management did not appear to have changed greatly. We did, however, review the waste generated and conduct a tour of the plant and some of the outside areas. Please see the enclosed process description/waste activities summary sheets.

No violations of Ohio's hazardous waste, used oil, or universal waste laws were found.

Ms. Coltman did mention that, at times, partially full drums of spent SP331 FV (generated in the laboratory) are shipped out in order to comply with the 90 day accumulation limit. We discussed that this waste may be able to be stored in the same drum as the spent SP173C in order to avoid this problem.

Also enclosed is a list of references regarding energy conservation.

Premix may be able to reduce its operating costs with waste minimization and energy conservation practices. The Ohio EPA offers Pollution Prevention Assessments to help you decide which practices would benefit your operations. Ms. Coltman and I are in the process of setting up such as assessment for your office operations. This will focus on such things as paper use reduction. If you would like to have an expanded or additional Pollution Prevention Assessment or would like more information regarding waste minimization, please contact me. The Office of Pollution Prevention web site at <a href="http://www.epa.state.oh.us/opp/oppmain.html">http://www.epa.state.oh.us/opp/oppmain.html</a> also has information regarding waste minimization.



Bill Kennedy, CEO Premix, Inc. July 8, 2004 Page 2

You can find copies of the laws and other information on the Ohio EPA web page at <a href="www.epa.state.oh.us">www.epa.state.oh.us</a>. If you have any questions, please contact me by phone at (330) 963-1217, or by email at <a href="mailto:robert.almquist@epa.state.oh.us">robert.almquist@epa.state.oh.us</a>.

Sincerely,

Robert almquist

Division of Hazardous Waste Management

RA:cl

ec: Harry Courtright, DHWM, NEDO

cc: Tammy McConnell, DHWM, CO Kenna Coltman, Premix Brenda Oswald, US EPA

### NOTICE:

Ohio EPA's failure to list specific deficiencies or violations in this letter does not relieve your company from having to comply with all applicable regulations.



July , 2004

RE: PREMIX, INC.

LARGE QUANTITY GENERATOR OHD 004 200 044 ASHTABULA COUNTY

Bill Kennedy, CEO Premix, Inc. P.O. Box 281 North Kingsville, OH 44068

Dear Mr. Kennedy:

On June 10, 2004 Brenda Oswald of the US EPA and I conducted an inspection of Premix, Inc. located at Rt. 20 and Harmon Road in North Kingsville, Ohio. Ms. Oswald inspected to determine Premix's current state of compliance with the organic air emission standards contained in the Code of Federal Regulations, Title 40, Parts 264/265. She will provide a separate letter covering this.

The purpose of my inspection was to determine Premix's state of compliance with Ohio's hazardous waste, used oil, and universal waste laws as found in Chapter 3734 of the Ohio Revised Code and Chapter 3745 of the Ohio Administrative Code and to discuss pollution prevention options. We did not conduct a complete inspection covering all rules and reviewing all paperwork. This was because I had conducted such an inspection in September 2003 and the processes and waste management did not appear to have changed greatly. We did, however, review the waste generated and conduct a tour of the plant and some of the outside areas. Please see the enclosed process description/waste activities summary sheets.

No violations of Ohio's hazardous waste, used oil, or universal waste laws were found.

Ms. Coltman did mention that, at times, partially full drums of spent SP331 FV (generated in the laboratory) are shipped out in order to comply with the 90 day accumulation limit. We discussed that this waste may be able to be stored in the same drum as the spent SP173C in order to avoid this problem.

Also enclosed is a list of references regarding energy conservation.

Premix may be able to reduce its operating costs with waste minimization and energy conservation practices. The Ohio EPA offers Pollution Prevention Assessments to help you decide which practices would benefit your operations. Ms. Coltman and I are in the process of setting up such as assessment for your office operations. This will focus on such things as paper use reduction. If you would like to have an expanded or additional Pollution Prevention Assessment or would like more information regarding waste minimization, please contact me. The Office of Pollution Prevention web site at <a href="http://www.epa.state.oh.us/opp/oppmain.html">http://www.epa.state.oh.us/opp/oppmain.html</a> also has information regarding waste minimization.

You can find copies of the laws and other information on the Ohio EPA web page at <a href="https://www.epa.state.oh.us">www.epa.state.oh.us</a>. If you have any questions, please contact me by phone at (330) 963-1217, or by email at robert.almquist@epa.state.oh.us.

Sincerely,

Robert Almquist Division of Hazardous Waste Management

RA:cl

Harry Courtright, DHWM, NEDO Kenna Coltman, Premix

kenna.coltman@premix.com Brenda Oswald, US EPA

oswald.brenda@epa.gov

Tammy McConnell, DHWM, CO

### NOTICE:

Ohio EPA's failure to list specific deficiencies or violations in this letter does not relieve your company from having to comply with all applicable regulations.

State INSPECTION REPORT

Premix, Rt. 20 and Harmon Road, North Kingsville, OH (OHD 004 200 044) 6-10-04
Brenda Oswald, US EPA
Robert Almquist, Ohio EPA (notes of)

We met with Kenna Coltman, Ken Lazo, and John Tackett. They are a Title 5 air pollution facility. They use heater bands to polymerize some waste in an outside unit. Ethyle acetate is the main solvent they use for cleanup. They have talked to some companies about getting a solvent recycler. They have determined that there is a big cost savings to running the polymerization unit. Kenna has posted some of their waste material on Ohio Materials Exchange (OMEX) but has not gotten any takers. They are looking to become certified ISO 14001 next year. ISO 14001 is an environmental management system. In early 2004 they updated their contingency plan. They have it in Adobe electronic form. They did hazardous waste refresher training in Jan. 2004.

We then took a tour of the facility. It had new looking lights. It had a strong solvent smell. They tried covered drum lids, but the screens go clogged. They save the pipe cleanout from loading to be used for the next pump flush. The large tank washer we saw uses SP-298 to clean the tanks. They have 3 air compressors. As part of their scrap (waste paste) reduction they got rid of the AB system because it was prone to leaks. Waste in the labs is collected in gallon, glass jugs. These are put into lab packs which go out every 90 days. At the pump and pipe cleaning area there are five washers - 3 are ethyl acetate and 2 are SP-298.

They make bulk molded compound (used for injection molding) and sheet molded compound. All the molding they do there is closed molding. They have injection molding machines. Premix is now getting products in drums that are UN certified so that they can be used to ship waste out.



## Waste, Pesticides and Toxics Division

Type of Document: ☐ Notice of	of Violation and Inspection F	Report/Checklist	
<b>≱</b> No Viol	ation Letter and Inspection R	eport/Checklist	
☐ Letter of	f Acknowledgment		
<u>□</u> Informa	tion Request		
□ Pre-Filin	ng and Opportunity to Confer	r	
□ State No	otification of Enforcement Ac	ction	
0			
Facility Name: YREMIX			
0.0	000 291		
Facility Location: P.O.	BOX 281		= **
A1 1/ -		0.11	
City: NORTH KIND	State:	<u>Ott</u>	
U.S. EPA ID# 0HD 009	200 0 44		
Assigned Staff Buch	Buled Phon	ne:_ 3-4796	-
		2 2	

Name	Signature	Date
Author	Bull Boild	7-6-04
Regional Counsel		
Section Chief	PR HO	7904
Branch Chief		

### **Directions/Request for Clerical Support:**

After the Section Chief/Branch Chief signs this sheet and original letter:

- 1. Date stamp the cover letter;
- 2. Make four copies of the contents of this folder:

One copy for the assigned staff;

One copy for the section file;

One copy for the branch file; and

One copy for the official file.

- 3. Make any additional copies for cc's or bcc's.
- 4. Mail the original certified mail and distribute office copies and cc's and bcc's. Once the certified mail receipt is returned:
- 5. File the certified mail receipt (green card), with this sign-off sheet and the official file copy, and take to 7<sup>th</sup> floor RCRA file room;
- 6. E-mail staff the date that the letter was received by facility.

7001 0320 0006 0177 2664



### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

DE-9J

JUL 1 2 2004

CERTIFIED MAIL RETURN RECEIPT REQUESTED

Mr. Bill Kennedy Chief Executive Officer Premix, Inc. P.O. Box 281 North Kingsville, OH 44068

Re:

Compliance Evaluation Inspection EPA I.D. No.: OHD 004 200 044

Dear Mr. Kennedy:

On June 10, 2004, representatives of the United States Environmental Protection Agency (U.S. EPA) and the Ohio Environmental Protection Agency (OEPA) inspected Premix located in North Kingsville, Ohio. The U.S. EPA's purpose for the inspection was to evaluate your facility's compliance with certain requirements of the Resource Conservation and Recovery Act (RCRA), specifically the Air Emission Standards Applicable to Generators of Hazardous Waste set forth in 40 CFR 265, Subparts AA, BB, and CC. Enclosed, please find copies of the applicable checkli

As of t inspect require require statutes Standa contin

ists and the federal inspection report dated June 18, 2004.			
this writing, based upon information available to the U.S. EPA, our review of the tion has not resulted in the detection of violations of any of the specific RCRA ements under evaluation. This determination does not limit the applicability of the ements evaluated, other RCRA regulations, or regulations under other environmental s. The OEPA will issue a separate letter regarding their findings based on the general ards Applicable to Generators of Hazardous Waste. The U.S. EPA and OEPA will use to evaluate your facility in the future.			
Recycled/Recyclable . Printed with Vegetable Oil Based Inks on 100% Recycled Paper (50% Postconsumer)	• •		

If you have any questions or concerns regarding this matter, please contact Brenda Oswald of my staff at 312-353-4796.

Sincerely,

Paul Little, Section Chief Enforcement and Compliance Assurance Branch

Compliance Section 2
Waste, Pesticides, and Toxics Division

Enclosures

ec: Robert Almquist, OEPA



### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY **REGION 5** 77 WEST JACKSON BOULEVARD CHICAGO, ILLINOIS 60604

### **MEMORANDUM**

DATE:

June 18, 2004

TO:

File

FROM:

Brenda Oswald - Environmental Engineer

Waste, Pesticides and Toxics Division

Enforcement and Compliance Assurance Branch

Compliance Section 2

**SUBJECT:** Inspection Notes for June 10, 2004

Compliance Evaluation Inspection - Premix

OHD 004 200 044

Large Quantity Generator

A joint Compliance Evaluation Inspection (CEI) of Premix, located at Rt. 20 and Harmon Road, North Kingsville, OH 44068, was conducted on June 10, 2004. The federal portion of the inspection focused on 40 CFR 265, Subparts AA, BB, and CC. The following people were present for this inspection:

Kenna Coltman, PE, CHMM - Environmental Manager

Premix

Ken Lazo - Director Human Resources

Premix

John Tackett - Operations Manager

Premix

Robert Almquist - Division of Hazardous Waste Management

**OEPA** 

Brenda Oswald - Environmental Engineer

U.S. EPA

### Facility Background

Premix develops, formulates and manufactures thermoset compounds. The corporation was founded in 1958 and operations at the North Kingsville plant began prior to 1980. Premix

products are used in various sectors such as the aerospace, automotive, appliance, electric and

construction industries. Premix's international customer base includes Boeing, Harley Davidson, Cummins, Trane, Dana, and Eaton. The North Kingsville facility houses corporate headquarters, compound manufacturing, compression and injection molding, and research and development for Premix. A second facility, located in Bay City, MI, is named Quantum Composites. High performance molding compound development, formulations, and compound manufacturing occur at this site.

#### Introductory Conference

The inspectors, Robert Almquist and Brenda Oswald, arrived at the facility at approximately 9:30am. The weather was overcast with occasional rains and the temperature was between 65° and 70°F. The inspectors signed in the logbook with a written stipulation that disagreeing to the company policy of confidentiality. Facility personnel, Kenna Coltman and Ken Lazo, met the inspectors at the front lobby where the inspectors showed identification and exchanged business cards with Ms. Coltman and Mr. Lazo. In a conference room, the group discussed Premix's hazardous waste generation and handling procedures. John Tackett joined the conversation before taking the group on a plant tour.

The hazardous waste produced on site consists of resins, paints, thickeners, and solvents, and all are stored in 55 gallon drums. Solvent contaminated rags are incinerated and cannot be laundered because of the thick consistency of the paste picked up on the rags. Organic peroxides may also be scrapped for contamination, expired shelf life, or because the type is not known. All waste paste in the facility is combined as a single type for polymerization treatment. The flammable waste paste drums are placed in one of two outdoor metal enclosures (See Picture 1, Appendix A), and the drums are equipped with band heaters to initiate the polymerization. The paste solidifies within 24 hours eliminating its hazardous ignitability characteristic. The drums are then sent as non-hazardous waste to a solid waste landfill. The drums are tested monthly by drilling a core into the hardened material in order to make sure that no liquid is present. Also, an evaluation is performed annually to ensure no change in the waste constitution. The waste paste that does not get polymerized is classified as D001 and sent as hazardous waste to Chemical Solvents, Inc (CSI).

Premix holds an air Permit to Install for the waste treatment units, which covers the venting system. The permit allows a maximum treatment of 1350 pounds per day per unit and states that the containers, doors and openings, other than the make-up air inflow vents, must be closed during treatment. The permit also has record-keeping requirements.

Ethyl acetate is treated as a hazardous waste along with any waste mixed with it. SP-298 is a hydrocarbon-based solvent that has a flash point above 140°F, but is sometimes accidentally mixed with ethyl acetate in parts washer cleanouts in the Pipe and Pump Cleaning Room. The resulting mixture is referred to as "SP-298 +," which is sent for fuel blending and is treated at CSI as hazardous waste. Other spent ethyl acetate from machine clean-outs is sent to CSI for

-2

-	::				
	* Market American				
	***************************************				
,					

recovery. Premix has developed a color-coding method to prevent unintentional mixing of ethyl acetate with any other solvents so as to reduce the amount of hazardous waste produced.

When the machinery is cleaned out for a color change, plastic is used to line the floor to catch resin that drips out of the open pipes. Drum liners, gloves and other debris become contaminated with ignitable paste and all are treated as hazardous waste.

Fluorescent bulbs (taken by Air Cycle, IN) and batteries are treated as universal waste. Air Cycle also takes computer equipment and other light bulbs.

The facility no longer houses any paint lines or bake ovens. The old paint room is now used as a storage area for molds.

#### Facility Tour

The tour began in the Molding Division at the southwest end of the plant. Specially formulated fiberglass materials, which are processed in the Compound Division, are molded into high strength, light-weight items such as firefighter helmets. One drum was held in a metal storage room in this division. It contained hydrocarbon-based solvents from the machine room. The drum was closed and labeled. Further north along the west wall, was an area set aside for fire protection equipment including a small vehicle able to transport fire suppressant foam to the main indoor 90 day storage area and outside to the waste polymerization unit and second main 90 day storage area.

The Compound Division is the northern sector of the facility. Near the south wall of this section was a drum of waste ethyl acetate that was labeled, dated from 03/26/04, and treated as a 90 day area with weekly inspections and a spill kit. Because this drum fills up slowly, the inspectors suggested making it a satellite drum as it is near the point of waste generation and under the control of the operator.

Upstairs on a mixing platform for the different paste formulations, another small 90 day area with 3 drums was positioned next to a tank washer. All drums were closed, labeled with a description of the material and the words "Hazardous Waste," and dated as 5/20/04, 6/08/04, and 4/16/04. A spill kit is next to the drums as well. Approximately 20 feet from these three drums was a satellite container holding waste polyester resins labeled as hazardous waste and closed. The tank washer is approximately 6 feet square. Premix holds a Permit to Install for daily emissions tracking even though it is classified as an insignificant emissions source. The solvent used in the tank washer is non-hazardous SP-298.

Downstairs, on the main floor, is another small 90 day area with 2 drums. A container of waste ethyl acetate was closed, labeled, and dated as 5/21/04. The second drum containing waste polyester pastes was closed, labeled, and dated 6/09/04. A spill kit is located nearby.

-3

·	:					
	4, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,					

The main indoor 90 day storage area lies to the east of the sheet molding compound area and the bulk molding compound area. Sheet molding compound is used for compression molds, whereas bulk molding compound is generally used for injection molding. An emergency containment cabinet is located by the 90 day area in which a drum in distress may be placed and a fire suppressant from the vehicle mentioned previously may be pumped in to diminish the ignitability hazard. At the time of the inspection, 10 drums were in the area. One drum of waste resin with debris was positioned in the compactor and was dated 6/09/04. Two drums contained non-hazardous materials: waste thickener, dated 6/03/04, and used oil. All seven other drums were labeled with a description of the waste and the words "Hazardous Waste," closed, and dated within 90 days of the inspection. Inspections are performed weekly on all drums in the facility. Spill kits are located nearby.

South of the 90 day area is a quality control (QC) lab. Lab pack waste is kept in a drum that is removed every 90 days. Most waste is produced from glass washing with a solvent called ES 2-173. Prior practice involved using a giant bath bin for washing, which has now been reduced to individual covered washing units in order to reduce air emissions.

The pipe and pump cleaning room is behind (east of) the main 90 day storage area. Pipes and pumps are disassembled from the process machinery when colors and paste consistencies change between different products. The equipment is then rinsed in parts washers using either SP-298 or ethyl acetate. SP-298 waste can be disposed of as non-hazardous waste because of its high flash point. The two solvent wastes are kept in separate drums, but are accidentally mixed at times.

In the bulk molding compound area, two satellite drums are labeled and closed. The mixers and extruders in the area are all covered under air permits.

To the east of the building is an outdoor 90 day storage shed. This shed houses the polymerization waste treatment units, and the drums which contained the polymerized material. Forty-eight drums of non-hazardous polymerized material were being held in the shed at the time of the inspection. A housekeeping station with brooms and shovels is located on the back wall of the shed along with spill kits. Nine drums of hazardous waste were also in this shelter. Seven drums contained cleanup material from a vinyl toluene spill and were dated from 5/04/04. Two other drums, one labeled as waste hydranol (sp?), and the other as waste pyridine, were closed and dated from 4/05/04.

On the northeast end of the property is a separate brick building that contains organic peroxides. As strong oxidizers, the materials are kept at a distance from the facility.

In the supply area, Ms. Coltman explained that the special drums in which pigment is received, are now being replaced by uncertified drums that can be reused for waste right away. Premix saves some resources by reusing these drums rather than reconditioning the old ones or buying new ones for waste.

The inspection tour concluded at this time.

### 40 CFR § 265 Subparts AA, BB, and CC

This facility is exempt from RCRA air emissions regulations of 40 CFR § 265, Subparts AA, and BB. Subpart AA does not apply because the facility does not have any process vents associated with distillation, fractionation, thin film evaporation, solvent extraction, or air stripping units. Subpart BB is not applicable because the facility does not have equipment (pumps, compressors, pressure release devices, sampling connections, open-ended valves and lines, valves, flanges or connectors) associated with units as delineated in 40 CFR § 265.1050(b)(1)-(3). Subpart CC does apply to this generator. All containers in 90 day storage areas, however, were properly closed and inspected.

0	INTERIM STATUS FACILITIES ORGANIC AIR EMISSION STANDARDS FOR PROCESS VENTS	AA
acility's Name PREMIX	•	
6-10-04	1D# OHD 004 200 644	
stripping operations managing haza ote: Total Organic Emissions shall be a	means process vents associated with distillation, fractionation, thin-film evaporation, solver ardous waste with organic concentrations of at least 10 ppmw (time weight annual average abbreviated to TOE	nt extraction or air or steam basis).
- DO NOT HOUS POOL	NI - not inspected N/A - not applicable	
- DO NOT HAVE PROC ASSOCIATED WITH .	THE ABOVE.	YES NO NI N/A
	APPLICABILITY (40 CFR 265.1030)	
Manage hazardous waste w/ organ	nic concentrations of at least 10 ppmw in units w/ process vents? (265.1030(b)) QAE	No
THE STREET AND ASSESSMENT OF THE STREET ASSESS	IF YES	
a) Are the units subject to the pe	emitting requirements under part 270? (265.1030(b)(1)) DAE	. *
	OR	
h) Ara there hazardous waste re	ecycling units with process vents that are located at the facility that is otherwise subject to	
the permitting requirements?		*
* If the answers to the above question 40 CFR 265.1034(d) and 40 CFR 2	ns is $\underline{no}$ the following regulations do not apply, except you must verify the facility waste h 265.1034(e) and this information must be recorded in a log: 40 CFR 265.1035(f).	as less than 10 ppmw: see
Note: A determination of vent emissi requirements of 265.1034(c).	STANDARDS: PROCESS VENTS (40 CFR 265.1032) ions may be based on engineering calculations or tests (265.1032(c)) with any performance	tests meeting the
2. Has the owner/operator of a faci	lity with process vents:	
a) Reduced TOE from all affect	ted process vents < 1.4 kg/h (3 lb/h) & 2.8 mg/yr (3.1 tons/yr)? (265.1032(a)(1)) DAI	E NI N/A
	OR	
b) Reduced, by use of a control by 95 weight percent? (265.	device (that meets the requirements of 265.1033) the TOE from all affected process vents 1032(a)(2))  DAT	
Note: If the process vents emit below	the limits with out an add-on control device the facility the only additional requirement is	; 265.1035(f)
STANDARDS	: CLOSED-VENT SYSTEMS AND CONTROL DEVICES (40 CFR 26	5.1033)
	ontrol device installed by 12/21/90 or as per an implementation schedule with a completion later than June 21, 1992? (265.1033(a)(2))	
4. If the owner/operator has install	led a closed-vent system and control device by their effective date, was: (265.1033(a)(1))	
a) Control device involving va 95 weight percent or greater less than 95 weight percent?	por recovery designed/operated to recover organic vapors vented to it w/ an efficiency of r? (265.1033(b)) (N/A if TOE for all affected process vents can be attained at an efficiency DA	
······································	designed and operated to reduce organic emissions vented to it by 95 weight percent or gr	reater to: (265.1033(c))
Achieve a total organic co	ompound concentration of 20 ppmv?. DA	E [] NI N/A
	OR	
ii) Provide minimum reside	ent time of 0.50 seconds at minimum temp. of 760 degrees C? (265.1033(c)) DA	E [] NI N/A
c) A flare:		1
	to visible emissions except periods not to exceed total of 5 minutes during any 2 5.1033(d)(1))	E [] NI N/A
	esent at all times? (265.1033(d)(2)) DA	E [] NIN/A

Air	Emission	Standards	tor	Process	Vents

		YES NO NI N/A
iii) Used only if: (265.1033(d)(3))	فليرــــــ	
a) Net heating value of gas being combusted is $\geq$ 300 Btu/scf if flare is steam or air assisted?	DAE	[] NI N/A
OR		
b) If the net heating value of the gas being combusted is 200 Btu/scf. or greater if the flare is non-assisted?	DAE	[] NI N/A
d) Was the steam-assisted or non-assisted flare designed and operated with an exit velocity: (265.1033(d)(4)(I-iii))		
I) Less than 60 ft/s? Except if,	DAE	[] NI N/A
ii) $\geq$ 60 ft/s but < 400 ft/s? (Only allowed if net heating value of gas is greater than 1000 Btu/scf)	DAE	[] NI N/A
iii) Less than the velocity, Vmax and less than 400 ft/s?	DAE	[] NI N/A
e) Was air-assisted flare designed and operated with an exit velocity less than the velocity Vmax? (265.1033(d)(5))	DE	[] NI N/A
Note: The formulas needed to determine #4.d & #4.e. are found in 265.1033(e)(2-5).	1	1
f) For a flare was:	F	
I) Method 22 used to determine compliance with visible emissions? (265.1033(e)(1))	Dag	co rep. said [] NI N/A
ii) The net heating value of the gas being combusted calculated correctly? (265.1033(e)(2))	DAR	co rep. said
iii) The actual exit velocity correctly determined? (265.1033(e)(3))	DAE	co rep. said
iv) The maximum allowed velocity calculated correctly? (265.1033(e)(4))	DAE	co rep. said
v) The maximum allowed velocity for air assisted flare calculated correctly? (265.1033(e)(5))	DAE	co rep. said [] NI N/A
5. Did the owner/operator monitor and inspect each control device required to ensure proper operation and maintenance b	y: (26	5.1033(f)(1))
a) Installing/calibrating/maintaining/operating flow indicator w/ record of vent stream flow at least once per hour?	DAE	[] NI N/A
b) Installing/calibrating/maintaining/operating device to continuously monitor control devices as specified below: (2)	265.103	33(f)(2))
Thermal vapor incinerator, a temperature monitoring device equipped with a continuous recorder?	DAE	[] NI N/A
ii) Catalytic vapor incinerator, a temperature monitoring device equipped with a continuous recorder?	DAE	[] NI N/A
iii) Flare/heat sensing monitoring device have a continuous recorder giving continuous ignition pilot flame?	DAE	[] NI N/A
iv) Boiler/process heater w/ design heat input capacity < 44MW, a temp. monitoring device w/ a continuous recorder?	DAE	[] NI N/A
v) Boiler/process heater w/ design heat input capacity ≥ 44MW, a monitoring device w/ a continuous recorder to measure parameter(s) that indicates good combustion operating practices?	DAE	[] NI N/A
vi) For a condenser, either: (265.1033(f)(2)(vi))		
a) Monitoring device w/ continuous recorder for concentration of organic compounds in exhaust vent stream?	DAE	[] NI N/A
OR .		
b) A temperature monitor device equipped with continuous recorder?	DAE	[] NI N/A
vii) A carbon adsorption system that regenerates the carbon bed directly in the control device, either: (265.1033(f)	(2)(vi)	
a) Monitoring device w/ continuous recorder for concentration of organic compounds in exhaust vent stream?	DAE	[] NI N/A

OR

2



Air Emission Standards for Process Vents

A		YES N	O NI N/A
b) Monitor device w/ continuous recorder to measure parameter that indicates the carbon bed is regenerated or regular predetermined time cycle?	n a DAE:		NI N/A
AND			u
c) Replaces existing carbon w/ fresh at pre-set interval no longer than carbon service life? (265.1033(g))	DAE	[]_	ni n/a
viii) If using a carbon adsorption system that does not regenerate carbon bed on-site in the control device, the exist fresh carbon on a regular basis by either: (265.1033(h)(1-2))	sting carb	on will l	ne replaced w/
a) Monitoring the concentration level of the organic compounds regularly and replace the carbon with fresh in	mmediate	ly after	break-through?
l) Monitoring daily?	DÆ	U_	NI N/A
ii) Monitoring at interval no greater than 20% of time required to consume total carbon working capacity?	DAG	U	NI N/A
b) Replace the existing carbon with fresh at regular, predetermined intervals?		U	NI N/A
<ul> <li>Inspecting readings from (except 265.1033(h)) monitoring device(s) at least once each operating day? (265.1033(f)(3))</li> </ul>	DAB		NI N/A
AND			
d) If needed, implement necessary corrective measures to ensure control devices work? (265.1033(f)(3))	TMAG		NI N/A
Note: An alternative operational or process parameter may be monitored see 40 CFR 265.1033(I).	and the second s		
6. The closed-vent system(s):			
a) Was it designed for and operated with no visible emissions? (265.1033(j)(1))	DAE.		NI N/A
b) Have initial leak detection monitoring conducted: (265.1033(j)(2))			
By date facility becomes subject to these regulations?	DAB		NI N/A
ii) Annually thereafter?	DAS		NI N/A
c) Control detectable emissions (>500 ppm) as soon as possible but: (265.1033(j)(3-4))			
No later than 15 calendar days after detected?	DAE		NI N/A
ii) First attempt at repair made no later than 5 calendar days after detection?	DAE		NI N/A
7. Were closed-vent systems and control devices operated at all times when emissions may be vented to them? (265.1033(k))	DAS	co. r	ep said NI_N/A
			-
TEST METHODS AND PROCEDURE (40 CFR 265.1034)			
8. Were correct test methods and procedures used? (265.1034(a))		<del></del>	
a) For a closed-vent system tested for no detectable emissions? (265.1034(b)(1-7))	DAE	10	NI N/A
b) To determine compliance with the 10 ppmw and with the total organic compound limit (95%)? (265.1034(c))	DAB		NI N/A
9. Did the facility determine that the process vents are not subject to the requirements of this subpart? If so, did the determination that the time-weighted annual average total organic concentration managed by the unit is less than 10	owner/op 0 ppmw l	erator m	ake an initial .1034(d))
a) Direct measurement? (265.1034(d)(1))	DAE	<u> </u>	NI N/A
b) Using knowledge? (265.1034(d)(2))	DAE		NI N/A
10. Was the determination that distillation, fractionation, thin-film evaporation, solvent extraction or air or stream stri	pping op 4(e))	erations	manage hazardous
wastes time-weighted annual average total organic concentration is less than 10 ppmw made as follows: (265.103			
wastes time-weighted annual average total organic concentration is less than 10 ppmw made as follows: (265.103  ) By date the facility is first subject to the regulations or the date the waste is first managed, whichever is first?	DAE		NI N/A

Air Emission Standards for Process Vents

YES NO NI N/A


OR

c) \	When there is change in way waste being managed or in the process that generates the waste	? (265.1034(e)(3))	DAB	r 1	NI N/A
		. (====================================			

# RECORDKEEPING REQUIREMENTS (40 CFR 265.1035)

Note: If there is more than one managed unit the facility can use one recordkeeping system. (265.111035(a)(2))		
11. Did the owner/operator record the following information in the facility operating record: (265.1035(b))		
a) The schedule and the rational, if the facility needed to develop an implementation schedule? (265.1035(b)(1)) DAE		NI N/A
b) Up-to-date process vent documentation?		
I) Information & data: (265.1035(b)(2)(I))		
a) Identifying all effected process vents?	Li_	NI N/A
b) Annual throughput and operating hours of each effected unit?		NI N/A
c) Estimated emission rates for each effected vent & for overall facility?	L)	NI N/A
d) Location of each effected vent on plot plan?	U	NI N/A
ii) Information and data supporting determinations of vent emissions and emission reductions achieved by add-on control devices based on engineering calculations or source tests? (265.1035(b)(2)(ii))		NI N/A
<ul> <li>c) If tests were used to determine organic removal efficiency or total organic compound concentration was there a perform include: (265.1035(b)(3)(ii)(A-E))</li> </ul>	ance test j	plan, which
Engineering description of closed vent system and control device including:		
a) Manufacture name and model #?	lu_	NI N/A
b) Type of control device?	Ü	NI N/A
c) Dimensions?	IJ	NI N/A
d) Capacity?		NI N/A
e) Construction materials?		NI N/A
ii) Description of sampling and monitoring procedures, including: (265.1035(b)(3)(iii))		,
a) Location?		NI N/A
b) Equipment?	lu_	NI N/A
c) Frequency?	L)	NI N/A
d) Procedures?	U_	NI N/A
d) Documentation on the closed-vent systems and the coatrol devices required in 265.1033, specifically: (265.1035(b)(4))	)	
I) List of all information, references and sources used to prepare documentation? (265.1035(b)(4)(l)) DAE		NI N/A
ii) Records with dates of compliance tests?	U_	NI N/A
iii) Engineering calculations for design analysis/specifications/drawings/schematics/piping/instrument diagrams include	: (265.103	35(b)(4)(iii))
a) Thermal vapor incinerators, consider vent stream composition/constituent composition/flow rate. Included design minimum, average temperature & residence time in the combustion zone? (265.1035(b)(4)(iii)(A)) DAB		NI N/A
b) Catalytic vapor incinerators, consider vent stream composition/constituent composition/flow rate. Include design minimum & average temperature across the catalyst bed inlet and outlet? (265.1035(b)(4)(iii)(B))  DAE		NI N/A
c) Boiler or process heater, consider vent stream composition/constituent composition/flow rate. Include design minimum & average flame zone temperatures, combustion zone residence time & where vent system is	*	
		NI N/A
d) Flare, consider vent stream composition/constituent composition/flow rate. Design analysis requirements are in 265.1033(d)? (265.1035(b)(4)(iii)(D)) DAE	1	NI N/A







INTERIM DIAIOD FACILITED AND FULLE REGULATED GENERATOR

	12	The state of the s		7
		YES NO	N IN C	I/A
b) It operates with no detectable emissions as indicated w/ emission reading of < 500 ppm. (265.1052(e)(2))	DAE		NI N	I/A
c) Is tested for compliance initially, annually and when requested by Regional Administrator. (265.1052(e)(3))	DAE		ИІИ	1/A
4. Is the pump equipped with a closed-vent system capable of capturing and transporting any leakage from seal(s) to the control device? If yes, the pump is exempt from monthly monitoring (#5), visual monitoring (#6), repairs (#7a & #7b barrier fluid system (#2) and no detectible emission (#3). (265.1052(f))	)), D <u>a</u> e		_ NI I	A/A
5. Is each pump in light liquid service monitored monthly to detect leaks? (265.1052(a)(1))	D&G	U	·NII	N/A
<ol> <li>Does each pump in light liquid service have a visual inspection each calendar week for indications of liquid dripping? (265.1052(a)(2))</li> </ol>	Dist	(J	NI I	N/A
7. Was an instrument reading of 10,000 ppm or greater measured or were there are any indications of liquids dripping fithe pump seal? If yes, a leak is detected and:	rom		NI_	N/A
a) Was it repaired as soon as practicable but no later than 15 calendar days after detected? (265.1052(c)(1))		U_	NI	N/A
b) Was a first attempt at repair made no later than 5 calendar days after leak is detected? (265.1052(c)(2))	DES	<u>l·u    </u>	NI	N/A
STANDARDS: COMPRESSORS (40 CFR 265.1053)  NOTE: Delays in repair are allowed see 265.1059 (#37)	ÿ			
8. Is the compressor designed as described in 265.1064(g)(2), for no detectable emissions indicated by instrument readin < 500 ppm above background? If yes the compressor is exempt from seal system and operation (#10-11), barrier flu concentration (#12), barrier system sensor(#13-14), criteria for failure (#15), leak detection/repair (#16) and closed-v (#9). (265.1053(l))	id		·	N/A
			141	INIA.
<ol> <li>Is the compressor equipped with a closed-vent system capable of capturing and transporting leakage from the scal(s) to control device in compliance w/ 265.1060? If yes, the compressor is exempt from scal system (#10) and scal system operation (#11). (265.1053(h))</li> </ol>			NI	N/A
10. Each compressor equipped w/ seal system that has barrier fluid system that prevents leakage of TOE? (265.1053(a))			NI	N/A
11. Is each compressor seal system: (265.1053(b))				
a) Operated with the barriers fluid at a greater pressure than the stuffing box pressure? (265.1053(b)(1))	DAE	<u>lu</u>	NI	N/A
OR				
b) Equipped with a barrier fluid system connected by a closed-vent system to a control device? (265.1053(b)(2))	Wa.		М	N/A
OR				
c) Equipped with a system that purges the barrier fluid system with no detectable emissions? (265.1053(b)(3))	MG.		NI	N/A
12. Is the barrier fluid system a hazardous waste w/ an organic concentration of 10% or greater by weight? (265.1053(c)	) Des		] NI	N/A
13. Each barrier system equipped w/ a sensor to detect failure of the seal/barrier fluid system? (265.1053(d))	DAS		NI	N/A
14. Is each barrier system sensor checked: (265.1053(e)(1))				
a) Daily?	DAB	Lu	NI	N/A
OR				
b) Equipped with audible alarm that is checked monthly to see if working?	DAE	lu	NI	N/A
UNLESS		20 ml . 200		o <del>r Tymail</del> i
c) The compressor is located at an unmanned plant then is the sensor checked daily?	DAE	<sub>[]</sub>	NI	N/A
15. Has the owner/operator determined a criterion to indicate failure of the seal/barrier fluid system? (265.1053(e)(2))	DAE	Tri	NI	
16. Did the sensor indicates failure of the scaling fail and 20.5 for a 1.1 for 10.5 for	* ×	1	- 14 - 17	<u></u>

Ais Emission Standards for Equipment Leaks		
	YES NO	NI N/A
a) Was it repaired as soon as practicable but no later than 15 calendar days after detected? (265.1052(g)(1)) DAE		NI N/A
b) Was a first attempt at repair was made no later than 5 calendar days after leak is detected? (265.1052(g)(2))  DAE		NI N/A
STANDARDS: PRESSURE RELIEF DEVICES IN GAS/VAPOR SERVICE (40 CFR 26 NOTE: Delays in repair are allowed see 265.1059 (#37)	5.1054)	The second secon
17. Is the pressure relief device equipped with a closed-vent system capable of capturing and transporting leakage to a control devices specified in 265.1060? If yes, the device is exempt from relief device monitored for no detectable emissions (#18), specifications to reset device and time frame (#19 & #20). (265.1054(c))		NI N/A
18. Pressure relief devices in gas/vapor service operated w/ no detectable emissions indicated by an instrument reading of <500 ppm above background, except during pressure releases? (265.1054(a))		NI N/A
19. After a pressure release, was the device returned to a condition of no detectable emissions indicated by an instrument reading of < 500 ppm above background, as soon as practical but no later than 5 calendar days? (265.1054(b)(1))		NI N/A
20. No later than 5 calendar days after a pressure release, is the pressure relief device monitored to confirm no detectable emissions indicated by an instrument reading of < 500 ppm above background,? (265.1054(b)(2))	<u>Li</u>	NI N/A
STANDARDS: SAMPLING CONNECTING SYSTEMS (40 CFR 265.1055)		AACTON TO THE TOTAL THE TOTAL TO AL TO THE T
21. Is the sampling system in situ? If yes, the system isn't required to have closed-vent or closed-purge system (#22 & #23).  (265.1055(c))		NI N/A
22. Is each sampling connection system equipped with a closed-purge system or closed-vent system? (265.1055(a))		NI N/A
23. Does each closed-purge or closed-vent system: (265.1055(b))		
a) Return purged hazardous waste stream directly to hazardous waste management process line w/ no detectable emissions? (265.1055(b)(1))		NI N/A
OR		-
b) Collect and recycle the purged hazardous waste stream with no detectable emissions? (265.1055(b)(2))	<u>lu</u>	NI N/A
OR		
c) Designed/operated to capture/transport all purged hazardous waste stream to a control device? (265.1055(b)(3))		NI N/A
STANDARDS: OPEN-ENDED VALVES OR LINES (40 CFR 265.1056)  Note: Delays in repair are allowed see 265.1059 (#37)  Note: Did the owner/operator subject to the provisions of this subpart comply with the required test methods and procedures:	(265.1063(	b-I)) (#41)
24. Is each open-ended valve or line equipped with a cap, blind flange, plug or second valve? (265.1056(a)(1))		NI N/A
25. Cap/blind flange/plug/second valve always seal open end except when waste must flow through? (265.1056(a)(2))		NI N/A
26. If using a second valve, is the first valve closed before the second? (265.1056(b))		NI N/A
27. If a double block and bleed system is used and the bleed line/valve stays open during venting, is the line between the bloc valves have cap/blind flange/plug/second value and sealed at all other times? (265.1056(c))		NI N/A
STANDARDS: VALVES IN GAS/VAPOR SERVICE OR IN LIGHT LIQUID SERVICE (44 Note: There are alternate standards for valves in gas/vapor or light liquid service where owners/operators may elect to have a waste management unit comply with alternative standards which: (1) allows no greater than 2% of the valves to leak. allows for skip period leak detection and repair. (265.1062(a-b))  Note: Delays in repair are allowed see 265.1059 (#37)	l valves wit	hin a hazardous

Valve designated as an unsafe-to-monitor valve as described in 265.1064(h)(1). If yes, the valve is exempt from monthly monitoring (#31) if: (265.1057(g))

NI N/A

	•	YES NO	NI N/A	
<ul> <li>a) The owner/operator of the valve determines that the valve would be unsafe to monitor because monitoring person would be exposed to an immediate danger. (265.1057(g)(1))</li> </ul>	onnel DAE		NI N/A	
<ul> <li>The owner/operator of the valve adheres to a written plan that requires monitoring of the valve as often as poss during safe-to-monitor times. (265.1057(g)(2))</li> </ul>	ible D&R	<u> </u>	A\N IN	
29. Valve designated as a difficult to-monitor valve in 265.1064(h)(2). If yes, the valve is exempt from monthly monitor (#31) if: (265.1057(h))	oring	magada milika muraja aaram	NI N/A	A_
<ul> <li>a) The owner/operator of the valve determines the valve cannot be monitored without elevating personnel more the meters above a support surface. (265.1057(h)(1))</li> </ul>	an 2		NI N/A	
b) Hazardous waste management unit where valve is located was in operation before 6/21/90. (265.1057(h)(2))	u.o		NI N/A	
c) Follow written plan that requires monitoring of valve at least once per calendar year. (265.1057(h)(3))		U	NI N/A	`
30. Valve designated for no detectable emissions, as indicated bt instrument reading of < 500 ppm above background, described in 265.1064(g)(2). If yes, the valve is exempt from monthly monitoring (#31) if: (265.1057(f))	and		NI N/	Α
a) It has no external actuating mechanism in contact with the hazardous waste streams. (265.1057(f)(1))		L)	NI N/A	4.
b) It is operated with emissions < 500 ppm above background. (265.1057(f)(2))	<b>4</b>	[]	NI N/A	A
c) It is tested for emissions initially and then annually. (265.1057(f)(3))			NI N/A	<u>A</u>
31. Is each valve, other than unsafe or difficult-to-monitor or no detectible emissions (#28-30), in gas/vapor or light service monitored monthly for leaks? (265.1057(a)) (exemptions 33 & 34)	iquid		NI N/A	A
OR				
32. Any valve for which a leak has not been detected for two successive months may be monitored the first month of succeeding quarter, until a leak is detected? (265.1057(c)(1))	ечегу		NI N//	A
AND				
AND  33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was no detected for 2 consecutive months? (265.1057(c)(2))	ot sas		NI N/A	Ά
33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was no			NI N//	'A
33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was no detected for 2 consecutive months? (265.1057(c)(2))			NI N//	
<ul> <li>33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was no detected for 2 consecutive months? (265.1057(c)(2))</li> <li>34. When a leak is detected, by an instrument reading of 10,000 ppm or greater: (265.1057(b)): (265.1057(d)(1))</li> </ul>				Ά_
<ul> <li>33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was no detected for 2 consecutive months? (265.1057(c)(2))</li> <li>34. When a leak is detected, by an instrument reading of 10,000 ppm or greater: (265.1057(b)): (265.1057(d)(1))</li> <li>a) Was it repaired as soon as practicable but not later than 15 calendar days after detected? (265.1052(d)(1))</li> </ul>			NI N//	Ά_
<ul> <li>33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was no detected for 2 consecutive months? (265.1057(c)(2))</li> <li>34. When a leak is detected, by an instrument reading of 10,000 ppm or greater: (265.1057(b)): (265.1057(d)(1))</li> <li>a) Was it repaired as soon as practicable but not later than 15 calendar days after detected? (265.1052(d)(1))</li> <li>b) Was a first attempt at repair made no later than 5 calendar days after leak is detected? (265.1052(d)(2))</li> </ul>			NI N//	'A 'A
<ul> <li>33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was need detected for 2 consecutive months? (265.1057(c)(2))</li> <li>34. When a leak is detected, by an instrument reading of 10,000 ppm or greater: (265.1057(b)): (265.1057(d)(1))</li> <li>a) Was it repaired as soon as practicable but not later than 15 calendar days after detected? (265.1052(d)(1))</li> <li>b) Was a first attempt at repair made no later than 5 calendar days after leak is detected? (265.1052(d)(2))</li> <li>c) Was the first repair attempt include, but not limited to: (265.1057(e))</li> </ul>	5445 5462		NI N//	A A
<ul> <li>33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was no detected for 2 consecutive months? (265.1057(c)(2))</li> <li>34. When a leak is detected, by an instrument reading of 10,000 ppm or greater: (265.1057(b)): (265.1057(d)(1))</li> <li>a) Was it repaired as soon as practicable but not later than 15 calendar days after detected? (265.1052(d)(1))</li> <li>b) Was a first attempt at repair made no later than 5 calendar days after leak is detected? (265.1052(d)(2))</li> <li>c) Was the first repair attempt include, but not limited to: (265.1057(e))</li> <li>l) Tightening of bonnet bolts?</li> </ul>	E43		NI N//	A A
<ul> <li>33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was no detected for 2 consecutive months? (265.1057(c)(2))</li> <li>34. When a leak is detected, by an instrument reading of 10,000 ppm or greater: (265.1057(b)): (265.1057(d)(1))</li> <li>a) Was it repaired as soon as practicable but not later than 15 calendar days after detected? (265.1052(d)(1))</li> <li>b) Was a first attempt at repair made no later than 5 calendar days after leak is detected? (265.1052(d)(2))</li> <li>c) Was the first repair attempt include, but not limited to: (265.1057(e))</li> <li>l) Tightening of bonnet bolts?</li> <li>ii) Replacement of bonnet bolts?</li> </ul>	E43		NI N/A NI N/A NI N/A	A A A
<ul> <li>33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was no detected for 2 consecutive months? (265.1057(c)(2))</li> <li>34. When a leak is detected, by an instrument reading of 10,000 ppm or greater: (265.1057(b)): (265.1057(d)(1))</li> <li>a) Was it repaired as soon as practicable but not later than 15 calendar days after detected? (265.1052(d)(1))</li> <li>b) Was a first attempt at repair made no later than 5 calendar days after leak is detected? (265.1052(d)(2))</li> <li>c) Was the first repair attempt include, but not limited to: (265.1057(e))</li> <li>l) Tightening of bonnet bolts?</li> <li>iii) Replacement of bonnet bolts?</li> <li>iiii) Tightening of packing gland nuts?</li> </ul>	EAS	U U U U	NI N// NI N// NI N// NI N// NI N// NI N//	'A 'A 'A
33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was no detected for 2 consecutive months? (265.1057(c)(2))  34. When a leak is detected, by an instrument reading of 10,000 ppm or greater: (265.1057(b)): (265.1057(d)(1))  a) Was it repaired as soon as practicable but not later than 15 calendar days after detected? (265.1052(d)(1))  b) Was a first attempt at repair made no later than 5 calendar days after leak is detected? (265.1052(d)(2))  c) Was the first repair attempt include, but not limited to: (265.1057(e))  l) Tightening of bonnet bolts?  ii) Replacement of bonnet bolts?  iv) Injection of lubricant into lubricating packing?  STANDARDS: PUMPS AND VALVES IN HEAVY LIQUID SERVICE, PRESSURE RELATION OR HEAVY LIQUID SERVICE AND FLANGES AND OTHER CONNECTOR	EAS EAS EAS EAS (40 and other	U U U U	NI N// NI N// NI N// NI N// NI N// NI N//	A A A A A A A A A A A A A A A A A A A
33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was redetected for 2 consecutive months? (265.1057(c)(2))  34. When a leak is detected, by an instrument reading of 10,000 ppm or greater: (265.1057(b)): (265.1057(d)(1))  a) Was it repaired as soon as practicable but not later than 15 calendar days after detected? (265.1052(d)(1))  b) Was a first attempt at repair made no later than 5 calendar days after leak is detected? (265.1052(d)(2))  c) Was the first repair attempt include, but not limited to: (265.1057(e))  l) Tightening of bonnet bolts?  ii) Replacement of bonnet bolts?  iii) Tightening of packing gland nuts?  standards: PUMPS AND VALVES IN HEAVY LIQUID SERVICE, PRESSURE RELATIONATE: Delays in repair are allowed see 265.1059 (#37)  35. Are pumps and valves in heavy liquid service, pressure relief devices in light or heavy liquid service and flanges a connectors monitored within 5 days if evidence of a potential leak is found by visual, audible, olfactory or other decompositions.	EF DEV	U U U U VICES IP CFR 265	NI N// NI LIGHT 5.1058)	A A A A A A A A A A A A A A A A A A A
<ul> <li>33. If the monitoring was every quarter and a leak is detected was the monthly monitoring resumed until a leak was medetected for 2 consecutive months? (265.1057(c)(2))</li> <li>34. When a leak is detected, by an instrument reading of 10,000 ppm or greater: (265.1057(b)): (265.1057(d)(1))</li> <li>a) Was it repaired as soon as practicable but not later than 15 calendar days after detected? (265.1052(d)(1))</li> <li>b) Was a first attempt at repair made no later than 5 calendar days after leak is detected? (265.1052(d)(2))</li> <li>c) Was the first repair attempt include, but not limited to: (265.1057(e))</li> <li>l) Tightening of bonnet bolts?</li> <li>ii) Replacement of bonnet bolts?</li> <li>iii) Tightening of packing gland nuts?</li> <li>iv) Injection of lubricant into lubricating packing?</li> <li>STANDARDS: PUMPS AND VALVES IN HEAVY LIQUID SERVICE, PRESSURE RELL LIQUID OR HEAVY LIQUID SERVICE AND FLANGES AND OTHER CONNECTO NOTE: Delays in repair are allowed see 265.1059 (#37)</li> <li>35. Are pumps and valves in heavy liquid service, pressure relief devices in light or heavy liquid service and flanges a connectors monitored within 5 days if evidence of a potential leak is found by visual, audible, olfactory or other d method? (265.1058(a))</li> </ul>	EAS  EEF DEV RS (40)  und other etection  DES	U U U U VICES IP CFR 265	NI N//	A A A A A A A A A A A A A A A A A A A

		YES NO	O NI N/A				
c) Was the first repair attempt include, but not limited to: (265.1058(d))							
l) Tightening of bonnet bolts?	DAE		NI N/A				
ii) Replacement of bonnet bolts?	DAE	<u>U</u>	NI N/A				
iii) Tightening of packing gland nuts?	DAE		NI N/A				
iv) Injection of lubricant into lubricating packing?	Dae	LL_	AN IN				
STANDARDS: DELAY OF REPAIR (40 CFR 265.1059)		enting was a state of the state					
37. Was there a delay in repair of equipment for which leaks have been detected? If yes, the delay is allowed if:	DAS		NI N/A				
<ul> <li>a) Was the repair technically infeasible without a shutdown of the hazardous waste management unit and did the reposcur before the end of the next shutdown? (265.1059(a))</li> </ul>	air Dae		NI N/A				
<ul> <li>b) Was the equipment isolated from the hazardous waste management unit and the unit does not contain or contact hazardous waste with organic concentrations at least 10% by weight. (265.1059(b))</li> </ul>	DAE	<u> </u>	NI N/A				
38. Was there a delay in repair of a valve? If yes, the delay is allowed if:	DAE		NI N/A				
<ul> <li>a) Determine emissions from purged material from immediate repair are greater than emissions resulting from a determine repair. (265.1059(c)(1))</li> </ul>	lay of		NI N/A				
b) When repaired, the purged material is collected and destroyed or recovered in a control device. (265.1059(c)(2))	IN.		NI N/A				
39. Was there a delay in repair of a pump? If yes, the delay will be allowed if:			NI N/A				
a) Repair requires the use of a duel mechanical seal system that includes a barrier fluid system. (265.1059(d)(1))	DAR	<u>LU</u>	NI N/A				
b) Repair is completed as soon as practicable but within 6 months. (265.1059(d)(2))	DAE	U	NI N/A				
40. Was there a delay in repair of a valve beyond a hazardous waste management unit shutdown? If yes, the delay will allowed until the next shutdown or longer if the shutdown is within 6 months if: (265.1059(e))	be DAE		NI N/A				
a) The valve assembly replacement is necessary during shutdown.	DAE		NI N/A				
b) Valve assembly supplies have been depleted & supplies were sufficiently stocked before supplies were depleted.	DAE		NI N/A				
TEST METHODS AND PROCEDURES (40 CFR 265.1063)	and the state of		-				
41. Did the owner/operator subject to the provisions of this subpart comply with the required test methods and procedu	res: (2	65.1063(b	<b>⊢</b> Ī))				
a) For leak detection monitoring? (265.1063(b))	DA	U	NI N/A				
b) For 'no detectible' emissions determination? (265.1063(c))	DA		<u>'</u> NI N/A				
c) To determine if each piece of equipment contains or contacts a hazardous waste w/ organic concentrations > 1 weight? (265.1063(d))	0% by		NI N/A				
d) To determine if pumps or valves are in light liquid service? (265.1063(h))	DA	<u>U</u>	NI N/A				
e) To determine if the control device achieved 95 weight percent organic emissions? (265.1063(I))	DA		NI N/A				
42. Were samples used in determine the percent organic content representative of the highest TOC hazardous waste that	t is						

#### RECORDKEEPING REQUIREMENTS (40 CFR 265.1064)

Note: Owners/operators with more than one hazardous waste management unit, subject to these regulations, may use one recordkeeping system if each unit is identified.

expected to be contained in or contact the equipment? (265.1063(g))

Did the owners/operators record the following information in the operating record for each piece of equipment subject to Subpart BB? (265.1064(b))

NI N/A

DAE

			YES NO	NI N/A				
a) Equ	ipment identification number and hazardous waste management unit identification? (265.1064(b)(1)(l))	DAE	U	NI N/A				
b) Арр	orox. location(s) of the equipment (e.g., identify unit on facility plot plan)? (265.1064(b)(1)(ii))	DAE	<u>U</u>	NI N/A				
с) Тур	e of equipment (eg: pump or pipeline valve)? (265.1064(b)(1)(iii))	DAE	<u>f</u> 1	NI N/A				
d) Pen	cent-by-weight total organics in the hazardous waste stream at the equipment? (265, 1064(b)(1)(iv))	DAE	<u>[]</u>	NI N/A				
e) Stat	e of the hazardous waste at the equipment (eg: liquid or gas/vapor)? (265.1064(b)(1)(v))	DAB	U	NI N/A				
f) Me	thod-of compliance w/ the standard (monthly leak detection/repair or equipped w/ dual mechanical seals?	DAE	U	NI N/A				
g) Imp	olementation schedule, if facility can't install a closed-vent system & control device in time?(265.1064(b)(2))	DAB	U.	NI N/A				
	performance test plan if the owner/operator chose to use test data to demonstrate the organic removal efficiency of organic compound concentration by the control device? (265.1064(b)(3))	y or Dae	U_	NI N/A				
I) Inc	ude documentation of compliance with the closed-vent and control device standards? (265.1064(b)(4))	DAS	U	NI N/A				
j) Ifa	leak is detected?							
Ŋ	A weatherproof & readily visible identification attached to the leaking equipment and marked with: (265.1064(c)(1))							
a	The equipment i.d. number?	Dae	IJ	NI N/A				
ъ	) Date evidence of a potential leak was found?	DAY.	<u> </u>	NI N/A				
c	) Date leak was detected?			NI N/A				

Note: The identification on equipment, except a valve, may be removed after repair. (265.1064(c)(2))

Note: The identification on a valve may be removed after being monitored for two successive months without leaks. (265.1064(c)(3))

Note: The identification on a valve may be removed after being monitored for two successive months without leaks. (265)	. IOONC	<u> </u>	
ii) In an inspection log the following information? (265.1064(d))			
a) Instrument, operator and equipment id number? (265.1064(d)(1))	DAE	u_	NI N/A
b) Date evidence of a potential leak was found? (265.1064(d)(2))	DAB		NI N/A
c) Date leak was detected? (265.1064(d)(3))	DAE	U_	NI N/A
d) Date of each attempt to repair the leak? (265.1064(d)(3))	DAE	U_	NI N/A
e) Repair methods applied in each attempt to repair the leak? (265.1064(d)(4))	DAE	LU_	NI N/A
f) "Above 10,000" instrument readings? (265.1064(d)(5))	DAB		NI N/A
g) "Repair delayed" and the reason? (265.1064(d)(6))	DAB	Lu_	NI N/A
h) Documentation supporting delay in valve repair? (265.1064(d)(7))	DAE	U	NI N/A
Signature of owner/operator whose decision it was not to repair until shutdown? (265.1064(d)(8))	DAE	Lu_	NI N/A
j) If the repair is not done in 15 days the expected date of a successful repair? (265.1064(d)(9))	DAR	Lu_	NI N/A
k) The date of successful repair of the leak? (265.1064(d)(10)	DAE	U	NI N/A
iii) Up-to-date design documentation, monitoring, operating, inspection information for closed-vent & control de (265.1064(e))	vices?	U_	NI N/A
iv) Control device (other than thermal or catalytic vapor incinerator/flare/boiler/process heater/condenser/carbon adsorption system) have monitoring/inspection information indicating proper operation/maintenance of control device? (265.1064(f))	DAE		NI N/A
v) The following information regarding the equipment recorded in a log: (265.1064(g))			
<ul> <li>a) List of identification numbers for the equipment subject to the requirements and equipment designated for r detectable emissions? (265.164(g)(1)&amp;(2)(1))</li> </ul>	DAE		NI N/A
b) The designation of the equipment signed by the owner/operator? (265.1064(g)(2)(ii))	DAE		NI N/
c) List of identification numbers for pressure relief devices? (265.1064(g)(3))	DAĔ	U	NI N
d) For each compliance test:			
	DAE		NI N.

		YES NO	NI	N/A
1) Dates of each test? (265.1064(g)(4)(I))	DAE		NI	N/A
2) Background level measured during each test? (265.1064(g)(4)(ii))	DAE	<u>U                                    </u>	NI	N/A
3) The maximum instrument reading measured at the equipment during each test? (265.1064(g)(4)(iii))	DAB	<u> </u>	NI	N/A
e) List of all identification numbers for equipment in vacuum service? (265.1064(g)(5))	DAE	<u>U                                    </u>	NI	N/A.
<ul> <li>vi) A log with a list of identification numbers for the valves that are designated unsafe or difficult to monitor, an explanation stating why they are unsafe or difficult and the plan for monitoring? (265.1064(h)(1-2))</li> </ul>	DAE	<u>U</u>	NI	N/A
vii) For valves in gas/vapor or light liquid service with alternative standards the operating record will record: (26	5.1064	(I))		
a) A schedule of monitoring? (265.1064(I)(1))	DAYS	<u> </u>	NI	N/A
b) The percent of valves found leaking during each monitoring period? (265.1064(I)(2))	DAE		NI	N/A
viii) Is the following information shall be recorded in a log and kept in the operating record: (265.1064(j))				
a) Criteria for failure of seal system indicated by sensor used w/ light liquid service pumps? (265.1064(j)(1))	DAE	U_	NI	N/A
b) Criteria for failure of seal system indicated by sensor used w/ compressors? (265.1064(j)(1))	DAR	<u> </u>	NI	· N/A
c) Any changes to these criteria and the reason for change? (265.1064(j)(2))	PMI	<u>U</u>	NI	N/A
ix) The following information kept in a log and used to determine exemptions for the hazardous waste management	t unit:	(265.1064(	k))	
a) An analysis determining the design capacity of the management unit? (265.1064(k))	DAE	<u> </u>	NI	· N/A
<ul> <li>b) A statement listing the hazardous waste influent to and effluent from each unit and analysis determining where the waste is a heavy liquid? (265.1064(k)(2))</li> </ul>	nether	l O	NI	N/A
c) Up-to-date analysis/supporting data used to determine if equipment is subject to standards? (265.1064(k)(3	)) DIAB	LU	N	N/A
d) Documentation when knowledge of the hazardous waste stream or process is used? (265.1064(k)(3))	DAS	<u>Lo</u>	N	N/A
<ul> <li>e) Any new determinations if the owner/operator takes any action that could result in an increase of the organ content of the waste? (265.1064(k)(3))</li> </ul>	nic ÇAÇ	<u> </u>	N	I N/A
43. Are records of equipment leak information in 265.1064(d) and closed-vent and control device information in 265.1 kept 3 years? (265.1064(1))	064(e) Dae		N	I N/A

Comments:				_
Committeens.		 ······································	 -	 
	*			

# PREMIX - 6/10/04 OHD! OOY 200 044

#### Inspection Checklist for Subpart CC: Air Emission Standards (Containers)

Item# 40 CFR:

CC-1 265.1080 Do any of the following exclusions apply? If yes, please circle.

YES (

NO

Applicability: The air emission requirements apply to units subject to subpart I \* unless the following apply (circle if applicable):

- 1. Waste was placed in unit prior to Oct. 6, 1996, and none has been added since.
- 2. The container capacity is less than .1 cubic meter (26 gallons)
- 3. A unit (e.g. tank) has stopped adding waste and is undergoing closure
- 4. The unit is used solely for onsite treatment or storage as a result of remedial activities required under corrective action. Superfund, or other similar state program
- 5. The unit is used solely to manage radioactive mixed waste
- 6. The unit is regulated by and operates in accordance with Clean Air Act regulations
- \*Note: 1. Satellite containers are exempt 2. CESQG's and SQG's are exempt

CC-2 265.1083 Do any of the following exemptions apply? If yes, please circle

YES



General Standards: The owner/operator must control air emissions from waste management units except the unit is exempt if (please circle if applicable):

- 1. All hazardous waste entering the unit has an average VO concentration at the point of origination less than 500 parts per million by weight (waste determination required)
- 2. The organic content of all waste entering the unit has been reduced by one of the 8 acceptable destruction or removal processes.
- 3. The unit is a tank used for certain biological treatment
- 4. The hazardous waste placed in the unit meets the LDR numerical concentration limits or has been treated using the specified LDR treatment technology (for organics)
- 5. The unit is a tank used for bulk feed to an incinerator and meets certain requirements

#### CC-3 265.1084 Waste Determination

Determination
Not Needed

Defecciónación Needed

Was the VO concentration properly determined for each waste which the facility manages in a unit which does not meet Subpart CC requirements? The concentration must be determined by either direct measurement or knowledge. Please see 265.1084 for specific requirements for measurement and knowledge. Determination is <u>not</u> needed for waste managed in containers which meet standards. It may be necessary to evaluate container management prior to requiring VO concentration determination.

#	-In Compliance, DF=Deficiency	NA NI OK OF						
CONTAINER MANAGEMENT 265.1087								
Level 2 Level 3								
Larger than 26.4 gallons and less than or equal to 122 gallons, or larger than 122 gallons and do not manage H.W. in light material service	Larger than 122 gallons and manage H.W. "in light material service" (definition at 265.1081)	Larger than 26.4 gallons and treat H.W. by a stabilization process						
CC-4 265:1087 (OK) Con	trols							
One of the following:  -Use containers that meet DOT requirements  -Use a cover and control with no visible gaps, holes or other open spaces into the interior of the container  -Use organic vapor suppression on or above the container  265.1087(c)	One of the following:  -Use containers that meet DOT requirements  -Use containers that operate with no detectable emissions (method 21)  -Use containers that are demonstrated to be vapor-tight within the last 12 months (method 27)  265.1087(d)	-Containers used to stabilize H.W. with volatile organics greater than 500 ppm -For waste stabilized in a container either: 1.container must be vented directly to a control device; or 2.container is vented inside an enclosure which is exhausted through a closed vent to a control device -Conservation vents are not allowed 265.1087(b)(2)						

	Level 1	Level 2		
#, 2	NA=Not Applicable, NI=Not Inspected,			Level 3
CC-5		· · · · · · · · · · · · · · · · · · ·	NA .	NI OK DF
<u></u>	I south	ansfer requirements		
	transfer requirements apply	-Waste transfer requirements apply regardle of container alternative used in level 2 -Transfer waste into or out of a container in such a manner as to minimize exposure of the waste to the atmosphere. Acceptable method include a submerged fill pipe, vapor recover system, or fitted opening with a line purge 265.1087(b)(3)	e	able
CC-6	265.1087 Decrat	ing requirements (OK)		
2. betwee perform closed) 3. While 4. Consert Containers Safety val A cover ne	performing sampling and equipme vation and safety vents are allowed may be open while performing saves and conservation vents may be sed not to be on a RCRA empty conc.)(3), (d)(3)	e containers minutes between transfer (note: if the person the process shuts down, the container must be nt access d mpling or equipment access used if normally left in close position ntainer, as defined in 40 CFR 261.7	device, ther criteria that have closed -If an enclose meet the dispecified in Verification Total Enclose The contain	rs are directly vented to a contre are specific design and operarmust be met same as tanks that vent and control device system sure is used, the enclosure must lesign and operating criteria "Procedure T-Criteria for and of a Permanent or Temporary sure" under 40 CFR 52.741 er, enclosure, control device or system may have safety relief
e to care on	pection required:	requirements (OK)		
when facil f wastes ar inspection 55.1087(c)	ity accepts container and it is not e e stored greater than a year, then v is are required, facility must develo (4), (d)(4)	risually inspect once a year op written plan and schedule to perform inspection		quirements are the same as for
<b>中国共享的</b>				STATES
Do not us	4), (d)(4)	remove the container from service	immediately in	rective measures shall be implemented to ensure that the is operated in compliance
To have your executive selections	5:1090 Recordkeeping	requirements (NA)		
et DOT sta	exceeds 122 gallons and does not andards, records indicating that is not managing H.W. in light ce	Since Level 2 waste is "in light material service", no records need to be kept	-If an enclosur maintained for calculations an verify that the e a permanent tot -Records for the	how the organic emissions are re is used, records must be the most recent set of d measurements performed to enclosure meets the criteria of rai enclosure (Procedure T) the closed vent and control are the same for those used on (e)
anems:				· · · · · · · · · · · · · · · · · · ·

August 9, 1989

Ms Marion Tomazos Ohio EPA 2110 Aurora Road Twinsburg, Ohio 44087

SUBJECT:

Premix, Inc., OHD 004200044

(216) 224-2181

Dear Ms Tomazos:

In accordance with 40 CFR 265.56 (a-g7), Emergency Procedures, this is to further notify you that a reportable incident occurred at the Premix, Inc. Route 20 and Harmon Road facility located in North Kingsville, Ohio.

On July 27, 1989, at approximately 5:00 p.m., a fire occurred in the waste accumulation area. Within minutes, the North Kingsville Fire Department was notified and the facility was evacuated of all personnel. The flames were extinguished by 5:40 p.m. by using dry chemical extinguishers, with a foam blanket to cool the containers. By 6:14 p.m., the situation was completely under control. At 10:45 p.m., the fire department released the scene to Premix, Inc. personnel. No injuries were sustained.

The fire was determined to be caused by spontaneous combustion which initiated exothermic reactions among the S01 storage containers.

The accumulation area contained non-hazardous waste polyester paste; waste polyester resin (D001); waste combustible liquid (F002, F003, F005); and waste paint related materials (D001).

Four samples were pulled from the holding lagoon where the overflow of excess water was collected and submitted to Free-Col Laboratories for analysis the night of the incident. The morning following the incident, the trenches surrounding the accumulation did not contain any residue due to the evaporation of the foam.

On Monday, July 31, 1989, the clean-up operations were initiated. Waste that was not damaged due to the incident was separated and readied for disposal. On Wednesday, August 2, any combustible liquid waste was removed by Chemical Solvents, Inc. (OHD 980897656) for reclamation. Also on Wednesday, Sunrise Waste Transfer removed the non-hazardous polyester paste for disposal. On Thursday, August 3, Sunrise removed the remainder of the non-hazardous paste, and Ross Incineration Services (OHD 048415665) removed all the ignitable liquids for disposal. By Friday, August 4, the accumulation area was free of contamination and back to normal routine procedures.

No hazardous waste occurred outside of the accumulation area other than the smoke/vapor emissions that were generated during the incident.

Analysis of the water samples from the holding lagoon revealed results of less that 0.002 ppm of styrene monomer which is considered to be non-detectable. Styrene was the main component in the waste that was ignited during the incident.

Marion Tomazos Page Two August 9, 1989

also analyzed were components of the combustible liquid, acetone 7.00 ppm; 1,1,1 tricholorethane 2.5 ppm; MEK 2.10 ppm. All of which were below the TPQ, RQ and OSHA permissible exposure limits. All waste collected during decontamination was disposed of at a licensed RCRA facility.

Due to containment of the waste during the incident, coinciding with test results, it is believed that hazards to human health and the environment were nonexistent.

Sincerely.

PREMIX, INC.

Debra Parshall-Hall, CHMM

Environmental/Industrial Hygiene Coordinator

arshall-Hal

dg1

cc: Administrative Director
US EPA
Region 5

Region 5 230 South Dearborn Street Chicago, Illinois 60604

Mr. Allen Bowers North Kingsville Fire Department

Mr. Ford Davey Mr. Joe Moroski Mr. Ken Roxberry Premix, Inc.

Investigation Committee File

4 N, LB, II, I 53

**OhieEPA** 

State of Ohio Environmental Protection Agency

Northeast District Office 2110 E. Aurora Road Twinsburg, Ohio 44087-1969 (216) 425-9171 CE= 26-94; 2:8.7, 268.50



Richard F. Celeste Governor

December 10, 1987

RE: PREMIX

ASHTABULA COUNTY OHD 004-200-044 #02-04-0567 G-TSD

Premix
Debra Parshall-Hall
P. O. Box 281
N. Kingsville, Ohio 44068

Dear Ms. Parshall-Hall:

Thanks for your time and cooperation during my visit to Premix on December 8, 1987. During the inspection a few violations were noted. They are detailed below:

- 1. No weekly inspections were done in the month of October for the drums storage areas. This is a violation of 40 CFR 265.194 and OAC 3745-66-94. When this was bought to your attention during the inspection, you were made aware that the person assigned to do the inspections was off sick. Please train a back-up inspector or make other arrangements so this does not happen again.
- 2. Premix has not determined if their F-solvent waste exceeds the treatment standards, in accordance with 40 CFR 268.7(a)(1). Please test the wastes to determine the concentration of the F-solvent wastes.
- 3. The containers which store the F-solvent waste were not labeled nor was the accumulation on the container. (40 CFR 268.50) Please label these waste containers.

Also, please submit to this office and the Central Office a copy of your closure plan for your storage pad as soon as it is complete. If you have any questions, please give me a call. Thanks for your time.

Sincerely,

Teresa Sabol

Environmental Engineer

Division of Solid and Hazardous Waste

Management

TS/sp

cc: Dave Sholtis, DSHWM, Central Office

Debby Berg, DSHWM, NEDO

Enclosure

# Date and Time of Inspection

		HWFAB # 62 04 656
		U.S. EPA I.D. # OHDOOTZOCKAT
GENERAL INFORMATION	Address: Route 20 4 Harma	
Facility: <u>Premix</u>	Address: Poste 20 4 170 me	•
State: Ohio	Itp Code: 41068 County: Ashtabula	
	INSPECTION PARTICIPANT(S)	(Telephone)
(Name)	(Title)	
1. Debra Hall	Environmental Coordin	1815 - DZZ 912
2.		
2		
	. INSPECTOR(S)	
1. Teresa Sabol	Environmental En	aineer 216 425-9171
2.		
3.	INSTALLATION ACTIVITY	ą į
Mark One	If the site is a TSDF, check the boxes in	dicating which areas were reviewed.
	General Facility Standards, Prepare	dness / / Waste Piles SO3
Generator only (G)	and Prevention, Contingency and Eme	rnency
/ / Transporter (T)	Manifests/Records/Reporting, Closur	e /_/ Land Treatment DB1
/ / TSDF only	Containers SO1	/_/ Landfills D80
	/_/ Tanks S02/T01	/ / Chemical/Physical/ Biological TO4
√√ G-TSDF	Surface Impoundments S04/T02	/ / Groundwater Monitoring
	/_/ Incineration/Thermal Treatment	/ / Post-Closure
G-T-TSDF	, ·	

		<u>Yes</u>	<u>No</u>	N/A	<u>Remark #</u>
		/		<del></del>	
1.	Has the facility submitted a Part A to Ohio?				·
2.	If "yes", is it complete and accurate?		<del></del>		
3.	Has the facility submitted a Part B?				
	Was advance notice of the inspection given? If so, how far in advance?	1	******	<del></del>	Zweek
	IF THE SITE HAS RECEIVED A PART B PERMIT, USE THE RCRA STATUS INSPECTION FORM.				

REMARKS. GENERAL INFORMATION
Include a brief description of site activity and waste handling.

40	<u>CFR 265 (OAC 3745-65-et seq.) GENERAL INTERIM STATUS REQUIREMENTS AND TSD REQUIREME</u>	NTS	•		I
		Yes	No	N/A	Remark #
	Subpart B: General Facility Standards				
1.	The operator has a detailed chemical and physical analysis of the waste material containing all of the information which must be known to properly treat or store the waste as required by Section 265.13(a) [3745-65-13(A)(1)]	~			
2.	The operator has a written waste analysis plan which describes analytical parameters, test methods, sampling methods, testing frequency and responses to any process changes that may affect the character of the waste. (Section 265.13(b)) [3745-65-13(B)]	<u> </u>			: . :
3.	a) Would physical contact with the waste structures or equipment injure unknowing/unauthorized persons or livestock entering the facility? (265.14(a)(1)) [3745-65-14(A)(1)]	<del>de skriver</del>			
	b) Would disturbance of the waste cause a violation of the hazardous waste regulations? (265.14(a)(2)) [3745-65-14(A)(2)]				† †
	IF BOTH 3a AND 3b ARE "NO", MARK QUESTIONS 4 AND 5 "NOT APPLICABLE".				•
4.	The facility has -		,		
	a) A 24-hour survelllance system, <u>or</u>		_		, `
	b) An artificial or natural barrier and a means to control entry at all times $(265.14(b)(2))$ . $[3745-65-14(B)(2)(a and b)]$	<u> </u>		•	
5.	The facility has a sign "Danger-Unauthorized Personnel Keep Out" at each entrance to the active portion of the facility and at other locations as necessary. ( $265-14(c)$ ) [ $3745-65-14(C)$ ]	_			!

		,	<u>Yes</u>	No	N/A	Remark #
6.	nlan and docume	as developed and followed a comprehensive, written inspecented the inspections, malfunctions and any remedial actionating record log which is kept for at least three years 5-65-15]	UIIS	<u></u>	. <del></del>	
	ctorage areas.	to spills (i.e., loading and unloading areas, container etc.) are inspected daily when in use and according to o lations when not actively in use. (265.15(b)(4))	ther <u>~</u>		. <u></u>	:
7.	Section 265.16(a)(b	rovided a Personnel Training Program in compliance with b)(c) including instruction in safe equipment operation a procedures, training new employees within 6 months and training program refresher course. [3745-65-16(A)(B)(C	,			
8.	The facility keeps written job titles, [3745-65-16(D)(E)]	all records required by Section 265.16(d)(e) including , job descriptions and documented employee training recor	ds.		. <u> </u>	
9.	If required due to incompatible waste (Section 265.17)	the actual hazards associated with Ignitable, Reactive of materials, the facility meets the following requirements [3745-65-17]	or ::			
	a) Protection from	m sources of ignition.			· ·	
	b) Physical separa	ation of incompatible waste materials.	~		- <del></del>	
	c) "No Smoking" or Reactive wastes	r "No Open Flames" signs near areas where Ignitable or s are handled.		•		1 1
	d) Any comingling	of waste materials is done in a controlled, safe manner Section 265.17(b). [3745-65-17(B)]	as	·	<u> </u>	'1

40	CFR 2	62 (OAC 3745-52) GENERATOR REQUIREMENTS		-		<u> </u>
· <del>-</del> -			<u>Yes</u>	<u>No</u>	<u>N/A</u>	Remark #
١.	actn	hazardous waste(s) generated at this facility have been tested or are lowledged to be hazardous waste(s) as defined in Section 261 and in limitance with the requirements of Sections 262.11. [3745-52-11(0)]	<u> </u>			
2.	real	this facility generate any hazardous wastes that are excluded from Hation under Section 261.4 [3745-51-04] (statutory exclusions) or Hon 261.6 [3745-51-06(A)(1)] (recycle/reuse)?		~		
3.	from	this facility have waste or waste treatment equipment that is excluded regulation because of totally enclosed treatment (Section 265.1(c)(9))   15-65-01  or via operation of an elementary neutralization unit and/or tewater treatment unit (Section 265.1(c)(10) [3745-65-01]	***************************************	<u>~</u>		
4.	The use	generator meets the following requirements with respect to the preparation, and retention of the hazardous waste manifest:				1 : - <sub>2</sub> 1
	a)	The manifest form used contains all of the information required by Section 262.21(a) and (b) [3745-52-21] and the minimum number of copies required by Section 262.22 [3745-52-22].	<u> </u>			
	b)	The generator has designated at least one permitted disposal facility and has/will designate an alternate facility or instructions to return waste in compliance with Section 262.20 [3745-52-20(B)(C)(D)].	<u>~</u>	——	***********	· ·
	c)	Prepared manifests have been signed by the generator and initial transporter in compliance with Section 262.23 [3745-52-23(A)(1 and 2)].				
	d)	The generator has complied with manifest exception reporting requirements (investigate after 35 days, report after 45 days) in Section 262.42(a)(b) [3745-52-42].	<u> </u>			
	e)	Signed copies of all hazardous waste manifests and any documentation required for Exception Reports are retained for at least 3 years as required by Section 262.40 [3745-52-40]. (262.40(a)) [3745-52-40(a)]				11.
						1.

		<u>Yes</u>	<u>No</u>	N/A	Remark #
5.	The generator meads the following hazardous waste pre-transport requirements:				1,
	a) Prior to offering hazardous wastes for transport off-site the waste material is packaged, labeled and marked in accord with applicable DOT regulations (Section 262.30, 262.31 and 262.32(a)) [3745-52-30, 3745-52-31, 3745-52-32]	<u>~</u>			1
	b) Prior to offering hazardous wastes for transport off-site each container with a capacity of 110 gallons (416 liters) or less is affixed with a completed hazardous waste label as required by Section 262.32(b) [3745-52-32].	<u> </u>			
	c) The generator meets requirements for properly placarding or offering to properly placard the initial transporter of the waste material in compliance with Section 262.33 [3745-52-33].	<u> </u>			
6.	Hazardous wastes imported from or exported to foreign countries are handled in accordance with the requirements of Section 262.50 [3745-52-50]			~	
7.	If the generator elects to store hazardous waste on-site in <u>containers</u> or <u>tanks</u> for <u>90 days</u> or less without a RCRA storage permit as provided under Section 262.34 [3745-52-34], the following requirements with respect to such storage are met:				
	a) The containers are clearly marked with the words "Hazardous Waste".		·	<del></del>	
	b) The date that accumulation began is clearly marked on each container.				
8.	The generator has provided a Personnel Training Program in compliance with Section 265.16(a)(b)(c) [3745-65-16(A)(B)(C)] including instruction in safe equipment operation and emergency response procedures, training new employees within 6 months and providing an annual training program refresher course. (Section 262.34) [3745-52-34(A)(4)]	<u> </u>			. ,
9.	The generator keeps all of the records required by Section 265.16(d)(e) $[3745-65-16(D)(E)]$ including written job titles, job descriptions and documented employee training records (Section 262.34) $[3745-52-34(A)(4)]$ .	_	<del></del>		

NOTE: SHORT-TERM STORAGE FOR 90 DAYS OR LESS IN TANKS AND CONTAINERS ALSO REQUIRES THAT REGULATIONS IN SECTION 265 [3745-65], SUBPARTS C AND D (PREPAREDNESS AND PREVENTION PLUS CONTINGENCY AND EMERGENCY) AND CERTAIN PORTIONS OF THE "CONTAINERS" AND "TANKS" RULES BE MET. COMPLETE THE APPROPRIATE SECTIONS OF THE INSPECTION FORM.

REMARKS, GENERATOR REQUIREMENTS

		Yes	. <u>No</u>	N/A	Remark #
•	Subpart C: Preparedness and Prevention				1
۱.	Has there been a fire, explosion or non-planned release of hazardous waste at this facility? (265.31) [3745-65-31]	<del></del>	<u>~</u>		
2.	If required due to actual hazards associated with the waste material, the facility has the following equipment: (265.32) [3745-65-32(A)(B)(C)(D)]				
	a) Internal alarm ystem.	<u>~</u>			
	b) Access to telephone, radio or other device for summoning emergency assistance.	<u>~</u>	<del></del>		<del> </del>
	c) Portable fire control equipment.	<u> </u>			
	d) Water of adequate volume and pressure via hoses sprinkler, foamers or sprayers.	$\checkmark$			· · · · · · · · · · · · · · · · · · ·
3.	All required safety, fire and communications equipment is tested and maintained as necessary; testing and maintenance are documented. (265.33) [3745-65-33]	_		<del></del>	
4.	If required due to the actual hazards associated with the waste material, personnel have immediate access to an emergency communication device during times when hazardous waste is being physically handled. (265.34) [3745-65-34]	<u> </u>		*********	
5.	If required due to the actual hazards associated with the waste material, adequate aisle space to allow unobstructed movement or emergency or spill control equipment is maintained. (265.35) [3745-65-35]	<u>~</u>			
6.	If required due to the actual hazards associated with the waste material, the facility has attempted to make appropriate arrangements with local emergency service authorities to familiarize them with the possible hazards and the facility layout. (265.37(a)) [3745-65-37(A)]		, 		· · · · · · · · · · · · · · · · · · ·
7.	Where state or local emergency service authorities have declined to enter into any proposed special arrangements or agreements the refusal has been documented. (265.37(b)) [3745-65-37(B)]			<u> </u>	·

			<u>Yes</u>	· <u>No</u>	<u>N/A</u>	Remark #
		Subpart D: Contingency and Emergency				! ;
•	fir	facility has a written Contingency Plan designed to minimize hazards from e, explosions or unplanned releases of hazardous wastes (265.51) 45-65-52(A)(B)(C)(D)(E)] and contains the following components:				!
	a)	Actions to be taken by personnel in the event of an emergency incident.	<u>/</u>			
	b)	Arrangements or agreements with local or state emergency authorities.	_			<u> </u>
	c)	Names, addresses and telephone numbers of all persons qualified to act as emergency coordinator.	<u>~</u>	<del></del>		· ;
	d)	A list of all emergency equipment including location, physical description and outline of capabilities.	<u>/</u>		<del></del>	
	e)	If required due to the actual hazards associated with the waste(s) handled, an evacuation plan for facility personnel. (265.51(f)) [3745-65-52(F)]	$\sqrt{}$		<del> </del>	•
2.	bee	opy of the Contingency Plan and any plan revisions is maintained on-site and has n submitted to all local and state emergency service authorities that might be uired to participate in the execution of the plan. (265.53) [3745-65-53(A)(B)]	<u> </u>	•		; ·
3.		plan is revised in response to facility, equipment and personnel changes failure of the plan. (265.54) [3745-65-54]	<u> </u>			
۱.	fam	emergency coordinator is designated at all times (on-site or on-call) is illiar with all aspects of site operation and emergency procedures and has the hority to implement all aspects of the Contingency Plan. (265.56) [3745-65-55]	<u> </u>			· · · · · · · · · · · · · · · · · · ·
5.	a11	an emergency situation has occurred, the emergency coordinator has implemented or part of the Contingency Plan and has taken all of the actions and made all the notifications deemed necessary under Sections 265.56(a-j). [3745-65-56(A-J)			$ \underline{\checkmark} $	

		Subpart E: Man1fests/Records/Reporting	i			1 1
<u>NOT</u>	<u>E</u> :	THE FOLLOWING REQUIREMENTS ARE APPLICABLE TO $\underline{\text{BOTH}}$ ON-SITE AND OFF-SITE TREATMED DISPOSAL FACILITIES.	NT, STO	RAGE A	ND	
1.		e operator maintains a written operating record at his facility as required by ction 265.73 [3745-65-73(A)] which contains the following information:				
	a)	Description and quantity of each hazardous waste treated, stored or disposed of within the facility and the date(s) and method(s) pertinent to such treatment, storage or disposal. (265.73(b)(1)) [3745-65-73(B)(1)]	_/	·	••••	d
	b)	Common name, EPA Hazardous Waste Identification Number and physical state (liquid, solid, gas) of the waste(s).		<del></del>		***************************************
	c)	The estimated (or actual) weight, volume or density of the waste material(s).	$\checkmark$		·	
	d)	A description of the method(s) used to treat, store or dispose of the waste(s using the EPA Handling Codes listed in 45 FR 33252 (May 19, 1980).	) _		, <del></del>	I I I I I I I I I I I I I I I I I I I
	e)	The present physical location of each hazardous waste within the facility.	<u> </u>	<del></del>		:
	f)	FOR DISPOSAL FACILITIES, the location and quantity of each hazardous waste recorded on a map of the facility and cross-references to any pertinent manifest document number(s). (265.73(b)(2)) [3745-65-73(B)(2)]			<u> </u>	1
	g)	Records of any waste analyses and trial tests required to be performed.	_		<del></del>	
	h)	Records of the inspections required under Section 265.15 [3745.65.14] (General Inspection Requirements - Subpart B).		_	<del></del>	inspections in 191
	1)	Records of any monitoring, testing or analytical data required under other Subparts as referenced by Section 265.73(b)(6). [3745-65-73(B)(6)]			~	-
	1)	Records of Closure cost estimates and Post-Closure (DISPOSAL ONLY) cost estimates required under Subpart G.	<u> </u>	-	<u> </u>	· · · · · · · · · · · · · · · · · · ·
		• •				

Remark #

N/A

Yes · No

•		<u>Yes</u>	No	N/A	Remark #
2.	The operators has submitted an annual Treatment-Storage-Disposal Operating Report (by March 1) containing all of the operating information required under Section 265.75. [3745-65-75]				
มกา					F
110	E: THE FOLLOWING REQUIREMENTS ARE APPLICABLE TO ONLY OFF-SITE TREATMENT, STORAGE	AND DIS	POSAL	FACILIT	IES.
3.	Manifests received by the facility are signed and dated; one copy is given to the transporter, one copy is sent to the generator within 30 days and one copy is kept for at least 3 years. (265.71) [3745-65-71(A)			~	;
	a) If shipping papers are used in lieu of manifests (bulk shipments, etc.) the same requirements are met. (265.71(b)) [3745-65-71(B)]		<del></del>		
	b) Any significant discrepancies in the manifest, as defined in Section 265.72(a) $[3745-65-72(A)]$ are noted in writing on the manifest document. $(265.71(a)(2))$ $[3745-65-71(A)(2)]$			_	:
4.	Any manifest discrepancies have been reconciled within 15 days as required by Section 265.72(b) or the operator has submitted the required information to the Regional Administrator/Director. [3745-65-72(B)]	-		<u>~</u>	
5.	If the facility has accepted any unmanifested hazardous wastes from off-site sources (except from small quantity generators) for treatment, storage, or disposal an unmanifested waste report containing all the information required by Section 265.76 has been submitted to the Regional Administrator/Director within 15 days. [3745-65-76(A)]	•			

		Subpart G: Closure and Post-Closure				1
<u> 101</u>	<u>E</u> :	THE FOLLOWING REQUIREMENTS ARE APPLICABLE TO BOTH DISPOSAL AND NON-DISPOSAL FAC	ILITIES	s.		
1.		ritten Closure Plan is on file at the facility and contains the following ments: (Section 265.112) [3745-66-12]	<u> </u>	*·····	_	· .
	a)	A description of how and when the facility will be closed. (265.112(a)(1)) [3745-66-12(A)(1)]	<u> </u>	<del></del> -		
	b)	A description of how any of the <u>applicable</u> closure requirements in other Subparts of Section 265 [3745-66] (Tanks, Surface Impoundments, Landfill, etc.) will be carried out.		<del></del>	<u> </u>	1
	c)	An estimate of the maximum amount of hazardous wastes being treated or in storage at the facility. (NOTE: Maximum inventory should agree with the permit.)	_			; ;
	d)	A description of steps taken to decontaminate facility equipment.	<u> </u>			*****
	e)	The year closure is expected to begin and a schedule for the various phases of closure.	<u> </u>		<del></del>	
2.	The 1n	Closure Plan has been amended within 60 days in response to any changes facility design, processes or closure dates. (265.112(4)(B)) [3745-66-12(B)]	_		<del></del>	!
3.	The 180	Closure Plan has been submitted to the Regional Administrator/Director days prior to beginning the Closure process. (265.112(4)(C)) [3745-66-12(C)]	<u>~</u>			

N/A Remark #

Yes · No

		<u>Yes</u>	. <u>No</u>	N/A Remark#
•	Subpart H: Financial Requirements			
•	The owner or operator of the facility has established financial assurance for closure by use of one of the following: (265.143) [3745-66-43]			
	a) A closure trust fund, or			
	b) A surety bond, or	~		
	c) A closure letter of credit, or			
	d) A combination of financial mechanisms.	<del></del>	—	
₹.	A written cost estimate for closure of the facility (as specified in the closure plan) is available. How much is it?	<u>~</u>	<b></b>	#13,600
3.	When was the most recent estimate made?	<del></del>		<u> 2/87</u>
4.	A written cost estimate for post closure care of the facility (if applicable) is available. How much is it?		******	<u> </u>
5.	When was the most recent estimate made?			!

REMARKS. GENERAL INTERIM STATUS REQUIREMENTS

#### Subpart I: Management of Containers

	•	163	<u>NO</u>	11/14	Kemark #
1.	Hazardous wastes are stored in containers which are:				ing Tight
	a) Closed (265.173) [3745-66-73(A)]			<u>-</u>	
	b) In good physical condition (265.171) [3745-66-71]				• ;
	c) Compatible with the wastes stored in them (265.172) [3745-66-72]				. 1
2.	Containers are stored closed except when it is necessary to add or remove wastes. (265.173(a)) [3745-66-73(A)]	<u>~</u>			
3.	Hazardous waste containers are stored, handled and opened in a manner which prevents container rupture or leakage. (265.173(b)) [3745-66-73(B)]	<u> </u>			
4.	The area where containers are stored is inspected for evidence of leaks or corrosto at least weekly and such inspections are documented. (265.174) [3745-66-74]	n 	_		in 10/87
5.	Containers holding Ignitable or Reactive waste(s) are located at least 50 feet (15 meters) from the property line and the general requirements for handling				
	such wastes in Section 265.17 (physical separation, signs and safety) are met (265.176) [3745-66-76]	<u>~</u>			;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;
6.	Containers holding hazardous wastes are stored separate from other materials which	_			

# REMIX, INC.

P. O. BOX 281

NORTH KINGSVILLE, OHIO 44068

PHONE (216) 224-2181

June 27, 1986

Lun (52) 500 [nn]

JUL 03 1986

SOLID WASTE BRANCH
U.S. EPA, REGION V

OHD 004 200 044 V

Chicago, IL 60604

SUBJECT:

230 South Dearborn Street

Mr. Ken Chui

USEPA Region V

RD&D\Permit Application

Dear Mr. Chui:

Enclosed is the information required for a trial solidification process for ignitible waste. The information has been gathered to meet the requirements of the Guidance Manual for Research, Development and Demonstration permits, under 40 CFR Section 270.65.

#### Facility

Premix, Inc. Route 20 and Harmon Road North Kingsville, OH 44068 (216) 224-2181

Contact Person: Debra Parshall-Hall, CHMM

PURPOSE:

to reduce toxicity of hazardous waste and danger to

human health and environment.

EXPLANATION OF PROPOSED ACTIVITY;

Solidification process for ignitible wastes to render characteristic to non-ignitible.



Mr. Chui Page two June 27, 1986

#### GENERAL DESCRIPTION OF PROPOSED ACTIVITY:

The solidification process occurs by blending ignitible waste streams together in a portable auger mixer and adding calciumated lime and water. This mixture is thoroughly blended; within 30 minutes the water evaporates leaving a solid insert mass.

TYPE AND QUANTITY OF HAZARDOUS WASTE:

 Waste resin solution Flammable liquid UN 1866/D001

Signen monomer 40.50%

- 2. Waste paint related materials Flammable liquid UN 1263/D001
- 3. Non-hazardous polyester paste which has been approved for sanitary landfill by the OEPA

Estimated quantities would be approximately 10 drums paste, 2 drums resin, 2 drums of paint per month. Initial trial process would be 2 drums paste, 1 drum resin, 1 drum paint (55 gallons).

A ninety-day time limit should be sufficient for trial analysis.

From previously analyzed samples from lab testing, no characteristic residues were found.

No emissions are present during treatment.

Waste will be contained in an auger mixing vessel located outside facility building on a concrete pad, no danger to human health or environment is possible.

ruler ord

্বৰ ক্ৰি

Mr. Chui Page three June 27, 1986

#### PERSONNEL QUALIFICATIONS:

Debra Parshall-Hall has been trained in all aspects of hazardous materials management and is capable of appreciating the health and environmental risks associated with hazardous waste. She also understands the appropriable methods of conducting scientific experimentation, analysis and research in order to minimize risks. She has just recently achieved the Certification of Hazardous Materials Manager. See attached certificates of training.

If I can be of any further assistance, please contact me.

Sincerely,

PREMIX, INC.

Debra Parshall-Hall, CHMM Environmental Engineer

mk1

Attachments

cc:

Ms. Deborah Burg Mr. Robert Carrie

0EPA

PREMIX, INC.

P. O. BOX 281

NORTH KINGSVILLE, OHIO

DEBRA PARSHALL-HALL

#### Certification Statement

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PREMIX, INC.

Debra Parshall-Hall, CHMM

Environmental Engineer

# Plant Emergency Organization and Job Duties

In the event of a fire or a hazardous spill, emergency control of the situation is imperative. To do this, each person at Premix must keep in mind that our objectives are 1) to protect the lives of the employees of Premix, and 2) to protect the property of the plant where we work. To do this we must follow guidelines to job duties to bring the situation under control as listed on the following pages.

People not assigned to specific duties are to evacuate the plant immediately to the nearest exit when the alarm sounds. People are asked to shut down all equipment in that area. If the emergency is in that area, the people are to exit immediately to the nearest exit. DO NOT EXIT THROUGH HAZARDOUS WASTE STORAGE AREA.

EMPLOYEES ARE NOT TO GO TO THEIR LOCKERS TO GET PERSONAL POSSESSIONS NOR ARE THEY TO ENTER THE BUILDING AFTER EXITING UNLESS INSTRUCTED TO DO SO BY A MEMBER OF THE EMERGENCY ORGANIZATION.

AFTER EXITING, ALL PERSONNEL ARE TO PROCEED TO PREMIX COMMUNITY CENTER.

ALL PERSONNEL, OFFICE AND PLANT, ARE TO EXIT THE BUILDING WHEN AN ALARM SOUNDS.

Any spill in lagoon will be covered by:

Environmental Systems, Inc.

#### Fire and Rescue

1. 2. 3. 4. 5. 6.	Chief Oxley Assistant Chief Roxberry Captain Urich Captain Savel Assistant Chief Shauberger Captain Bisbee Lieutenant Kortyka	998-7200 224-2181 224-1411 (Fire Department) 224-1411 224-1411 224-1411

Ohio Trade and Industrial Fire Fighting Manual is used for fire fighting instruction.

The fire department is aware of the type of waste we generate and of the storage areas. They have had a tour through the facility. They are also aware of all the hazardous raw materials and where they are stored. In case of a fire, the fire department will be called by the person who finds the fire, and they will carry the proper foams and equipment for extinguishing the fire.

In the case of a hazardous spill, the waste (if small quantity) will be cleaned by trained personnel. Our waste, other than solvent, will not have time to contaminate any water source and is so viscous that it will not spread far. Ground soil and waste will be shoveled into drums and treated as a hazardous waste for disposal.

#### Plant Emergency Organization

August 28, 1984

In the event of an emergency or accident, the local rescue squad (North Kingsville) and hospitals (Brown Memorial, Conneaut and Ashtabula County Medical Center, Ashtabula) will respond immediately to any problems that may occur. They have in their files copies of our evacuation plan, plans of emergency exits and storage of all hazardous chemicals and possible exposure effects of these chemicals. They have been on a tour through the plant and feel that they could handle any problems that may occur. The fire department is aware of the type of waste we generate and of the storage areas. They have had a tour through the facility. They are also aware of all the hazardous raw materials and where they are stored. In case of a fire, the fire department will be called by the person who finds the fire, and they will carry the proper foams and equipment for extinguishing the fire. They do not wish to have a copy of the Contingency Plan due to the fact that Ken Roxberry (Emergency Coordinator) is the assistant Fire Chief for North Kingsville and is on call 24 hours a day.

Upon an accident or emergency happening, the person finding the emergency sets off the in-plant alarm system to which plant personnel respond. In that case, the emergency coordinator or one of the persons licensed in paramedics will call the rescue squad and the hospital to alert them on what problems have occurred. It takes less than five minutes generally to have the rescue squad at the plant. At this time if the emergency was an exposure problem, the Environmental Engineer or emergency coordinator will have any source of information that is available to help the rescue people or the hospital in treating the person or persons exposed.

#### HAZARDOUS WASTE ANALYSIS PLAN

#### (OAC 3745-65-13)

The following wastes are current that we have been disposing of in the past year. Explained is the procedure used for analysis and individual types of waste that are generated.

# WASTE RESIN SOLUTION:

Is resin that is either obsolete and cannot be used any longer or resin that is used for flushing lines for the SMC system. The waste is basically pure. The flash point is 80°-100°. Analysis used for the flash point was Tag Closed Cup ASTM Std. #D-93-79. Ph range is 8-12 and the average viscosity is 6,000 to 10,000 cps. The waste is incinerated by Ross Incineration Services, (WPS-19279) EPA ID #D001 and DOT ID #UN1866, Flammable Liquid.

#### WASTE PAINT RELATED MATERIAL:

Is waste urethane paint that is pre-catalyzed and cannot be used by the end of the shift. The paint that is left to dispose of is approved for incineration at Ross, Inc. (WPS 19278). EPA ID number is D001, DOT ID #UN 1325, Flammable Liquid NOS. Flash point of 80°-85% by Tag Closed Cup ASTM-D-93-79.

# NON-HAZARDOUS WASTE PASTE:

Is a polyester paste that is generated from the thermoset reinforced fiberglass industry. The waste was sampled for ignitibility by using 16 CFR 1500.44 solid flammability analysis.

Samples were pulled from our waste containers in a quart quantity as the waste is placed in drums. If it is a liquid, it is analyzed by Pensky-Martin ASTM Std. #D-93-79 or an equivalent method as approved by the administrator.

Normally our waste would be reevaluated once a year by the disposal facilities. At this time, we would check to see if there were any differences. If any new waste were to be disposed of, these would be analyzed in the above manner.


The flammable waste (D001) is stored away from the non-hazardous waste. Each waste is segregated into specific sections on separate pallets with three-foot aisles between rows.

To enable inspections that are done weekly, or for any firefighting that may need to be done, they are stored as designated by the Ohio Fire Code 1301:702, Section F.305.0 Materials Storage.

mkl

Revised May 1986

# PREMIX, INC. North Kingsville OH. Hazardous Waste Storage Area



#### INSPECTION PLAN

(OAC 3745-65-15)

An artificial barrier surrounds the area of our facility. The main drive through the center of the plant has a mesh fence that can be closed and locked when there is no one at the plant. This fence is labeled as to being part of the hazardous waste storage area. Along the wall behind where the flammable wastes are stored is also a sign stating that the wastes are flammable. Down in the center of the plant on a concrete area is a partially diked storage area for solvent waste, paint waste and waste resin. Each area has been designated as to specific waste and also has a sign stating that it is part of the hazardous storage area along with "No Smoking" signs. A weekly inspection sheet is filed for permanent records of the inspections that are done for the storage area. This form is attached. The guards are trained as to what to check for; i.e., leaking drums, drums stacked neatly with aisles between rows. All of this above information is noted.

On days that we are loading waste trucks for waste disposal, a trained person is present to verify that there are not any spills incurred and that all the waste was handled and labeled properly. This is documented on the waste inventory log sheet.

There has never been, nor do we expect, any kind of disturbance of the waste by unauthorized personnel.

# Financial Assurance OAC 3745-66-43)

A surety bond was posted according to OAC-3745-66-45 in May of 1984 for the amount of \$12,000 which was the amount of the estimated cost of closure at that time.

According to regulations (OAC-3745-66-42), this amount must be adjusted for inflation within 30 days of each anniversary date on which the first closure was prepared.

Upon calling the RCRA hot line for the Consumer Index Deflator, which is derived from the Annual Implicit Price Deflator for GNP and is published by the U.S. Department of Commerce in their Annual Survey of Current Business report, the implicit price deflator for 1985 is 223.45. Subtracting the 1984 price deflator of 215.34 yields an increase of 1.038 for 1985.

Due to the increased cost of disposal over the past year, the closure cost has risen from \$12,000 to \$22,000 for 1985. Using the 1985 estimated closure cost of \$22,000 multiplied by the 1.038 deflator factor equals \$22,836 that the surety bond must be increased to in order to be in compliance with the regulations. The anniversary date of the first closure prepared was August 17, 1984.

In September of 1985, Ross increased incineration prices for 1986. At this time the surety bond for Financial Assurance was increased to \$25,000 to 1986 coverage.

mkl

Revised May 1986

#### CLOSURE PLAN

#### (OAC 3745-66-11 thru 14) (OAC 3745-66-42)

This facility is an ongoing operation that does not intend to close. It is an operation that is profitable in the FRP industry.

But, if at any time this facility would have to close, the following would be implemented:

1. An inventory would be done on all hazardous waste that is currently in inventory (with the maximum being 210 drums). Due to the facility closing, there would not be any further waste generated other than waste generated from the decontamination process.

Approximate inventory would be:

			二基語 网络红色 医圆面切除的
	#Drums	Type of Waste	Disposal Cost
Α.	100	drums of waste resin solution	\$144.00/drum
в.	6	drums of waste paint related materials	152.00/drum
<b>C.</b>	100	drums of waste combustible liquid NOS  (contaminated SP-21)  drums of waste pyridine mixture NOS	alanest.
D	3	drums of waste pyridine mixture NOS (QA solvent)	93.00
Ε.	1	5-gallon pail waste alcohol mixture NC (R&D solvent)	OS 66.00

Dod Individual Color

- 2. Ross Incineration Services, Inc., Grafton, Ohio, would be used for removal and incineration of the following waste:
  - A. Waste resin solution
  - B. Waste paint related materials
  - C. Waste combustible liquid NOS
  - D. Waste pyridine mixture NOS
  - E. Waste alcohol mixture NOS

Estimated cost for disposal of these wastes is \$15,657, including disposal for 1986. Since the total quantity of the above mentioned waste is 110 drums, this waste will be removed in two different shipments for incineration.

3. The waste combustible liquid NOS will be reclaimed by Chemical Solvents, Inc., Cleveland, Ohio. Cost for disposal of 100 drums would be approximately \$4,000, including transportation, which includes disposal cost for still bottoms of the reclaimed spent solvent. There will not be a credit gain for reclamation of above mentioned waste solvent.

Closure Plan Page two Premix, Inc.

- 4. Total cost estimate for waste disposal would be \$22,400 for 1986. This would be for the removal of all waste currently on site and should be accomplished within two months' time.
- 5. Any decontamination that needed to be done after closure would be completed in the following manner:
  - A. Decontamination of the waste storage area (having a concrete foundation) would be done by washing the foundation with soap and water, absorbing the liquid with an inert clay and placing the waste in drums in preparation for disposal. After this has been completed, a sample will be analyzed for contaminants using EPA methods SW-846 to insure that all contaminants have been removed.
    - (1) The driveway that is located east of the Compound building was previously used for waste resin storage. This area will also be sampled for contaminants, a surface scraping will be done and any contaminated soil will be placed in drums for disposal.

\*A partial closure plan is intended to be submitted for this area prior to 1987.

- (2) Estimated labor cost for decontamination of both areas is \$416 (2 men x 16 hours x \$13/hr.).
- (3) An extra allotted \$300 is included for decontamination disposal.
- 6. When all decontamination is complete, an Independent Registered Engineer will be engaged for justification that the facility has been closed in accordance with specifications from OAC 3745-66, 11 thru 14, and OAC 3745-66-42.
  - A. Estimated cost for the registered engineer to prepare closure is \$2,000.
- 7. This brings the total estimated cost for closure to \$22,400 for 1986.

If, at any time, there are process changes, this plan will change accordingly.

mkl

Revised May 1986

# Certificate of Accomplishment

PRESENTED BY



This is to certify that

Debra Parashall~ Hall

has participated in and successfully completed

Transporting Dangerous Goods By Day

By participating in this program

the above-named individual has demonstrated a dedication to the development and growth of the airfreight industry.

Charle B. Maddex
Director of Training & Development

March 13, 1986

Date

## GREATER CLEVELAND POISON CONTROL CENTER'S HAZARD COMMUNICATION COORDINATOR SCHOOL

Certificate of Training

This is to certify that _	DEBRA HALL of
PREMIX, INC.	has attended and completed a
sixteen (16) hour trair	ning program on hazard communication
compliance during Ma	arch 1986 at the Greater Cleveland
Poison Control Cente	er of University Hospitals of Cleveland,
Cleveland, Ohio.	
nichael Dreed	Greater Goveld & Gland of

Michael D. Reed, Pharm.D.

Co-Director

Greater Cleveland Poison Control Center

Michael Dress

University Hospitals of Cleveland

Cleveland, Ohio




Ronald E. Hurst, M.S. Industrial Toxicologist Greater Cleveland Poison Control Center University Hospitals of Cleveland Cleveland, Ohio

This certificate has been awarded to

at CLEVELAND, OH.	Debra Hall
----------------------	------------

of the United States Environmental Protection (Igency and the United States Department of Transportation regarding the safe Compliance Management Course on the applicable regulations For successfully completing the Lion Technology Inc. disposal of wastes designated as hazardous,

as a 19th JULY 1985





## Certificate of Completion





DEBRA S. HALL

Has completed

Hazardous Materials Management — Advanced Training

This day

May 16, 1985

HAZPRO PROFESSIONAL SYMPOSIUM BALTIMORE, MARYLAND

Richard Young

General .

Conference Chairman

Instructor

# Certificate of Completion





DEBRA HALL

Has completed

Hazardous Materials Management - Workshop A

Awarded with Distinction
This day

May 15, 1985

HAZPRO PROFESSIONAL SYMPOSIUM

BALTIMORE, MARYLAND

Richard Young

General

Conference Chairman

Instructor

RANSPORTATION SKILLS PROGRAMS

TRANSPORTATION SKILLS PROGRAMS, INC.

This is to certify that \_

Debra S. Hall

has successfully completed the

TSP Hazardous Materials, Chemicals, and Waste Management and Compliance Seminar

in a sincere effort to comply with the mandatory and annual training requirements of the U.S. Department of Transportation, the Environmental Protection Agency, and the Occupational Safety and Health Administration.

Robert Keegan, President

May 7, 1485

### RCRA LAND DISPOSAL RESTRICTION INSPECTION

Facility:	Pr	emix				-
U.S. EPA	I.D. No.	OHD:	004-200	-044		<del>-</del>
Street:	Harr	non R	d + Route	. 20		_
City:	N. Kin	geville	State:	Ohio	Zip Code: <u>44068</u>	<u></u>
						-
Operator:						
Street:						_
City:			State:		Zip Code:	_
Telephone	e: _					_
Owner:						<b>–</b>
Street:						_
City:	<del></del>		State:		Zip Code:	_
Telephone	e: _					_
-	_	2/8 <i>18</i> 7	Time: <u>8:30</u> -	11:30 Weather Co	onditions: Partly Cloudy 4	- '2'5
-	n Date: [	lame	Aſ	<u>filiation</u>	Telephone	•
-	n Date: [	lame	Aſ	<u>filiation</u>	•	•
Inspection	n Date: [	lame	Aſ	<u>filiation</u>	Telephone	•
Inspection	n Date: [	lame Peresa	Sabol	filiation OEPA	Telephone	<u>7</u> 1 -
Inspection	n Date: [	lame Peresa	Sabol	filiation OEPA	Telephone 216-425-91	<u>7</u> 1 -
Inspection	n Date: [	lame Peresa	Sabol	filiation  OEPA  ra Hall	Telephone 216-425-91	<u>7</u> 1 -
Inspection	n Date: [	eresa.	Sabol Deb	filiation  OEPA  ra Hall	Telephone 216-425-91- 216-224-2181  LDR Status	<u>7</u> 1 -
Inspection	n Date: [	eresa.  atatives:	Sabol Deb	filiation  OEPA  ra Hall	Telephone 216-425-91- 216-224-2181  LDR Status	<u>7</u> 1 -
Inspection	n Date: [	tatives:	Sabol Deb	filiation  OEPA  ra Hall	Telephone 216-425-91- 216-224-2181  LDR Status	<u>7</u> 1 -
Inspection	n Date: [  No. 1]  S:  Represent  General  Transp	tatives:	Sabol Deb	filiation  OEPA  ra Hall	Telephone 216-425-91- 216-224-2181  LDR Status	<u>7</u> 1 -

#### INSPECTION SUMMARY

## RCRA LAND DISPOSAL RESTRICTION INSPECTION APPLICABILITY CHECKLIST

Does the facility handle the following wastes?

				Gen.	Treat	Store	Disp.	Trans.
A.	<u>F-S</u>	olvent Was	stes					
	1.	F001						
	2.	F002				<u>~</u>		
	3.	F003						*****
	4.	F004					***************************************	<del></del>
	5.	F005			<del></del>			
		Note:		dix A to dete		ther the fa	icility is	

### B. California List Wastes N/A

1. Liquid hazardous waste (including free liquids associated with any solid or sludge) that contains the following metals at concentrations greater than or equal to those specified

	•					
	•	Gen.	Treat	Store	Disp.	Trans.
Arsenic	500 mg/L				<del></del>	<u></u>
Cadmium	100 mg/L					
Chromium VI	500 mg/L		<del></del>			
Lead	500 mg/L					
Mercury	20 mg/L					-
Nickel	134 mg/L			-		<del></del>
Selenium	100 mg/L					
Thallium	130 mg/L					

2.	Liquid hazardous waste (including free liquids associated with any solid or sludge) that contains free cyanides at concentrations greater than or equal to 1,000 mg/L WA							
	Gen. Treat Store Disp. Trans							
3.	Liquid hazardous waste that has a pH of less than or equal to 2.0 N/A							
4.	Liquid hazardous waste that contains PCBs at concentrations greater than or equal to N/A  50 ppm							
	Yes No NA  If yes, state reasons for mixing:							
5.	Liquid hazardous waste-that is primarily water and that contains HOCs greater than or equal to 1,000 mg/L (dilute HOC wastewater) and less than 10,000 mg/L N/A							
	Note: The prohibitions of 268.32(a)(3) and (e) do not apply if the HOC waste is also subject to the solvent restrictions of 268 Subpart C or a specific HOC.							

### RCRA LAND DISPOSAL RESTRICTION INSPECTION

#### GENERATOR CHECKLIST

### GENERATOR REQUIREMENTS

•	F-Solvent Wastes: Does the generator correctly determine the appropriate treatability group of the waste?
	Yes No NA
	If yes, check the appropriate treatability group.
	Wastewaters containing solvents (less than or equal to 1% TOC by weight)  Pharmaceutical wastewater containing spent methylene chloride All other spent solvent wastes
2.	California List Wastes: Does the generator correctly determine the appropriate treatment standard of the waste?
	a. For liquid hazardous waste that contains PCBs at concentrations greater than or equal to 50 but less 500 ppm, is the treatment in accordance with existing TSCA thermal treatment regulations for burning in high efficiency boilers (40 CFR 761.60) or incineration (40 CFR 761.70)?
	Yes No NA
	If yes, specify the method:
	b. For liquid hazardous waste that contains PCBs at concentrations greater than or equal to 500 ppm, is the waste incinerated or disposed of by other approved alternate methods (40 CFR 761. 60 (c))?
	Yes No NA
	If yes, specify the method and state whether the facility has submitted a written request to the Regional Administrator or Assistant Administrator for an exemption from the incineration requirement:

Woo	ta Ar	nalysis
1.		olvent Wastes
1.	12	Olyent wastes
	2.	Does the generator determine whether the F-solvent waste exceeds treatment standards?
		Yes No NA
		How was this determination made?
		- Knowledge of waste
		No
		If yes, note how this is adequate:
		- TCLP Yes No
		If yes, provide the date of last test, the frequency of testing and note any problems. Attach test results.
	b.	Does the F-solvent waste exceed applicable treatability group treatment standards upon generation [268.7(a)(2)]?  Don't kw
		Yes No · NA
		If yes, specify the waste stream:
	c.	Does the generator dilute the F-solvent waste as a substitute for adequate treatment [268.3]?
		YesNo NA
	đ.	How does the generator test F-solvent waste when a process or waste stream changes?
		4
2.	Cali	ifornia List Wastes
	<b>a</b> .	
	a.	Does the generator determine whether the waste is a liquid according to the Paint Filter Liquids Test (PFLT method 9095) as described by SW-846?

b.		waste is determined to be a liquid according to PFLT, absorbent added to the waste?
		Yes No NA
	Check added	type of absorbent is used?  the types of waste to which absorbent is  Liquid hazardous waste having a pH less than or equal to 2
		Liquid hazardous waste containing HOCs in concentrations greater than or equal to 1,000 mg/L, but less than 10,000 mg/L
	····	Liquid hazardous waste containing metals
	:	Liquid hazardous waste containing free cyanides
c.	extrac	the generator determine whether the concentration levels (not et or filtrate) in the waste equal or exceed the prohibition or whether the waste has a pH of less than or equal to 2.0 on:
	<b>-</b> 1	Knowledge of wastes
		Yes No NA
	]	If yes, note how this is adequate:
	-	Testing Yes No NA
	1	If yes, list test method used:
d.		the generator determine if concentration levels in PFLT extract d cyanide and metals concentration levels?
		Yes No NA
		If yes, list test method used and constituent and concentration levels that exceeded prohibition levels:
	-	
c.		the generator dilute the waste as a substitute for adequate nent [268.3]?
		Yes No NA

Ma	nagen	<u>nent</u>
1.	On-	-Site Management
	Is w	vaste that exceeds the treatment standards treated stored disposed on-site?
		Yes No Don't know
	If y	yes, the TSD Checklist must be completed.
2.	Oli	S-Site Management
	2.	Does the generator ship any waste that exceeds the treatment standards to an off-site treatment or storage facility?
		Yes No Don't know
		If yes, does the generator provide notification to the treatment or storage facility [268.7(a)(1)]?
		Yes No
		If yes, does notification contain the following?
		EPA Hazardous waste number(s) Yes No
		Applicable treatment standards Yes No
		Manifest number Yes No
		Waste analysis data, if available Yes No
		Identify off-site treatment or storage facilities: <u>Chemical Solvent</u> Pennison
	ъ.	Does the generator ship any waste that meets the treatment standards to an off-site disposal facility?
		Yes No Don't know
		If yes, does the generator provide notification and certification to the disposal facility [268.7(a)(2)]?
		Yes No

C.

	If yes, does notification contain the fo	ollowing?		
	EPA Hazardous waste number(s)		Yes	No
	Applicable treatment standards		Yes	No
	Manifest number		Yes	No
	Waste analysis data, if available		Yes	No
	Certification that the waste meets treatment standards		Yes	No
	Identify off-site land disposal facilities	es:		
	provide notification to the off-site dis that the waste is exempt from land dis restrictions [268.7(a)(3)]?		lity	
		posal faci	lity	
	Yes	No	NA	
(i.e., boile	t Using RCRA 264/265 Exempt Units or ers, furnaces, distillation units, wastewath tanks, elementary neutralization, etc.)	ter .	<u>s</u>	
	treatment residuals generated from unit er RCRA 264/265?	ts or proce	esses exem	pt
	Yes	No	N/A	
If y	es, list types of waste treatment units an	nd process	es:	

### RCRA LAND DISPOSAL RESTRICTION INSPECTION

#### TSD CHECKLIST

### TSD REQUIREMENTS

l.	Does the waste analysis plan cover Part 268 requirements [264.13 or 265.13]?							
	o I	F-solvent Yes No NA						
	0 (	California List Yes No NA						
2.		es the facility obtain representative chemical and physical analyses of stes and residues?						
		Yes No						
	a.	What date was the waste analysis plan last revised? 1986						
	b.	Are analyses conducted on-site or off-site?						
		On-siteOff-site						
		Identify off-site lab: Free-col Meadville PA						
	c.	Is F-solvent waste analyzed using TCLP?						
	-	Yes No NA						
	đ.	Describe the frequency of sampling:						
	e,	Describe procedures used to identify manifest discrepancies:						
٠.		the operating records, including analyses and quantities,						

Stor	age (268.50)
1.	Are restricted wastes stored on-site?
	Yes No
	If no, go to C, Treatment in Surface Impoundments.
2.	If yes, check the appropriate method.
	Tanks Containers
3.	Are all containers clearly marked to identify the contents and date(s) entering storage?
	Yes No NA
4.	Do operating records track the location, quantity of the wastes, and dates that the wastes enter and leave storage?  Yes No
5.	Do operating records agree with container labeling?
	Yes No NA
6.	Have wastes been stored for more than I year since the applicable LDR regulations went into effect?
	Yes No NA
	If yes, can the facility show that such accumulation is necessary to facilitate proper recovery, treatment, or disposal?
	Yes No N/A
	If yes, state how:

В.

	regulations went into effect?
	Yes No NA
	If yes, do the operating records show that the volume of waste removed from tanks annually equals or is more than the tank volume?
	Yes No
8.	Are all tanks clearly marked with a description of the contents, the quantity of wastes received, and date(s) entering storage, or is such information recorded and maintained in the operating record?
	Yes No NA
<b>T</b> -	atment
1.	Does the facility treat restricted wastes other than in surface impoundments?
	Yes No
	Yes No  If no, go to D, Treatment in Surface Impoundments.
<b>_2</b> .	
<b>_2</b> .	If no, go to D, Treatment in Surface Impoundments.
<b>.2</b> .	If no, go to D, Treatment in Surface Impoundments.
<b>.2.</b> 3.	If no, go to D, Treatment in Surface Impoundments.  Describe the treatment processes:  Does the facility, in accordance with an acceptable waste analysis plan, determine whether the residue from all treatment processes is less than treatment standards
•	Describe the treatment processes:  Does the facility, in accordance with an acceptable waste analysis plan, determine whether the residue from all
•	If no, go to D, Treatment in Surface Impoundments.  Describe the treatment processes:  Does the facility, in accordance with an acceptable waste analysis plan, determine whether the residue from all treatment processes is less than treatment standards [268.7(b)]?
3.	Describe the treatment processes:  Does the facility, in accordance with an acceptable waste analysis plan, determine whether the residue from all treatment processes is less than treatment standards [268.7(b)]?  Yes No
3.	If no, go to D, Treatment in Surface Impoundments.  Describe the treatment processes:  Does the facility, in accordance with an acceptable waste analysis plan, determine whether the residue from all treatment processes is less than treatment standards [268.7(b)]?  Yes No
3.	Describe the treatment processes:  Does the facility, in accordance with an acceptable waste analysis plan, determine whether the residue from all treatment processes is less than treatment standards [268.7(b)]?  Yes No

6.	Are notifications prepared by the generators kept in the facility's operating record?
	Yes No
7.	Does the facility ship any waste or treatment residue that meets the treatment standards to an off-site disposal facility?
	Yes No NA
	If yes, does the treatment facility provide notification and certification to the disposal facility?  Yes No
	If yes, does notification contain the following?
	EPA Hazardous waste number(s) Yes No
	Applicable treatment standards Yes No
	Manifest number Yes No
	Waste analysis data, if available Yes No
	Certification that the waste meets the treatment standards Yes No
	Identify off-site disposal facilities:
Tre	atment in Surface Impoundments
i.	Are restricted wastes placed in surface impoundments for treatment?
	Yes No
	If no, go to E, Land Disposal.
2.	If yes, did the facility submit to the Agency the waste analysis plan and certification of compliance with minimum technology and ground-water monitoring requirements?
	Yes No

D.

3.		e minimum technology requirements have not met, has a waiver been granted for that unit?
		Yes No
4.	from	representative samples of the sludge and supernatant the surface impoundment tested separately, ptably, and in accordance with the sampling frequency analysis specified in the waste analysis plan?
		Yes No
	Atta	ch test results.
5.		he hazardous waste residues (sludges or liquids) ed the treatment standards specified in 268.41?
		Yes No
6.		ride the frequency of analyses conducted on treatment
7.		s the operating record adequately document the results raste analyses performed in accordance with 268.41?
		Yes No
8.	treat	the hazardous waste residues that exceed the ment standards (268.41) removed adequately and n annual basis?
		Sludge Yes No
		Supernatant Yes No
	a.	If no, and supernatant is determined to exceed treatment concentrations, is annual volume of liquid flowing through the impoundment greater than the impoundment volume?
		Yes No
	b.	Are adequate precautions taken to protect liners, and do records indicate that liner integrity is inspected?
		Yes No

		C.	Are residues subsequently managed in another surface impoundment?
			Yes No
		đ.	Are residues treated prior to disposal?
			Yes No
			If yes, are waste residues treated on-site or off-site?
			On-site Off-site
			Identify treatment method:
E.	Lan	d Dis	posal
	1.	land	restricted wastes placed in land disposal units such as fills, surface impoundments waste piles, wells, land treatment s, salt domes/beds, mines/caves, or concrete vault or bunker?
			Yes No
		Note	e: Do not include surface impoundments addressed in D, Treatment in Surface Impoundments.
			es, specify which units and what wastes each unit has ived:
	2.		s the facility operating record have notices and certifications from erators/storer/treaters [268.7(c); 268.7(a),(b)]?
			Yes No
	3.	to the	s the facility obtain waste analysis data or test the wastes (according the waste analysis plan) to determine that the wastes comply with the licable treatment standards [268.7(c)]?  Yes No
		If y	es, at what frequency?

4.	If restricted wastes that exceed the treatment standards are placed in land disposal units (excluding national capacity variances) [268.30(a)], does facility have an approved waiver based on no migration petition [268.6], an approved case-by-case capacity extension [268.5], or variance [268.44]?
	Yes No
5.	Does the facility dispose of restricted wastes that are subject to a national capacity variance?
	Yes No
	If yes, are these wastes disposed of in a new, replacement, or laterally expanded landfill or impoundment that meets the minimum technology requirements (double liner and leachate collection)?
	Yes No
6.	Does the facility have notices [268.7(a)(3)] and records of disposal for disposed wastes that are subject to a national capacity variance, case-by-case extensions [268.5], or no migration petitions [268.6]?
	Yes No NA
7.	What is the volume of the restricted wastes disposed of to date?
8.	If the facility has a case-by-case extension, is the facility making progress as described in progress reports?
	Yes No NA

## APPENDIX B TREATMENT STANDARDS FOR F-SOLVENTS

	CONCENTRATION (IN MG/L)						
F001-F005 SPENT SOLVENTS	WASTEWATERS	OTHER WASTES					
Acetone	0.05	0.59					
N-butyl .	5.0	5.0					
Carbon disulfide	1.05	4.81					
Carbon tetrachloride	.05	.96					
Chlorobenzene	.15	.05					
Cresols (and cresylic acid)	2.82	.75					
Cycohexanone	.125	.75					
1,2-dichlorobenzene	.65	.125					
Ethyl acetate	.05	.75					
Ethyl benzene	.05	.053					
Ethyl ether	.05	.75					
Isobutanol	5.0	5.0					
Methanol	.25	.75					
Methylene chloride	.20	.96					
Methylene chloride (from the pharmaceutical							
industry)	12.7	.96					
Methyl ethyl ketone	0.05	0.75					
Methyl isobutyl ketone	0.05	.33					
Nitrobenzene	0.66	0.125					
Pyridine	1.12	0.33					
Tetrachloroethylene	0.079	0.05					
Toluene	1.12	0.33					
1,1,1-Trichloroethane	1.05	0.41					
1,2,2-Trichlor 1,2,2-trifluoroethane	1.05	0.96					
Trichloroethylene	0.062	0.091					
Trichlorofluoromethane	0.05	0.96					
Xylene	0.05	0.15					

Chemical Solvents

Wastes shipped to:

TSD NAME

TYPE OF

LOCATION EPA 10 NO.

**FACILITY** T/D HETHOOS

WASTE CODE

WASTE QUANTITY COMMENTS (shipment dates, waste descriptions, etc.)

, · · ·

Chemical Solvents Reclamation F002,3,5
Ross Incineration Incineration F002,3,5



Re: DHMM

Ashtabula County Permit No. 02-04-0567

Ms. Debbi Hall, Environmental Specialist Premix, Inc. P.O. Box 281 North Kingsville, Ohio 44068 December 3, 1982

Dear Ms. Hall:

This letter is in response to our telephone conversation of November 29, 1982. Based upon your comments and the October 1, 1982, document submittal for this facility, the RCRA compliance status of Premix, Inc. is as follows:

į	Description of Violation	<u>40 CFR</u>	<u>OAC</u>
1.	The revised Waste Analysis Plan is still deficient in a delineation of approved sampling techniques, required parameters and analytical procedures.	265.13 (b)	3745-55-13 (B)
2.	As the primary emergency coordinator, Ken Roxberry should be included in your training program and all appropriate records for him maintained. Formalize dates of training and describe the types of training received by your nine (9) hazardous waste handlers.	265.16 (a) thru (e)	3745-55-16 (A) thru (E)
3.	I understand that the Contingency Plan (September 1982) has now been incorporated into the Plant Safety Manual. Please forward a copy of this manual. This manual must include all items required in the hazardous waste regulations.	265.51 thru 265.56	3745-55-51 thru 3745-55-56
4.	As we agreed, the Closure Plan (September 17, 1982) needs revision to reflect appropriate maximum volumes, disposal options and costs, and decontamination procedures.	265.112 265.113	3745-56-03 3745-56-04
5.	Please forward example copies of your storage inspection log and waste handling/operating log as requested in my August 18, 1982, letter.	265.174 265.73 (b)( (b)(2),(b)	3745-56-54 (1), 3745-55-73 (5) (B)(1),(B)(2), (B)(5)

Re: DHMM

Ashtabula County Permit No. 02-04-0567 TO EL 1982 BRANCA

Ms. Debbi Hall, Environmental Specialist Premix, Inc.
P.O. Box 281
North Kingsville, Ohio 44068

August 18, 1982

Dear Ms. Hall:

Thank you for the courtesies extended by you during my June 22, 1982, inspection at the Premix, Inc., facility. Mr. Gary Gifford, of this office, accompanied me at that time. The purpose of this inspection was to ascertain compliance with State and Federal hazardous waste management rules. A copy of the inspection report is enclosed for your information. This inspection report will become a part of the official records of the Ohio Environmental Protection Agency's Division of Hazardous Materials Management, and will also be forwarded to Ms. Kathy Homer of U.S. EPA, Region V.

During the inspection, we discussed the analytical procedures you had undertaken relative to the ignitable/nonignitable character of the waste resin paste, and had the opportunity to view a bench demonstration in your laboratory. The Agency is in receipt of your June 30, 1982, letter which delineates the various analytical procedures undertaken and the physical composition of the waste. Considering the present RCRA definition of ignitable solid and the currently available testing procedures, the Ohio EPA recognizes your change in status for the waste resin paste to be a nonhazardous characteristic. As this change in status influences the content of your Part A permit application, you may wish to submit a revised Part A application to U.S. EPA, Region V, and the Ohio Hazardous Waste Facility Approval Board, with appropriate justification comments included. At the State level, this matter will be handled through permit modification procedures.

The inspection report indicates that the following violations exist at the Premix, Inc., storage facility:

Description of Violation	40 CFR	OAC
<ol> <li>The existing Waste Analysis Plan should be expanded to include sampling techniques, analytical procedures, frequency of analysis, and parameters necessary to assure proper storage of wastes.</li> </ol>		3745-55-13 (B)
<ol> <li>The written inspection plan should indicate that the storage area should be inspected each day that handling/loading activities occur.</li> </ol>	265.15 (b)(4)	3745-55-15 (B)(4)

Ms. Debbi Hall Premix, Inc. August 18, 1982 Page Two

Description of Violation			40 CFR	OAC
	3.	Personnel training records should be for- malized for all personnel associated with waste handling activities. Types of training should be described all dates of training documented.	265.16 (a) thru (e)	3745-55-16 (A) thru (E)
	4.	The existing plant emergency plan should be expanded to meet the requirements of a Contingency Plan for hazardous waste.	265.51 thru 265.56	3745-55-51 thru 3745-55-56
	5.	An operating record should be maintained for the waste solvents, in addition to the waste paint.	265.73 (b)(1),(2)	3745-55-73 (B)(1),(2)
	6.	Inspections of the storage area should be documented;	265.174	3745-56-54
	7.	and maintained as a part of the operating record.	265.73 (b)(5)	3745-55-73 (B)(5)
	8.	The existing Closure Plan needs to be amended due to status change of waste resin paste. Decontamination steps should be discussed. Wastes must be removed from the site within 90 days of receipt of the final volume. (Note: A revised closure cost estimate may be appropriate.)	265.112 265.113	3745-56-03 3745-56-04

Please submit documentation for correction of the above noted violations to my attention, at the Northeast District Office of the Ohio EPA, within thirty (30) days of receipt of this letter.

Please feel free to contact me, or Ms. Kathy Homer at (312) 886-7435, if you have further questions.

Sincerely,

Deborah J. Berg, R.S. Environmental Scientist Division of Hazardous Materials Management

#### DJB:cl1

#### Enclosure

Mr. Bob Fragale, Hazardous Waste Facility Approval Board, Central Office Ms. Paula Cotter, Div. of Hazardous Materials Management, Central Office

### RCRA Inspection Report

EPA Identification Number OHD	004200044	•
HMFAS Permit Number (if appropria	ate) <u>02-04- 0507</u>	
Facility Name Premix, Inc.	(mailing: 20. Box 281)	1
Location Hormon Road & Route	20	
North Kingsville	, Ohio Ohio 44068	•
Person(s) Interviewed	Title	Telephone
Debbi Hall	Environmental Specialist	216-224-2181
	Section 2.	
Inspector(s)	Agency/Title	Telephone
Deborah J. Berg	Ohio EPA Enu. Scientist	216-425-917/
	· Ohio EPA	
•	Ohio EPA	
	Installation Activity	•
Mark One	If the site is a TSD	F, check the boxes
Generator only (G)	indicating Which for	ms were used -
Transporter only (T)	and Prevention	ty Standards, Preparedn , Contingency and ifests/Records/Reportin
TSDF only	Groundwater Mo	
G-T	Closure and Po	
「ビ」 G-TSDF	Financial Requ	
T-TSDF	Containers SO1	11 chiencs
G-T-TSDF	Tanks S02/T01	•
// Waste Piles SO3	Surface Impound	dments S04/T02
	•	hermal Treatment 103
Landfills D80		cal/Biological TO4

RCRA INTERIM STATUS INSPECTION FORM U.S. EPA I.D. NO. OHD 004200044

Location: Harmon Road & Route 20 PART 1. GENERAL INFORMATION Facility: Premix Inc. Address: P.O. Box 281 City: North Kingsville State: Ohio Zip Code: 44068 County: Achtabula Telephone: 3/6-324-3/8/ Facility Operator: Debbie Hall Title: Environmental Specialist Telephone: 214-224-2181 Facility Owner: Premix, Inc. Address: P.O. Box 281 . City: North Kingsville State: Ohio Zip Code: 44068 Telephone: 210-224-2181 Date of Inspection: 6-22-92 Time of Inspection: (Start) 1:00 pm (Finish) 4:00 p.m. Advance Notification? No V Yes: <u>scheduled 6-14-82</u> Weather Conditions: partly sunny temp. low 70°s F. INSPECTION PARTICIPANT(S) (Telephone) (Title) (Name) Debbi Hall Environmental Specialist 216-224-2181 Gary Gifford Environmental Scientist - OEPA 216-425-9171

### INSPECTOR(S)

(Name)	(Title)	(Telephone)
Deberah T. Berg	Environmental Scientist	316-435-9171
		. ,
		Constitution of the Consti
Type(s) of hazardous waste site acti	vity: A. V Generation B. V Stor	•
Specific hazardous wastes handled at		
a) Listed Wastes: Fooa, Fooa	, Foot solvent waste consisting pred	Weeknaathi of
	roetone & Goluene.	
b) Non-Listed Wastes:I D001	D002 C D003 R D000 T	
5001 - joritable pail	et waste	
		<del>agamentaragunit, adament Erangeling ging agamen mangaminan a</del> ggiramentaraguning mendeling genera 6 eta 1600
Has this facility submitted a Part A	Permit Application?	garagin (garagan) (garagan and an displayed Garagin Advertice) (and an Advertice) (garagin Advertice) (garagin and an
Does this facility store, treat or d	ispose of any hazardous waste from any off-si	te domestic sources?
Yes, See Remark #	✓ No	•

5.	Does this facility store, treat or dispose of any hazardous waste from any foreign sources?
	Yes, See Remark #
6.	Does this facility transport hazardous waste materials off-site for itself or other generators?
	Yes, Complete Part 3 (Transp.) No
	a) Applicable U.S. EPA I.D. Number
	b) Ohio P.U.C.O. GR TRSF Number
7.	A brief description of site activity:
	storage in drams (maximum) 11,550 gullons & 210 drams) of listed solvents ?

### REMARKS, PART 1. (GENERAL INFORMATION)

Company originally considered a waste vesin paste to be bool. Subsequent yesting of this waste by the company has considered demonstrated the waste is not bool (ignitable solid) by currently available desting procedures (company statement attacked).

		RCRA INTERIM STATUS INSPECTION FORM				
PAR	Τ 2.	GENERATOR REQUIREMENTS	gaine anaphalaithean an gl	· · · · · · · · · · · · · · · · · · ·	and a second second	and the state of t
÷	-		<u>Yes</u>	No	N/A	Remark #
1.	kno	hazardous waste(s) generated at this facility have been tested or are activated by hazardous waste(s) as defined in Sections 261 and 3745-51 in appliance with the requirements of Sections 262.11 and 3745-52-11.	<u>/</u>	Constant and	ರಿಸಿಕ <del>ಾತಿ</del> ಂದಿಸಿದು	Research #1
2.	tio	es this facility generate any hazardous wastes that are excluded from regula- on under Sections 261.4 and 3745-51-04 (statutory exclusions) or Sections .6 and 3745-51-06 (recycle/reuse)?	, <b>LONGO</b>	<u>V</u>	`	State of the state
3.	fro and	es this facility have waste or waste treatment equipment that is excluded om regulation because of totally enclosed treatment (Sections 265.1(c)(9)   3745-55-C-9 or via operation of an elementary neutralization unit and/or treatment unit (Sections 265.1(c)(10) and 3745-55-C-10.	. والمهوالماليات	· . <u> </u>	фактивнічені Іга	<del>premius, premius, na primary a mana</del>
4.		generator meets the following requirements with respect to the preparation, and retention of the hazardous waste manifest:		٠,	-	٠
	a)	The manifest form used contains all of the information required by Sections 262.21(a), (b) and 3745-52-21-A-B and the minimum number of copies required by Sections 262.22 and 3745-52-22.	<u> </u>	<b>Communication</b>	gaugephoops	
	b)	The generator has designated at least one permitted disposal facility and has/will designate an alternate facility or instructions to return waste in compliance with Sections 262.20 and 3745-52-20.	<u> </u>	ecciminate d	· <del></del>	
	c)	Prepared manifests have been signed by the generator and initial transporter in compliance with Sections 262.23 and 3745-52-23.	1	<del>(2001</del>		
	d)	The generator has complied with manifest exception reporting requirements (investigate after 35 days, report after 45 days) in Sections 262.42(a), (b) and 3745-52-42.	cimina/Al/Onca	a maximum ij	V	at Whis tim
	e)	Signed copies of all hazardous waste manifests and any documentation required for Exception Reports are retained for at least 3 years as required by Sections 262.40 and 3745-52-40.	<u> </u>	. <u></u>		

			<u>Yes</u>	No	N/A	Remark #
5.	The	generator meets the following hazardous waste pre-transport requirements:			•	
	a)	Prior to offering hazardous wastes for transport off-site the waste material is packaged, labeled and marked in accord with applicable DOT regulations (Sections 262.30, 262.31 and 262.32(a) and 3745-52-30, 52-31, and 52-32-A).	L	<b>്ര</b> ംമരുപ്പു	. المعارفة ا	Standard Street water review for 1944 (1945)
	b)	Prior to offering hazardous wastes for transport off-site each container with a capacity of 110 gallons (416 Liters) or less is affixed with a completed hazardous waste label as required by Sections 262.32(b) and 3745 52-32-B.	L	emorabies	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	<b>Anni Stanle</b>
•	c)	The generator meets requirements for properly placarding or offering to properly placard the initial transporter of the waste material in compliance with Sections 262.33 and 3745-52-33.		ShoФ <del></del>	no-re-initia	
ō.	The	generator meets the following recordkeeping and reporting requirements:				
	a)	The generator has submitted an annual report for all hazardous waste shipped off-site as required by Sections 262.41(a) and 3745-52-41-A-B.	<u> </u>	<del>(2011) - 11-1</del> 0	e	del constructivo de la construcción de la construcc
		The generator has submitted an annual report for all hazardous waste treated, stored or disposed of on-site as required by Sections 262.41(b) and 3745-52-41-C and in compliance with Sections 265.71 and 3745-55-71, when applicable.	<u> </u>	;	· Portuneros	CONTINUED AND THE CONTINUED
•	Haza acco	rdous wastes imported from or exported to foreign countries are handled in rdance with the requirements of Sections 262.50 and 3745-52-50.	<del></del>		1	brane'es - summer es a vastatante
•	tank Sect	he generator elects to store hazardous waste on-site in <u>containers</u> or <u>s</u> for <u>90 days</u> or less without a RCRA storage permit as provided under ions 262.34 and 3745-52-34, the following requirements with respect to storage are met:		Standard Comme	<u> </u>	
		Containers: the waste is stored in closed containers which meet all applicable DOT pre-transport requirements for packaging, labeling and marking.	,	CONTRACTOR OF THE PROPERTY OF	<u> </u>	

		<u>Yes</u>	No	N/A	Remark #
b)	The date that accumulation began is clearly marked on each container.	d California and a strong	-	1	Control of the Contro
c)	The area where containers are stored is inspected for evidence of leaks or corrosion at least weekly and such inspections are documented (265.174 and 3745-56-54).	BMMSQuellellich	(Millendows/Milled)	<u> </u>	Control of the partners of the state of the
d)	Containers holding ignitable or reactive waste(s) are located at least 50 feet (15 Meters) from the property line (Sections 265.176 and 3745-56-56), and the general requirements for handling such wastes in Sections 265.17 and 3745-55-17 (physical separation, signs and safety) are met.	***		· <u>/</u>	
e)	Tanks: the tank(s) are operated in compliance with the safety requirements of Sections 265.17, 265.192(b), 3745-55-17 and 56-72-B and are equipped with a waste-feed cutoff or bypass system as required in Sections 265.192(d) and 3745-56-72-D.			<u></u>	On the control of all the control of
f)	Uncovered tanks have at least 2 feet (60 cm.) of freeboard <u>unless</u> they are equipped with a spill containment system with a capacity that equals or exceeds the volume that 2 feet of freeboard would otherwise provide (265.192 (c) and 3745-56-72-C).	<del>Omer No</del>	он меретипи	<u> </u>	
g)	Daily inspections are made of all systems pertinent to the proper operation of the tank: discharge and cutoff, monitoring equipment, tank level and freeboard (265.194 and $3745-56-74-\Lambda-B-C$ ).	<u> </u>	stronome-sp	· .	CONTRACTOR OF THE PROPERTY OF
h)	Weekly inspections are made of all tank construction materials and containment structures (265.194 and 3745-56-74-D-E).	<del></del>	· ·	<u> </u>	Description of the second state of the second
tion men	generator has provided a Personnel Training Program in compliance with Sec- ns 265.16(a)(b)(c) and 3745-55-16-A-B-C including instruction in safe equip- t operation and emergency response procedures, training new employees within		·		
6 m	onths and providing an annual training program refresher course (Sections .34 and 3745-52-34).	<del>040***********</del>	<u> </u>	THEOREM SAN	see Part 4, <u>Subject</u> E
3748	generator keeps all of the records required by Sections 265.16(d)(e) and 5-55-16-D-E including written job titles, job descriptions and documented loyee training records (Sections 262.34 and 3745-52-34).		<u> </u>	•	· ·

2-3

10.

Yes

No

N/A

Remark #

	·		•		
٦.	Whenever a tank is permanently taken out of service or upon closure of the fa	86			
. , ,					
	cility all hazardous wastes and residues are removed and properly disposed of	ř			•
	(Sections 265,197 and 3745-56-77) as referenced in Sections 262.34 and 3745-				
	(Sections for 13) and Sydomore, as releighed in Sections for 34 and 3740.				
	FO 24			. /	
	52-34.			. V	
		-	 \$4-1-10-20-5-0	*********	

SHORT-TERM STORAGE FOR 90 DAYS OR LESS IN TANKS AND CONTAINERS ALSO REQUIRES THAT REGULATIONS IN SECTION 265, SUBPARTS C AND D (PREPAREDNESS AND PREVENTION PLUS CONTINGENCY AND EMERGENCY) AND 3745-55-30 THRU 37 AND 3745-55-50 THRU 70 BE MET. COMPLETE THESE SECTIONS OF THE INSPECTION FORM UNDER PART 4 - GENERAL INTERIM STATUS REQUIREMENTS.

#### REMARKS, PART 2. GENERATOR REQUIREMENTS

Remark #1 Classification of solvent waste as hazardous has been based upon the company's knowledge of the waste I show material date sheets. Point waste has been should other destring to be ignitable and not PP solve. Material date sheets exist for point components as well as the resin paste waste (Rumert, Porti).

### PART 4. GENERAL INTERIM STATUS REQUIREMENTS

EPA 9303

	SUBPARTS INCLUDED				
B: C: D:	The state of the s	H: F	inanci	al Requ	uirements
	Subpart B: General Facility Standards				
		Yes	No	N/A	Remark #
	The operator has a detailed chemical and physical analysis of the waste material containing all of the information which must be known to properly treat or store the waste as required by Sections 265.13(a)(1) and 3745-55-13-A-2.	.Y.			·
2.	The operator has a written waste analysis plan which describes analytical parameters, test methods, sampling methods, testing frequency and responses to any process changes that may affect the character of the waste (Sections 265. 13(b) and 3745-55-13-B).		· /	***************************************	
	If required due to the actual hazards associated with the waste material, the operator has prevented unauthorized access to the active portions of the facility and has provided the following features and equipment (Sections 265.14 and 3745-55-14).	:			
	a) 24-hour surveillance system.		Population	GDIs-shimmung.	2 days a week
	b) Artificial or natural barrier completely surrounding the active portion of the facility.		edminiprocess of the	<del></del>	Setal plant ferced
	c) Controlled entry (gates, monitors) to the active portion of the facility at all times (265.14(2)(ii) and 3745-55-14-B-2-b).	· ;		<del>Carles and C</del>	access controlled
	d) "Danger-Unauthorized Personnel Keep Out" signs at each entrance to the active portion of the facility (265.14(c) and 3745-55-14-C).	<u> </u>		· ·	or storage were

4-]

		Yes	No	N/A	<u>Remark #</u>
4.	The operator must develop and follow a comprehensive, written inspection plan and must document the inspections, malfunctions and any remedial actions taken in an operating record log which is kept for at least three years. The plan	<b>F</b>			
	includes the following elements: (Section 265.15 and 3745-55-15)	×	*************		copy attached
	a) Inspect emergency equipment.	~		P07	ESCON ATTO CONTRACT AND
	b) Inspect monitoring equipment.	•			·
	c) Inspect security, alarm and communication devices.	<u> </u>			
	d) Inspect process equipment (pipes, pumps, etc.).			$\checkmark$	<del></del>
	e) Inspect containment structures (dikes, curbs, etc.).		<del></del>	<u> </u>	± 4024-022-020-0-7-
	f) Inspect facility for structural malfunctions (roof, floor, etc.).		<del></del>	<u> </u>	
	g) Inspect hazardous waste handling/loading areas each day used.		<u>/</u>		
	h) Record of any malfunctions due to equipment or operator errors.			<u>/</u>	at this time
	i) Record of any hazardous waste discharges.	transactus (Transactus)		~	at this time
5.	The facility has provided a Personnel Training Program in compliance with Sections 265.16(a)(b)(c) and 3745-55-16-A-B-C including instruction in safe equipment operation and emergency response procedures, training new employees within 6 months and providing an annual training program refresher course.		· ·		Rumark ± 1
=	The facility keeps all records required by Sections 265.16(d)(e) and 3745-55-16-		<u></u>		<u> </u>
	D-E including written job titles, job descriptions and documented employee training records.	, a <del>u,</del>	1		Remark#1
7.	If required due to the actual hazards associated with Ignitable, Reactive or incompatible waste materials, the facility meets the following requirements (Sections 265.17 and 3745-55-17).				

EPA 9303

			<u>Yes</u>	<u>No</u>	N/A	Remark #
	a)	Protection from sources of ignition.	V		<del></del>	· .
	b)	Physical separation of incompatible waste materials.	processioner		<u> </u>	
	c)	"No Smoking" or "No Open Flames" signs near areas where Ignitable or Reactive wastes are handled.	<u></u>		warkondorens	
	d)	Any comingling of waste materials is done in a controlled, safe manner as prescribed by Sections 265.17(b) and 3745-55-17-B.	***************************************		<u> </u>	
		Subpart C: Preparedness and Prevention				
1.	Has thi	there been a fire, explosion or non-planned release of hazardous waste at s facility? (265.31 and 3745-55-31).		<u></u>	apanga andaba	
2.	If i	required due to actual hazards associated with the waste material, the fa- ity has the following equipment: (265.32 and 3745-55-32).	<u>/</u>			
	a)	Internal alarm system.	V			plant alarm system tied to N Kingsville
	b)	Access to telephone, radio or other device for summoning emergency assistance.	<u> </u>	, con		telephone access to coordinators office of
	c)	Portable fire control equipment.	<u> </u>			to outside assistant
	d)	Water at adequate volume and pressure via hoses sprinkler, foamers or sprayers.	<u> </u>	Salvalla Havalla validida		budrant Thoses at
},	All as n	required safety, fire and communications equipment is tested and maintained necessary; testing and maintenance are documented. (265.33 and 3745-55-33).	$\angle$			storage avea.
	sonn	required due to the actual hazards associated with the waste material, per- nel have immediate access to an emergency communication device during times a hazardous waste is being physically handled (Sections 265.34 and 3745-55-		,		
	34).	man and made to being physically handled (sections 205.54 and 5745-55-	<u> </u>	Califf Land	<u> </u>	***************************************

			Yes	Ň.	K1 / 8	
t	;	If required due to the set of	162	No	N/A	Remark #
		If required due to the actual hazards associated with the waste material, adequate aisle space to allow unobstructed movement or emergency or spill				
		control equipment is maintained (265.35 and 3745-55-35).	. 1/			
6		If required due to the actual hazards accominted with the	<u></u>	**********		<del></del>
ŧ		service authorities to familiarize them with the possible hazards and the facility layout (265.37(a) and 3745-55-37-A).				
7		,	<u></u>			<del></del>
/	0	Where state or local emergency service authorities have declined to enter			•	•
		into any proposed special arrangements or agreements the refusal has been documented (265.37(b) and 3745-55-37-B).				
			. ————	C	<u> </u>	
		Subpart D: Contingency and Emergency			•	
1.	•	The facility has a written Contingency Plan designed to minimize hazards from				•
		fires, explosions or unplanned releases of hazardous wastes (265.51 and 3745-551) and contains the following components:	•			
			·	V		Recark # 3
	ā	) Actions to be taken by personnel in the event of an emergency incident.		V		
	b	) Arrangements or agreements with local or state emergency authorities.	,		<del>*************************************</del>	<del></del>
	C		<del></del>	<u> </u>	<del></del>	//
	_	Names, addresses and telephone numbers of all persons qualified to act as emergency coordinator.				
	d	A list of all emergency equipment:				
	-	A list of all emergency equipment including location, physical description and outline of capabilities.				
	е		#300-000000	<u>V</u>	<del></del>	l)
	Ĭ	an evacuation plan for facility personnel (Sections 265 51/5) and 2745 55				
		51-F).				Remark #3
2.	Α	copy of the Contingency Plan and any plan revisions is maintained on-site and			<del></del>	Names 3
		ght be required to participate in the execution of the plan. (Sections 265.				•
ĘDΛ		•	*.	<u> </u>	<del></del>	Remark #4
EPA	93	U3 4-4				

				<u>Yes</u>	No	N/A	Remark #
3,	Th fa	e plan is revised in response to facility, equipment and personnel changes (ilure of the plan (265.54 and 3745-55-54).	or	<u> </u>			evisting plan was revised on
4.	the	emergency coordinator is designated at all times (on-site or on-call) is miliar with all aspects of site operation and emergency procedures and has e authority to implement all aspects of the Contingency Plan (Sections 265, and 3745-55-55).		·	Y		6(Cas114)
5.	and	an emergency situation has occurred, the emergency coordinator has implented all or part of the Contingency Plan and has taken all of the actions d made all of the notifications deemed necessary under Sections 265.56 d 3745-55-56.		· · · · · · · · · · · · · · · · · · ·	· ·	<u> </u>	Specific distribution of the specific distrib
		<u>Subpart E: Manifests/Records/Report</u>					÷
NOT	E:	THE FOLLOWING REQUIREMENTS ARE APPLICABLE TO $\underline{BOTH}$ ON-SITE AND OFF-SITE TREAFACILITIES.	ATMENT,	STORAG	E AND	DISP	OSAL
				Yes	<u>No</u>	N/A	Remark #
1.	The by	e operator maintains a written operating record at his facility as required Sections 265.73 and 3745-55-73 which contains the following information:		<del>[</del>	<u> </u>		rujured Lor Waste Daint 4 <u>Waste Solvents</u>
	a)	Description and quantity of each hazardous waste treated, stored or disposed of within the facility and the date(s) and method(s) pertinent to such treatment storage or disposal (262.73(b) (1) and 3745-55-73-B-1).			·		
	b)	Common name, EPA Hazardous Waste Identification Number and physical state (liquid, solid, gas) of the waste(s).		,	,/	<del></del>	Andrews Control of the Control of th
	c)	The estimated (or actual) weight, volume or density of the waste material(s).		gen-li-valpania	·	**************************************	· Andrews in the second
	d)	A description of the method(s) used to treat, store or dispose of the waste(s) using the EPA Handling Codes listed in 45 FR 33252 (May 19, 1980)	•		<u></u>	***************************************	Application of State

4-5

EPA 9303

			Yes	No	N/A	Remark#	
	e)	The present physical location of each hazardous waste within the facility.	واستواما	<u>V</u>			
	, <b>f</b> )	FOR DISPOSAL FACILITIES, the location and quantity of each hazardous waste recorded on a map of the facility and cross-references to any pertinent manifest document number(s) (265.73(b) (2) and 3745-55-73-B-2).			<u>/</u>		
	g)	Records of any waste analyses and trial tests required to be performed.	<u></u>		<del></del>		
	h)	Records of the inspections required under Sections 265.15 and 3745-55-15 (General Inspection Requirements - Subpart B).	Mindle or a	<u> </u>		,	of storage documented
	i)	Records of any monitoring, testing or analytical data required under other Subparts as referenced by Sections $265.73(b)(6)$ and $3745-55-73-B-6$ .	nidologum <sub>ad 4,5</sub> 50a		<u> </u>		
	j)	Records of Closure cost estimates and Post-Closure (DISPOSAL ONLY) cost estimates required under Subpart H and Section 3745-56-30, 32 and 34.	V	-			
2.	pont	operator has submitted an annual Treatment-Storage-Disposal Operating Re-t (by March 1) containing all of the operating information required under tions 265.75 and 3745-55-75.	<u> </u>			-	
<u>10T</u>	<u>Е:</u> Т	THIS REPORT IS NOT THE SAME AS THE REPORT REQUIRED TO BE FILED BY GENERATORS	UNDE	R SECT	TIONS	262.41 AND	
•	wasi	applicable, the operator has submitted reports on releases of hazardous es, fires, explosions, groundwater contamination data and facility closure .77 and 3745-55-77).	············		<u> </u>		
ОТЕ	<u>:</u> ⊤	HE FOLLOWING REQUIREMENTS ARE APPLICABLE TO ONLY OFF-SITE TREATMENT, STORAGE	E ÁND	DISPO	SAL FA	ACILITIES.	
	che i	fests received by the facility are signed and dated; one copy is given to transporter, one copy is sent to the generator within 30 days and one copy ept for at least 3 years (Sections 265.71 and 3745-55-71).			<b>/</b> '		
	٠.		<del></del>	***************************************	<u></u>		

EPA 9303

		<u>Yes</u>	<u>No</u>	N/A	Remark #
	a) If shipping papers are used in lieu of manifests (bulk shipments, etc.) the same requirements are met (265.71(b) and 3745-55-71-B).			<u> </u>	
	b) Any significant discrepancies in the manifest, as defined in Sections 265.72(a) and 3745-55-72-A, are noted in writing on the manifest document (Sections 265.71(a)(2) and 3745-55-71-A-2).		· .	<u>/</u>	
5.	Any manifest discrepancies have been reconciled within 15 days as required by Sections 265.72(b) and 3745-55-72-B or the operator has submitted the required information to the Regional Administrator/Director.	-		¥	National Confession of Confess
6.	If the facility has accepted any unmanifested hazardous wastes from off-site sources (except from small quantity generators) for treatment, storage or disposal an unmanifested waste report containing all the information required by Sections 265.76 and 3745-55-76 has been submitted to the Regional Administrator/Director within 15 days.			<u> </u>	
	Subpart F: Groundwater Monitoring		•		
NOT	E: THESE REQUIREMENTS ARE APPLICABLE TO SURFACE IMPOUNDMENTS, LANDFILLS AND LAND AND AFTER NOVEMBER 19, 1981.	TREA	TMENT	FACIL	ITIES ON
	<u>\</u>	<u>′es</u>	No	<u>N/A</u>	Remark #
1.	The facility has implemented one or more of the following alternatives with respect to the Groundwater Monitoring requirements in Sections 265.90(a) and 3745-55-90-A:				
	a) A Groundwater Monitoring System meeting the minimum requirements of Sections 265.91 and 3745-55-91 has been installed which is sampled, tested and operated in accordance with the requirements of Sections 265.92, 265.93, 265.94, 3745-55-92, -93 and -94.	·		./	
				<u></u>	

			<u>Yes</u>	<u>No</u> .	<u>N/A</u>	Remark #
	b)	A waiver of all or part of the Groundwater Monitoring requirements has been obtained by demonstrating a low potential for the migration of hazardous wastes and constituents in accordance with the requirements of Sections 265.90(c) and 3745-55-91-C.	، نوسمورواسانشان	, , , , , , , , , , , , , , , , , , ,	<u>V</u>	gyadd annu antar eu all deillion de characht (f
	c)	An alternate Groundwater Monitoring System Plan that was first submitted to the Regional Administrator/Director was implemented and is operated and maintained in accordance with Sections 265.90(d) and 3745-55-90-D.	ورسممتيدي	**************************************	<u>V</u>	ngay yaya ahada da dhada da dha aha aha aha aha
		Subpart G: Closure and Post-Closure				•
NO.	TE:	THE FOLLOWING REQUIREMENTS ARE APPLICABLE TO BOTH DISPOSAL AND NON-DISPOSAL F	ACILI	TIES:		•
			Yes	<u>No</u>	N/A	Remark #
1.	A w	written Closure Plan is on file at the facility and contains the following ements: (Sections 265.112 and 3745-56-03)	<u> </u>			Bemark #5
	a)	A description of how and when the facility will be closed (265.112(a)(1) and $3745-56-03-A-1$ ).	<u>.</u>	<del></del>		MACONING CONTRACTOR
	<b>b)</b>	A description of how any of the <u>applicable</u> closure requirements in other Subparts of Sections 265 and 3745-55,-56,-57,-58 (Tanks, Surface Impoundments, Landfills, etc.) will be carried out.	· · · · · · · · · · · · · · · · · · ·		<u></u>	<del></del>
÷	c)	An estimate of the maximum amount of hazardous wastes being treated or in storage at the facility.	<u> </u>			· · · · · · · · · · · · · · · · · · ·
	d)	A description of steps taken to decontaminate facility equipment.	-	×		<del>}</del>
	e)	The year closure is expected to begin and a list of dates over which the various phases of closure are expected to be completed.	<del></del>	<u>/</u>	, <del>(20-0-1-10</del>	Remark #5
2.		Closure Plan has been amended within 60 days in response to any changes in ility design, processes or closure dates.	<u> </u>	emet Schwerp de Stig		nowly revised plan with be developed due
		1.0				On about 1.25 pm

4-8

•		<u>Yes</u>	, <u>No</u>	N/A	Remark #
3.	The Closure Plan has been submitted to the Regional Administrator/Director 180 days prior to beginning the Closure process.		<del></del>	<u>/</u>	
4.	If Closure has been completed, the facility was closed in a manner which minimizes any future problems in compliance with the Closure performance standard in Sections 265.111 and 3745-56-02.			V	
ı	a) The facility has been closed within the time limits specified in Sections 265.113 and 3745-56-04.	<del></del>	<del></del>	· V	**************************************
	b) Upon completion of Closure all facility equipment and structures were de- contaminated and any hazardous residues were properly disposed of (265.114 and 3745-56-05).	_			
	c) Completion of Closure has been certified to the Regional Administrator by the Owner/Operator and an independent Professional Engineer (265.115 and 3745-56-06).	California and Califo	Opposite MARKET	V	
NOT	E: THE FOLLOWING REQUIREMENTS ARE APPLICABLE TO ONLY DISPOSAL FACILITIES.				
5.	A written Post-Closure Plan is on file at the facility which describes all Post Closure activities and addresses all of the plan elements required by Sections 265.118(a) and 3745-56-08-A.	<del>-</del> ->			· .
6.	The Post-Closure Plan has been amended within 60 days in response to any changes in facility design or operation.	(MANA) (TATA-O-O-O-O-O-O-O-O-O-O-O-O-O-O-O-O-O-O	Saltoropagas	·	<sup>*</sup> <del>«Май-чактум-шеруйлеру—Соучастью</del>
7.	The Post-Closure Plan has been submitted to the Regional Administrator/Director 180 days prior to beginning Closure.	Commonwealth Commo		<u> </u>	
8.	The Owner/Operator has submitted all of the information on prior use of the property required in Sections 265.119 and 3745-56-10 to the Local Land Authority within 90 days after Closure is completed.	econscionables)	Çanaşıları	·	·
		<del></del>	entrance, and	<del></del>	<del></del>

EPA- 9303

		Yes	No	N/A	Remark #
9.	The property owner has attached a notation to the property deed or other instrument which will notify any potential purchaser that the property has been used to manage hazardous waste and future use of the property is restricted under Sections 265.117(c) and 3745-56-08-C as required in Sections 265.120				
	and 3745-56-10.	<del>ijagama Kapalakij</del>	<del>0,- , 200</del>	<u> </u>	<del></del>
	Subpart H: Financial Requirements	. ′			
1.	A written cost estimate for Closure of the facility (by the methods and procedures specified in the facility Closure Plan) is available for review on and after May 19, 1981 (Sections 265.142 and 3745-56-32).	1/			

NOTE: REGULATIONS PROMULGATED IN 46 FR 2877-2892 IN REGARD TO FINANCIAL REQUIREMENTS HAVE BEEN STAYED UNTIL OCTOBER 13, 1981 AND MAY BE AMENDED OR REPROPOSED AT THAT TIME.

#### REMARKS, PART 4. GENERAL INTERIM STATUS REQUIREMENTS

Remark#1 Training records need to be dermalized for all personnel immediately associated with waste handling activities, including inspection duties, operating log dunctions of contingency plan implementation. Various types of chaining conducted should be described a dates of chaining (a annual review) decumented.

Remark #2 Facility has on file a plant emergency plan which delineates duties & responsibilities for the emergencies within the plant. This plan should be expanded to specifically address spill & fire emergencies of the waste storage area.

Remark #3 Existing Plant con plan is inappropriate in wars instance, as plan indicates what a substantial number of plant employees would exist directly into the storage area. Remark #4 Expanded plan (see above) should be submitted when developed.

Remark #5 Closure plan needs revision due to change in has status of wasto rasin. Pay particular EPA 9303 attention to maximum volumes & chine 4-10 restrictions for waste removal after start of closure.

<b>5</b> .4.1		1/01/	H INTERIO STATOS INSPEC	ITON FOR	<u>"</u>	•			
PAI	RT 5. TREATMENT/STORAGE/DISPOSAL	-	SUBPARTS INCLUDED		. •	inneren minere mit ville general des debit del med innere se	<del></del>	dealthine data (A) (D) (or lawy (or to as a	
J:	Management of Containers Management of Tanks Surface Impoundments	M:	Waste Piles Land Treatment Landfills	Р:		Treatment		ogical	Treatment
		Subpa	art I: Management of C	ontainers				,	
		•				Yes	No	N/A	Remark #
1. 2.	Hazardous wastes are stored in clos condition and are compatible with t 171, .172, .173 and 3745-56-51,-52- The area where containers are stored	he wast 53).	es stored in them (Sec	tions 265		<u> </u>	es manerales	Отпонания	Carrier State State State Superpagne
<b></b>	corrosion at least weekly and such 3745-56-54).	inspect	ions are documented (26	f leaks o 65.174 an	r d	Симуцавческог	<u> </u>	C <del>o</del>	Inspections
TOV	E: FACILITIES OPTING FOR LONG TERM SUBJECT UNTIL THE CONTAINERS ARE ACTUALLY DATE. (SECTIONS 262 AND 3745-52)	I UFFEK	ARE NOT REQUIRED TO ME ED FOR TRANSPORT AND AF	EET PRE-T RE NOT RE	RANSPORT QUIRED TO	LABELING AFFIX AN	REQUI N ACCL	REMENT	Aocumen IS ION
					,	Yes	<u>No</u>	N/A	Remark #
3.	Containers holding (Ignitable) or Read (15 Meters) from the property line a such wastes in Sections 265.17 and 3 and safety) are met (265.176 and 374	ina the 3745-55:	CONORDI MOGUINAMONTO f	Though was	* 10 m				- -
· p	Incompatible waste materials are not contaminated containers unless it is conditions as specified in Sections 177(a), (b) and 3745-56-57-A-B).	: done i	under completely contro	hae hall	cafo				

EPA 9304

5. Containers holding hazardous wastes are never stored near other materials which may interact with the waste in a hazardous manner (Sections 265.177 (C) and 3745-56-57-C).

Yes No N/A Remark #

DHEMI. ., INC.

P. O. BOX 281

NORTH KINGSVILLE, OHIO 44068

PHONE (216) 224-2181

June 30, 1982

Ms. Debby Burg Ohio EPA Northeast Office 2110 E. Aurora Road Twinsburg, OH 44087

Dear Debby:

Regarding our conversation on paste waste, we do not feel that this waste should be classified a flammable solid. We have done numerous tests on this waste for flash points using the Pensky-Martin closed cup tester. We have tried igniting this waste, and samples were also analyzed by two different outside Labs.

The testing we've done consists of using six month old waste paste and letting the sample cans sit open for two weeks before we tried to ignite them, and also using a waste that was recently generated for comparison. Both samples reacted identically. On some of the samples there was an ignition and a small flame that gradually burnt across the sample, but in no way was the sample considered "burning vigorously".

Gilbert Laboratories of Reading, Pennsylvania, analyzed three paste samples for us, using their own ignitability test. The procedure is as follows:


- 1. Introduction of flame to sample at ambient temperature  $(24^{\circ}C)$ .
- 2. Introduction of flame to sample at 60°C.
- Gradual heating in an electric muffle furnace to 400°C.

Free-Col Laboratories, Meadville, Pennsylvania, analyzed five of our paste can samples using the test prescribed in 16 CFR, Section 1500.44, which is an amendment to 29 CFR, OSHA standards. In this test a sample is placed in a metal shaped boat and a flame is introduced to the sample at one end (the sample is not sheltered from the air). If the sample ignites and burns with a self-sustained flame at a rate greater than one-tenth of an inch per second along its major axis, it is considered flammable. None of the above samples exhibited the characteristics of a flammable solid when tested.

RECEIVED

JUL 1 - 1982

OHIO ENVIRONMENTAL PROTECTION AGENCY N. E. D. O.



September 28, 1981

Ms. Debbi Hall Environmental Specialist Premix, Inc. P.O. Box 281 North Kingsville, Ohio 44068

Dear Ms. Hall:

On September 22, 1981, Chris Frazier and Deborah Berg of the Ohio Environmental Protection Agency conducted an inspection of your facility as part of the Hazardous Waste facility permit review process. Your facility was represented by yourself.

Enclosed are two forms. The one titled "TREATMENT, STORAGE AND DISPOSAL FACILITY" is a copy of the form used during the inspection to evaluate your facility.

The other form, "DEFICIENCY NOTIFICATION TABLE", relates to the "TREATMENT, STORAGE AND DISPOSAL FACILITY" form and specifies what action must be taken where deficiencies were noted. A mark in column four of the "DEFICIENCY NOTIFICATION TABLE" denotes a violation of current regulations or pinpoints areas which will be covered by regulations not yet effective. The capital letter codes in column four are explained on the last page of the "DEFICIENCY NOTIFICATION TABLE".

You are hereby advised that total compliance with the regulations contained in 40 CFR 265 is required as a condition of continuing interim status with the U.S. EPA. Failure to list specific deficiencies in this communication does not relieve you from the responsibility of complying with all applicable regulations.

Very truly yours,

Paul Flanigan, P.E.

Hazardous Waste Materials Management

Paul Flanger

PF/maf

cc: Kathleen Homer, U.S. EPA, Region V Chris Frazier and Deborah Bert, NEDO

CERTIFIED MAIL

## DEFICIENCY NOTIFICATION TABLE ISS INSPECTION

FACILITY NO. - 81-HW-0567

OWNER - PREMIX, INC

FACILITY NAME - PREMIX, INC

FACILITY LOCATION - P-O. BOX 281, N. ICINGSUILLE, OHIO 4406 F

FACILITY CONTACT - DEBBI. HALL, ENVIRONMENTAL SPECIALIST

PHONE NO. (216)

224-2181

	COLUMN I	COLUMN II	COLUMN III	market many	COLUMN IV	COLUMN V	COLUMN VI
Page	Item No.	OAC Reference	USEPA Refere	nce	See Code Following	Refer To ISS Remark	OEPA
3	III A 1	3745-55-12(A)	265.12 (A)		nediningsper		•
un com ma transfer and transfer	8 <u>1</u>	3745-55-13 3745-55-13	265.13 265.13	B			and the second of the second o
**************************************	<u>C</u> 1	3745-55-14	265.14			Marian Company	
)	2 3 4	pus Bis The second se	. 50 66 .				
	D 1	3745-55-15	265.15	B		V.	
4	<u>z</u> 3 4	þ	H .	B Ps			
	<u>.</u> 5	\$8 58	99	·B			- The second
C	· 7	. 15	£8	В			
**************************************	E 1 2	3745-55-16	265.16	<u>B</u>		<u> </u>	
	3 4 5	B B	. SE	<u> </u>			The second secon
	6 F 1	3745-55-17	265.17		·		
<del></del>	2 3	» »	81 35				-
5	IV A ]	3745-55-31 3745-55-32	265.31 265.32				
	2 3 C 1	3745-55-33	\$6 \$9	- 1,			
·.	2	3745-55-34	265.33		emando depresada a proprio de la constanta de		
6	D 1 E V A 1	3745-55-34 3795-55-35 3745-55-52	265.34 265.35	· -			
	e // 1	3/40-00-04	265.52	' '			

						46
Page	Item No.	/ ? Reference	USEPA Referen	See Code Following	Refer To ISS Remark	OEP! Use
	A 2	3745-55-52	265.52			
	4 5	10 11	88 18			
7	B 1 C 1	3745-55-53 3745-55-55	265.53 265.55			
<del> </del>	2 3 	1) 1) 1) 1	1) 83			
	VI A 1	3745-55-56 3745-55-71	265.56 265.71			
8	B 1 C 1	3745-55-72 3745-55-73	265.72 265.73	B		
**************************************	2b C d	p	# #	U		
**************************************	e	FI FI	ę	B		<u>                                      </u>
	g	£\$	11	B		<u> </u>
9	VII A 7	3745-56-03	265.112	В		
	3 4	3745-56-32	265.142	В		
	VIII I I	3745-56-09 3745-56-51	265.118 265.171			
<del></del>	2 3 4	3745-56-52 3745-56-53	265.172 265.173			
description of the state of	<u>5</u>	3745-56-54 3745-56-56	265.174 265.176			
10		3745-56-57	<u>265.177</u>			-
*	J 7	3745-56-72	<u>265-192</u>			-
	<u>3</u>	3745-56-73	265-193			
<del></del>	<u>5</u> 6 7	3745-56-74 3745-56-78 3745-56-79	265.194 265.198			+-
		3745-56-78 3745-57-03	265.199 265.198 265.222			
	2 3	3745-57-04 3745-57-06	265.223 265.225			
	<b>4</b> 5	3745-57-07	265.226			
	6 7	3745-57-10 3745-57-11	265.229 265.230			

,		: -	•					•
		· · · · · -				•		
Carlo Say								
nage	Item	No.	OAC Reference	USEPA Refer	ence	See Code Following	Refer To ISS Remark	OEPA Use
12	٠.		3745-57-31 3745-57-32	265.251	. ,	-	•	
		<u> </u>	3745-57-32	265.252 265.258			and the second second	
	<del></del>	<u>4</u> 5	3745-57-36	265.256 **	<del></del>			
<del>-</del>		<u> 6</u>	3745-57-37	265.257				-
13		M 1	3745-57-37 3745-57-52	265.257 265.272			•	amplification and a supplication
		2 3	3745-57-53	265.273	And the second s			_
		4	3745-57-56	265.276				
		5	3745-57-58	265.278				To the second se
		6 7	3745-57-58	265.278	and the state of t			
		<u>/</u> 8	3745-57-59 3745-57-61	265.279 265.281				<u> </u>
		9	3745-57-62	265.282			•	•
14	. <i>I</i>	A 1 2	3745-57-72	265.302				
		3	gs Bs	. #5			haranna dhee ga karaban ya sa an	
		B 1 2	3745-57-79	265.309				
-		C 1 2	3745-56-03	265.112			•	
		3 4	3745-56-32	265,192				
		D 1	3745-57-82	265.312				
15			3745-55-17	265.17(b)	•			
		E 1	3745-57-83 3745-55-17	265.313 265.17(b)				
	•	F ]	3745-57-84	265.314				
-	<del> </del>	3	CONTRACTOR	94	<del>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</del>			
		<u>4</u> G 1	3745-57-85	265.315	-			
16	0	)&P B \ 1	3745-58-33	265.373				
	<u>.</u>	2	88	203.3/3 8				
	·	3 4	88	B				•
	II	5 A 1		265.375			The conference of the conferen	
<del></del>	£ A		b #	u B	· · · · · · · · · · · · · · · · · · ·			
17			C	<del> </del>	<del></del>			
	<del> </del>	2	а <u>3745-58-35</u> Б "	265.375	non the same with the same same same same same same same sam			
·		B 1	# # # # # # # # # # # # # # # # # # #	£6				
		2 3	\$\$	<b>(1)</b>	<u>.</u>			
· •		4 5	\$2	31 St				
					<u></u>	<u></u>		
				•				
			•				•	

Page	Item No		AC Reference	USEPA Refere	3	See Code Following	Refer To 0E ISS Remark Us
	III A		3745-58-37	265.377			
	C D		Q2 0.0	41 18			
			54 FE	69 89			
18	IV A	1	<u>3745-58-42</u>	265.382			
	Q	2 ]	<u>3745–58–51</u>	265.401		**************************************	
19		2 3	3745-58-52	265.402			
		4 5	3745-58-53 3745-58-55	265.403 265-405			
<u> </u>		6	3745-58-56 3745-52-40 3745-52-21	265.406 262.40 262.21			
20	<b>, , , , , , , , , , , , , , , , , , , </b>	<u>2</u> 3	3/43-32-21 8	202 - 21 R			
		# 5	<b>6</b>	E 68	•		
· · · · · · · · · · · · · · · · · · ·		<u>6</u> . 8	150-42	/22.\$			
v	2. (A)	)	3745-52-42 3745-52-30	262.42 262.30	-	The state of the s	
<u> </u>	(B) (C)	)	3745-52-31 3745-52-33	262.31 262.33		*	•
21	3	<u>1</u> 2	3745-52-34	262.34		nazyeyndirinati maqoojin le 1980 oo daddaan markedi oo <sup>m</sup>	
e 	<u> </u>		3745-56-54 3745-56-72	265.174 265.192			
•		<u>b</u>	2745 56 74	265.184		-	
		d e f	3745-56-74 3745-56-78 3745-56-79	265.198 265.199			
22	VI A B		3745-52-40 3745-52-41	262.40 262.41			
<del>-</del>	VII	la b	3745-52-50	-262.50			
Engraphica - Ch		с 2	n	14 31			
23 X	I II A		3745-53-22 3745-53-20	263.22 263.20			***
	В			16		1	

#### EY TO CODED ITEMS (COLUMN IV)

- A. Because the inspection at this facility was conducted prior to May 19, 1981, requirements which became effective on that date were not checked. These requirements are now effective and must be met as a condition of interim status under the federal regulations and as part of the consideration for issuance of an Ohio Hazardous Waste Permit.
- B. or C. The inspection revealed a deficiency in compliance with this item, which must be satisfactorily corrected. A determination of compliance will be made in the future.
- D. The inspection revealed a violation of regulations pertaining to this item. Since the environmental consequences of this violation may be quite serious this problem must be corrected as soon as possible. We will schedule another inspection no sooner than 10 days after the date of this letter to determine if compliance has been achieved. Further steps in the permitting process will be delayed until the re-inspection.
- E. Regulations concerning this item will become effective November 19, 1981. These requirements were not addressed in the inspection, but compliance is required by November 19, in order to meet federal interim status requirements and as a part of the considerations in issuing an Ohio Hazardous Waste Permit.
- F. Inspection revealed non-compliance with this item. Compliance with this item is required unless a facility has filed as a storage facility. You should either correct the deficiency listed or file an amended Part A application for a storage facility.
- G. NFPA's code requires that the tanks be located 50 feet from the property line.

, 

## TREATMENT, STORAGE, AND DISPOSAL FACILITIES Form A. - General Facility Standards

#### I. General Information:

)	Facility	/ Name:	Premix,	Inc.			
•				Harmon A	Poad		*
)	City: 2	North KI	agsville	(D) State:	Ohio	(É) Zip Code:	44068
)	Phone:	216 -	224-2181	(G) Coun	ity:	9shtabula	-
)	Operator	gra. g.	same	as above	o		
)	Street:	•	and the second seco				
):	City:		· · · · · · · · · · · · · · · · · · ·	(K) State:		(L) Zip Code	
}	Phone:			(N) Count	.y:		•
) }	Owner:		same	as above			
)	Street:	. <del></del>		i		•	
)	City: _	· · · · · · · · · · · · · · · · · · ·		(R) State:		(S) Zip Code:	•
)	Phone:	P .		(U) Coun	ıty:		
} ·	Date of	Inspecti	on: <u>9-22-</u>	<i>81</i> (W) Time of	Inspection	(From) <u>9:45</u> (To)	12:45
)	Weather	Conditio	ns:	rainy low	60°F's.		
					•		

(Y) Person(s) Interviewed	Title	Telephone
Debbi Hall	Environmental Specialist	216-224-2181
(Z) Inspection Participants	Agency/Title	Telephone
AA) Preparer Information		
Name Chris Frazier	Agency/Title Ohio EPA - Env. Sci.	Telephone <u>210-425-9171</u>
Deborah Berg	Ohio EPA - Env. Sci.	216-425-9171
Complete sections I through VII refacilities. Complete the forms to the site activities identified	(in parenthesis) in section VII	/or disposal I corresponding
to the state activities identified	i below.	
/A. Storage/and/or Treatment I. /Containers (I) 2. Tanks (J)	D. Incineration and/o	or Thermal Treatment
3. Surface Impoundments (K) 4. Waste Piles (L)  B. Land Treatment (M)	E. Chemical, Physical Treatment (Q)	, and Biological
C. Landfills (N)		

Note: If facility is also a generator or transporter of hazardous waste complete secti IX and X of this form as appropriate.

# III. GEMERAL FACILITY STAMDARDS: (Part 265 Subpart B)

Has the Regional Administrator been notified regarding:   N.A. = not applicable		Yes No	NI* Remark
Waste from a foreign source?  2. Facility expansion?  V. N.A.  3. General Waste Analysis:  1. Has the owner or operator obtained a detailed chemical and physical analysis of the waste?  2. Does the owner or operator have a detailed waste analysis plan on file at the facility?  3. Does the waste analysis plan specify procedures for inspection and analysis of each movement of hazardous waste from off-site?  3. Security - Do security measures include:  (if applicable)  1. 24-Hour surveillance?  2. Artificial or natural barrier around facility?  3. Controlled entry?  4. Dangar sign(s) at entrance?  4. Dangar sign(s) at entrance?  5. Artificial or Operator Inspections  1. Records of malfunctions?  4. Pargar of operator procedures for procedure area waste of the with the face of the waste of t	Has the Regional Administrator been notified regarding:		N.A. = not applicable
2. Facility expansion?    M. A.     General Waste Analysis:   Has the owner or operator obtained a datailed chemical and physical analysis of the waste?     Does the owner or operator have a detailed waste analysis plan on file at the facility?   Institute to be formalized     Does the waste analysis plan specify procedures for inspection and analysis of each movement of hazardous waste from off-site?   I. A. A.     Security - Do security measures include: (if applicable)     24-Hour surveillance?   I. A. A.     Artificial or natural barrier around facility?   Institute to the formal facility?     Antificial or natural barrier around facility?   Institute to the formal facility?     Antificial or natural barrier around facility?   Institute to the face of the following face of the face o	1. Receipt of hazardous waste from a foreign source?		NA
1. Has the owner or operator obtained a detailed chemical and physical analysis of the waste?  2. Does the owner or operator have a detailed waste analysis plan on file at the facility?  3. Does the waste analysis plan specify procedures for inspection and analysis of each movement of hazardous waste from off-site?  5. Security - Do security measures include: (if applicable)  1. 24-Hour surveillance?  2. Artificial or natural barrier around facility?  3. Controlled entry?  4. Danger sign(s) at entrance?  4. Danger sign(s) at entrance?  5. Area must check in with treotions.  5. Controlled entry?  6. Do Owner or Operator Inspections  7. Include:  7. Include:  8. Records of malfunctions?  8. Operator has not been keeping inspections with discussions with	2. Facility expansion?		N.A
a detailed chemical and physical analysis of the waste?  2. Does the concer or operator have a detailed waste analysis plan on file at the facility?  3. Does the waste analysis plan specify procedures for inspection and analysis of each movement of hazardous waste from off-site?  Security - Do security measures include: (if applicable)  1. 24-Hour surveillance?  2. Artificial or natural barrier around facility?  3. Controlled entry?  4. Danger sign(s) at entrance?  Do Owner or Operator Inspections Include:  1. Records of malfunctions?  2. Records of operator error?  Very operator bas not been Keeping Inspections with	) General Waste Analysis:		
a detailed waste analysis plan on file at the facility?  3. Does the waste analysis plan specify procedures for inspection and analysis of each movement of hazardous waste from off-site?  N. A.  Security - Do security measures include: (if applicable)  1. 24-Hour surveillance?  2. Artificial or natural barrier around facility?  3. Controlled entry?  4. Danger sign(s) at entrance?  Do Owner or Operator Inspections Include:  1. Records of malfunctions?  V. Operator has not been Keeping inspection records hausure, discussions with	a detailed chemical and physical	<u> </u>	
Security - Do security measures include:  (if applicable)  1. 24-Hour surveillance?  2. Artificial or natural barrier around facility?  3. Controlled entry?  4. Dangar sign(s) at entrance?  Do Owner or Operator Inspections Include:  1. Records of malfunctions?  2. Records of operator error?  V. Applicable of M. A.   1. And Analysis of each movement of hazardous waste storage area.  N. A.  1. Analysis of each movement of hazardous week  1. Records of operator error?  V. Operator has not been  Keeping Inspection records.  Include:  V. Operator has not been  Keeping Inspection records.  Include:	a detailed waste analysis plan		needs to be formalized.
1. 24-Hour surveillance?  2. Artificial or natural barrier around facility?  3. Controlled entry?  4. Danger sign(s) at entrance?  Do Owner or Operator Inspections Include:  1. Records of malfunctions?  2. Records of operator error?  1. Operator has not been keeping inspection records boulever, discussions with	specify procedures for inspection and analysis of each movement of		in writing  N. A.
2. Artificial or natural barrier around facility?  3. Controlled entry?  4. Danger sign(s) at entrance?  Do Owner or Operator Inspections  Include:  1. Records of malfunctions?  2. Records of operator error?  V total plant fenced  All haulers accessing storage  area must check in with receptionist:  A hazardous waste storage  Area  Operator has not been  Keeping inspection records  however, asscussions with	Security - Do security measures include (if applicable)		
3. Controlled entry?  4. Danger sign(s) at entrance?  Do Owner or Operator Inspections Include:  1. Records of malfunctions?  2. Records of operator error?  Very plant fenced  Area  Area  Area  Operator has not been  Keeping inspection records  however, discussions with	1. 24-Hour surveillance?	<u> </u>	1 dans a maar
3. Controlled entry?  4. Danger sign(s) at entrance?  Do Owner or Operator Inspections Include:  1. Records of malfunctions?  2. Records of operator error?  Y  All haulers accessing storage area must check in with receptionist.  Area  Area  Operator Inspections  Include:  Y  Operator has not been  Records of operator error?  Y  Area  Operator has not been  Records of operator error?  Inspection records however, discussions with	2. Artificial or natural barrier around facility?	<u> </u>	total plant formed
Do Owner or Operator Inspections Include:  1. Records of malfunctions?  2. Records of operator error?  Y Operator has not been Keeping inspection records however, discussions with	3. Controlled entry?	<u> </u>	
Do Owner or Operator Inspections Include:  1. Records of malfunctions?  V operator has not been  2. Records of operator error?  V however, discussions with	<pre>4. Danger sign(s) at   entrance?</pre>	<u> </u>	area must check in with receptionist: at hazardous waste storage
2. Records of operator error?  V	Do Owner or Operator Inspections Include:		area
2. Records of operator error?  V  Records of operator error?  Keeping inspection records- however, discussions with	1. Records of malfunctions?		- Oberator has not been
2 Description of the second of	2. Records of operator error?		Keeping inspection records
3. Records of discharges?  V - Operator Indicate that ho spills of discharges have	3. Records of discharges?	<u> </u>	spills or discharges have

### II' GENERAL FACILITY STANDARDS · Tontinued

•	. •		Yes	No	NI*	Remarks
•	4.	Inspection schedule?		·	** <u>*</u>	formalize schedule do
	5.	Safety, emergency equipment?	./		duran en	Include storage area inspec
• • ,	6.	Security devices?	. ,	One description	and for fine	extinguishers water hoses, alarm & sprinkler systems
			<u>V</u>	*	ter derive	former transaction for similarized and anomicalization-templetor-temperature que tool-say que transaction
	7.	Operating and structural devices?		<u> </u>	March meritisars	N. A.
•	8.	Inspection log?	<b>6</b> 00 <b>6</b> 00- <b>6</b> 00	L	Chris delandiga.	start storage area
/c\	Da			•	•	inspection log-with
(5)	inc	personnel training records :lude: (Effective 5/19/81)				COFFACTIVE actions columns
. •	1.	Job titles? :	Construction .	1		Cormalize as to specific
	2.	Job descriptions?	Co-Re-goo			dutils which relate do
	3.	Description of training?	سوسسته	<b>L</b>	Commission of the Commission o	Sermalize emount of training
	4.	Records of training?	¥_	•		necessary for each job p
	5.	Have facility personnel received required training by 5-19-81?	<b>√</b>			by dearning documentation
."	ć.	Do new personnel receive required training within				g vurbat discussions.
		six months?	~	terreprise .	<del>0-1-0</del> 0	no new personnel
(F)	requ	required are the following special uirements for ignitable, reactive, or ompatible wastes addressed?				
	1.	Special handling?	1			use bronze bung wrench
•	2.	No smoking signs?	V		Charles and	readily visible
	3.	Separation and protection from ignition sources?	1	Same special	Attended Color	Consequence of the second

\*Not Inspected

# IV. PREPAREDNESS AND PREVENTION: (Part 265 Subpart C)

Maintenance and Operation of Facility:	Van de Stranger
Is there any evidence of fire, . explosion, or release of hazardous waste or hazardous waste constituent?	Yes No NI* Remarks
If required, does the facility have the following equipment:	alarm system throughout plant, rings to N. Kingsville tire depair
l. Internal communications or alarm systems?	alarm box within 2004. of stora
2. Telephone or 2-way radios at the scene of operations?	telephones inside plant, within 200 feet of storage area
3. Portable fire extinguishers, fire control, spill control equipment and decontamination equipment?	extinguishers a absorbant mater Sire hydrant a hoses immediate ovailable, Sire department
Indicate the volume of water and/or	foam available for fire control:
Indicate the volume of water and/or	foam available for fire control:
Indicate the volume of water and/or  Testing and Maintenance of Emergency Equipment:	foam available for fire control:
Testing and Maintenance of	foam available for fire control:  Inspections on regular schodule, by safety director, maintenant  Staff, & quards.
Testing and Maintenance of Emergency Equipment:  1. Has the owner or operator established testing and maintenance procedures	Inspections on regular schodule, by safety director, maintena

t Inspected

(E)	Is	there	adequate	e aisl	e space
•	for	unobs	tructed	moas.	∍ດէ?

# CONTINGENCY PLAN AND EMERGENCY PROCEDURES: (Part 265 Subpart D)

Ţ.	ollowing information:	Yes	No	NI*	Remarks	
	The actions facility personnel must take to comply with §265.51 and 265.56 in response to fires, explosions, or any unplanned release of hazardous waste? (If the owner has a Spill Prevention, Control, and Countermeasures (SPCC) Plan, he needs only to amend that plan to incorporate hazardous waste management provisions that are sufficient to comply with the requirements of this Part (as applicable.)					
.2.	Arrangements agreed by local police departments, fire departments hospitals, contractors, and State and local emergency response teams to coordinate emergency services pursuant to §265.37?				Cire department rescue squad Ashtabula Clinic	
3.	Mames, addresses, and phone numbers (office and home) of all persons qualified to act as emergency coordinators?	<u> </u>			- Grano	
4.	A list of all emergency equipment at the facility which includes the location and physical description of each item on the list and a brief outline of its capabilities?	V			map shows location of hydrants and sprinkle extinguishers	246
5.	An evacuation plan for facility personnel where there is a possibility that evacuation could be necessary? (This plan must describe signal(s) to be used to begin evacuation, evacuation routes, and alternate evacuation routes?)	y			received 9-23-81	

### V. CONTINGENCY PLAN AND EMERGENCY PROCEDURES - Continued

		Yes	No	NI*	Remarks	
3)	Are copies of the Contingency Plan available at site and local emergency organizations?			-	North Kings ville Fire Departm	16
:)	Emergency Coordinator					
	l. Is the facility Emergency Coordinator identified?	~				_
	2. Is coordinator familiar with all aspects of site operation and emergency procedures?	<u>/</u>	-			
	3. Does the Emergency Coordinator have the authority to carry out the Contingency Plan?	V		(Married Control of Co		
11	Emergency Procedures		•			
	If an emergency situation has occurred at this facility, has the Emergency Coordinator followed the emergency procedures listed in 265.56?	Service Company (		•	No A.	- -
	VI. MANIFEST SYSTEM, R (Part 26				REPORTING	
,		Yes	No	NI÷.	Remarks	
1)	Use of Manifest System		· · ·	un.		
4	Does the facility follow the procedures listed in §265.71 for processing each manifest?	abbratter mornetar	*********	Мартина	N. A.	
	2. Are records of past shipments retained for 3 years?				N. A.	+
)	Does the owner or operator meet requirements regarding manifest discrepancies?	•				
•					No Ho	

•.				
(C)	Operating Record			
	l. Does the owner maintain an oprecord as requestion 265.73?	erating		Some records are presently kept
•	<ol><li>Does the opera contain the fo information:</li></ol>	ting record * - llowing		
	storage, o	(s) and date(s) ste's treatment, r disposal as n Appendix I?		drums tagged at start of accumulation, records at accomption area and by manifest
	c. The locati of each ha within the	on and quantity zardous waste facility?	<u> </u>	storage area located
	cell or displaying the showing the quantity of waste? (The should be a to specific number, if			
	e. Records and waste analy	results of all ses, trial tests, data, and operator		Waste analysis present, but inspections not yet clormally recorded.
	f. Reports det	ailing all		

costs as applicable? (Effective 5-19-81)

All closure and post closure

implementation of the Contingency Plan?

\* See page 33252 of the May 19, 1980, Federal Register.

\*\*\* Only applies to disposal facilities

yet available.

# VII. CLOSURE AND POST CLOSURE (Part 265 Subpart 6)

		Yes	No	NI*	Remarks	•	
Clo	sure and Post Closure						
1.	Is the facility closure	diana-reminin	<u>V</u>		COMPANY	will submit	plah
2.	Has this plan been submitted to the Regional Administrator		<u>~</u>	***************************************			
3.	Has closure begun?	- <del></del>	V	constant of the second	Brown Control of the		
4.	Is closure estimate available by May 19, 1981?		<u>/</u>	**************************************	dam-no-a-rate and a section of the s		
Pos	t closure care and use of property	•					
Q	the owner or operator supplied ost closure monitoring plan? fective by May 19, 1981)		•	-		N. A.	
ity	USE AND MANAGER Name: Premiy Inc.	I	F CON	TAINERS	nspections	9-22-81	
		Yes		MI*	Remarks	<u> </u>	
1.	Are containers in good condition?				<del></del>		
2.	Are containers compatible with waste in them?	1		O,	<del></del>	on the state of th	
3.	Are containers stored closed?						
4.	Are containers managed to prevent leaks?	<u></u>	محمسم	***************************************	stored	upright on	Dallets
5.	Are containers inspected weekly for leaks and defects?	<u>~</u>		- - -	_ daily		
6	Are ignitable & reactive wastes stored at least 15 meters (50 feet) from the facility property line? (Indicate if waste is ignitable or reactive.)	L		•	ignit	rble.	

	Yes	No	NI:	Remarks	
7.	Are incompatible wastes stored in separate containers? (If not, the provisions of 40 CFR 265.17(b) apply.)	algo-Aggro-pass	Security 450	N.A.	Managioring and regional data blanks downey against a subsequence
8.	Are containers of incompatible waste separated or protected from each other by physical barriers or sufficient distance?	an-fundada		N. A.	
	J TANKS	No.	Â.		
acilit	y Name:	Date	of Ins	pection	
1.	Are tanks used to store only those wastes which will not cause corrosion, leakage or premature failure of the tank?	-	manhaminapoint.		
2.	Do uncovered tanks have at least 60 cm (2 feet) of freeboard, or dikes or other containement structures?		Осторительн		
3.	Do continuous feed systems have a waste-feed cutoff?	- Aller State -	Финуалирия		
4.	Are waste analyses done before the tanks are used to store a substantially different waste than before?	శ్వించి భయాశ్విమ	agus Bacerija		
5.	Are required daily and weekly inspections done?	Si 12-140			
6.	Are reactive & ignitable wastes in tanks protected or rendered non-reactive or non-ignitable? Indicate if waste is ignitable or reactive. (If waste is rendered non-reactive or non-ignitable, see treatment requirements.)				
7.	Are incompatible wastes stored in separate tanks? (If not, the provisions of 40 CFR 265.17(b) apply.)	ومسومين			

Tank capacity:		gallons		
Tank diameter:		feet		
Distance of tank from	property line		feet	
(See table 2 - 1 thro Code - 1977" to dete	ough 2 - 6 of NFPA ermine compliance.	's "Flammable and	Combustible Li	quids
	K SUBFACE IMPO	INDMENTS N.A.		
Name:	Som Man III Co			
e de la companse production de la column de	مراسي شوران والمرابع	Date of	Inspection:	
Do surface impoundment at least 60 cm (2 feet freeboard?		De Sprojenský garnynejský nyspek		
Do earthem dikes have covers?	protective	حديد معوامعيات الكثارة الأوامية الأ		
Are waste analyses don impoundment is used to substantially differen than before?	store a			
Is the freeboard level at least daily?	inspected	D Drogonia deregologie		
Are the dikes inspecte for evidence of leaks deterioration?	d weekly or			
Are reactive & ignitab rendered non-reactive ignitable before stora surface impoundment? waste is rendered non-or non-ignitable, see requirements.)	or non- ge in a (If reactive			
Are incompatible waste in different impoundme not, the provisions of	nts? (If			and an extending from the

Facility	Name:	Date of Inspection:
	Yes No	NI* Remarks
1.	Are waste piles covered or protected from dispersal by wind?	
2.	Is each in-coming movement of waste analyzed before being added to the waste pile?	
3.	Are leachate, run-off, and run-on controlled as per the requirements of 265.258? (The effective date of this provision is Nov. 19, 1981.)	
	Are reactive & ignitable wastes rendered non-reactive or non-ignitable before storage in a pile? Indicate if waste is ignitable or reactive. (If waste is rendered non-reactive or non-ignitable, see treatment requirements.)	
- 5.	Are piles of reactive or ignitable waste protected from materials or conditions that might cause them to ignite or react?	
6.	Are incompatible wastes stored in different piles? (If not, the provisions of 40 CFR 265,17(b) apply.)	
7.	Are piles of imcompatible waste protected by barriers or distance	

ility	Mane:	Date of Inspection:
Q emanana q	Is treated hazardous waste capable of biological or chemical degradation?	
2.	Are run-off and run-on diverted from the facility or collected? (Effective date: November 19, 1981)?	
3.	Is waste analyzed according to 265.273?	
4.	If food chain crops are grown at the facility, has the owner or operator addressed the requirements of 265.276?	
<b>5.</b>	Is an unsaturated zone monitoring plan designed and implemented to detect the vertical migration of hazardous waste and provide information on the background concentrations of the hazardous waste available?	
6.	Does the unsaturated zone moni- toring plan address the minimum information specified in 265.278?	
7.	Are records kept regarding application dates and rates, quantities, and locations, of all hazardous waste placed in the facility?	
8.	Are the special requirements fulfilled regarding land treatment of ignitable or reactive wastes? (Indicate if waste is ignitable or reactive.)	
	Are incompatible wastes land treated? (If yes, 265.17(b) applies)	

# N LANDFILLS N.A.

Fa	cili	ty Name:	Da	Date of Inspection: Yes No NI* Remarks			d town that the numerous right thintends right high right town
•			Yes	No	NI*	Remarks	
(A)	Ben Doe	eral Operating Requirements the facility provide the following:					
	***	Diversion of run-on away from active portions of the fill?	2	The state of the s	مينا موسي		
	**2.	Collection of run-off from active portions of the fill?	digarder (Sala)	-			
	**3.	Is collected run off treated?	-				
	<u>.</u>	Control of wind dispersal of hazardous waste?	-		distribuição.		
		(**Effective 11-19-81)	:				
(8)		veying and Recordkeeping s the Operating Record Include:					
	1.	A map showing the exact location and dimensions of each cell?	<del>an an</del>	Quercy Acto	<del>go-u-go</del> -	April Control of the	
-	2.	The contents of each cell and the location of each hazardous waste type withing each cell?	-		ago-stronger		
(C)	Clo	sure and Post-Closure	*.				
	1.	Is the Closure Plan available for inspection by 5-19-81?	<del></del>	<del></del>			
	2.	Has this plan been submitted to the Regional Administrator?	<del>and the state</del>		San American	Company that the same than the company of the company of	the first standards for the standards.
-* -* .	3.	Has closure begun?	<b>-</b>	<del></del>	EST Appendix	Con according to the Conference of the Conferenc	
· .	Ĺ	Is closure cost estimate available by 5-19-81?	خان محاجمته		e disconnection de la connection de la c		
/n/\	۲	eil manuimemente fam idaitable am	•	* . * *	٠.		
(D)		cial requirements for ignitable or ective waste					
•	tre	e ignitable or reactive waste eated so the resulting mixture no longer ignitable or reactive?		<del>(</del>	Ghamaz-roz-salistado		
				•			

tida og men staller er e	Yes N	0	/[=	Remarks	
(If waste is rendered non-reactive or non-ignitable see treatment					
requirements)	-		<del>-</del>		•
If not, the provisions of 40 CFR 265.17(b) apply.	COOMPANIES dames				
		n			
Special Requirements for Incompatible					-
Wastes.			-		
Does the owner or operator dispose of incompatible wastes in separate cells?	-			•	
not, the provisions of 40 CFR	•				
	- 1 - 1 <del>-</del> 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1				-
Special requirements for liquid waste (effective 11-19-81)					•
Are bulk or non-containerized liquid placed in the landfill?	5	onesservices (s-e			<del></del>
2. Does the landfill have a chemically and physically resistant liner system?					
3. Does the landfill have a functional leachate collection system?					
4. Are free liquids stabilized prior to or immediately after placement in the landfill?					
Special requirements for Containers (effective 11-19-81)					
ire empty containers crushed flat, shredded, or similarly reduced in volume sefore being buried beneath the surface	•		•		
of the landfill?					

# O and P INCINERATION and THERMAL TREATMENT N.A.

(A)	Facility Name:	•						
(8)	Date of Inspection:							•
		•		•				
	<u>I.</u> De	termi	inatioπ	of St	eady Sta	<u>te</u>		
								•
À.	Type of unit (i.e., type of inci	nerat	or or t	herma	l treatm	ent):		
Y				· , •				
3.	Components and steady state cond	ition	1:		r i Jākā aiz			
· v.			**** 1/2	s thi	s compon	ent at SS pa	for to addin	g wast
	Component		Υe	s No	NI*	Remarks		
10	Charles and the second			-	-			<del></del> -
2.		•	-					
<b>}.</b>		•			_			<del> </del>
ī Io			<del></del>					-
) <u>.</u>	Company of the Compan	ر کم بند م						<del>4)</del>
•		II.	Waste	Analy	sis			ve≡
	Minimum requirements, for wastes	not	previou	sly b	urned/tr	eated.		
	1. Required analyses; has analysis been performed for the following?		Ye	s No	NI÷	Renarks		
	a. Heating value		•					
٠.	b. Halogen content		<del></del>					•
	c. Sulfur content					•		
				•		-		_ :

		Yes No	NI*	Re ks		· · · · · · · · · · · · · · · · · · ·
2. Has documented or been substituted or either:	written data for analysis			•		
a. Lead?		سبست مست	<del>Oppositions of</del>	/ <del></del>		
b. Mercury?		- Allen and specific and the specific an	· ————————————————————————————————————			
st other parameters for eady state or determine marks any which you feel	the types of a	oollutants v	d to enab which may	le owner or be emitted.	operator to (Note in	establi
				Remar	<b>ks</b>	
				*		(Personal and Personal and Pers
	andrian appropriate to the state of the stat	CORPORATION CONTRACTOR	•			
	بروجية والمراج والمنطقة والمحاج	-		<del></del>	a a la faire de la faire d	
	III. Monitor	ing and Ins	pections NI*	Renarks		
a combustion/emission co nitored at least every l		ents	- Character Control			
steady state maintained tempted?	or correction	15	**************************************			
stack plume observed at normal color and opaci		***************************************		-		
i any stack observations mer or operator show a prent than normal?**			National Association (Co.			
yes to D above, were co le to return emissions t searance?**	errections o normal	аштаматар Саруан атумса	Character spice			
the complete unit and it inspected daily for l fugitive emissions?	associated equeaks, spills,	-qii	O-Andrea - Angresia	· November of the state of the		
emergency shutdown constant alarms checked dail						

operation?

inspected fy in Remarks for what period of time this was checked.

#### IV. Open Burning

2	Only	complete	this	part	the	facility	open	burns	haza	us waste.
**	446 6 7			E -			-			

Yes No NI\* Remarks

- Does this facility burn only waste explosives?
   (A No answer means other hazardous waste is open-burned.)
- If this facility openburns waste explosives, does it burn the waste at a distance greater than or equal to the minimum specified distance (below)

Pounds of waste explosives or propellants	burn		deto	nati	on to	
0 to 100	204 r 380 r 530 r	n n l	670	ft ft ft		

0

CHEMICAL, PHYSICAL and BIOLOGICAL TREATMENT

N. A.

Fac	ility Name:						
Dat	e of Inspection:	· · · · · · · · · · · · · · · · · · ·	<del> </del>				
•			Ye	s No	NI+	Remarks	
1.	Is equipment used to those wastes which w leakage, corrosion, failure?	ill not cause					
2.	Is a continuously fe equipped with a mean waste inflow stoppag	s of hazardous a or control			O Description		

	Yes No NI* Remarks	••
	Has the owner or operator addressed the waste analysis requirements of 265.402?	
•.	Are inspection procedures followed according to 265.403?	
	Are the special requirements fulfilled for ignitable or reactive wastes?	
٠.	Are incompatible wastes treated? (If yes, 265.17(b) applies.)	
	보고 하는 것이 되었다. 그는 사람들은 소프로 사용하는 사용하는 사용하는 사용하는 사용하는 사용하는 사용하는 것이 되었다. 그는 사용하는 사용하는 사용하는 사용하는 사용하는 사용하는 사용하는 사용하	
	waste regulations in 40 CFR Parts 122, 264 and 265 to owners and operators of wastewater treatment tanks that receive, store, and treat wastewaters that are hazardous waste or that generate, store or treat a wastewater treatment sludge is a hazardous waste where such wastewaters are subject to regulation under Se 402 or 307(b) of the Clean Water Act (33 U.S.C. 1251 et seq.) and (2) neutralitanks, transport vehicles, vessels, or containers which neutralize wastes which hazardous only because they exhibit the corrosivity characteristic under 40 CF or are listed as hazardous wastes in Subpart D of 40 CFR Part 261 only for this	which ctions zation in are
	Complete this section if the owner or operator of a TSD facility also generates hazardous waste that is subsequently shipped off-site for treatment, storage, o disposal.	
	1. MANIFEST REQUIREMENTS	
)	Yes No NI* Remarks  ) Does the operator have copies of the manifest available for review?	
)	Do the manifest forms reviewed contain the following information:  (If possible, make copies of, or record information from, manifest(s) that do not contain the critical elements)	
	l. Manifest document number?	•
	2. Name, mailing address, telephone number, and EPA ID Number of Generator	den de de la constante de la c

.^			
	3. Name and EPA ID Number of Transporter(s)?	<u> </u>	
	4. Name, address, and EPA ID Number of Designated permitted facility and alternate facility?	<u> </u>	
	5. The description of the waste(s) (DOT shipping name, DOT hazard class DOT identification number)?	s, <u>/</u>	
	6. The total quantity of waste(s) and the type and number of containers loaded?		
	7. Required certification?	1	
	8. Required signatures?		
(C)	Does the owner or operator submit exception reports when needed?		N.A. at this time
	2. PRE-TRANS	PORT REQUIREMENTS	
(A)	Is waste packaged in accordance with DOT Regulations? (Required prior to movement of hazardous waste off-site)		
(8)	Are waste packages marked and labeled in accordance with DOT regulations concerning hazardous waste materials? (Required to movement of hazardous waste off-site)	<u> </u>	
•			
(C)	If required, are placards available to transporters of hazardous waste?		+toncanter Commister
•••			transporter furnishes  Dlacards

Yes

No N

Remarks

Omit Section 3 if the facility has interim status and its Part A permit application describes storage

# 3. On Site Accumulation N. A.

·		Yes	No	NI÷	Remarks	
1.	Are containers marked with start of accumulation date?	Charm Mary 100	-			
2.	Are the containers of hazardous waste removed from installation before they can accumulate for more than 90 days?	Gaster	Сочиновическ			
3.	Are wastes stored in containers managed in accordance with 40 CFR Part 265.174 and 265.176 (weekly inspections of containers, container holding ignitable or reactive waster located at least 15 meters (50 Feet from facility's property line?	5	and the state of t			
4	If wastes are stored in tanks, are the tanks managed according to the following requirements?  a. Are tanks used to store only those wastes which will not cause corrosion leakage or premature		•			
a	failure of the tank?  b. Co uncovered tanks have at least 60 cm (2 feet) of freeboard, dikes, or other containment structures?		- Common - S			
	c. Do continuous feed systems have a waste-feed cutoff?					
	d. Are required daily and weekly inspections done?		- Commission		\$400-section and the section a	
	e. Are reactive & ignitable wastes in tanks protected or rendered non-reactive or non-ignitable? (If waste is rendered non-reactive or non-ignitable, see treatment requirements?	<u> </u>				
	f. Are incompatible wastes stored in separate tanks? (If not, the provisions of 40 CFR §265.17(b) apply)	Saubscrambin-ga-	ومستندسي			•

# VI. RECORDKEEPING and REPORTING (Part 262, Subpart D)

			Yes No N	∐÷ Remarks	
(A)		ts, and all test lyses retained for	·	mani fests	g waste analys
(B)	Has the general Annual Reports Reports as requ	and Exception		No A.	
		VII. II (Pa)	TERNATIONAL SHIPME t 262, Subpart E)	<u>NTS</u>	
	Has the install or exported Haz				
	(If ans	wered Yes, complete	the following as a	pplicable.)	
·	l. Exporting H has a gener	azardous waste, ator:			
	a. Notifie in writ	d the Administrator ing?			
	foreign deliver	d the signature of t consignee confirming y of the waste(s) in country?	o D		
	c. Met the	Manifest requiremen	ts?		
	<ol><li>Importing H has the gen</li></ol>	azardous Waste, erator:			
•	Net the	manifest requiremen	ts?		

# TRANSPORTER REQUIREMENTS , / 40 CFR Part 263

Complete this Section if the owner or operator transports hazardous waste-

# I. MANIFEST SYSTEM AND RECORDKEEPING (Subpart B)

- Yes No NI\* Remarks

Are copies of the completed manifests or shipping paper(s) available for review and retained for three years?

## II. INTERNATIONAL SHIPMENTS

- Does the transporter record on the manifest the date the waste left the U.S.?
- Are signed completed manifest(s) on file?

### V. MISCELLANEOUS

- Does transporter transport hazardous wasta into the U.S. from abroad?
- Does the transporter mix hazardous waste of different DOT shipping descriptions by placing them into a single container?

OTE: If (A) or (B) were answered "Yes" then the Transporter is also a Generator and must comply with the Generator regulations.

lot Inspected

#### REMARKS

Use this section to briefly describe site activities observed at the time of the inspection. Note any possible violations of Interim Status Standards.

Premix, Inc. generates and stores three hazardous wastes on site still bottoms, paint sludge and resin paste. All three wastes are stored in drums before shipment off-site for disposal.

Company made whe dollowing revisions to application:

FOOD remains unchanged by includes FOO3+FOO5 (SHII bottoms)

D003 changed to D001 (waste resin paste)

FOIT changed to DOOI (paint residue)

Revised application received at district office on 9/23/81.

Major deficiencies include lack of storage area inspection log, no waste analysis plan, and no closure plan or estimates was available. Also training records need some improvements company agreed to correct deficiences and submit eopies of the waste analysis plan & closure plan as verification.

ECEINED

T-1 1981 RE: Application Number 81-HW-0567 Ashtabula County

WASTE MANAGEMENT BRANCH
EPA REGION V

September 28, 1981

Ms. Debbi Hall Environmental Specialist Premix, Inc. P.O. Box 281 North Kingsville, Ohio 44068

Dear Ms. Hall:

On September 22, 1981, Chris Frazier and Deborah Berg of the Ohio Environmental Protection Agency conducted an inspection of your facility as part of the Hazardous Waste facility permit review process. Your facility was represented by yourself.

Enclosed are two forms. The one titled "TREATMENT, STORAGE AND DISPOSAL FACILITY" is a copy of the form used during the inspection to evaluate your facility.

The other form, "DEFICIENCY NOTIFICATION TABLE", relates to the "TREATMENT, STORAGE AND DISPOSAL FACILITY" form and specifies what action must be taken where deficiencies were noted. A mark in column four of the "DEFICIENCY NOTIFICATION TABLE" denotes a violation of current regulations or pinpoints areas which will be covered by regulations not yet effective. The capital letter codes in column four are explained on the last page of the "DEFICIENCY NOTIFICATION TABLE".

You are hereby advised that total compliance with the regulations contained in 40 CFR 265 is required as a condition of continuing interim status with the U.S. EPA. Failure to list specific deficiencies in this communication does not relieve you from the responsibility of complying with all applicable regulations.

Very truly yours,

Paul Flanigan, P.E.

Hazardous Waste Materials Management

PF/maf

cc: Kathleen Homer, U.S. EPA, Region V Chris Frazier and Deborah Bert, NEDO

CERTIFIED MAIL

Premix, Inc. P.O. Box 281 N. Kingsville, Ohio July 28, 1981 OHD004200044 OK

USEPA Region V RCRA Activities P.O. Box A 3587 Chicaeo, Il. 60690

To whom it may concern:

Attached is a letter that was submitted to you when we filed our Form # 3. The photographs that were not forwarded are now enclosed. If there are any questions concerning this, please do not hesitate to phone.

> Yours truly, Premix, Inc.

Debbi Parshall Hall

Environmental Specialist

SUB. PART A



NORTH KINGSVILLE, OHIO

DEBBI HALL

ENVIRONMENTAL SPECIALIST

PHONE 216 224-2181

2 n 1001 JUL 3 n 1981

November 18, 1980

U.S.E.P.A.
Region V
RCRA Activities
P.O. Box 7861
Chicago, IL 60680

Dear Sirs:

In the EPA Form #3, RCRA Section VI requests photographs of existing storage, treatment and disposal areas. We are in the process of having these prepared, but they are not yet available at the time of the submission of this form.

They will be forwarded as soon as possible.

Yours truly,

PREMIX, INC.

Debbi Parshall Environmental Specialist

mkp

33

P. O. BOX 281

#### NORTH KINGSVILLE, OHIO 44068

PHONE (216) 224-2181

November 18, 1980

U.S.E.P.A. Region V RCRA Activities P.O. Box 7861 Chicago, IL 60680

Dear Sirs:

In the EPA Form #1, General Section XI requests a topographic map of the plant and surrounding area. We are in the process of having this prepared, but it is not available at the time of the submission of this form.

The map will be forwarded as soon as it is complete.

Yours truly,

PREMIX, INC.

Debbi Parshall

Environmental Specialist

mkp

# **Determination: NFA**

# PA/VSI Or RFA FILE REVIEW CHECKLIST

Facil	ity Nai	ne: Pre	mix, Inc.						
EPA	ID: Ol	HD 004	200 044 City: North Kingsville State: OH						
Nam	e of Re	eviewer	: Maureen McHugh Date of Review: 7/22/08						
1	Yes	No	Is this a one folder site?						
2	Yes	No	Are there Superfund files for this site?						
3	Yes	No	Did you Read the Executive Summary?						
			There are:8 SWMUs and1 AOCs at this site.						
4	Yes	No	Did you review the regulatory history?						
5	Yes	No	Does the facility have interim status or a permit?						
			This facility is a: SQG,X_ LQG, orX_ Less than 90 day.						
6	Yes	No	Was the Facility closed per RCRA? RCRAInfo 380 (1988, 1989)						
			If Yes, was the closure: _X_ CC, or CIP.						
7	Yes	No	Are there documented (historical) releases? Briefly describe on Page 2.						
8	Yes	No	Were there releases identified during the inspection? Briefly describe on Page 2.						
9	Yes	No	Do you agree with the Conclusions and Recommendations?						
			If No, briefly describe on Page 2.						
CONTRACTOR OF THE PROPERTY OF									
As a	result	of your r	review of the PA/VSI or RFA file, please classify this site as:						
and	any oth	er SWM	corrective action recommended or warranted: These are sites that closed the regulated units IUs or AOCs at the site did not warrant any further corrective action (no historic releases or						
evid			s observed during the Visual Site Inspection).						
SWI	Further Action Required: Soil or sediment sampling or groundwater sampling or monitoring or any type of investigation that was recommended in the report in response to a documented or observed release at any SWMU or AOC and where such investigation, whether being addressed during the inspection or after, does not have the necessary documentation in the facility record files.								
	More Information Needed: There is no RFA, PA/VSI or RCRA closure information available.								

# PA/VSI Or RFA FILE REVIEW CHECKLIST

Notes
INUICS
Briefly describe any documented (historical) releases for any SWMU or AOC recorded in the report. For each release, please identify the SWMU or AOC and a one or two line description of release.
· · · · · · · · · · · · · · · · · · ·
Fire in 1989 in the outdoor covered drum storage area (SWMU3), an area that contained nonhazardous waste, excess liquid from fighting the fire drained into the on-site pond (AOC1) but samples indicated it had not been contaminated. No releases aside from smoke and vapor generated during the fire.
Odor complaints in 1984 and 1987
Briefly describe any releases observed during the inspection for any SWMU or AOC recorded in the report. For each release, please identify the SWMU or AOC and a one or two line description of release.
release, please identify the SWMU or AOC and a one or two line description of release.
release, please identify the SWMU or AOC and a one or two line description of release.  PA/VSI Recommendations
release, please identify the SWMU or AOC and a one or two line description of release.
release, please identify the SWMU or AOC and a one or two line description of release.  PA/VSI Recommendations
release, please identify the SWMU or AOC and a one or two line description of release.  PA/VSI Recommendations
release, please identify the SWMU or AOC and a one or two line description of release.  PA/VSI Recommendations
release, please identify the SWMU or AOC and a one or two line description of release.  PA/VSI Recommendations



#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

### REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

RECEIVED DEC 2 2 1992
WMD RCRA
RECORD CENTER Compliance

REPLY TO THE ATTENTION OF:

HRE-8J

December 15, 1992

Mr. Raymond Kovacs Premix, Inc. P.O. Box 281 North Kingsville, Ohio 44068

Re: Visual Site Inspection
Premix, Inc.
North Kingsville, Ohio
OHD 004 200 044

Dear Mr. Kovacs:

The U.S. Environmental Protection Agency is enclosing a copy of the final Preliminary Assessment/Visual Site Inspection (PA/VSI) report for the referenced facility. The executive summary and conclusions and recommendations sections have been withheld as Enforcement Confidential.

If you have any questions, please call Francene Harris at (312) 886-2884.

Sincerely yours,

Kevin M. Pierard, Chief

Minnesota/Ohio Technical Enforcement Section

RCRA Enforcement Branch

PRC Environmental Management, Inc. 233 North Michigan Avenue Suite 1621 Chicago, IL 60601 312-856-8700 Fax 312-938-0118



#### PRELIMINARY ASSESSMENT/ VISUAL SITE INSPECTION

PREMIX, INC. NORTH KINGSVILLE, OHIO OHD 004 200 044

FINAL REPORT

#### Prepared for

#### U.S. ENVIRONMENTAL PROTECTION AGENCY Office of Waste Programs Enforcement Washington, DC 20460

Work Assignment No. : C05087

 EPA Region
 : 5

 Site No.
 : OHD 004 200 044

 Date Prepared
 : November 6, 1992

 Contract No.
 : 68-W9-0006

PRC No. : 009-C050870H5V
Prepared by : PRC Environmental Management, Inc.

(Jean Michaels)
Contractor Project Manager : Shin Ahn

Telephone No. : (312) 856-8700 EPA Work Assignment Manager : Kevin Pierard Telephone No. : (312) 886-4448

# TABLE OF CONTENTS

Section	<u>l</u> .																																																		Ī	<sup>2</sup> a	g	<u>e</u>
EXEC		SUMM																																																		_	<b></b> .	1
1.0	INTRO	DUCT	ΓI	(C	C	C	)]	N	ſ																	•				•														• .•							٠.			1
2.0	FACIL	ITY DE	ES	ES	S	S	C		R	IJ	PT	IC	N	ĵ																													• •	• • •									4	4
	2.1 2.2 2.3 2.4 2.5 2.6	FACIL FACIL WASTI HISTO REGU ENVIR	LI FE OR UL	I E R L	ITER	[] R L	T C S	Y	E T	C C C C C	P IE F IR	EF R. D( Y	Α΄ Α΄ Η	AT TI- CU IS	)( () () () ()	10 N IN O	NS EN EN	5 4.1 V. Y.	N] T]	D EI	N O	/I.	A E	N El		E	G A	S	N E	/I S	El	\	T			•								• •				• •		•		•		1
·		2.6.1 2.6.2 2.6.3 2.6.4	]	<b>I</b>	I	F	3 3	lo e	0	d lc	P Og:	la y a	in in	a d	nc Sc	d S oil	St Is	1r ,	fa 	ıcı	e	W	/a	tı	: :				•											•									· •	•			1.1.1.1	3
	2.7	RECE	EΡ	PT	37	7	Γ	O	) Į	3.5	3								٠.							•																											1	4
3.0	SOLID	WAST	ГΕ	Ε	Ξ	:	N	VI	[/	¥.	N/	/C	έE	M	1E	ΞN	ΙŢ	<u>,</u> 1	U	N	ľ	ΓS	3																														1	5
4.0	AREA	S OF C	CO	0	Э	)	N	I	С	E	R	N							٠.																										. <b>.</b>								2	1
5.0	CONC	LUSIO	N	V.	15	ŢŞ	S	Ė	4	N	D	R	E	C	01	M	M	ſΕ	EN	١Ľ	),	4	Γ	IC	)]	Ν	S																										2	2
REFE	RENCE	S		•	•		•	•	•			٠.				•	•	•				•	٠	•		•			•	•	•		٠	•							•	•			, <b>.</b>	•	•			•			2	6
Attach	ment										•									•																																		
Α	EPA P	RELIM	ΜI	I	IÌ	[]	N	Δ	¥.	R	Y	Α	SS	Έ	SS	SN	11	Εl	N.	Γ	F	·C	R	·	<b>√1</b>		2(	)7	0	-	12	2																						
В	VISUA	AL SITE	Έ		. ]	I	Ιľ	J	S	P	Ε(	CT	Ι	N	1 ;	SĮ	JI	M	M	ĺ.	١,	R.	Y	F	1	N	I.	)	P	Н	C	Γ	. C	)(	jΕ	₹.	4]	PΕ	SF	,														
C	VISUA	AL SITE	E		]	]	n	V	S	P	ΕŒ	CT	Ί	ባር	1	FI	ΙE	EL	,D	) [	N	O	Т	E	S																													

# LIST OF TABLES

<u>Table</u>		Page	₽
1	SOLID WASTE MANAGEMENT UNITS	. 7	7
2	SOLID WASTES	. 9	9
3	SWMU AND AOC SUMMARY	2.	5
	LIST OF FIGURES		
<u>Figure</u>		Page	<u>e</u>
1	FACILITY LOCATION	- :	5
2	FACILITY LAYOUT	. !	8

# ENFORCEMENT CONFIDENTIAL

#### **EXECUTIVE SUMMARY**

PRC Environmental Management, Inc. (PRC), performed a preliminary assessment and visual site inspection (PA/VSI) to identify and assess the existence and likelihood of releases from solid waste management units (SWMU) and other areas of concern (AOC) at the Premix, Inc. (Premix), facility in North Kingsville, Ashtabula County, Ohio. This summary highlights the results of the PA/VSI and the potential for releases of hazardous wastes or hazardous constituents from SWMUs and AOCs identified. In addition, a completed U.S. Environmental Protection Agency (EPA) Preliminary Assessment Form (EPA Form 2070-12) is included in Attachment A to assist in prioritizing RCRA facilities for corrective action.

Premix employs 535 people in the manufacture of reinforced thermoset molding compounds and custom molded fiberglass parts. Premix sells approximately half the molding compounds it manufactures. The remaining compounds are used on site to manufacture the custom molded fiberglass parts. In 1964, Premix began operations at the 61-acre facility, which is located in a rural area near North Kingsville, Ohio. In November 1980, Premix submitted a Part A permit application to operate as a hazardous waste treatment, storage, or disposal facility, storing D001, D003, F002, F003, and F005 wastes in containers (S01). In July 1989, Premix submitted a certification of closure for its former hazardous waste storage areas and indicated that the facility would be operating as a generator of hazardous waste.

Premix currently generates the following hazardous wastes: waste flammable resin (D001); waste organic peroxide (D003); waste solvent ES-2173C (D001); waste pyridine (D001 and F003); waste mixed solvents (D001, F002, F003, and F005); waste solvent ES-265E (D001); waste solvent SP-731 (D001); waste paint and thinner (D001 and D035); and waste stoddard solvent (D001). Premix also generates several nonhazardous wastes: waste glass dust, scrap molding compounds, scrap molded parts, and waste hydraulic oil. Premix currently operates as a large-quantity generator of hazardous waste, storing waste for less than 90 days.

The PA/VSI identified the following eight SWMUs and one AOC at the facility:

Solid Waste Management Units

- 1. Former Hazardous Waste Storage Area
- 2. Former Hazardous Waste Storage Pad
- 3. Outdoor, Covered Drum Storage Area
- 4. Waste Solvent Accumulation Area
- 5. Waste Organic Peroxide Storage Area
- 6. Waste Paint Accumulation Area
- 7. Dust Collectors
- 8. Waste Hydraulic Oil and Stoddard Solvent Storage Area

ENFORCEMENT CONFIDENTIAL

#### Area of Concern

#### 1. On-site Pond

The potential for a release of hazardous constituents from SWMUs to ground water, surface water, air, and on-site soils is low. All active SWMUs have concrete floors and are either bermed or located within the facility building. Several solvent drums, stored within the building, were found stored open during the VSI. Some solvents may volatilize from these open drums; however, because the bung openings are small, the quantity would be minimal.

Premix maintains a 5-acre On-site Pond (AOC 1) into which it discharges treated sanitary waste, noncontact cooling water, and storm run-off. The pond is unlined and may seep into local ground water. Floor drains exist within the facility building only in areas where molding compounds have already been mixed, and therefore, are nonhazardous. The purpose of the floor drains is to drain sprinkler water, in the event of a fire, to the pond. The potential for a hazardous release to a floor drain within the facility building with subsequent discharge to the pond is low.

Receptors which might be affected by potential releases from Premix are limited to wildlife in the On-site Pond because ground water is not used as a source of drinking water in the vicinity of the facility. The closest school is located about I mile southwest of the facility. Wetlands exist within 0.5 mile to the south and southeast of the facility. No state or national parks or wildlife preserves exist within 2 miles of the facility.

PRC recommends that a means of containing floor drain discharge, before it enters the pond, be installed. PRC also recommends that all waste drums be stored closed.

RELEASENS OF RIN #
INITIALS

#### 1.0 INTRODUCTION

PRC Environmental Management, Inc. (PRC), received Work Assignment No. C05087 from the U.S. Environmental Protection Agency (EPA) under Contract No. 68-W9-0006 (TES 9) to conduct preliminary assessments (PA) and visual site inspections (VSI) of hazardous waste treatment and storage facilities in Region 5.

As part of the EPA Region 5 Environmental Priorities Initiative, the RCRA and CERCLA programs are working together to identify and address RCRA facilities that have a high priority for corrective action using applicable RCRA and CERCLA authorities. The PA/VSI is the first step in the process of prioritizing facilities for corrective action. Through the PA/VSI process, enough information is obtained to characterize a facility's actual or potential releases to the environment from solid waste management units (SWMU) and areas of concern (AOC).

A SWMU is defined as any discernible unit at a RCRA facility in which solid wastes have been placed and from which hazardous constituents might migrate, regardless of whether the unit was intended to manage solid or hazardous waste.

The SWMU definition includes the following:

- RCRA-regulated units, such as container storage areas, tanks, surface impoundments, waste piles, land treatment units, landfills, incinerators, and underground injection wells
- Closed and abandoned units
- Recycling units, wastewater treatment units, and other units that EPA has usually exempted from standards applicable to hazardous waste management units
- Areas contaminated by routine and systematic releases of wastes or hazardous constituents. Such areas might include a wood preservative drippage area, a loading or unloading area, or an area where solvent used to wash large parts has continually dripped onto soils.

An AOC is defined as any area where a release of hazardous waste or constituents to the environment has occurred or is suspected to have occurred on a nonroutine and nonsystematic basis. This includes any area where a strong possibility exists that such a release might occur in the future.

The purpose of the PA is as follows:

- Identify SWMUs and AOCs at the facility
- Obtain information on the operational history of the facility
- Obtain information on releases from any units at the facility
- Identify data gaps and other informational needs to be filled during the VSI

The PA generally includes review of all relevant documents and files located at state offices and at the EPA Region 5 office in Chicago.

The purpose of the VSI is as follows:

- Identify SWMUs and AOCs not discovered during the PA
- Identify releases not discovered during the PA
- Provide a specific description of the environmental setting
- Provide information on release pathways and the potential for releases to each medium
- Confirm information obtained during the PA regarding operations, SWMUs, AOCs, and releases

The VSI includes interviewing appropriate facility staff; inspecting the entire facility to identify all SWMUs and AOCs; photographing all visible SWMUs; identifying evidence of releases; making a preliminary selection of potential sampling parameters and locations, if needed; and obtaining additional information necessary to complete the PA/VSI report.

This report documents the results of a PA/VSI of the Premix, Inc. (Premix), facility (EPA Identification No. OHD 004 200 044) in North Kingsville, Ashtabula County, Ohio. The PA was completed on June 19, 1992. PRC gathered and reviewed information from the Ohio Environmental Protection Agency (OEPA), Ohio Department of Natural Resources (ODNR), U.S. Geological Survey (USGS), and from EPA Region 5 RCRA files. The VSI was conducted on June 25, 1992. It included interviews with facility representatives and a walk-through inspection of the facility. PRC identified eight SWMUs and one AOC at the facility.

PRC completed EPA Form 2070-12 using information gathered during the PA/VSI. This form is included as Attachment A. The VSI is summarized and eight inspection photographs are included in Attachment B. Field notes from the VSI are included in Attachment C.

#### 2.0 FACILITY DESCRIPTION

This section describes the facility's location; past and present operations; waste generating processes and waste management practices; a history of documented releases; regulatory history; environmental setting; and receptors.

#### 2.1 FACILITY LOCATION


The Premix facility is located at the intersection of Harmon Road and Route 20 in North Kingsville, Ashtabula County, Ohio (latitude 41°55'20"N and longitude 80°39'30"W). The 61-acre facility is located in a rural area and is bordered on the north by railroad tracks and on all other sides by sparsely populated land. Figure 1 shows the facility location in relation to surrounding topographic features. The drive-in theater, shown east of the facility, is no longer present.

#### 2.2 FACILITY OPERATIONS

Premix manufactures reinforced thermoset molding compounds and custom molded fiberglass parts. Approximately half of the molding compounds manufactured at Premix are for sale, while the other half are used by Premix to manufacture custom molded fiberglass parts. Premix has operated at the North Kingsville facility since 1964, and employs approximately 535 people. The facility consists of one building, which has undergone several additions over the years, and a drainage pond. The building currently occupies 280,000 square feet and the pond covers approximately 5 acres.

Premix receives raw materials, including polyester resins, fillers, pigments, and catalysts in drums, bags, and bulk. These raw materials are mixed in 1,000-pound mixing vessels. Finished molding compounds are either rolled into sheets, approximately 0.5 inch thick, or weighed into specific bulk weights. Once molding compounds have been formed into sheets or bulk units, they are either packaged for sale or sent to Premix's press area for molding.

In the press area, molding compounds are injection, compression, or transfer molded into custom parts. After molding, most molded parts are packaged and shipped to customers. However, some molded parts require finishing. Finishing operations include grinding, build-up, solvent bonding, machining, and painting. After finishing operations, finished parts are packaged and shipped to customers.



Solid wastes generated from facility operations and the SWMUs where they are managed are discussed in detail in Section 2.3

#### 2.3 WASTE GENERATION AND MANAGEMENT

Premix generates nine hazardous wastes and four nonhazardous wastes at various locations within the facility. SWMUs and their current status are identified in Table 1. The locations of the SWMUs and the AOC in relation to the facility layout are shown in Figure 2. Wastes generated at the facility are summarized in Table 2. Facility generation and management of both hazardous and nonhazardous wastes are discussed below.

Premix receives polyester resins, fillers, pigments, and catalysts as raw materials for producing molding compounds. These raw materials are mixed in 1,000-pound mixing vessels. The mixing process generates waste flammable resin (D001) and waste organic peroxide (D003). Approximately 6 to 15 drums of waste flammable resin are generated per week and stored in the Outdoor, Covered Drum Storage Area (DSA) (SWMU 3), before being transported to Chemical Solvent, Inc. (CSI), of Cleveland, Ohio for disposal. One drum of waste organic peroxide is generated every 2 months and is stored in the Waste Organic Peroxide Storage Area (SWMU 5). Waste organic peroxide is disposed of at Ross Incineration of Grafton, Ohio.

Premix operates several quality control laboratories that monitor different components of the molding compounds. Measuring the glass content of the molding compounds generates approximately one drum of waste solvent ES-2173C (D001) per week. Measuring the water content of the molding compounds generates one drum of waste pyridine (D001 and F003) per month. Waste solvent ES-2173C is accumulated in the Waste Solvent Accumulation Area (SWMU 4), stored in the Outdoor, Covered DSA (SWMU 3), and disposed of at CSI. Waste pyridine is accumulated in small quantities in the laboratory and transferred directly to SWMU 3 before being transported to Ross Incineration.


Premix uses several solvents and solvent blends for equipment cleaning and solvent bonding molded parts. Over the years Premix has varied the solvents used, using safer, less toxic solvents when appropriate. Waste mixed solvents (D001, F002, F003, and F005), currently consisting of trichloroethane, methanol, toluene, acetone, and Freon-113, are used throughout the facility to clean various equipment. Waste mixed solvents are generated at a rate of 1 to 1.5 drums per week, and accumulated in the Waste Solvent Accumulation Area (SWMU 4) before being transferred to the Outdoor, Covered DSA (SWMU 3). Waste solvent ES-265E (D001), generated at a rate of two to four drums per week, is used to clean equipment during quick change-out operations. Waste solvent SP-731 (D001), generated at a rate of one drum every

TABLE 1
SOLID WASTE MANAGEMENT UNITS

SWMU Number	SWMU Name	RCRA Hazardous Waste <u>Management Unit</u> <sup>a</sup>	Status
	Former Hazardous Waste Storage Area	Yes	Inactive, ceased operation in 1982, RCRA closure approved in 1989
2	Former Hazardous Waste Storage Pad	Yes	Inactive, ceased operation in 1989, RCRA closure approved in 1989
3	Outdoor, Covered Drum Storage Area	No	Active, less than 90-day storage of hazardous waste
4	Waste Solvent Accumulation Area	No	Active
5	Waste Organic Peroxide Storage Area	No	Active
6	Waste Paint Accumulation Area	No	Active
7	Dust Collectors	No	Active
8	Waste Hydraulic Oil and Stoddard Solvent Storage Area	No	Active

# Note:

A RCRA hazardous waste management unit is one that currently requires or formerly required submittal of a RCRA Part A or Part B permit application.



# TABLE 2 SOLID WASTES

Waste/EPA Waste Code <sup>a</sup>	Source	Solid Waste Management Unit
Waste Flammable Resin/D001	Molding compound production	3, and formerly 1 and 2
Waste Organic Peroxide/D003	Molding compound production	5
Waste Solvent ES-2173C/D001	Quality control laboratory	3, 4, and formerly 1 and 2
Waste Pyridine/D001 and F003	Quality control laboratory	3, and formerly 1 and 2
Waste Mixed Solvents/D001, F002, F003, and F005	Equipment cleaning	3, 4, and formerly 1 and 2
Waste Solvent ES-265E/D001	Equipment cleaning	3, and formerly 1 and 2
Waste Solvent SP-731/D001	Solvent bonding	3, and formerly 1 and 2
Waste Paint and Thinner/D001 and D035	Painting operations	3, 6, and formerly 1 and 2
Waste Stoddard Solvent/D001	Maintenance	3, 8, and formerly 1 and 2
Waste Glass Dust/(NA)	Sanding and grinding operations	7
Scrap Molding Compounds/(NA)	Off-specification and excess material	General facility refuse
Scrap Molded Parts/(NA)	Defective and damaged products	General facility refuse
Waste Hydraulic Oil/(NA)	Molding press heating	8

# Notes:

a Not applicable (NA) designates nonhazardous waste.

6 months, is used to solvent-bond molded parts. These wastes are transferred directly to the Outdoor, Covered DSA (SWMU 3). All of these wastes are disposed of at CSI.

Some molded parts require painting. Painting operations generate waste paint and thinner (D001 and D035) at a rate of about one drum every 2 to 4 weeks. Waste paint and thinner is accumulated in the Waste Paint Accumulation Area (SWMU 6), stored in the Outdoor, Covered DSA (SWMU 3), and disposed of at CSI. From 1975 to 1987 Premix operated a water wash paint spray booth. Nonhazardous water from the booth discharged to the On-site Pond (AOC 1). Currently, Premix operates a dry paint spray booth. In 1991, Premix had the paint spray booth filters analyzed for full scan toxicity characteristic leaching procedure (TCLP) analysis. The filters were determined to be nonhazardous and are disposed of in Lake County Landfill in Chesterland, Ohio.

General facility maintenance operations generate waste stoddard solvent (D001) at a rate of one drum per month. This waste is accumulated at the Waste Hydraulic Oil and Stoddard Solvent Storage Area (SWMU 8) before being transferred to the Outdoor, Covered DSA (SWMU 3), and ultimately disposed of at CSI.

Nonhazardous waste glass dust, generated during sanding and grinding of molded parts, is collected in three bag house-type Dust Collectors (SWMU 7). Approximately 200 pounds of glass dust are generated per month. Premix collects the waste glass in drums. A waste hauler transfers the dust from the drums to a roll-off box for disposal at a landfill.

Premix generates nonhazardous scrap molding compounds and molded parts. Scrap molding compounds are generated from off-specification compounds and excess molding compounds returned by customers. Defective and damaged molded parts constitute scrap molded parts. Both of these nonhazardous waste streams are disposed of in the facility's general refuse.

Premix uses hydraulic oil to heat the molding presses. Waste hydraulic oil is accumulated in the Waste Hydraulic Oil and Stoddard Solvent Storage Area (SWMU 8) and sent off site for recycling. Quantities generated were not available.

All wastes that are currently stored in the Outdoor, Covered DSA (SWMU 3), were previously stored in the Former Hazardous Waste Storage Area (SWMU 1) from 1980 until 1982, and at the Former Hazardous Waste Storage Pad (SWMU 2) from 1982 until 1989.

#### 2.4 HISTORY OF DOCUMENTED RELEASES

This section discusses the history of documented releases to ground water, surface water, air, and on-site soils at the facility.

No documented releases to ground water, surface water, or on-site soils have occurred at the facility. However, in July 1989, a fire occurred in the Outdoor, Covered DSA (SWMU 3). The cause of the fire was determined to be spontaneous combustion which initiated exothermic reactions among the storage containers. The North Kingsville Fire Department extinguished the flames using dry chemical extinguishers with water propellant. At the time of the fire, SWMU 3 contained nonhazardous waste polyester paste, waste polyester resin (D001), waste combustible liquid (F002, F003, and F005), and waste paint related material (D001). Excess liquid from fighting the fire drained, via one of the facility's two drains, to the On-site Pond (AOC 1). Analysis of water samples collected from the On-site Pond indicated that the pond had not been contaminated. The facility maintains that no hazardous waste migrated outside of the storage area other than the smoke and vapor emissions that were generated during the fire (Premix, 1989b).

OEPA received odor complaints from citizens in 1984 and 1987. After investigation in 1984, OEPA found that the complaint was unsubstantiated (OEPA, 1984b). In 1987, OEPA informed a citizen that an independent firm would conduct emission testing in September 1987. Based on the testing data, OEPA would perform computer dispersion modeling to estimate the ground level concentrations of contaminants (OEPA, 1987c). PRC found no follow-up documents indicating whether the testing and modeling was completed.

#### 2.5 REGULATORY HISTORY

Premix submitted a Notification of Hazardous Waste Activity form on August 13, 1980. The form indicated that Premix would be a generator, transporter, and treatment, storage, or disposal (TSD) facility for D001, D00X, F002, F005, and F017 wastes (Premix, 1980a). On November 18, 1980, Premix submitted a RCRA Part A permit application. The application indicated that, as a TSD facility, Premix would handle 26,000 gallons of F002, F003, and F005 waste; 133,200 gallons of D001 and D003 waste; and 20,000 gallons of D001 waste in containers (S01) (Premix, 1980b).

In February 1987, Premix submitted a Request for Partial Closure of its Hazardous Waste Storage Area (SWMU 1) (Premix, 1987a). In October 1987, OEPA approved the partial closure plan, but added several modifications (OEPA, 1987d). EPA concurred with OEPA in a letter to

Premix, dated December 2, 1987 (EPA, 1987). Premix submitted a Request for Closure of Hazardous Waste Storage Unit [SWMU 2], in December 1987 (Premix, 1987b). OEPA approved the closure plan with modifications (OEPA, 1988) and EPA concurred (EPA, 1988). In June 1988, Premix submitted certification of closure for SWMU 1 (Premix, 1988). In July 1989, Premix submitted certification of closure for SWMU 2 (Premix, 1989a). In a 1991 letter from OEPA to EPA, OEPA states that Premix underwent full closure and received a Final Letter on August 8, 1989 (OEPA, 1991). PRC found no record of the August 8, 1989 letter during the PA. In April 1992, OEPA confirmed that Premix submitted a closure plan, OEPA approved the plan, Premix certified closure, and OEPA conducted a closure certification inspection. Based on its inspection and records review, OEPA determined that the storage areas (SWMUs 1 and 2) had been closed in accordance with the approved closure plans, and Premix was now to be regulated as a generator of hazardous waste (OEPA, 1992).

Over the years of operation, Premix has been inspected by OEPA several times. Most inspections resulted in letters of deficiency being sent to Premix for violations related to lack of inspection logs, no waste analysis plan, no closure plan, and inadequate personnel training records (OEPA, 1981a; 1982; 1984c; 1986; 1987a; and 1987e). In July 1987, OEPA filed a Final Findings and Orders against Premix for not having financial and liability coverage (OEPA, 1987b).

In June 1983, OEPA required that Premix apply for a Permit to Install under state law with appendices for several operations, including drying ovens, parts washers, dust collectors, parts grinders, and paint spray booths (OEPA, 1983). Premix submitted the application and OEPA issued Premix's air permit in February 1984 (OEPA, 1984a).

According to a 1981 OEPA "Non-major Industrial Wastewater Inspection Report," Premix discharges all wastewaters, including floor drains, paint booth holding tank overflow, and parts washers, to an on-site pond. Discharge from the facility flows through two underground drains to the on-site pond. The pond does not overflow into "waters of the State" and, therefore, does not require a National Pollutant Discharge Permit (OEPA, 1981b). Premix operates a wastewater treatment system to treat sanitary wastes. Once treated, water discharges to the on-site pond. Storm water run-off from the facility also drains to the pond.

#### 2.6 ENVIRONMENTAL SETTING

This section describes the climate; flood plain and surface water; geology and soils; and ground water in the vicinity of the facility.

#### 2.6.1 Climate

The climate in Ashtabula County is continental. The average daily temperature is 49.2 degrees Fahrenheit (°F). The lowest average daily temperature is 25.6°F in January. The highest average daily temperature is 71.3°F in July (NOAA, 1982). In summer, northern areas nearest Lake Erie are markedly cooler than the rest of the county. The total average annual precipitation for the county is 38 inches. The mean annual lake evaporation is about 31 inches (ODNR, 1991). The 1-year, 24-hour maximum rainfall is 4.0 inches. The prevailing wind is from the southwest. Average wind speed is highest in January at 13 miles per hour from the southwest (USSCS, 1980).

#### 2.6.2 Flood Plain and Surface Water

According to ODNR, no identified 100-year flood plain exists within the corporate limits of North Kingsville, Ohio; therefore, the Premix facility is not located within a 100-year flood plain (PRC, 1992b). The closest body of surface water is an on-site pond, approximately 5 acres in size. The facility is about 1 mile south of Lake Erie and 1.5 miles north of Conneaut Creek. Seasonal, forested and emergent, Palustrine wetlands exist within 0.5 mile of the facility to the south and southeast (USDI, 1977).

#### 2.6.3 Geology and Soils

Soil borings drilled at the facility in 1979 indicate that crushed limestone exists from 0 to 0.5 feet below ground surface (bgs). Brown coarse to fine sand, with some silt and gravel, was encountered from 0.5 to 18 feet bgs; brown medium and fine sand, with trace amounts of silt, was encountered from 18 to 23 feet bgs; gray medium and coarse sand, with traces of gray silty clay, was encountered from 23 to 28 feet bgs; and gray silty clay, with some layers of gray silty fine sand, was encountered from 28 to 31 feet bgs, where the boring ended (Herron, 1979).

Regional geology indicates that glacial till extends to 120 feet bgs. Bedrock of the Ohio Shale formation is first encountered at a depth of 120 feet bgs and extends to approximately 620 feet bgs (PRC, 1992a).

#### 2.6.4 Ground Water

According to the 1979 soil borings drilled at the facility, ground water is encountered below the facility at about 15 to 18 feet bgs (Herron, 1979). Most ground water is found in the glacial till; very little ground water is encountered in the Ohio Shale (PRC, 1992a). Ground water in the area generally flows northward to Lake Erie. Ground water is not used as a municipal

source of drinking water. However, one private well exists 1 mile southeast of the facility. PRC was unable to determine if the well is active. The city of North Kingsville obtains its drinking water from the city of Ashtabula, which gets drinking water from Lake Erie.

#### 2.7 RECEPTORS

The 61-acre Premix facility is located in a rural area near North Kingsville, Ohio, and is bordered on the north by railroad tracks, and on all other sides by sparsely populated land. The facility is secured by 24-hour security guards. Visitors to the facility must check in through a receptionist at the main entrance.

The closest school is located about 1 mile southwest of the facility. Wetlands exist within 0.5 mile to the south and southeast of the facility. No state or national parks or wildlife preserves exist within 2 miles of the facility.

#### 3.0 SOLID WASTE MANAGEMENT UNITS

This section describes the eight SWMUs identified during the PA/VSI. The following information is presented for each SWMU: description of the unit, dates of operation, wastes managed, release controls, history of documented releases, and PRC's observations. Figure 2 shows the SWMU locations.

SWMU 1

Former Hazardous Waste Storage Area

Unit Description:

This unit consisted of an outdoor gravel area, about 15 by 30 feet, located on the east side of the west leg of the facility building (see Photograph No. 1).

Date of Startup:

This unit began storing waste in November 1980.

Date of Closure:

This unit ceased storing waste in July 1982. OEPA approved

closure for this unit in August 1989.

Wastes Managed:

This unit managed most wastes produced at the facility, including: waste flammable resin (D001); waste solvent ES-2173C (D001); waste pyridine (D001 and F003); waste mixed solvents (D001, F002, F003, and F005); waste solvent ES-265E (D001); waste solvent SP-731 (D001); waste paint and thinner (D001 and D035); and waste

stoddard solvent (D001).

Release Controls:

This unit had no release controls.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

During the VSI, PRC observed miscellaneous pieces of equipment in this unit. The area is still covered with gravel. PRC observed no hazardous wastes or evidence of spills in this area.

SWMU 2

Former Hazardous Waste Storage Pad

Unit Description:

This unit consisted of a partially bermed, 910-square-foot concrete pad located in the center of the facility complex (see Photograph No. 2). Some of this unit has now been built upon.

Date of Startup:

This unit began storing waste in August 1982.

Date of Closure:

This unit ceased storing waste in July 1989. OEPA approved closure for this unit in August 1989.

Wastes Managed:

This unit managed most wastes produced at the facility, including: waste flammable resin (D001); waste solvent ES-2173C (D001); waste pyridine (D001 and F003); waste mixed solvents (D001, F002, F003, and F005); waste solvent ES-265E (D001); waste solvent SP-731 (D001); waste paint and thinner (D001 and D035); and waste stoddard solvent (D001).

Release Controls:

This unit was partially bermed and on a concrete pad.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

During the VSI, PRC observed that part of the concrete pad had been built on and the other part was paved over. No waste was stored in this area. Because of the building and paved area, PRC was unable to determine if evidence of release existed.

SWMU 3

Outdoor, Covered Drum Storage Area

Unit Description:

This unit consists of a 40- by 60-foot concrete pad with one north-south seam (see Photograph No. 3). The area is bermed on the north side by a 4.5-foot cinderblock wall, on the east side by the facility building wall, on the south side by a 2.5-foot berm, and the west side is unbermed. The western edge of the unit is a 6- by 8-inch grate-covered trench, which ties into a 2- by 3-foot grate-covered trench that runs along the north side of the unit, within the cinderblock wall.

Date of Startup:

This unit began storing waste in July 1989.

Date of Closure:

This unit is currently active as a less than 90-day storage area.

Wastes Managed:

This unit manages most wastes produced at the facility, including: waste flammable resin (D001); waste solvent ES-2173C (D001); waste pyridine (D001 and F003); waste mixed solvents (D001, F002, F003, and F005); waste solvent ES-265E (D001); waste solvent SP-731 (D001); waste paint and thinner (D001 and D035); and waste stoddard solvent (D001).

Release Controls:

This unit is bermed on three sides (north, south, and east), has two connected containment trenches that run along the north and west sides of the unit, and has a 10-foot deep sump, located at the east end of the north-side trench. The sump has a 6-inch diameter discharge line, via one of the facility's two drains, to the on-site pond. The sump discharge is located 4 inches below the trench grade (PRC, 1992d).

History of Documented Releases:

In July 1989, a fire broke out in this unit. Overflow from extinguishing the fire drained, via one of the facility's two drains, to the on-site pond. Water samples were collected from the pond; sample results indicated that no contamination was present in the pond. The facility claims that no hazardous contaminants escaped from the unit except for smoke and vapors during the fire.

Observations:

During the VSI, this unit contained 56 drums of nonhazardous resin waste, 13 drums of flammable liquid, and 2 drums of combustible liquid. PRC noted no cracks or stains on the concrete floor or berm. The sump was clean and dry. Because of the depth of the sump, PRC was unable to determine if the sump wall or floor was cracked.

SWMU 4

Waste Solvent Accumulation Area

Unit Description:

This unit is an unbermed concrete area within the mixing, bulk molding, and sheet molding area of the facility building (see

Photograph No. 4).

Date of Startup:

This unit began storing waste in 1980.

Date of Closure:

This unit is currently active.

Wastes Managed:

This unit manages waste solvent ES-2173C (D001) and waste mixed

solvents (D001, F002, F003, and F005).

Release Controls:

This unit is located on a concrete floor within the facility building.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

During the VSI, PRC observed two drums of waste solvent in this

unit. The drums were stored open with funnels in the bung

openings.

SWMU 5

Waste Organic Peroxide Storage Area

Unit Description:

This unit is a 5- by 9-foot concrete block building located north of the east leg of the facility building. No photograph is available because, during the VSI, facility representatives did not indicate

that this building stored hazardous waste.

Date of Startup:

This unit began storing waste in 1975.

Date of Closure:

This unit is currently active.

Wastes Managed:

This unit manages waste organic peroxide (D003).

Release Controls:

This unit is a concrete building with no floor drains (PRC, 1992c).

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

PRC observed the outside of this unit. The integrity of the

building was sound.

SWMU 6

Waste Paint Accumulation Area

Unit Description:

This unit is an unbermed concrete area, located in the paint area

within the facility building (see Photograph No. 5).

Date of Startup:

This unit began storing waste in 1977.

Date of Closure:

This unit is currently active.

Wastes Managed:

This unit manages waste paint and thinner (D001 and D035).

Release Controls:

This unit is located on a concrete floor within the facility building.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

During the VSI, PRC observed one drum of solvent waste and one drum of paint related waste in this unit. These drums were stored open, with funnels in the bung openings. PRC observed paint

stains, but no cracks, on the concrete floor.

SWMU 7

**Dust Collectors** 

Unit Description:

This unit consists of three bag house-type dust collectors. The dust collectors are located on the east side of the west leg of the facility building and in the central area of the complex (see Photograph No.

2).

Date of Startup:

The two dust collectors located on the east side of the west leg of the building began operating in 1980. The other dust collector

began operating in 1972.

Date of Closure:

This unit is currently active.

Wastes Managed:

This unit manages nonhazardous waste glass dust from sanding and

grinding operations.

Release Controls:

This unit is a release control for exhaust from sanding and grinding

operations.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

PRC observed that the unit is properly managed. No glass dust was

observed on the ground surrounding the area.

SWMU 8

Waste Hydraulic Oil and Stoddard Solvent Storage Area

Unit Description:

This unit is an unbermed concrete area within the facility building

(see Photographs No. 6 and 7).

Date of Startup:

This unit began storing waste in 1984.

Date of Closure:

This unit is currently active.

Wastes Managed:

This unit manages nonhazardous waste hydraulic oil and waste

stoddard solvent (D001).

Release Controls:

This unit is located on a concrete floor within the facility building.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

During the VSI, PRC observed three drums of stoddard solvent,

and one full tote of waste hydraulic oil in this area. PRC observed

oil stains, but no cracks, on the concrete floor.

### 4.0 AREAS OF CONCERN

PRC identified one AOC during the PA/VSI. This AOC is discussed below. Its location is shown in Figure 2.

### AOC 1 On-site Pond

Premix maintains a 5-acre On-site Pond (AOC 1) into which it discharges treated sanitary waste, noncontact cooling water, and storm run-off (see Photograph No. 8). The pond, built in 1964, is unlined and may seep into local ground water. Floor drains exist within the facility building only in areas where molding compounds have already been mixed, making the compounds nonhazardous. The purpose of the floor drains is to drain sprinkler water, in the event of a fire, to the pond. The potential for a hazardous release to a floor drain within the facility building with subsequent discharge to the pond is low.



### 5.0 CONCLUSIONS AND RECOMMENDATIONS

The PA/VSI identified eight SWMUs and one AOC at the Premix facility. Background information on the facility's location; operations; waste generating processes and waste management practices; history of documented releases; regulatory history; environmental setting; and receptors is presented in Section 2.0. SWMU-specific information, such as the unit's description, dates of operation, wastes managed, release controls, history of documented releases, and observed condition, is presented in Section 3.0. The AOC is discussed in Section 4.0. Following are PRC's conclusions and recommendations for each SWMU and AOC. Table 3, at the end of this section, summarizes the SWMUs and AOC at the facility and the recommended further actions.

SWMU 1

Former Hazardous Waste Storage Area

Conclusions:

No releases from this unit have been documented. This unit is no longer active and was RCRA-closed in 1989. Therefore, the potential for release of hazardous constituents from this unit to environmental media is low.

Recommendations:

PRC recommends no further action for this unit.

SWMU 2

Former Hazardous Waste Storage Pad

Conclusions:

No releases from this unit have been documented. This unit is no longer active and was RCRA-closed in 1989. Therefore, the potential for release of hazardous constituents from this unit to environmental media is low.

Recommendations:

PRC recommends no further action for this unit.

SWMU 3

Outdoor, Covered Drum Storage Area

Conclusions:

This unit has adequate secondary containment and is in good condition. Therefore, the potential for release of hazardous constituents from this unit to environmental media is low.

Recommendations:

PRC recommends no further action for this unit.

DATE ASEMS (8)
RIN # UNITIALS UNITIALS



SWMU 4

Waste Solvent Accumulation Area

Conclusions:

No releases from this unit have been documented. This unit is located on a concrete floor within the facility building. Therefore, the potential for release of hazardous constituents from this unit to environmental media is

low.

Recommendations:

PRC recommends that all drums in this unit be stored closed.

SWMU 5

Waste Organic Peroxide Storage Area

Conclusions:

No releases from this unit have been documented. This unit is a concrete building with no floor drains. Therefore, the potential for release of hazardous constituents from this unit to environmental media is low.

Recommendations:

PRC recommends no further action for this unit.

SWMU 6

Waste Paint Accumulation Area

Conclusions:

No releases from this unit have been documented. This unit is located on a concrete floor within the facility building. Therefore, the potential for release of hazardous constituents from this unit to environmental media is

low.

Recommendations:

PRC recommends that all drums in this unit be stored closed.

SWMU 7

**Dust Collectors** 

Conclusions:

No releases from this unit have been documented. This unit does not handle hazardous waste or constituents. Therefore, the potential for release of hazardous constituents from this unit to environmental media is

low.

Recommendations:

PRC recommends no further action for this unit.

DATE SES (15/0)
PRIN #
INITIALS MY

23

# ENFORCEMENT CONFIDENTIAL

**SWMU 8** 

Waste Hydraulic Oil and Stoddard Solvent Storage Area

Conclusions:

No releases from this unit have been documented. This unit is located on a concrete floor within the facility building. Therefore, the potential for release of hazardous constituents from this unit to environmental media is

low.

Recommendations:

PRC recommends no further action for this unit.

AOC 1

On-site Pond

Conclusions:


This AOC is an unlined pond that receives treated sanitary waste, noncontact cooling water, and storm run-off. The potential for hazardous constituents to be discharged via floor drains from the facility to the pond is low.

Recommendations:

PRC recommends that a means of containing floor drain discharge before

it enters the pond be installed.

RELEASED SISON
RIN #
INITIAL 3 WY



## TABLE 3 SWMU AND AOC SUMMARY

<del></del>	SWMU	Dates of Operation	Evidence of Release	Recommended Further Action
1.	Former Hazardous Waste Storage Area	1980 to 1982	None	No further action
2.	Former Hazardous Waste Storage Pad	1982 to 1989	None	No further action
3.	Outdoor, Covered Drum Storage Area	1989 to present	None	No further action
4.	Waste Solvent Accumulation Area	1980 to present	None	Store drums closed
5.	Waste Organic Peroxide Storage Area	1975 to present	None	No further action
6.	Waste Paint Accumulation Area	1977 to present	None	Store drums closed
7.	Dust Collectors	1972 and 1980 to present	None	No further action
8.	Waste Hydraulic Oil and Stoddard Solvent Storage Area	1984 to present	None	No further action
	AOC	Dates of Operation	Evidence of Release	Recommended Further Action
1.	On-site Pond	1964 to present	None	Contain floor drain discharge before it enters the pond

RELEASED ()
DATE
RIN #\_\_\_\_\_\_

### REFERENCES

- Herron Testing Laboratories, Inc. (Herron), 1979. Report of Soil Boring Operations at Proposed Addition--Premix, Inc. (Premix), March 27.
- National Oceanic and Atmospheric Administration (NOAA), 1982. Monthly Normals of Temperature, Precipitation, and Heating and Cooling Degree Days 1951-1980, Report No. 81, Ohio, September.
- Ohio Department of Natural Resources (ODNR), 1991. Hydrologic Atlas for Ohio, Water Inventory Report No. 28.
- Ohio Environmental Protection Agency (OEPA), 1981a. Letter to Premix, Regarding September 22, 1981 Inspection, September 28.
- OEPA, 1981b. Non-major Industrial Wastewater Inspection Report, December 12.
- OEPA, 1982. Letter to Premix, Regarding June 22, 1982 Inspection, August 18.
- OEPA, 1983. Letter to Premix, Requiring Air Permit Application, June 22.
- OEPA, 1984a. Letter to Premix, Issuing Air Permit, February 8.
- OEPA, 1984b. Letter to Ms. Eleanor Barry (Private Citizen), Regarding Odor Complaint, June 22.
- OEPA, 1984c. Letter to Premix, Regarding July 26, 1984 Inspection, August 8.
- OEPA, 1986. Letter to Premix, Regarding January 8, 1986 Inspection, March 31.
- OEPA, 1987a. Letter to Premix, Regarding December 16, 1986 Inspection, February 18.
- OEPA, 1987b. Letter to Premix, Final Findings and Orders, July 29.
- OEPA, 1987c. Letter to Mrs. Pat Doty (Private Citizen), Regarding Odor Complaint, September 14.
- OEPA, 1987d. Letter to Premix, Approving Partial Closure Plan, October 15.
- OEPA, 1987e. Letter to Premix, Regarding December 8, 1987 Inspection, December 10.
- OEPA, 1988. Letter to Premix, Approving Closure Plan, April 18.
- OEPA, 1991. Letter to U.S. Environmental Protection Agency (EPA), Regarding Final Closure for Premix, April 3.
- OEPA, 1992. Letter to Premix, Approving Final Closure and Granting Generator Status, April 20.
- PRC Environmental Management, Inc. (PRC), 1992a. Record of Telephone Conversation between J. Michaels and Rick Pavey, ODNR, August 27.
- PRC, 1992b. Record of Telephone Conversation between J. Michaels and Cindy Crecelius, ODNR, August 28.

- PRC, 1992c. Record of Telephone Conversation between J. Michaels and Ed Trenn, Premix, August 28.
- PRC, 1992d. Record of Telephone Conversation between J. Michaels and Ray Kovacs, Premix, October 29.
- Premix, 1980a. Notification of Hazardous Waste Activity Form, August 13.
- Premix, 1980b. RCRA Part A Permit Application, November 18.
- Premix, 1987a. Letter to OEPA, Requesting Partial Closure, February 26.
- Premix, 1987b. Letter to OEPA, Requesting Closure of Hazardous Waste Unit, December 14.
- Premix, 1988. Letter to OEPA, Submitting Certification of Partial Closure, June 30.
- Premix, 1989a. Letter to EPA, Submitting Certification of Closure, July 27.
- Premix, 1989b. Letter to OEPA, Describing Events of Fire, August 9.
- U.S. Department of Interior (USDI), 1977. National Wetlands Inventory Map of North Kingsville, Ohio Quadrangle.
- EPA, 1987. Letter to Premix, Concurring with OEPA for Partial Closure Plan Approval, December 2.
- EPA, 1988. Letter to Premix, Concurring with OEPA for Closure Plan Approval, May 31.
- U.S. Geological Survey (USGS), 1979. 7.5-Minute Topographic Map of North Kingsville, Ohio Quadrangle.
- U.S. Soil Conservation Service (USSCS), 1980. Soil Survey of Cuyahoga County, Ohio.

ATTACHMENT A
EPA PRELIMINARY ASSESSMENT FORM 2070-12



### POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 1 - SITE INFORMATION AND ASSESSMENT

I. IDENTI	FICATION
01 STATE	02 SITE NUMBER
ОН	HD 004 200 044

II. SITE NAME AND LOCATION						
01 SITE NAME (Legal, common, or descriptive name of	site)	02 STREET	, ROUTE NO., OF	SPECIFIC LOCA	TION IDENTIFIER	
Premix, Inc.		Harm	on Road and Rou	te 20		
		l ·				
03 CITY		04 STATE	05 ZIP CODE	06 COUNTY	07 COUNTY CODE	08 CONG DIST
North Kingsville		OH	44068	Ashtabula		
	LONGITUDE 9' 30". W				·	WWW.
10 DIRECTIONS TO SITE (Starting from nearest public ro	sed)	<u> </u>		***************************************		
From I-90 take Hwy. 193 north to U.S. Route 20, g	o east on Route 20 for 2 to	3 miles, fac	ility is on the nor	th side of Route	20	
III. RESPONSIBLE PARTIES		·				
01 OWNER (if known)		02 STREET	(Business, mailin	g residential)	, W. O W.	
Premix, Inc.			Box 281			
03 CITY		04 STATE	05 ZIP CODE	06 TELEPHONE	NUMBER	
North Kingsville		ОН	44068	(216) 224-2181		
07 OPERATOR (If known and different from owner)		08 STREET	(Business, mailir	g, residential)		
O9 CITY		10 STATE	11 ZIP CODE	12 TELEPHONE	NUMBER	-
13 TYPE OF OWNERSHIP (Check one)				1		
MS A. PRIVATE ☐ B. FEDERAL:	cy name)	<b>□</b> C	. STATE	D, COUNTY	E. MUN	ICIPAL '
☐ F. OTHER(Specify)		□ G. ÚNK	NOWN			
14 OWNER/OPERATOR NOTIFICATION ON FILE (Check	ell that sankil					
A. RCRA 3010 DATE RECEIVED: 08/13/80  MONTH DAY YEA	B. UNCONTROLLED WA	STE SITE (C	ERCLA 103 c) [	ATE RECEIVED:	/ / MONTH DAY	C. NONE
IV. CHARACTERIZATION OF POTENTIAL HA	ARD.					
01 ON SITE INSPECTION BY (Check	all that apply)					
11 A. EPA 12 YES DATE 06 / 25 / 92 11 E. LOCA	B. EPA CONTRA AL HEALTH OFFICIAL		C. STATE	□ D. O	THER CONTRACT	OR
D NO	•			(Specify)		
CONTRAC	FOR NAME(S): PRC Envi					
02 SITE STATUS (Check one)	O3 YEAR	S OF OPERA	ATION			
ME A. ACTIVE DE B. INACTIVE DE C.	UNKNOWN	196 BEGINNING Y	4 Present	_	UNKNO	NWO
04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESE	NT, KNOWN, OR ALLEGE	D				
			,			
Flammable resins, flammable solvents, organic pe	roxide, paint and thinner					
OF DESCRIPTION OF POTENTIAL UNIVERSITY OF PARTY	ONATENT AND OR DODLE					
05 DESCRIPTION OF POTENTIAL HAZARD TO ENVIR	IONWIENT AND/OR POPUL					
		ATION				
None		ATION				
None	·	ATION .				
None			·		,	
None  V. PRIORITY ASSESSMENT		ATION				,
V. PRIORITY ASSESSMENT	edium is checked. comolete		e Information and	Part 3 - Descrintin	on of Hazardous Co	nditions and Incidents
V. PRIORITY ASSESSMENT  01 PRIORITY FOR INSPECTION (Check one. If high or me	UM 🐯 C. L.C	Part 2 - Wast		D. NONE		
V. PRIORITY ASSESSMENT  01 PRIORITY FOR INSPECTION (Check one. If high or me	UM 🐯 C. L.C	Part 2 - Wast		D. NONE		nditions and incidents.) Trent disposition form)
V. PRIORITY ASSESSMENT  01 PRIORITY FOR INSPECTION (Check one. If high ar me  B. A. HIGH  (Inspection required promptly) (Inspection	UM 🐯 C. L.C	Рап 2 - Wast W on time-avails		D. NONE		
V. PRIORITY ASSESSMENT  01 PRIORITY FOR INSPECTION (Check one. If high or me  1 A. HIGH (Inspection required promptly) (Inspection  VI. INFORMATION AVAILABLE FROM  01 CONTACT Kevin Piererd	UM B C. LC required) (Inspect of 02 OF (Agency/Organization U.S. EPA	Рап 2 - Wast W on time-avails		D. NONE		03 TELEPHONE NUMBER (312) 886-4448
V. PRIORITY ASSESSMENT  01 PRIORITY FOR INSPECTION (Check one. If high or me  1 A. HIGH (Inspection required promptly) (Inspection  VI. INFORMATION AVAILABLE FROM  01 CONTACT	UM B C. LC required) (Inspect of the control of the	Рап 2 - Wast W on time-avails	ble basis) (No	D. NONE	eeded; complete cu	orent disposition form)

ATTACHMENT B
VISUAL SITE INSPECTION SUMMARY AND PHOTOGRAPHS

### VISUAL SITE INSPECTION SUMMARY

Premix, Inc. (Premix)
P.O. Box 281
North Kingsville, Ohio 44068
OHD 004 200 044

Date:

June 25, 1992

Primary Facility Representative: Representative Telephone No.:

Raymond Kovacs, Environmental Manager

216/224-2181

Additional Facility Representatives:

Ed Trenn, Assistant Environmental Manager

216/224-2181

Inspection Team:

Jean Michaels, PRC Environmental Management, Inc.

(PRC)

Manoj Mishra, PRC

Photographer:

Manoj Mishra, PRC

Weather Conditions:

Sunny, 75°F

Summary of Activities:

The visual site inspection (VSI) began at 9:00 a.m. with an introductory meeting. The inspection team explained the purpose of the VSI and the agenda for the visit. Facility representatives then discussed the facility's past and current operations, solid wastes generated, and release history. Facility representatives provided the inspection team with copies of requested documents.

The VSI tour began at 10:30 a.m. The inspection team observed the molding compound mixing area; bulk and sheet molding areas; press area; finishing area; paint area; and all solid waste management units (SWMU). PRC photographed all SWMUs except SWMU No. 5.

The tour concluded at 12:30 p.m., after which the inspection team held an exit meeting with facility representatives. The VSI was completed and the inspection team left the facility at 1:00 p.m.



Photograph No. 1 Orientation: Southwest

Description: Former Hazardous Waste Storage Area

Location: SWMU 1 Date: June 25, 1992



Photograph No. 2 Orientation: South

Description: Former Hazardous Waste Storage Pad and Dust Collectors

Location: SWMU 2 and 7 Date: June 25, 1992

B-2



Photograph No. 3 Orientation: Southeast

Description: Outdoor, Covered Drum Storage Area

Location: SWMU 3 Date: June 25, 1992



Photograph No. 4 Orientation: Southwest Location: SWMU 4 Date: June 25, 1992

Description: Solvent distribution and Waste Solvent Accumulation Area--two waste drums

stored open with funnels in bung openings



Location: SWMU 6 Photograph No. 5 Orientation: East Date: June 25, 1992

Waste Paint Accumulation Area--two drums stored open with funnels in bung Description:

openings



Photograph No. 6 Orientation: East Location: SWMU 8 Date: June 25, 1992 Waste Hydraulic Oil and Stoddard Solvent Storage Area--stoddard solvent in drums

Description:



Photograph No. 7 Orientation: West Description: 500-gallon tote for waste hydraulic oil

Location: SWMU 8 Date: June 25, 1992



Photograph No. 8 Orientation: South

Description: On-site Pond Location: AOC 1 Date: June 25, 1992

ATTACHMENT C
VISUAL SITE INSPECTION FIELD NOTES

6/25 Premix, Inc.

Met started op in Nkngwille name of compained for autside we g small parts for autside op have graven over years to what make is to safe Scrap parts - plactic fiberglass
molded thru compression
compound - michnu of very catalog
feles, glass (sheet & bulk from)
off-spec, customers returned natil
Whample: hearts molds - recycled fisite
Unitraple K - (clealand - recycle fisite
Chan Solver - disposes unrecycle.

(DOD) Whole Flum learn: Remaid

> Olds17e-Mc. Systec. Inc. Indiana.
Chemical Solvent, Inc. / Claulard
(6-15 dr/WL)
Chemical Solvent, Sort of eithe S-12.

(DODI, FEUZ, FPOS, FEOS) TRA METHON TOE, According CFC 113: Let since phaned out CHECLE. In process of phaning the court from two (2-3d/2WKs) took room paint, molding therethy

(3) New solv. [CDD1) -ethers-yectate trac.
(2) SP-24 sylenylacetare to quick change.
(3) SP-34 no longer used incorpe (able)
ES2173C - now was chigher flew?

ES2173C - now was chigher flew?

from QA lab -determines 1/20 contint Whote pyradine 2 DOI, 1003 m DA lah - 4 + (Idr/mp)

aunt waste (DOB), DOBS) : (Idr/54WK) parts pointing (paint booth standard (Dool) maintenance diguasing - reclaimed (CS)

Sp-72(DOO) framsduent bonding taly smo paint filter non has 30#/w/ Ruw Mid Is polypotr reino, filler catalysts,

Moldiad par 15/0/er all

Moded compd. form sheeks bulk compds edeply who

injection, compression, transfer other parts regular finishing Some package & shupped Molded park: presses

buildup, solvent bonding, machining Imishing repairs grinding paint prep.

Paint : dry booths, take over,

ward to be solvent wash (s-eyisage) Wash, water wash particulate and solvent remove / remove elletrostatic charges

Fried Insp. / Mulkagney

यमार्थिक विकास

Scrap parts - compactor system
to trash
working on ideas to chind up and
recycle or reuse in other application

Acres: 6 | 29 ft : 180 K Employer: 535 / Corp.

NPDES. starm to pand

WWTS: treats sandary wasted to pand

Mf Compd - no drains -

Pond is in lowest. - all drawings from face goes to pond - pond close not discharge to other water

Pand stocked w/ full & frag-

N: residence/Consul RR E presidences/pumic

>: Yesidinu

W. residences

City Water - Ashfabula from lake Eric Security. I day set how guarder; outside guard for non operation time, chack-in through recep.

3-shifts / set his operation 6-7 days

Air parmits: Asylan bootho, other cruas permited by area - melt molding, company

open whisher

(8) No spills

Golay: 12t. 20 beach / sandy

No US/8

Scrap mestal - minimal - al, cu

10:30 bourd organis perovided - me edysmaoftenger; vosidual ands; OAlds

Pond-Samo

Former Huss (1980: 1986) grund our solid polymer 2N photos. Current Holssa: SE photos.

ryse nul

S/90/01 / VI

Wind the Condend of t

12:30 - medotioned Report

exill bottoms — not form distillation unit — tank bottoms from tub washing and drum washing - Soil borings

- water avalign from fire

- Don't have "Final" letter - 8/8/89

On Closure

copy of updated blowing map

4 samples <.003 ng/1 styrenc

100 subt fair liter de sha

an phis/na



### CORRECTIVE ACTION STABILIZATION QUESTIONNAIRE

Completed by:	Rick Hers			
Date:	<u>September</u>	9, 1992	Agend Conference of the Confer	
Background Faci	lity Informa	tion	CONFIDEN	The state of the s
Facility Name:		Premix, Inc.	The state of the s	de la contrata de contrata de contrata de la contrata del contrata de la contrata de la contrata del contrata de la contrata del la contrata del la contrata de  la contrata de la contrata del la contrata de la contrata de la contrata del la contr
EPA Identification	on No.:	OHD 004 200 044		
Location (City, S		North Kingsville,	OH	BICINT.
Facility Priority	Rank:	Low	<u> </u>	Wan pacern i
				OCT 18 1;
	management	mpleted for one unit (SWMU), entire facility?	3. If corrective action action initiated, are they being contact a permit or an enforcement	arried out under
The entire facility and 1 AOC	y, which in	cludes 8 SWMUs	() Operating permit () Post-closure permit () Enforcement order (X) Other (Explain)	
			No corrective action activinitiated.	ities have been
Status of Correc Facility			4. Have interim measures, completed [see Question 2 in preventing the fur contamination at the faci	], been successful ther spread of
2. What is the corrective ac		tatus of HSWA s at the facility?	( ) Yes ( ) No	
(Go to 5) (X) RCRA F	acility Asses	estivities initiated ssment (RFA) or	() Uncertain; still under (X) Not required	way
<del>-</del>	=	estigation (RFI)	Additional explanatory n	otes:
() RFI comp () Corrective complete	e Measures	s Study (CMS)		
(CMI) be	gun or comp			
( ) Interim N	neasures beg	un or completed		

RELEASED 15 0

Premix, Inc. - OHD 004 200 044

ractify Releases and Exposure Concerns	Auditional explanatory notes:
5. To what media have contaminant releases from the facility occurred or been suspected of occurring?	
() Ground water	
(X) Surface water	8a. Are environmental receptors currently
() Air () Soils	being exposed to contaminants released from the facility?
6. Are contaminant releases migrating off- site?	( ) Yes (Go to 9) ( ) No
	(X) Uncertain
() Yes; Indicate media, contaminant	
concentrations, and level of certainty.	Additional explanatory notes:
Groundwater:	Potential exists for spills to be discharged into
Surface water:	the On-Site Pond (AOC 1).
Air:	
Soils:	
(X) No	
() Uncertain	8b. Is there a potential that environmental receptors could be exposed to the
7a. Are humans currently being exposed to contaminants released from the facility?	contaminants released from the facility over the next 5 to 10 years?
() Yes (Go to 8a)	(X) Yes
(X) No	() No
() Uncertain	() Uncertain
Additional explanatory notes:	Additional explanatory notes:
Facility access is restricted.	Potential exists for spills to be discharged into the On-Site Pond (AOC 1).
7b. Is there a potential for human exposure to the contaminants released from the facility	
over the next 5 to 10 years?	
() Yes	
() No	
(X) Uncertain	

Anticipated Final Corrective Measures	Additional explanatory notes:
9. If already identified or planned, would final corrective measures be able to be implemented in time to adequately address any existing or short-term threat to human health and the environment?	
() Yes () No (X) Uncertain	Technical Ability to Implement Stabilization
Additional explanatory notes:  No final corrective measures have been identified or planned.	<ul><li>12. In what phase does the contaminant exis under ambient site conditions? Check all that apply.</li><li>(X) Solid</li><li>() Light non-aqueous phase liquid</li></ul>
10. Could a stabilization initiative at this facility reduce the present or near-term (e.g., less than two years) risks to human health and the environment?	(LNAPLs) () Dense non-aqueous phase liquid (DNAPLs) () Dissolved in ground water or surfac water () Gaseous () Other
(X) Yes ( ) No ( ) Uncertain	13. Which of the following major chemica groupings are of concern at the facility?
Additional explanatory notes:	<ul> <li>(X) Volatile organic compounds (VOCs and/or semi-volatiles</li> <li>() Polynuclear aromatics (PAHs)</li> <li>() Pesticides</li> <li>() Polychlorinated biphenyls (PCBs and/or dioxins</li> <li>() Other organics</li> <li>() Inorganics and metals</li> </ul>
11. If a stabilization activity were not begun, would the threat to human health and the environment significantly increase before final corrective measures could be implemented?	() Explosives () Other
() Yes () No (X) Uncertain	

14. Are appropriate stabilization technologies available to prevent the further spread of contamination, based on contaminant	Timing and Other Procedural Issues Associated with Stabilization
characteristics and the facility's environmental setting? [See Attachment A for a listing of potential stabilization technologies.]	16. Can stabilization activities be implemented more quickly than the final corrective measures?
(X) Yes; Indicate possible course of action.	(X) Yes ( ) No ( ) Uncertain
Floor drains in facility should be capped to prevent spill discharges into the On-Site Pond (AOC 1).	Additional explanatory notes:
() No; Indicate why stabilization	
technologies are not appropriate; then go to Question 18.	17. Can stabilization activities be incorporated into the final corrective measures at some point in the future?
	(X) Yes ( ) No ( ) Uncertain
	Additional explanatory notes:
15. Has the RFI, or another environmental investigation, provided the site characterization and waste release data needed to design and implement a stabilization activity?	
( ) Yes (X) No	
If No, can these data be obtained faster than the data needed to implement the final corrective measures?	
(X) Yes ( ) No	

# Conclusion 18. Is this facility an appropriate candidate for stabilization activities? (X) Yes () No, not feasible () No, not required () Further investigation necessary Explain final decision, using additional sheets if necessary. The floor drains at the facility should be capped to prevent spills from discharging into the On-Site Pond (AOC 1). The On-Site Pond is the only environmental receptor at the facility. The 8 SWMUs at the facility have adequate secondary containment with no evidence of releases.



### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

### REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

HRE-8J

June 10, 1992

Mr. Raymond Kovacs Premix, Inc. P.O. Box 281 North Kingsville, OH 44068

Re:

Visual Site Inspection

Premix, Inc.

North Kingsville, OH OHD 004 200 044

Dear Mr. Kovacs:

The United States Environmental Protection Agency (U.S. EPA) Region V will conduct a Preliminary Assessment including a Visual Site Inspection (PA/VSI) at the referenced facility. This inspection is conducted pursuant to the Resource Conservation and Recovery Act, as amended (RCRA) Section 3007 and the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA) Section 104(e). The referenced facility has generated, treated, stored, or disposed of hazardous waste subject to RCRA. The PA/VSI requires identification and systematic review of all solid waste streams at the facility. The objective of the PA/VSI is to determine whether or not releases of hazardous wastes or hazardous constituents have occurred or are occurring at the facility which may require further investigation. This analysis will also provide information to establish priorities for addressing any confirmed releases.

The visual site inspection of your facility is to verify the location of all solid waste management units (SWMUs) and areas of concern (AOCs) to make a cursory determination of their condition by visual observation. The definitions of SWMUs and AOCs are included in Attachment I. The VSI supplements and updates data gathered during a preliminary file review. During this site inspection, no samples will be taken. A sampling visit to ascertain if releases of hazardous waste or constituents have occurred may be required at a later date.

Assistance of some of your personnel may be required in reviewing solid waste flow(s) or previous disposal practices. The site inspection is to provide a technical understanding of the present and past waste flows and handling, treatment, storage, and disposal practices. Photographs of the facility are necessary to document the condition of the units at the facility and the waste management practices used.

The VSI has been scheduled for June 25, 1992. The inspection team will consist of Jean Michaels and Manoj Mishra of PRC Environmental Management, Inc., a contractor for the U.S. EPA. Representatives of the Ohio Environmental Protection Agency (OEPA) may also be present. Your cooperation in admitting and assisting them while on site is appreciated.

The U.S. EPA recommends that personnel who are familiar with present and past manufacturing and waste management activities be available during the VSI. Access to any relevant maps, diagrams, hydrogeologic reports, environmental assessment reports, sampling data sheets, environmental permits (air, NPDES), manifests and/or correspondence is also necessary, as such information is needed to complete the PA/VSI.

If you have any questions, please contact me at (312) 886-4448 or Francene Harris at (312) 886-2884. A copy of the Preliminary Assessment/Visual Site Inspection Report, excluding the conclusions and Executive Summary portion will be sent when the report is available.

Sincerely yours,

Kevin M. Pierard, Chief

OH/MN Technical Enforcement Section

Enclosure

cc:

Ed Lim, OEPA Dave Wertz, OEPA

### ATTACHMENT I

The definitions of solid waste management unit (SWMU) and area of concern (AOC) are as follows.

A SWMU is defined as any discernable unit where solid wastes have been placed at any time from which hazardous constituents might migrate, regardless of whether the unit was intended for the management of a solid or hazardous waste.

The SWMU definition includes the following:

- RCRA regulated units, such as container storage areas, tanks, surface impoundments, waste piles, land treatment units, landfills, incinerators, and underground injection wells
- Closed and abandoned units
- Recycling units, wastewater treatment units, and other units that U.S. Environmental Protection Agency has generally exempted from standards applicable to hazardous waste management units
- Areas contaminated by routine and systematic releases of wastes or hazardous constituents, such as wood preservative treatment dripping areas, loading or unloading areas, or solvent washing areas

An AOC is defined as any area where a release to the environment of hazardous wastes or constituents has occurred or is suspected to have occurred on a nonroutine or nonsystematic basis. This includes any area where such a release in the future is judged to be a strong possibility.

PRC requests that, if available, the following facility information be provided during the VSI:

- 1. Two copies of a detailed map of the facility
- 2. Facility history, including dates of operation, ownership changes, and production processes
- 3. Current facility operations
- 4. Processes that generate waste that is treated, stored, or disposed of at the facility
- 5. Records of disposal of wastes generated at the facility (manifests, annual reports, etc...)
- 6. Security at the facility
- 7. Information regarding geology and the uses of ground water and surface water in the area
- 8. Permits (air, NPDES, etc...) the facility currently holds or has held in the past and documentation of any permit violations that may have occurred
- 9. Records of any spills that may have occurred at the facility
- 10. Descriptive operational information (location, dimensions, capacity, materials of construction, etc...), dates of start-up and closure, wastes managed, release controls, and release history for each SWMU

alosed 78I

O. WMD CC: RF(CERT-ROUTINE

# CERTIFICATION REGARDING POTENTIAL RELEASES FROM SOLID WASTE MANAGEMENT UNITS

FACILITY NAME: PREMIX INC	
EPA I.D. NUMBER: 0HD 0042 000 4	4 1/20 0 000 0000000000000000000000000000
LOCATION CITY: N. KINGSVILLE	CA CA CA
STATE: OHIO	0, 50 to 60 (1)
1. Are there any of the following solid waste ma closed) at your facility? NOTE - DO NOT INCLU CURRENTLY SHOWN IN YOUR PART A APPLICATION	nagement units (existing or DE HAZARDOUS WASTE UNITS
Landfill Surface Impoundment Land Farm Waste Pile Incinerator Storage Tank (Above Ground) Storage Tank (Underground) Container Storage Area Injection Wells Wastewater Treatment Units Transfer Stations Waste Recycling Operations Waste Treatment, Detoxification Other	FEB 18 1986  X  X  X  X  X  X  X  X  X  X  X  X  X
Provide a description of the wastes that were of in each unit. In particular, please focus would be considered as hazardous wastes or haz RCRA. Also include any available data on quar disposed of and the dates of disposal. Please of each unit and include capacity, dimensions Provide a site plan if available.	stored, treated or disposed on whether or not the wastes ardous constituents under stitles or volume of wastes also provide a description and location at facility.
NOTE: Hazardous wastes are those identified i constituents are those listed in Append  ). WMD	n 40 CFR 261. Hazardous ix VIII AONO 1936 A Part 1261.



•	For the units noted in Number 1 above and also those hazardous waste units
	in your Part A application, please describe for each unit any data available on any prior or current releases of hazardous wastes or constituents to the environment that may have occurred in the past or may still be occurring.
	Please provide the following information
	<ul> <li>a. Date of release</li> <li>b. Type of waste released</li> <li>c. Quantity or volume of waste released</li> <li>d. Describe nature of release (i.e., spill, overflow, ruptured pipe or tank, etc.)</li> </ul>
	NONE
	which would describe the nature and extent of environmental contamination
	that exists as a result of such releases. Please focus on concentrations hazardous wastes or constituents present in contaminated soil or groundwat None
	hazardous wastes or constituents present in contaminated soil or groundwat
	hazardous wastes or constituents present in contaminated soil or groundwat
	hazardous wastes or constituents present in contaminated soil or groundwat
	hazardous wastes or constituents present in contaminated soil or groundwat
	hazardous wastes or constituents present in contaminated soil or groundwat

Ford M. Davey Corporate Senior Vice President
Typed Name and Title

Signature

Typed Name and Title

Date

F.1 Imagery/Special Studies